

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5746M**AAD1812-132***Not Notarised**11 Sep 87**Book Value?*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5746M

VF1ABL15AUC281549

RENAULT

LATITUDE

13.12.2018

AIG

PART**LIST**

1	1	BUMPER COVER FRT	\$	<i>Mr</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>Mr</i> 181.75 ✓
3	1	BUMPER ABSORBER FRT	\$	<i>Mr</i> 394.68 ✓
4	1	BUMPER RETAINER FRT LH	\$	<i>CM</i> 151.41 ✓
5	1	BUMPER SUPPORT FRT	\$	<i>Di</i> 123.88 ✓
6	1	BUMPER RETAINER FRT RH	\$	<i>CM</i> 150.77 ✓
7	1	BUMPER SUPPORT FRT	\$	<i>Di</i> 123.88 ✓
8	1	BUMPER UNDERTRAY FRT	\$	<i>CM</i> 472.83 ✓
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Mr</i> 266.80 ✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Mr</i> 207.21 ✓
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Mr</i> 207.21 ✓
12	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 ✓
13	1	TOW COVER FRT	\$	<i>Mr</i> 28.61 ✓
14	1	RADIATOR GRILLE	\$	<i>CM</i> 1,707.78 ✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Mr</i> 225.36 ✓
16	1	RADIATOR GRILLE FRAME	\$	<i>CM</i> 1,353.75 ✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i> 615.90 ✓
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79 X
19	1	FRONT BRACE PANEL	\$	<i>R</i> 177.22 ✓
20	1	HORN	\$	<i>Sm</i> 314.17 X
21	1	HORN BRACKET	\$	<i>R</i> 40.45 X
22	1	HEADLAMP LH	\$	<i>Mr</i> 1,184.43 ✓
22	1	HEADLAMP HARNESS	\$	928.29 ?
22	1	HEADLAMP RH	\$	<i>Br</i> 1,184.43 ✓
22	1	HEADLAMP HARNESS	\$	928.29 ?
22	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
25	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 ✓
26	1	BONNET	\$	<i>R</i> 1,941.63 ✓

Trans-cab Auto Services Pte Ltd**AAD1812-132**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5746M

27	1	BONNET INSULATOR	\$	CM 405.73	✓
28	1	BONNET STRUT LH	\$	Pr 88.61	✓
29	1	BONNET STRUT RH	\$	R 88.61	✓
30	1	BONNET HINGE LH	\$	DI 348.31	✓
31	1	BONNET HINGE RH	\$	R 348.31	✓
32	1	BONNET LOCK	\$	DI 305.48	✓
33	1	BONNET CABLE	\$	Sn 119.19	X
34	1	BONNET CABLE COVER	\$	Sn 161.03	X
35	1	BONNET SEAL OUTER	\$	T 92.36	✓
36	1	BONNET SEAL INNER	\$	T 157.28	✓
37	1	FENDER PANEL FRT LH	\$	R 783.83	✓
38	1	WHEELARCH FRT LH	\$	CM 278.84	✓
39	1	FENDER PANEL INNER FRT RH L70Y	\$	1,654.50	?
40	1	FENDER PANEL SUPPORT FRT RH L70Y	\$	1,095.24	?
41	1	FENDER PANEL BRACKET FRT RH L70Y	\$	R 209.97	X
42	1	FENDER PANEL BRACKET FRT RH L70Y	\$	R 143.27	X
43	1	WHEEL HOUSING PANEL FRT RH L70Y	\$	4,682.09	?
44	1	FENDER BRACKET LOWER LH	\$	Sn 15.79	X
45	1	FENDER INSULATOR LH	\$	Sn 130.84	X
46	1	WIPER RESERVOIR	\$	De 348.25	✓
47	1	WIPER RESERVOIR NECK	\$	De 136.11	✓
48	1	WIPER RESERVOIR MOTOR	\$	Sn 270.06	} X
49	1	AIR CLEANER LOWER	\$	Sn 271.26	
50	1	AIR CLEANER HOSE	\$	Sn 76.14	
51	1	AIR CLEANER BOX	\$	Sn 464.20	
52	1	TURBO DUCT	\$	Sn 1,027.80	
53	1	A/C HEATER VALVE	\$	Sn 484.50	
54	1	SUBFRAME OUTER FRT	\$	Sn 2,652.45	
55	1	SUBFRAME BRACKET OUTER LH	\$	Sn 92.36	} X
56	1	SUBFRAME BRACKET OUTER RH	\$	Sn 92.36	
57	1	ENGINE UNDERTRAY	\$	Sn 564.98	
58	1	A/C CONDENSER	\$	R 2,020.37	
59	1	A/C CONDENSER GARNISH LH UPPER	\$	Sn 39.67	
60	1	A/C CONDENSER GARNISH RH UPPER	\$	Sn 39.67	} X
61	1	A/C CONDENSER GARNISH LH	\$	Sn 58.81	
62	1	A/C CONDENSER GARNISH RH	\$	Sn 59.60	
63	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	Sn 208.39	
64	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Sn 658.72	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5746M**AAD1812-132**

74	1	A/C PIPE COMPRESSOR	\$	S _h	334.29	}	X
75	1	A/C PIPE	\$	S _h	658.72		
76	1	A/C COMPRESSOR	\$	S _h	2,684.61		
77	1	AIR COOLER	\$	S _h	792.60		
78	1	AIR INTERCOOLER HOSE (LONG)	\$	S _h	1,014.13		
79	1	AIR INTERCOOLER HOSE (Short)	\$	S _h	375.14		
80	1	TRANSMISSION COOLER	\$	S _h	1,219.30	}	
81	1	TRANSMISSION COOLER PAD	\$	S _h	17.96		
82	1	RADIATOR	\$		1,202.20	✓	
83	2	RADIATOR STUD UPPER	\$	S _h	14.41	X	
84	2	RADIATOR BUSH UPPER	\$	S _h	50.12	X	
85	2	RADIATOR MTG LOWER	\$	S _h	55.85	X	
86	1	RADIATOR FAN COWLING	\$		820.54	✓	
87	1	RADIATOR FAN MOTOR LH	\$	S _h	967.36	X	
88	1	RADIATOR FAN MOTOR RH	\$	S _h	1,479.46	X	
89	1	RADIATOR TANK	\$	S _h	324.62	}	
90	1	RADIATOR HOSE UPPER	\$	S _h	240.56		
91	1	RADIATOR HOSE LOWER	\$	S _h	491.18		
92	1	RADIATOR TANK HOSE	\$	S _h	61.18		
93	1	AUTO COMPUTER	\$	S _h	5,032.17	}	X
94	1	INJECTION COMPUTER	\$	S _h	4,706.30		
95	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	S _h	5,154.52		
96	1	STEERING PUMP ELECTRIC	\$	S _h	2,306.90		
97	1	STEERING PINION RACK	\$	S _h	4,413.11		
98	1	DOOR PANEL FRT RH	\$	R _h	2,844.66	✓	
99	1	DOOR HINGE UPPER RH	\$	R	261.28	X	
100	1	DOOR HINGE LOWER RH	\$	R	300.55	X	
101	1	DOOR CHECK FRT RH	\$	R	194.77	}	
102	1	DOOR LOCK FRT RH	\$	R	908.75		
103	1	DOOR CATCH FRT RH	\$	S _h	131.23		
104	1	DOOR HANDLE OUTER FRT RH	\$	S _h	477.76		
105	1	DOOR HANDLE COVER FRT RH	\$	S _h	13.22	}	X
106	1	DOOR HANDLE MODULE FRT RH	\$	S _h	133.60		
107	1	DOOR REGULATOR FRT RH	\$	S _h	505.19		
108	1	DOOR REGULATOR MOTOR FRT RH	\$	S _h	796.46		
109	1	DOOR REGULATOR GUIDE FRT RH	\$	S _h	120.97		
110	1	DOOR PANEL REAR RH	\$	R _h	2,844.66	✓	
111	1	DOOR GUIDE REAR RH	\$	R	176.82	X	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5746M**AAD1812-132**

112	1	DOOR HINGE UPPER RH	\$	R	274.50	✓
113	1	DOOR HINGE LOWER RH	\$	R	300.55	X
114	1	DOOR CHECK REAR LH/RH L70Y	\$	SL	203.06	X
115	1	DOOR LOCK REAR RH	\$	R	908.75	X
116	1	DOOR HANDLE OUTER REAR RH	\$	BR	126.49	✓
117	1	DOOR HANDLE CAP REAR RH	\$	SL	35.52	X
118	1	DOOR HANDLE SEAL REAR RH	\$	SL	7.89	
119	1	DOOR HANDLE COVER REAR RH	\$	SL	13.22	
120	1	DOOR HANDLE MODULE REAR RH	\$	SL	133.60	
121	1	DOOR REGULATOR REAR RH	\$	SL	1,135.10	
122	1	DOOR REGULATOR MOTOR REAR RH	\$	SL	893.75	
123	1	DOOR REGULATOR NUT REAR L70Y	\$	SL	12.43	
124	1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	SL	6.31	
125	1	DOOR FINISHER REAR RH	\$	SL	423.10	
126	1	DOOR MOULDING REAR RH	\$	SL	176.82	
127	1	DOOR MOULDING CLIP L70Y	\$	SL	5.92	
128	1	DOOR MOULDING SCREW L70Y	\$	SL	6.91	
129	1	DOOR CASING REAR RH	\$	SL	1,509.06	
130	1	DOOR WATER SHIELD REAR RH	\$	SL	30.39	
131	1	DOOR CASING CLIP	\$	SL	12.63	
132	1	DOOR CASING LIGHT L70Y	\$	SL	48.74	
133	1	DOOR FINISHER INNER REAR RH	\$	SL	323.44	
134	1	DOOR FINISHER BRACKET INNER REAR RH	\$	SL	46.97	
135	1	DOOR FINISHER BRACKET INNER REAR RH	\$	SL	20.33	
136	1	DOOR FINISHER BRACKET INNER REAR RH	\$	SL	20.33	
137	1	DOOR FINISHER BRACKET INNER REAR RH	\$	SL	20.33	
138	1	DOOR GRAB HANDLE REAR RH	\$	SL	210.96	
139	1	DOOR BLIND REAR RH	\$	SL	741.80	
140	1	DOOR WHEATHESTRIIP REAR RH	\$	SL	410.66	
141	1	DOOR SEAL REAR RH	\$	SL	162.02	
142	1	DOOR GLASS RUNNER SEAL REAR RH	\$	SL	229.31	
143	1	DOOR WAIST SEAL OUTER REAR RH	\$	SL	334.69	
144	1	DOOR WAIST SEAL INNER REAR RH	\$	SL	115.64	
145	1	FENDER PANEL REAR RH	\$	BR	3,299.13	✓
146	1	FENDER PANEL INNER TRIM REAR	\$	SL	671.45	X
147	1	WHEELARCH REAR RH	\$	SL	543.47	X
148	1	DOOR MIRROR ASSY RH	\$	CM	1,483.40	✓
149	1	BUMPER COVER REAR	\$	R	1,108.46	X

Trans-cab Auto Services Pte Ltd**AAD1812-132**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5746M

150	1	BUMPER LOWER REAR	\$	768.84	X
151	1	BUMPER BRACKET CTR REAR	\$	113.47	X
152	1	BUMPER BRACKET SIDE RH REAR	\$	135.97	X
153	1	BUMPER RETAINER RH REAR	\$	44.99	X
154	1	REAR TAILLAMP RH	\$	552.55	

TOTAL	\$	97,903.37
10%	\$	9,790.34
	\$	88,113.04

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00	
2	1SET	BUMPER CLIP FRT	\$	66.00	
3	1	BUMPER BRACKET CLIP FRT LH	\$	12.00	} X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	
7	1	TOW COVER FRT	\$	14.50	
8	1SET	RADIATOR GRILLE SCREW	\$	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	
21	1	Windscreen moulding	\$	100.00	
22	1SET	Front licence plate with holder	\$	80.00	\$55.00
23	1	DOOR CHECK BOLT	\$	22.69	} X
24	1	DOOR GUIDE SCREW	\$	10.85	
25	1	DOOR HINGE BOLT	\$	10.85	
26	1	DOOR HINGE NUT RH	\$	14.60	
27	1	DOOR CHECK BOLT	\$	22.69	
28	1	DOOR CHECK NUT	\$	3.75	
29	1	DOOR LOCK SCREW L70Y	\$	6.12	
30	1	DOOR CATCH SCREW L70Y	\$	10.06	
31	1	FRONT DOOR STICKER 'TRANS-CAB'	\$	80.00	60.00
32	1	FRONT DOOR STICKER 'CHASSIS'	\$	50.00	15.00

Trans-cab Auto Services Pte Ltd

AAD1812-132

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5746M

33 1 REAR DOOR STICKER'6555-3333'

\$

80.00

TOTAL \$ 874.13**TOTAL PARTS \$ 88,987.17**

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$

6,000.00

Towing Fees.

\$

120.00

To apply paint protection system (PPS) maintain
and enhancement

\$

380.00

Putty and spray painting of the affected portion.

\$

6,000.00

To rust-proofing of the affected areas.

\$

170.00

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair.

\$

380.00

To check steering geometry and computer wheel
alignment

\$

220.00

To pull and jack out chassis frame and correct it to
symmetrical position with the aid of hydraulic
pneumatic jack.

\$

380.00

Labour charge to mount and dismount vehicle on
jig bench, to facilitate repair.

\$

380.00

To lift-up engine with gear box and refit.

\$

440.00

To remove and renew power steering pump, oil
cooler pipe and final checking and testing.

\$

440.00

Trans-cab Auto Services Pte Ltd

AAD1812-132

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5746M

To remove and refit air bag system and reset.	\$	nn 480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 100%
To replace, refix and top up coolant for radiator	\$	170.00 50%
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 50%
To Transfer Of Bumper Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00 X
To Transfer Of Bonnet Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00 X
To Transfer Of Door Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 60%

TOTAL \$ 17,170.00**Over All Total \$ 106,157.17****Repair Days (Lump Sum)****30 DAYS**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: