

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5279U**AAD1812-135***Not Notation*
1/18/18

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHC 5279U

VF1ABL15AUC276825

RENAULT

LATITUDE

16.12.2018

III

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Per</i> 1,108.46 —
2	1 BUMPER LOWER REAR	\$	<i>Per</i> 768.84 —
3	1 BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97
5	1 BUMPER RETAINER RH REAR	\$	<i>SL</i> 44.99
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97
8	1 BUMPER RETAINER LH REAR	\$	<i>SL</i> 44.99
9	1 BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61
10	1 BUMPER BEAM REAR	\$	<i>Per</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>SL</i> 225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>SL</i> 225.95
13	1 BOOT REAR	\$	<i>SL</i> 2,872.68
14	1 BOOT FINISHER	\$	<i>SL</i> 470.06
15	1 BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05
16	1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35
17	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35
18	1 BOOT BADGE 'RENAULT'	\$	<i>SL</i> 225.36
19	1 BOOT BADGE	\$	<i>SL</i> 225.36
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08
22	1 BOOT HINGE LH	\$	<i>SL</i> 367.84
23	1 BOOT HINGE RH	\$	<i>SL</i> 367.84
24	1 BOOT INNER TRIM	\$	<i>SL</i> 586.45
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13
26	1 BOOT LOCK	\$	<i>SL</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>SL</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81

Trans-cab Auto Services Pte Ltd**AAD1812-135**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5279U

30	1 DOOR PANEL REAR LH	\$	N	2,844.66	}	X
31	1 FENDER PANEL INNER TRIM REAR LH	\$	SL	671.45		
32	1 FENDER PANEL REAR LH	\$	N	3,299.13		
33	1 WHEELARCH REAR LH	\$	SL	543.47		
34	1 FENDER PANEL INNER TRIM REAR RH	\$	SL	671.45		
35	1 FENDER PANEL REAR RH	\$	N	3,299.13		
36	1 WHEELARCH REAR RH	\$	SL	543.47		
37	1 TAILLAMP RH	\$	SL	552.55		
38	1 TAILLAMP PANEL RH	\$	N	986.70		
39	1 TAILLAMP LH	\$	SL	552.55		
40	1 TAILLAMP PANEL LH	\$	N	986.70		
41	1 OUTER PANEL REAR (End Panel)	\$	B	1,471.77	}	X
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	SL	404.56		
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	N	2,189.88		
44	1 SPARE WHEEL PANEL TRIM	\$	SL	612.21		
45	1 EXHAUST REAR	\$	N	7,489.05		
46	1 EXHAUST CAP REAR	\$	N	230.49		
47	1 CHASSIS PANEL REAR RH	\$	N	3,766.43		
48	1 KUCKLE ARM REAR RH L70Y	\$	SL	736.67		
49	1 BRAKE DISC REAR L70Y	\$	SL	525.91		
50	1 WHEEL HUB NUT L70Y	\$	SL	51.11		
51	1 WHEEL HUB CAP L70Y	\$	SL	57.82		
52	1 ABS SENSOR REAR RH L70Y	\$	SL	255.75		
53	1 REAR AXLE L70Y	\$	SL	4,167.03	}	X
54	1 AXLE ARM RH L70Y	\$	SL	117.22		
55	1 LOWER ARM REAR RH L70Y	\$	SL	905.99		
56	1 ABSORBER REAR	\$	SL	389.75		
57	1 STABILIZER BAR REAR RH	\$	SL	604.65		
58	1 BRAKE CALIPER REAR RH	\$	SL	1,300.67		
59	1 WINDSCREEN REAR L70Y	\$	SL	1,463.28		
60	1 WINDSCREEN GARNISH INNER LH	\$	SL	263.74		
61	1 WINDSCREEN GARNISH INNER RH	\$	SL	263.74		
62	1 FENDER WHEEL HOUSE PANEL REAR RH	\$	N	3,039.04		
63	1 FENDER PANEL INNER TRIM REAR RH	\$	SL	671.45		
64	1 BUMPER COVER FRT	\$	B	1,259.42	}	✓
65	1 BUMPER SPOILER FRT	\$	DI	181.75		
66	1 BUMPER ABSORBER FRT	\$	CM	394.68		
67	1 BUMPER RETAINER FRT LH	\$	DI	151.41		

Trans-cab Auto Services Pte Ltd**AAD1812-135**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5279U

68	1 BUMPER SUPPORT FRT	\$	SL 123.88	} X
69	1 BUMPER RETAINER FRT RH	\$	DIR 150.77	
70	1 BUMPER SUPPORT FRT	\$	SL 123.88	
71	1 BUMPER UNDERTRAY FRT	\$	SL 472.83	
72	1 BUMPER GRILLE LOWER FRT	\$	SL 266.80	
73	1 BUMPER FOG LAMP GRILLE LH	\$	SL 207.21	
74	1 BUMPER FOG LAMP GRILLE RH	\$	SL 207.21	} X
75	1 BUMPER BEAM FRT	\$	' 914.08	
76	1 TOW COVER FRT	\$	SL 28.61	X
77	1 RADIATOR GRILLE	\$	CM 1,707.78	✓
78	1 RADIATOR GRILLE BADGE 'RENAULT'	\$	RL 225.36	✓
79	1 RADIATOR GRILLE FRAME	\$	CM 1,353.75	✓
80	1 FRAME FULL SUPPORT PANEL	\$	CM 615.90	✓
81	1 FRAME FULL SUPPORT BRACKET	\$	R 89.79	X
82	1 FRONT BRACE PANEL	\$	R 177.22	X
83	1 HORN	\$	SL 314.17	X
84	1 HORN BRACKET	\$	R 40.45	X
85	1 HEADLAMP LH	\$	mj,cm 1,184.43	✓
86	1 HEADLAMP RH	\$	CM 1,184.43	✓
87	1 HEADLAMP PANEL FRT LH	\$	R 152.15	X
88	1 HEADLAMP PANEL FRT RH	\$	R 152.15	X
89	1 BONNET	\$	B 1,941.63	✓
90	1 BONNET INSULATOR	\$	SL 405.73	} X
91	1 BONNET STRUT LH	\$	SL 88.61	
92	1 BONNET STRUT RH	\$	SL 88.61	
93	1 BONNET HINGE LH	\$	R 348.31	
94	1 BONNET HINGE RH	\$	R 348.31	
95	1 BONNET LOCK	\$	DIR 305.48	
96	1 BONNET CABLE	\$	SL 119.19	
97	1 BONNET CABLE COVER	\$	SL 161.03	
98	1 BONNET SEAL OUTER	\$	SL 92.36	
99	1 BONNET SEAL INNER	\$	SL 157.28	
100	1 FENDER PANEL FRT LH	\$	R 783.83	} X
101	1 WHEELARCH FRT LH	\$	SL 278.84	
102	1 FENDER BRACKET LOWER LH	\$	SL 15.79	
103	1 FENDER INSULATOR LH	\$	SL 130.84	
104	1 FENDER INSULATOR RH	\$	SL 130.84	
105	1 AIR CLEANER LOWER	\$	SL 271.26	

Trans-cab Auto Services Pte Ltd**AAD1812-135**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5279U

106	1 AIR CLEANER HOSE	\$	76.14	}	X
107	1 BASE BATTERY TRAY	\$	363.40		
108	1 AIR CLEANER BOX	\$	464.20		
109	1 TURBO DUCT	\$	1,027.80		
110	1 A/C HEATER VALVE	\$	484.50		
111	1 SUBFRAME OUTER FRT	\$	2,652.45		
112	1 SUBFRAME BRACKET OUTER LH	\$	92.36	}	
113	1 ENGINE UNDERTRAY	\$	564.98		
114	1 A/C CONDENSER	\$	2,020.37		
115	1 A/C CONDENSER GARNISH LH UPPER	\$	39.67	}	X
116	1 A/C CONDENSER GARNISH RH UPPER	\$	39.67		
117	1 A/C CONDENSER GARNISH LH	\$	58.81		
118	1 A/C CONDENSER GARNISH RH	\$	59.60		
119	1 A/C PIPE CONDENSER TO COMPRESSOR	\$	208.39		
120	1 A/C PIPE CONDENSER TO EXPENSION VALVE	\$	658.72		
121	1 A/C PIPE COMPRESSOR	\$	334.29		
122	1 A/C PIPE	\$	658.72		
123	1 A/C COMRPRESSOR	\$	2,684.61	}	
124	1 AIR COOLER	\$	792.60		
125	1 AIR INTERCOOLER HOSE (LONG)	\$	1,014.13		
126	1 AIR INTERCOOLER HOSE (Short)	\$	375.14		
127	1 TRANSMISSION COOLER	\$	1,219.30		
128	1 TRANSMISSION COOLER PAD	\$	17.96	}	
129	1 RADIATOR	\$	1,202.20		
130	2 RADIATOR STUD UPPER	\$	14.41	}	S X
131	2 RADIATOR BUSH UPPER	\$	50.12		
132	2 RADIATOR MTG LOWER	\$	55.85		
133	1 RADAITOR FAN COWLING	\$	820.54		
134	1 RADIATOR FAN MOTOR LH	\$	967.36		
135	1 RADIATOR FAN MOTOR RH	\$	1,479.46		
136	1 RADIATOR TANK	\$	324.62		
137	1 RADIATOR HOSE UPPER	\$	240.56		
138	1 RADIATOR HOSE LOWER	\$	491.18		
139	1 RADIATOR TANK HOSE	\$	61.18		

TOTAL	\$	96,257.18
10%	\$	9,625.72
	\$	86,631.46

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5279U**AAD1812-135****Specical Nett**

1 1SET PARKING AID	\$	Shat	700.00	Goosa
2 1SET REAR BUMPER CLIP	\$	na	66.00	✓
3 1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
4 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5 1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6 1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7 1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8 1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10 1 EXHAUST MOUNTING REAR	\$	Sh	17.82	X
11 1SET BOOT FINISHER CLIP	\$	na	24.20	X
12 1 BOOT STICKER "Trans-cab"	\$	na	30.00	✓
13 1 BOOT STICKER "6555-3333"	\$	na	30.00	✓
14 1 BOOT INNER TRIM CLIP	\$	na	45.00	} X
15 1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
16 1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
17 1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
18 1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
19 1 TAILLAMP CLIP RH	\$	na	5.00	
20 1 TAILLAMP CLIP LH	\$	na	5.00	
21 2 REAR WINDSCREEN SELANT	\$	na	80.00	
22 1 WINDSCREEN MOULDING	\$	na	100.00	
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sh	385.00	} X
25 1 SPARE TYRE	\$	Sh	330.00	
26 1SET RADIATOR GRILLE FRAME CLIP	\$	na	52.00	
27 1SET BUMPER CLIP FRT	\$	na	66.00	
28 1 BUMPER BRACKET CLIP FRT LH	\$	na	12.00	
29 1 BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
30 1 BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
31 1 BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
32 1 TOW COVER FRT	\$	Sh	14.50	
33 1SET RADAITOR GRILLE SCREW	\$	na	16.00	
34 1SET BUMPER GRILLE LOWER CLIP	\$	na	69.00	} X
35 1SET FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
36 2 FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	

Trans-cab Auto Services Pte Ltd**AAD1812-135**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5279U

37	1 LEFT REAR TYRE	\$	SL	330.00	X
38	1 LEFT REAR TYRE RIM	\$	SL	380.00	X
39	2 FRAME FULL SUPPORT PANEL STUD	\$	SL	30.00	X
40	1 Windscreen moulding	\$	NA	100.00	X
41	1SET Front licence plate with holder	\$	BM	80.00	45SL

TOTAL \$ 3,497.52**TOTAL PARTS \$ 90,128.98****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	1200
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	1320
To Rust-Proofing Of The Affected Areas.	\$	170.00	90
To reinstall rear bumper parking sensor.	\$	170.00	60
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	NA	170.00 X
To repair and realign rear exhaust pipe.	\$	NA	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	NA	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	60
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	NA	170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	NA	380.00 X

Trans-cab Auto Services Pte Ltd**AAD1812-135**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5279U

To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	nn 380.00 X
Towing Fees.	\$	120.00 506
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00 X
To rust-proofing of the affected areas.	\$	nn 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 401
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1812-135**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5279U

To lift-up engine with gear box and refit.	\$	<i>nn</i> 440.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>nn</i> 440.00	X
To remove and refit air bag system and reset.	\$	<i>nn</i> 480.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>nm</i> 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	380.00	<i>10d</i>
To replace, refix and top up coolant for radiator	\$	170.00	<i>501</i>
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	<i>501</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>m</i> 170.00	X

TOTAL \$ 19,720.00**Over All Total \$ 109,848.98****(LUMP SUM)****Repair Days*****25 DAYS****10 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: