

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5642D**AAD1812-124***Not Authored*
61 Sup B 70506

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5642D

VF1ABL15AUC280338

RENAULT

LATITUDE

15.12.2018

III

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>Not in</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47 X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97 X
5	1 BUMEP R RETAINER RH REAR	\$	<i>SL</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>CM</i> 43.61 ✓
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97 X
8	1 BUMEP R RETAINER LH REAR	\$	<i>SL</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>N</i> 225.95 X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>MI</i> 225.95 ✓
13	1 BOOT REAR	\$	<i>Bu</i> 2,872.68 ✓
14	1 BOOT FINISHER	\$	<i>SL</i> 470.06 X
15	1 BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05 X
16	1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35 X
17	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35 X
18	1 BOOT BADGE 'RENAULT'	\$	<i>N</i> 225.36 ✓
19	1 BOOT BADGE	\$	<i>N</i> 225.36 ✓
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08
22	1 BOOT HINGE LH	\$	<i>N</i> 367.84
23	1 BOOT HINGE RH	\$	<i>N</i> 367.84
24	1 BOOT INNER TRIM	\$	<i>SL</i> 586.45 } X
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13
26	1 BOOT LOCK	\$	<i>N</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>N</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5642D**AAD1812-124**

30	1 FENDER PANEL REAR LH	\$	R	3,299.13	
31	1 WHEELARCH REAR LH	\$	Sn	543.47	
32	1 FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	
33	1 WHEEL HOUSING PANEL REAR LH	\$	R	4,682.09	
34	1 FENDER PANEL REAR RH	\$	R	3,299.13	
35	1 WHEELARCH REAR RH	\$	Sn	543.47	
36	1 FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	
37	1 WHEEL HOUSING PANEL REAR RH	\$	Sn	4,682.09	
38	1 TAILLAMP LH	\$	Sn	552.55	
39	1 TAILLAMP PANEL LH	\$	R	986.70	
40	1 TAILLAMP RH	\$	Sn	552.55	
41	1 TAILLAMP PANEL RH	\$	R	986.70	
42	1 OUTER PANEL REAR (End Panel)	\$	B	1,471.77	
43	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sn	404.56	X
44	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
45	1 SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
46	1 EXHAUST REAR	\$	R	7,489.05	X
47	1 EXHAUST CAP REAR	\$	R	230.49	X

TOTAL	\$	45,233.12
10%	\$	4,523.31
	\$	40,709.81

Special Nett

1	1SET PARKING AID	\$	Sn	700.00	X
2	1SET REAR BUMPER CLIP	\$	Nbc	66.00	
3	1SET BUMPER BRACKET CTR CLIP	\$	nn	33.00	
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	nn	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	nn	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	
10	1 EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	1SET BOOT FINISHER CLIP	\$	nn	24.20	X
12	1 REAR BOOT ADVERTISEMENT STICKER	\$	nn	300.00	150Sn
13	1 REAR BUMPER ADVERTISEMENT STICKER	\$	nn	100.00	80Sn
14	1 REAR RIGHT FENDER ADVERTISEMENT STICKER	\$	nn	300.00	X

Trans-cab Auto Services Pte Ltd

AAD1812-124

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5642D

15	1 REAR LEFT FENDER ADVERTISEMENT STICKER	\$	<i>nn</i> 300.00	} X
16	1SET FENDER WHEELARCH REAR RH CLIP	\$	<i>nn</i> 35.00	
17	1SET FENDER WHEELARCH REAR LH CLIP	\$	<i>nn</i> 35.00	
18	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00	
19	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00	
20	1 TAILLAMP CLIP RH	\$	<i>nn</i> 5.00	
21	1 TAILLAMP CLIP LH	\$	<i>nn</i> 5.00	
22	2 REAR WINDSCREEN SELANT	\$	<i>nn</i> 80.00	
23	1 WINDSCREEN MOULDING	\$	<i>nn</i> 100.00	
24	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00	
25	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>nn</i> 385.00	
26	1 SPARE TYRE	\$	<i>nn</i> 330.00	

TOTAL \$ 3,120.02

TOTAL PARTS \$ 43,829.83

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 <i>6601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00 <i>6001</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>601</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>601</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1812-124**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5642D

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 X
To check steering geometry and computer wheel alignment	\$	220.00 X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	380.00 X

TOTAL \$ 14,340.00**Over All Total \$ 58,169.83****(LUMP SUM)****Repair Days****20 DAYS****5 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: