

REF: ALG

ASSIGNMENT

From:

Date: 19/12/18

Estimated Cost:

OT / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SHC 4404 G

at Workshop n/s

SMRT

of

woodlands Depot

Insured

Policy No

Claims No

Sum Insured


Excess:

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res:

Yes or No

Lum Sum:

10

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

SHC 4404 G

Reg: 6 Jan 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

CC 1799

Colour:

Maroon

A/C Insured / Std / NI / NA

Sp Reading:

524699

T/Radio: Insured / Std / NI / NA

Eng/No:

C/Nr

JTDKN36UX05721063

Gen. Cond: Good / Fair / Poor / BurntSteering: Knock / Jammed / Leaked / Burnt orBrake: Knock / Jammed / Leaked / Burnt orMod: Nil / 2/Rim / STD A/Rim or

Tyre Size:

F: 195/65 R15

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

17/12/18

D.O.A.

19/12/18

Survey held at

Smrt

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/18/2014

SLK 2086 P

L1516 2,750.00 (Red 4,764.63 / 63.40%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS. \$

) Photo

) Other

) :

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$



☐

: Weekend (\$

Poh Kim

Section A - Accident Details

Registration Number	SHC4404G
Case Reference Number	TAX/12/18/2074
Registration Date	6/1/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	YEOH LYE SAN(YANG LAISHAN)
Type of Accident	Head to Rear
Accident Date and Time	17/12/2018 6:25 PM
Accident Reported Date and Time	18/12/2018 1:25 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24099310
Special Instruction to ARC, if any	DROVE IN
Prepared Date and Time	18/12/2018 2:37 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Left Side

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,264.00	\$500.00
Total Spray Cost	\$1,296.00	\$500.00
Total Spare Part Cost	\$4,114.53	\$1,505.26
Total Other Cost	\$840.00	\$220.00
TOTAL COST	\$7,514.53	\$2,725.23
Lump Sum Total	\$7,500.00	\$2,750.00 (L/S)
Number of Repair Days	9.0	5.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	20/12/2018 7:55 AM	19/12/2018 3:52 PM
Signature		
Remarks	Initial estimate = 7 days Request number of days to extend 2 days	L/S photo after repair. Supplementary item send e-mail to: hweejie@lkkauto.com

Finalized - Hwee Jie

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1812-0555	Invoice Number	
Quotation Date	27.12.2018	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,014.00	\$400.00
TO REPAIR REAR END PANEL	\$250.00	\$100.00
Total Labour	\$1,264.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO REPSRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,296.00	\$500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$120.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$50.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$840.00	\$220.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.80	0.00	\$0.00	Replace	Check X
		75573-47060	TAIL GATE DOOR GLASS MOULDING, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given X
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given X
		75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace
		87881-47022	TAILGATE DOOR WEATHER STRIP	0.00	\$353.40	0.00	\$0.00	Replace	Not Given X
		69415-47020	TAILGATE LOCK, COVER	0.00	\$15.70	0.00	\$0.00	Replace	Not Given X
4006314			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given X
		58308-47011	UNDER COVER SUBASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given X

nn
nee
nn
nn
nee
nn
nn
nn



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 737798
FAX Number: 63989932
Estimate Telephone Number: 68962023
Account Reporting Number: 68862673

Date Generated : 11/01/2019

User ID : PehBuan

75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	✓	nec
52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check	X	nn
52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given	X	nn
69431-47010	STRIKER, BACK DOOR	0.00	\$48.90	0.00	\$0.00	Replace	Not Given	X	nn
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	✓	nec
75575-47030	MOULDING BACK WINDOW, LOWER NO.1	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓	nec
52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace	✓	nec
58311-47071	SPARE TYRE PANEL	0.00	\$667.70	0.00	\$0.00	Replace	Not Given	X	nn
52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check	X	nn
	SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace	✓	nec
	SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X	nn
58336-12090	REINFORCEMENT, RR	0.00	\$34.60	0.00	\$0.00	Replace	Check	X	nn
52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace	✓	CRF
52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace	✓	DEF
67005-47241	TAILGATE ASY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace	✓	DD
76097-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given	X	nn
52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X	nn
76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given	X	nn
89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given	X	nn
69350-47030	TAILGATE DOOR LOCK	0.00	\$444.10	0.00	\$0.00	Replace	Not Given	X	nn
58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check	X	nn
Total			\$6,008.91		\$1,515.14				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace	✓ DD
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace	✓ BT
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace	✓ BT
Total					484.90		363.68			

1882.82
- 20%
1506.26
+ 500.00
+ 720.00
2726.26
L/S \$2750/-

Hwee Jie-Lk

1/2/19 - Finalized L/S repair \$2,750/- 5 days.

Signature



Case Details

Case Reference Number : TAX/12/18/2074
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4404G

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5006-ID
 Assigned By : Kok Wah Wong

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 17/12/2018 10:25 AM
 Vehicle Age(In Months) : 59

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.92	Replace * DD
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace * NEC
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace * NEC
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace * NEC
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace * NEC
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0	Not Give *
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0	Not Give *
One Time Key In	Main			TAILGATE LOCK COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Not Give *
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0	Not Give *
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace * NEC
One Time Key In	Main			END PANEL	1	502.10	502.10	25.00	451.58	Replace	0	0	Check *
									Total Spare Part Cost			Surveyor Total	1,519.12
									Lump Sum Discount (%)	20.00		Lump Sum Dis (%)	20
									Final Spare Part Cost	3,823.70		Final Sur Total	1,215.30

SMRT Recommendation											Surveyor Approval				
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
One Time Key In	Main		4006314	REINFORCEMENT, RR	2	34.60	69.20	25.00	51.90	Replace	0	0	Check	*	
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	*	
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	0	0	Not Give	*	
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	*	OEF
One Time Key In	Main			BUMPER CLIPS	10	1.81	18.10	25.00	12.08	Replace	10	12.08	Replace	*	NEC
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	*	
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	*	
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	*	
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Not Give	*	
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	*	
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	*	NEC
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	*	
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	*	
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give	*	
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give	*	
One Time Key In	Main			BUMPER SEAL, RR RH	1	85.70	85.70	25.00	64.28	Replace	0	0	Not Give	*	
Total Spare Part Cost									4,779.62		Surveyor Total	1,519.12			
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20			
Final Spare Part Cost									3,823.70		Final Sur Total	1,215.30			

SMRT Recommendation											Surveyor Approval		
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER SIDE RETAINER RRLH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace * CRA
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give *
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give *
Total Spare Part Cost									4,779.62		Surveyor Total	1,519.12	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									3,823.70		Final Sur Total	1,215.30	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR REAR PORTION	1,014.00	400	
Total:		1,014.00	400.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
2	TO RESPRAY TAIL GATE	378.00	200	
3	TO RESPRAY REAR PANEL	180.00	0	
4	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	
Total:		1,116.00	400.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	TO TRANSFER REAR TAILGATE MECHANISM	120.00	50	
3	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120	
4	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	
5	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	120.00	0	
Total:		640.00	220.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
6	TO REPLACE SUNDRY PARTS	100.00	0	
7	TO WASH AND VACUUM	60.00	0	
Total:		840.00	220.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	3,623.70	1,215.30
Total Labour Cost	0.00	400.00
Total Spray Painting	0.00	400.00
Other	0.00	220.00
Overall Total	3,623.70	2,235.30
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	3,600.00	2,250.00
Surveyor Approved Amount		2,250.00
No of Repair Days*	7	4
Remarks		L/S photo after repair. Supplementary item send e-mail to: hweeje@lkkauto.com
Surveyor Name		Hwee je
Signature		
Survey Date	19/12/2018	

Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Poh Kin (LKKAUTO)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>
Sent: Monday, 11 March 2019 2:16 PM
To: Poh Kin (LKKAUTO)
Cc: Admin A
Subject: RE: Accident on 17/12/2018 involving SHC 4404G & SLK 2086P (AIG's insured) Our Ref: TAX/12/18/2074/lg *** LKK REF: CC3/AIG18022852/Jfa3

Dear Poh Kin,

We accept your global offer of \$4,070.00 (all in). Please let us have your DV. Thanks for your prompt settlement.

Regards

Tan Lee Gek (DID: 6866 2647)
Claims Department
SMRT Automotive Services Pte Ltd



From: Poh Kin (LKKAUTO) [mailto:pohkin@lkkauto.com]
Sent: 09/03/2019 13:47
To: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)
Cc: Admin A
Subject: RE: Accident on 17/12/2018 involving SHC 4404G & SLK 2086P (AIG's insured) Our Ref: TAX/12/18/2074/lg *** LKK REF: CC3/AIG18022852/Jfa3
Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC3/AIG18022852/Jfa3
Your Ref: TAX/12/18/2074/lg

Dear Lee Gek,

We refer to above matter.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement at global sum of **\$4,070.00(all in)** on this matter.

Kindly confirm acceptance on this matter.

Your prompt reply will be very much appreciated.

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Saturday, 9 March 2019 1:47 PM
To: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)
Cc: Admin A
Subject: RE: Accident on 17/12/2018 involving SHC 4404G & SLK 2086P (AIG's insured) Our Ref: TAX/12/18/2074/lg *** LKK REF: CC3/AIG18022852/Jfa3

Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC3/AIG18022852/Jfa3
Your Ref: TAX/12/18/2074/lg

Dear Lee Gek,

We refer to above matter.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement at global sum of **\$4,070.00(all in)** on this matter.

Kindly confirm acceptance on this matter.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>
Sent: Thursday, 7 March 2019 11:03 AM
To: CS A Team; Admin A
Subject: Re: Accident on 17/12/2018 involving SHC 4404G & SLK 2086P (AIG's insured) Our Ref: TAX/12/18/2074/lg
Attachments: TAX 12 18 2074.pdf; 20190102_175131.jpg

Dear All,

We quantify our claim as follows:-

Cost of Repair	\$2750.00
Loss of Rental	\$864.56 (8 days x \$108.07)
Loss of Income	\$701.36 (8 day x \$87.67)
LTA Search Fee	\$7.00
Total	\$4322.92

$108.07 \times 7 = 756.49$
 $87.67 \times 7 = 613.69$

We enclose the following documents:

- 1) Repair invoice
- 2) Proof of rental rate
- 3) police/GIA reports
- 4) Accident vehicle laid-up report
- 5) LTA search
- 6) Hirer's current income tax assessment

Please let us have your offer soon. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)
Claims Department
SMRT Automotive Services Pte Ltd





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC3/AIG18022852/Jfa3

19th February 2019

CHIN KIMPAT

512 Bedok North Avenue 2,
#06-283,
Singapore 460512.

Attn: Mr Chin Zhen Xing

Dear Sir/Madam,

**ROAD TRAFFIC ACCIDENT INVOLVING NOS. SLK 2086P AND SHC 4404G ALONG
PIE ON 17.12.2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Poh Kin, Chong

Case Handler

DID: 6841 2132

FAX: 6741 4108

Email: pohkin@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*

AUTHORISATION TO ACT

I/We, **SMRT TAXIS PTE LTD** ("the third party claimant") of **BLK 60 WOODLANDS INDUSTRIAL PARK E4 (S) 757705** (address), owner of **SHC 4404G** (vehicle no.) hereby authorize **SMRT AUTOMOTIVE SERVICES PTE LTD** ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. **SHC 4404G** that was damaged pursuant to the accident which occurred on **17/12/2018** (date) along **PIE** (location) involving vehicle no/s **SLK 2086P** ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of SMRT TAXIS PTE LTD.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 11 (day) of March (month) 2019 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, SMRT AUTOMOTIVE SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$4,070.00 (Global Sum) for vehicle no. SHC 4404G that was damaged pursuant to the accident which occurred on 17/12/2018 (date) along PIE (location) involving vehicle no/s SLK 2086P.

This is pursuant to the inspection conducted on 19/12/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SMRT TAXIS PTE LTD ("the third party claimant") of vehicle no. SHC 4404G make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SHC 4404G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 11 (day) of March (month) 2019 (year)

OKS


Signed by appointed surveyor



Signed by "the workshop" (with chop)



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705



SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV190200103
Date : 14.02.2019
Vehicle No. : SHC4404G
Your Ref No. : TAX/12/18/2074
Our Ref No. : 24099310
Terms : 30 Days

Description	Qty	Unit Cost	Add / (Discount) Amount	Amount
LUMP SUM AMOUNT FOR REPAIR AS PER SURVEYOR'S RECOMMENDATION	1.00		\$	2,750.00
GRAND TOTAL				\$ 2,750.00

Remark :

Make/Model : TOYOTA PRIUS
Accident Date : 17.12.2018

N.B. Payment by cheque should be crossed and
made payable to 'SMRT Automotive Services Pte Ltd'.
No receipt will be issued unless requested.

Authorised Signature
for SMRT Automotive Services Pte Ltd



SMRT Taxis Pte Ltd

MEMORANDUM

To: Claims Dept

Our Ref: TAX/12/18/2074

From: SMRT Taxis Pte Ltd

Date: 27/12/2018

ACCIDENT INVOLVING SHC 4404G & SLK 2086P ON 17/12/2018 ALONG PIE TOWARDS CHANGI AIRPORT

This is to confirm that the daily rental rate for SHC 4404G is \$108.07 per day.

Please proceed to recover any rental loss from the third party as a result of the above accident.

Thank you.

Yours sincerely
SMRT TAXIS PTE LTD



for Manager



Laid Up Report

Accident Start Date : 02/12/2018
Accident End Date : 01/01/2019

Date Generated : 02/01/2019
User Name : LeeGek

Case Reference Number	Vehicle Registration Number	Company Type	Vehicle Make	Vehicle Model	Job Card Number	Date and Time (Accident Repair)	Date and Time (Repair Completed)
TAX/12/18/2074	SHC4404G	SMART Taxis Pte Ltd	TOYOTA	PRUIS	24099310	17/12/2018 7:59 PM	26/12/2018 8:55 AM

Enquire Transaction History

Transaction History Details

Log Date/Time:	18 Dec 2018 / 15:52:34	Transaction Amount:	\$7.49
Asset Type:	Vehicle		
Asset ID:	SLK2086P		
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)	Channel:	External Agency
User ID:	ESASBAH0 - BALQISH BINTE ABDUL HALIL	Business Transaction Reference No.:	20181218155234368275

Search Date / Time: 17 Dec 2018 18:25:00
Insurance Company: AIG ASIA PACIFIC INSURANCE PTE. LTD.
Information displayed is correct as at the log date and time.

[Enquire Related Logs](#)[Back to List](#)

Tax Reference No: SXXXX574A
Year of Assessment: 2018
Income Tax
Date: 06 May 2018

NOTICE OF ASSESSMENT ORIGINAL




INLAND REVENUE
AUTHORITY
OF SINGAPORE

55 Newton Road
Revenue House
Singapore 307987
Tel: 1800-356 8300
Website: <http://www.iras.gov.sg>
e-Services: <https://mytax.iras.gov.sg>

Please quote the Tax Reference Number (eg NRIC, FIN, etc) in full when corresponding with us.

MR YEOW LYE SAN
326 WOODLANDS ST 32
#01-105
SINGAPORE 730326



11005-1

	S'PORE (\$)	OTHER COUNTRIES (\$)	TOTAL (\$)
TRADE	32,000.00		32,000.00
TOTAL INCOME	32,000.00		32,000.00
ASSESSABLE INCOME			32,000.00
LESS: PERSONAL RELIEFS			
Earned Income		1,000.00	
NSman-self/wife/parent		1,500.00	
Provident Fund/Life Insurance		541.00	
TOTAL PERSONAL RELIEFS			3,041.00
CHARGEABLE INCOME			28,959.00
FIRST 8,959.00 @ 2.00%			179.18
LESS: TAX SETOFFS			
Parenthood Tax Rebate/Further Tax Rebate			179.18
TAX PAYABLE			0.00

1. Your tax assessment is based on information given by you through e-Filing on 18 Apr 2018.
2. If you have any objection, please submit your objection online within 30 days via the Object to Assessment e-service or email us at my Tax Portal.

Signature

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING
















Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Dec 2018 Edit Reg		19 Dec 2018 00:00 Edit Adj Rpt	S\$2,750.00 Edit Estimates	S\$2,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	CHIN KIMPAT, ID: S2568340D								
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHC4404G	Date of Loss:	17/12/2018 18:00 - :59 [59 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4918358818SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SLK2086P	Policy No. (Claimant):	D-18090213MFSH						
		Excess:							
Reparer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands • Tel: 68662628								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 02/01/2019]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
• AIG_SG (21/12/2018): TP GIA REPORT									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC4404G (4918358818SG)
[SLK2086P]
TP
SMRT TAXIS PTE LTD
Dec 17 2018 6:00PM
[CHIN KIMPAT]
SMRT Automotive Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		<input type="checkbox"/>			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	28/12/18 15:24	Video - Accident From:OD - Reg. No: SLK2086P, Claimant: CHIN KIMPAT														Load MP4				
Letters/Correspondences															1 per page		<input type="checkbox"/>			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown														Edit				
Assessment Reports															1 per page		<input type="checkbox"/>			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	28/12/18 15:24	Accident Statement From:OD - Reg. No: SLK2086P, Claimant: CHIN KIMPAT														Load HTM				
Photos/Images															3 per page		<input type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	21/12/18 10:26	General View														Load JPG <input type="checkbox"/>				
2	21/12/18 10:26	General View														Load JPG <input type="checkbox"/>				
3	21/12/18 10:26	General View														Load JPG <input type="checkbox"/>				
4	21/12/18 10:26	General View														Load JPG <input type="checkbox"/>				
5	21/12/18 10:26	General View														Load JPG <input type="checkbox"/>				
6	21/12/18 10:26	General View														Load JPG <input type="checkbox"/>				
7	21/12/18 10:26	General View														Load JPG <input type="checkbox"/>				
8	21/12/18 10:26	General View														Load JPG <input type="checkbox"/>				
9	21/12/18 10:26	General View														Load JPG <input type="checkbox"/>				
10	21/12/18 10:26	General View														Load JPG <input type="checkbox"/>				
11	21/12/18 10:26	General View														Load JPG <input type="checkbox"/>				
12	21/12/18 10:26	General View														Load JPG <input type="checkbox"/>				
13	21/12/18 10:26	General View														Load JPG <input type="checkbox"/>				
14	21/12/18 10:26	General View														Load JPG <input type="checkbox"/>				
15	21/12/18 10:26	General View														Load JPG <input type="checkbox"/>				
16	21/12/18 10:26	General View														Load JPG <input type="checkbox"/>				
17	21/12/18 11:35	Dismantled Parts														Load JPG <input type="checkbox"/>				
18	21/12/18 11:35	Dismantled Parts														Load JPG <input type="checkbox"/>				
19	21/12/18 11:35	Dismantled Parts														Load JPG <input type="checkbox"/>				
20	21/12/18 11:35	Dismantled Parts														Load JPG <input type="checkbox"/>				
21	21/12/18 11:35	Dismantled Parts														Load JPG <input type="checkbox"/>				
22	21/12/18 11:35	Dismantled Parts														Load JPG <input type="checkbox"/>				
23	21/12/18 11:35	Dismantled Parts														Load JPG <input type="checkbox"/>				
24	21/12/18 11:35	Dismantled Parts														Load JPG <input type="checkbox"/>				
25	21/12/18 11:35	Dismantled Parts														Load JPG <input type="checkbox"/>				
26	21/12/18 11:35	Dismantled Parts														Load JPG <input type="checkbox"/>				

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
27	21/12/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
28	21/12/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	21/12/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	28/12/18 11:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
31	28/12/18 11:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
32	28/12/18 11:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/12/18 16:10	TP ESTIMATE - MARKED	 Load PDF	
2	23/12/18 16:10	TP GIA REPORT	 Load PDF	
3	20/02/19 16:51	LETTER TO OI	 Load PDF	
4	14/03/19 15:53	WORKSHOP INVOICE	 Load PDF	
5	14/03/19 15:53	AUTHORISATION TO ACT FORM	 Load PDF	
6	14/03/19 15:53	Release Voucher	 Load PDF	
7	14/03/19 15:53	RENTAL RECEIPT	 Load PDF	
8	14/03/19 15:53	RENTAL MILEAGE	 Load PDF	
9	14/03/19 15:53	LTA SEARCH	 Load PDF	
10	14/03/19 15:53	INCOME TAX	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)

Vehicle No:	SLK2086P (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHC4404G (TP veh)		
Date of Accident:	17/12/2018		

Global Sum Settlement	:	[X]	Yes	[]	No
Repair Estimate	:	\$	10,042.30		
Final Repair Cost	:	\$	4,070.00		
Loss of Use	:	\$		7.00 days at \$80.00 per day	
Rental (if any)	:	\$		7 days	
LTA / GIA Search Fee	:	\$			
Others:	:	\$			
	:	\$			
Final Settlement Sum (Global Sum)	:	\$	4,070.00		

Is Third Party Workshop GIA Registered?		[]	YES	[X]	NO	(Kindly indicate below)
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ 100 _____ (%)				
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.						
Remarks _____						

Payment Instruction: Payee's Breakdown			
1)	SMRT Taxis Pte Ltd	:	\$ 4,070.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

14 Mar
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18022852/JFA3Q2

Date: 14/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No: SHC4404G

Insured Vehicle No: SLK2086P

Date of Loss: 17/12/2018

Nature of Claim: TP

Claim No: 4918358818SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC4404G

Make & Model: TOYOTA PRIUS TAXI, 1.8 (A)

Engine No: 2ZR5899292

Reg. Date: 06/01/2014 (Man. Year: 2013)

Chassis No: JTDKN36UX05721063

Colour: Maroon

Odometer: 524699 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,642.30	1,882.82	4,759.48	71.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	1,220.00	2,180.00	64.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,042.30	3,102.82	6,939.48	69.10
Approved Total (Overridden) (S\$)		2,750.00		
Nett Amount (S\$)	10,042.30	2,750.00	7,292.30	72.62
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Car Rental (7.0 x S\$108.07/day) (S\$)		756.49		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		4,073.49		
Global Sum Settlement (S\$)		4,070.00		

INSPECTION

Date of Assignment: 19/12/2018

Date Inspected: 19/12/2018 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)

60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 5.0 days

Adjuster: ONG HWEE JIE

Manager: Chong Poh Kin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE DOOR GLASS MOULDING ,RH (DISC 25%)	Necessary	29.40 F	*22.05 F
2	1		*TAIL GATE DOOR GLASS MOULDING ,LH (DISC 25%)	Necessary	29.40 F	*22.05 F
3	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
4	1		*MOULDING BACK WINDOW LOWER NO.1 (DISC 25%)	Necessary	29.40 F	*22.05 F
5	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	16.10 F	*12.08 F
6	1		*BUMPER SIDE RETAINER RR/LH (DISC 25%)	Cracked	94.80 F	*71.10 F
7	1		*BUMPER REAR (DISC 25%)	Deformed	458.60 F	*343.95 F
8	1		*TAILGATE ASY (DISC 25%)	Dented	1,007.90 F	*755.93 F
9	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
10	3		*SEALANT W/SCREEN (SN)	Necessary	111.00 F	*111.00 F
11	1		*ARM SUB,ASSY ,RR BUMPER RH	Not Necessary	139.60 F	*- F
12	1		*BUMPER LIP COVER RR/LH	Not Necessary	72.20 F	*- F
13	1		*BUMPER SEAL ,RR LH	Not Necessary	88.90 F	*- F
14	1		*TAILGATE DOOR WEATHER STRIP	Not Necessary	353.40 F	*- F
15	1		*TAILGATE LOCK ,COVER	Not Necessary	15.70 F	*- F
16	1		*SEALANT SIKAFLEX	Not Necessary	37.00 F	*- F
17	1		*UNDER COVER SUBASSY ,RR FLOOR	Not Necessary	514.50 F	*- F
18	1		*BUMPER REINFORCEMENT REAR	Not Necessary	205.70 F	*- F
19	1		*BUMPER SEAL ,RR RH	Not Necessary	65.70 F	*- F
20	1		*STRIKER ,BACK DOOR	Not Necessary	48.90 F	*- F
21	1		*SPARE TYRE PANEL	Not Necessary	667.70 F	*- F
22	1		*ARM SUB-ASSY ,RR BUMPER ,LH	Not Necessary	139.60 F	*- F
23	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
24	1		*REINFORCEMENT ,RR	Not Necessary	34.60 F	*- F
25	1		*BUMPER LIP COVER RR/RH	Not Necessary	118.10 F	*- F
26	1		*BUMPER SIDE RETAINER RR/RH	Not Necessary	94.80 F	*- F
27	1		*BUMPER LIP REAR	Not Necessary	228.90 F	*- F
28	1		*ANTENNA ,ELECTRICAL LOWER REAR	Not Necessary	157.40 F	*- F
29	1		*TAILGATE DOOR LOCK	Not Necessary	444.10 F	*- F
30	1		*END PANEL	Not Necessary	602.10 F	*- F
31	1		*BUMPER REINFORCEMENT REAR (DISC 25%)	Dented	205.70 F	*154.28 F
32	1		*ARM SUB-ASSY ,RR BUMPER LH (DISC 25%)	Bent	139.60 F	*104.70 F
33	1		*ARM SUB-ASSY ,RR BUMPER RH (DISC 25%)	Bent	139.60 F	*104.70 F
Total Parts (\$\$)					6,642.30	1,882.82

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	1,264.00	500.00
2	SPRAY PAINT	New	1,296.00	500.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	0.00
5	TO REMOVE AND REFIX REAR WINDSCREEN	New	240.00	120.00
6	TO REPLACE SUNDRY PARTS	New	100.00	0.00
7	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	30.00
8	TO TRANSFER REAR TAILGATE MECHANISM	New	120.00	50.00
9	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			3,400.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >