

51 AUTOMOTIVE PTE LTD

AutoHub
Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005 96996151

TP111
Poh Kim.
JTDZS3EU02J028101

ESTIMATE

Repair Code : CLM14960

Date in : 18/12/2018

Vehicle Num. : SMA6869L

Model : TOYOTA PRIUS PLUS (AUTO)

Chassis/Eng# : JTDZS3EU00J028101/2ZR0B84358

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT LH DOOR <i>Dented</i>	1	1218.20	✓ 1,218.20
FRONT LH DOOR BLACK FRAME STICKER <i>new</i>	1	121.10	✓ 121.10
FRONT LH DOOR GLASS REGULATOR <i>Damaged.</i>	1	278.30	✓ 278.30
FRONT LH DOOR GLASS REGULATOR MOTOR <i>Damaged.</i>	1	780.50	595 780.50
FRONT LH DOOR INNER SEAL COVER <i>new</i>	1	168.20	x 168.20
FRONT LH DOOR INNER TRIM BOARD <i>could</i>	1	1217.30	743 1217.30
FRONT LH DOOR LOWER HINGE <i>new</i>	1	141.20	x 141.20
FRONT LH DOOR MECHANISM LOCK <i>Damaged.</i>	1	780.90	✓ 780.90
FRONT LH DOOR VERTICAL GARNISH <i>new</i>	1	151.30	x 151.30
FRONT LH DOOR WEATHER STRIP <i>new</i>	1	205.20	x 205.20
FRONT LH FENDER <i>Dented</i>	1	731.35	✓ 731.35
FRONT LH FENDER 'HYBRID' EMBLEM <i>new</i>	1	121.10	✓ 121.10
FRONT LH WHEEL CAP <i>new</i>	1	378.30	x 378.30
LH SIDE ROCKER PANEL GARNISH <i>behind</i>	1	972.45	722 972.45
REAR AXLE CARRIAGE <i>new</i>	1	2263.60	x 2,263.60
REAR BUMPER <i>torn</i>	1	523.90	✓ 523.90
REAR BUMPER LH END SEAL COVER <i>new</i>	1	131.10	x 131.10
REAR BUMPER LH SIDE RETAINER <i>new</i>	1	171.25	85 171.25

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005 96996151

ESTIMATE

Repair Code : CLM14960

Date in : 18/12/2018

Vehicle Num. : SMA6869L

Model : TOYOTA PRIUS PLUS (AUTO)

Chassis/Eng# : JTDZS3EU00J028101/2ZR0B84358

REAR LH DOOR <i>Dented</i>	1	1279.10	✓ 1,279.10
REAR LH DOOR ARCH PANEL <i>Repair</i>	1	967.70	X 967.70
REAR LH DOOR BLACK FRAME STICKER <i>new</i>	1	171.45	✓ 171.45
REAR LH DOOR CHECKER <i>new</i>	1	191.20	X 191.20
REAR LH DOOR GLASS REGULATOR <i>Damaged</i>	1	372.50	✓ 372.50
REAR LH DOOR GLASS REGULATOR MOTOR <i>Damaged</i>	1	789.10	558 789.10
REAR LH DOOR HINGES (TOP & LOWER) <i>2 x 1</i>	2	141.30	+ 282.60
REAR LH DOOR INNER SEAL COVER <i>new</i>	1	168.20	X 168.20
REAR LH DOOR INNER TRIM BOARD <i>cracked</i>	1	978.10	739.90 978.10
REAR LH DOOR VERTICAL GARNISH <i>new</i>	1	172.25	X 172.25
REAR LH DOOR WEATHER STRIP <i>new</i>	1	274.40	X 274.40
REAR LH SHOCK ABSORBER <i>new</i>	1	209.10	X 209.10
REAR LH WHEEL BEARING <i>Damaged</i>	1	781.90	✓ 781.90
REAR LH WHEEL CAP <i>lit</i>	1	378.30	60(SN) 378.30
Subtotal before discount			17,371.15

Percentage discount 25%

Sub-total 1

FRONT LH DOOR INNER TRIM BOARD CLIPS - SET *new*

50.00

30 ~~50.00~~

*** This is a computer-generated document which requires no signature. ***
page 2

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005 96996151

ESTIMATE

Repair Code : CLM14960
Date in : 18/12/2018
Vehicle Num. : SMA6869L
Model : TOYOTA PRIUS PLUS (AUTO)
Chassis/Eng# : JTDZS3EU00J028101/2ZR0B84358

FRONT LH DOOR VERTICAL GARNISH CLIPS - SET	1	20.00	X	20.00
FRONT LH FENDER INNER SHIELD CLIPS - SET	1	50.00	X	50.00
LH SIDE CENTER PILLAR INNER TRIM GARNISH CLIPS - SET	1	50.00	X	50.00
LH SIDE ROCKER PANEL GARNISH CLIPS - SET	1	50.00	30	50.00
REAR BUMPER CLIPS - SET	1	50.00	30	50.00
REAR LH DOOR INNER TRIM BOARD CLIPS - SET	1	50.00	30	50.00
REAR LH DOOR VERTICAL GARNISH CLIPS - SET	1	20.00	X	20.00
REAR LH TYRE	1	350.00	X	350.00
REAR LH WHEEL RIM	1	1250.00	X	1,250.00
Subtotal before discount				1,940.00
Percentage discount 0%				0.00
Sub-total 2				1,940.00
Parts-total				14,968.36

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall window glass. (to FR)

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

50.00
120.00
120 X 200.00
80 100.00
50 120.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005 96996151

ESTIMATE

Repair Code : CLM14960

Date in : 18/12/2018

Vehicle Num. : SMA6869L

Model : TOYOTA PRIUS PLUS (AUTO)

Chassis/Eng# : JTDZS3EU00J028101/2ZR0B84358

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

160 200.00

1100 1,600.00

800 1,200.00

X 120.00

3,860.00

18,828.36

*** This is a computer-generated document which requires no signature. ***

page 4

total: 9908.7

N/S: 7.9K

08 Days.

7.9K

08 Days.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: