

Hsiao Tong (LKKAuto)

From: Bryan Ang (LKKAuto)
Sent: Saturday, 25 May 2019 1:47 PM
To: claims@teamworkgarage.com; claims@teamworkgarage.com
Cc: Vic (LKKAuto)
Subject: SLN 3317B
Attachments: Untitled.png

Dear Darren

Please check with your driver whether any accident scene photo for this case.

Video from taxi show the wing mirror intact and not broken after the accident. Wing mirror was broken during my survey.

This case will have to KIV.

Best Regards,

Bryan Ang

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: bryanang@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)