

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18022856/DPB3Q2

Date: 24/06/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLN3317B	Insured Vehicle No :	SHA3242Z
Date of Loss: 18/12/2018	Nature of Claim: TP	Claim No: MCT18120529

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN3317B	Engine No:	BWA182197
Make & Model:	VOLKSWAGEN GOLF, 2.0 GTI (A)	Chassis No:	WVWZZZ1KZ8W093143
Reg. Date:	01/09/2008 (Man. Year: 2008)	Odometer:	177161 km
Colour:	Red		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,790.34	955.17	3,835.17	80.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,410.00	860.00	550.00	39.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,200.34	1,815.17	4,385.17	70.72
Approved Total (Overridden) (\$\$)		1,450.00		
Nett Amount (\$\$)	6,200.34	1,450.00	4,750.34	76.61
+ Car Rental (3.0 x S\$120.00/day) (\$\$)		360.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		1,817.45		
Global Sum Settlement (\$\$)		1,800.00		

INSPECTION

Date of Assignment:	20/12/2018	
Date Inspected:	20/12/2018 Inspected At:	Karz Work Solutions (HQ) 53 Ubi Avenue 1 #02-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	2.0 days	

Adjuster: BRYAN TANI**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2020)
Parts:	144	VOLKSWAGEN GOLF 2.0 GTI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN3317B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	1,444.26 FL	*- FL
2	1		*FRONT BUMPER RETAINER	Not Necessary	161.20 FL	*- FL
3	1		*FRONT RH DOOR PANEL	Repair	1,609.40 FL	*- FL
4	1		*FRONT RH FENDER	Not Necessary	655.70 FL	*- FL
5	1		*FRONT RH WING MIRROR	Broken	860.00 FL	*860.00 FL
6	1		*FRONT RH WING MIRROR COVER	Broken	201.30 FL	*201.30 FL
7	1		*FRONT RH QUARTER GLASS	Not Necessary	335.18 FL	*- FL
8	1		*SET BUMPER CLIP	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,317.04	1,061.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	526.70	106.13
Total Parts (\$\$)	4,790.34	955.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	PANEL BEATING ON AFFECTED AREAS	New	600.00	400.00
3	SPRAY PAINTING ON AFFECTED AREAS	New	600.00	400.00
4	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
Gross Labour Cost (\$\$)			1,410.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >