



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : SLE 4391 BMake & Model : TOYOTA AXIOYear of Manufacture : 2016Chassis No. : NRE1610012263Ins Company : SOMPO

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 10.12.2018Time of Accident : 12.55

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**Case Owner : JOHARI

Signature : _____

Parts (a) Cost / List Price Items _____

Plus/Less : \$-Total of Cost / List : \$-

(b) Nett Price Items _____

Less : _____

Total of Nett Item : _____

(c) Special Nett Items _____

Total Parts Cost (Appendix A) _____

Labour (Appendix B) _____

Total Repair Cost : _____

Contact No

6848 5726 - Jasmine Chng

Ubi_cr@sparkcarcare.com

TPAXA.

Joy.

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Adrian LingCompany : LKICSurvey conducted on : 28/12/18 at 11:20am.Remarks By Surveyor(a) The repair of this vehicle is authorized / is not authorized until further notice.(b) Recommended Days of Repair : 04 day(s) P/P.(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : [Signature] Date: 28/12/18

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Rd S(579701)
Tel: 6383362/63837102 Fax: 62815767

VEHICLE NO.: SLE 4391 E
MAKE: TOYOTA
MODEL: AXIO
YEAR OF MAKE: 2016
CHASSIS NO.: NRE1610012263

0

PAGE 1

COST / LIST

S/N	Parts Description	PART NUMBER	Qty	Remarks	
				COST	LIST
1	LHF FENDER <i>Dented</i>		1	\$185	✓
2	LHF FENDER COWLING CLIP'S <i>Assy</i>		8	\$16	✓
3	LHF DOOR <i>Dented</i>		1	\$450	✓
4	LHF SIDE MIRROR ASSY <i>Assy</i>		1	\$310	✓
5	LHF SIDE MIRROR COVER		1	\$40	✓
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					

651
+10% = 716.10

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 FAX : 67436072

Vehicle No.	: <u>SLE 4391 B</u>	Case Owner	: <u>JOHARI</u>
Make & Model	: <u>TOYOTA AXIO</u>	Year of Manufacture	: <u>2016</u>

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Spark Car Care
 ComfortDelgro Engineering Pte Ltd
 320 UBI ROAD 3 SINGAPORE 408649
 Tel: 68438723/68438736 FAX : 67436072

Finalization Form

Bil : _____ **Vehicle Number** : SLE 4391 B
Attn to : _____ **Type Of Claim** : TP

A. Spare parts <u>\$651.00</u> B. Supplementary <u>\$40.00</u> C. Nett Price <u>\$-</u> D. Supp Nett Price <u>\$-</u> E. S/Nett <u>\$-</u>	F. Total Parts <u>\$760.10</u> G. Total Labour <u>\$780.00</u> H. Total Repair <u>\$1,540.10</u> I. Excess _____ P/P Total <u>1,540.10</u>
--	--

Total Spare Parts Price		\$691.00
Cost plus / List Down	10%	69.10
Total		760.10

Total Nett Price		\$-
Nett Price Less		\$-
Total		-

Lump Sum Less _____ \$-

Lump Sum Rounding _____

Total Finalized \$1,460.10

N.B. If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.

Remarks : Please confirm and revert by Fax or Email

Date In : _____	Total Repair Day _____
Date Survey : _____	LOU/ Day _____
Date Out : _____	Total LOU _____
Sat/Sun/Ph. : _____	Rental/Day _____
Authorized Repair Day _____	Total Rental _____
Submitted By / Date : _____	Confirmed By / Date : _____

VEHICLE NO.:

MAKE:

MODEL:

YEAR OF MAKE:

CHASSIS NO.:

Supplementary .

0

PAGE 1

COST / LIST

S/N	Parts Description	PART NUMBER	Qty	Remarks	
				COST	LIST
1	FRONT LH DOOR STICKER <i>new</i>			\$40	<i>✓</i>
2					
3					
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					

40

+ 10% . 44

VEHICLE NO.:

0

0