

ISS2011

INS. CASE OWNER:

CC 0 / AXA1802

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO. Driver Name / Age: WW 6M 51M

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher: DS Form

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time: 0.01.19

Sent By: ASH

FINALIZATION

Date/Time:

Confirm with:

Confirm by: XGD

Repair Cost: 45 \$57,400.00

(6 days) Reduction: 40 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 26.04.19

Confirm with: RAYMOND

Email ☒ Call ☐

Final Liability: % 100

(Agreed / Assessed) BOLA S/N No.: 15

If NO or B 28, Ass. Lia:

Repair Cost: w/lsg \$57,971.50

DID CHANGED LANE HIT TP.

Loss of Rental (LOR): \$5 900.00 (9 days) x 100

Loss of Use (LOU): \$5 - (S x days)

Loss of Income (LOI): \$5 - (S x days)

LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search \$5 200

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/ Independent)

Legal Cost \$5 -

Total: \$58,873.50

Global Sum \$5:

FINAL PAYMENT

Date/Time: 26.04.19

Confirm with: RAYMOND

Email ☒ Call ☐

Payee 1: \$58,873.50

Name 1: VIN'S AUTOMOTIVE GROUP

Payee 2: (Strike if N.A.) \$5

Name 2:

Payee 3: (Strike if N.A.) \$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 7380

Surveyor

Xcel.

REF:

AXA

2

4087E

ASSIGNMENT

26

From:

Date:

Estimated Cost:

OD / TP BWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Vin's Motor

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$43k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKB48591

Yr Regn:

01 Jun 2011

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Merce C180

c.c

1597

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

283535

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2040452 A53 3295

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225 (45 R17)

R:

11

BS / DUN / EXNOVA / CY FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

5

mm

Rear

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

20-12-18

Survey held at

W/S

9AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

18/4

Finalized \$7450 with Raymond.

(RED: 74,920 40%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18022866/eb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 20-12-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XD 5189B	Veh. Inspected	SKB 4859Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/12/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/12/2018	Inspection Date	
Survey held at	VIN'S MOTOR PTE LTD 160 SIN MING DRIVE #03-03 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Vin's

AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/122018/3720
Accident date : 17/12/2018
Your Ref : XD5189B

Invoice No:
Date : 18/12/2018

MOTOR CLAIM DEPARTMENT
AXA INSURANCE (S) PTE LTD
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Estimate cost of repairs to Mercedes Benz C180 SKB4859Y

1	pc	Rear RH door / Bone	\$ / 1,100.00 ✓
1	pc	Rear RH door outer handle / Cut	\$ / 110.00 ✓
1	pc	Rear RH door outer moulding / MC	\$ / 100.00 ✓
1	pc	Rear RH door rubber / MC	\$ 89.6 180.00 ✓
1	pc	Rear RH door regulator / BT	\$ / 580.00 ✓
1	pc	Rear RH door regulator motor / MC / NN	\$ / 490.00 ✓
1	pc	Rear windscreen moulding / X	\$ X 100.00 X
1	pc	Rear windscreen gum / X	\$ X 60.00 X
1	pc	Rear RH fender / MC repair.	\$ X 1,250.00 X
1	pc	Rear bumper / CA	\$ / 910.00 ✓
1	pc	Rear bumper RH retainer / ll	\$ / 30.00 ✓
1	pc	Rear RH wheel sport rim / Cut	(SN) \$ 1,380.00 ✓
1	pc	Rear RH wheel tyre / X NN	\$ X 480.00 X
1	pc	Rear RH shock absorber / MC	\$ / 390.00 ✓
1	pc	Rear RH lower arm / BT	\$ / 390.00 ✓
1	pc	Rear RH knuckle arm / 700	\$ 1,300.00 ✓
1	pc	Rear RH knuckle arm bearing / MC	\$ / 210.00 ✓
1	pc	Rear RH top arm no 1 / BT	\$ / 140.00 ✓
1	pc	Rear RH top arm no 2 / X NN	\$ X 130.00 X
1	pc	Rear RH side arm no 1 / BT	\$ / 170.00 ✓
1	pc	Rear RH side arm no 2 / X NN	\$ X 160.00 X
Balance c/f			\$ 9,660.00

+15%

6221.04

Vin's

AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722

T 6453 2121 (4 lines) / 6458 1111 (24 hrs)

F 6459 9795 / 6459 0433

E admin@vinsautogroup.com.sg

W www.vinsautogroup.com.sg

Our Ref : TP/122018/3720

Date : 18/12/2018

Balance b/f \$ 9,660.00

To remove and refix rear glass	\$ 150.00	28 XNN
To remove and refix rear seat cushion & roof lining	\$ 180.00	60
To remove and refix rear undercarriage	\$ 380.00	250 320
To check wheel alignment - Alignment report	\$ 150.00	60
To repair rear damage (before & After)	\$ 880.00	600
To spray painting	\$ 980.00	600 700
	<u>\$ 12,380.00</u>	

1740

VIN'S MOTOR PTE LTD



9341.04

20% = 7450

6 Days.

Lump Sum Repair.

After repair photos.

Guo Qian 82880282

20/12/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Taufikh (LKK Auto)

From: Vincent Seah [vincent.seah@cyclecarriage.com.sg]
Sent: Tuesday, 16 April 2019 11:43 AM
To: Taufikh (LKKAuto)
Subject: RE: PART PRICE

FYA

-----Original Message-----

From: Taufikh (LKKAuto) [mailto:Taufikh@lkkauto.com]
Sent: Tuesday, 16 April 2019 11:22 AM
To: Vincent Seah <vincent.seah@cyclecarriage.com.sg>
Subject: PART PRICE

Hi Vincent,

Can help me check part price for these items?

SKB 4859Y CHASSIS:WDD2040452A533295 ^{-10% 610.2}
REAR RH DOOR REGULATOR -2047202579 \$678.07 (part number)
REAR RH DOOR REGULATOR MOTOR - 2048200242 \$615.35
REAR RH SPORT RIM - 2044016202 \$597.04 PARTS NO. WRONG
REAR RH KNUCKLE ARM - 2043320201 \$787.36

Thank you in advance.

^{-10%: 708.62}

w/s \$580 +15% 667
w/s \$490
w/s \$380
w/s \$700 +15%: 805

Regards
Taufikh
LKK Auto

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.



Service Request Details

Claim

S8M0172M

Reference

None 

Loss Date

17 December 2018

Request Date

19 December 2018

Due Date

27 December 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

'Virtual'
19.12.2018 @ 3.48pm
Raymond veh in.
GQ

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKB4859X

Make

TPVD MERCEDES-BENZ

Service Address

...

Primary Contact/Insured

TONG HENG MOTOR WORK
6 KRANJI LOOP, #01-26, 739542, Singapore
63380083
JEUNESSE@VIRTUALINVEST.BIZ

Claim Handler

KHOR Saw Theng
6568804754
sawtheng.khor@axa.com.sg

Additional Instructions

1. Virtual case. 2. TP Excess \$3,000.

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: Admin @ VAuG <admin@vinsautogroup.com.sg>
Sent: Tuesday, 18 December, 2018 4:05 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: Request For TP Survey SKB4859Y ; Yr Insured XD5189B
Attachments: SAS2522311.pdf; 20181218154339.pdf

Categories: Pragati

Good afternoon,

Please help us to arrange for survey ASAP

DOA: 17/12/2018

Location:
Sin Ming Autocity
160 Sin Ming Drive #08-09
Singapore 575722

Thanks!

Best Regards

Raymond Teo

--



Sin Ming AutoCity
160 Sin Ming Drive
Singapore 575722
Showroom/Office: #03-03
Workshops: #08-08/09
Tel: 64532121 (4 lines)
Fax: 64599795
Website: www.vinsautogroup.com.sg
Email: admin@vinsautogroup.com.sg

Follow us on :



** w.e.f 15th May 2017, we have shifted location! **

** w.e.f 20th November 2017, we have changed our email address! **



MANDATE IA (S8M0172M)

Type

🔔 Question

Message

Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (06/03/2019)

Reply

⏪ Re:MANDATE IA (S8M0172M)

Type

🔗 Question

Message

Please proceed.

Reply

Our Ref: TP/122018/3720

Your ref: XD5189B

AXA INSURANCE (S) PTE LTD

8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Attention: Motor Claims Department

Dear Sir/Mdm,

Accident Involving Vehicles : SKB4859Y & XD5189B
Along : BKE TWDS Woodlands
DOA : 17/12/2018

We are the authorized repair workshop for the owner of motor vehicle no: SKB4859Y, which was involved in the captioned accident with your insured vehicle: XD5189B. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

01) Cost of Repair (inclusive of GST)	\$ 7,971.50
02) GIA Search fees	\$ 2.00
03) Loss of Rental_wait for surveyor 2 day x \$180/-	\$ 360.00
04) Loss of Rental_1 days (Sunday) x \$180/-	\$ 180.00
05) Loss of Rental_6 days x \$180/-	\$ 1,080.00
	<u>\$ 9,593.50</u>

We enclosed herewith the following documents to support the claims:-


- a) Letter of Authorisation / GIA report(s) / Insurance Certificate, etc...
- b) Final Repair Bill
- c) GIA search/ Car Rental Bill & Invoice

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you
Yours faithfully

VIN'S MOTOR PTE LTD



Vincent Khong
(jt)

Please issue Cheque to: Vin's Motor Pte Ltd
Please transfer to: Vin's Motor Pte Ltd
UOB Current Account
A/C No: 451-307-638-4

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	XD 5189B (Insd veh)	Model:	MERCEDES BENZ C 180
	SKB 4859Y (TP veh)		
Date of Accident:	17/12/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	13,246.60
Final Repair Cost	:	\$	7,971.50
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	900.00 9 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$
---------	---	----

	:	\$
Final Settlement Sum	:	\$ 8,873.50

Is Third Party Workshop GIA Registered?	[X] YES	[] NO	(Kindly indicate below)
---	-----------	--------	-------------------------

A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ 100 _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	

Remarks

Payment Instruction: Payee's Breakdown		
1)	VIN'S AUTOMOTIVE GROUP	\$ 8,873.50

NUR SHAQILAH BTE ABDOL
WAHAB

31/05/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18022866/Geb3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: SAW THENG		Date : 31-05-2019 Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 5189B	Veh. Inspected	SKB 4859Y	
Policy No.	GA376461/1	Coverage (\$)	0.00	
Claim No.	S8M0172M	Excess (\$)	0.00	
Assign From	SAW THENG	Assign Date	20/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C 180	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WDD2040452A533295	Colour	BLACK	
Odometer	283535	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45R17	GOODYEAR	5 mm	
L/H Front Tyre	225/45R17	GOODYEAR	5 mm	
R/H Rear Tyre	225/45R17	GOODYEAR	5 mm	
L/H Rear Tyre	225/45R17	GOODYEAR	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/12/2018	Inspection Date	20/12/2018	
Survey held at	VIN'S MOTOR PTE LTD 160 SIN MING DRIVE #03-03 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 4859Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR RH DOOR (WCP) (CONSISTENT)	BUCKLED	1,100.00	1,100.00
1	REAR RH DOOR OUTER HANDLE (WCP) (CONSISTENT)	CUT	110.00	110.00
1	REAR RH DOOR OUTER MOULDING (WCP) (CONSISTENT)	NECESSARY	100.00	100.00
1	REAR RH DOOR RUBBER (WCP) (CONSISTENT)	NECESSARY	180.00	89.60
1	REAR RH DOOR REGULATOR (WCP) (CONSISTENT)	BENT	580.00	580.00
1	REAR RH DOOR REGULATOR MOTOR (WCP) (CONSISTENT)	NOT WORKING	490.00	490.00
1	REAR WINDSCREEN MOULDING (WCP) (CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN GUM (WCP) (CONSISTENT)	NOT NECESSARY	60.00	-
1	REAR RH FENDER (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	1,250.00	-
1	REAR BUMPER (WCP) (CONSISTENT)	CRACKED	910.00	910.00
1	REAR BUMPER RH RETAINER (WCP) (CONSISTENT)	DEFORMED	30.00	30.00
1	REAR RH WHEEL TYRE (WCP) (CONSISTENT)	NOT NECESSARY	480.00	-
1	REAR RH SHOCK ABSORBER (WCP) (CONSISTENT)	BENT	390.00	390.00
1	REAR RH LOWER ARM (WCP) (CONSISTENT)	BENT	390.00	390.00
1	REAR RH KNUCKLE ARM (WCP) (CONSISTENT)	BENT	1,300.00	700.00
1	REAR RH KNUCKLE ARM BEARING (WCP) (CONSISTENT)	NECESSARY	210.00	210.00
1	REAR RH TOP ARM NO 1 (WCP) (CONSISTENT)	BENT	140.00	140.00
1	REAR RH TOP ARM NO 2 (WCP) (CONSISTENT)	NOT NECESSARY	130.00	-
1	REAR RH SIDE ARM NO 1 (WCP) (CONSISTENT)	BENT	170.00	170.00
1	REAR RH SIDE ARM NO 2 (WCP) (CONSISTENT)	NOT NECESSARY	160.00	-
	COST PLUS 15%		-	811.44
			8,280.00	6,221.04
<u>SPECIAL NETT ITEMS</u>				
1	REAR RH WHEEL SPORT RIM (SN) (CONSISTENT)	CUT	1,380.00	1,380.00
			1,380.00	1,380.00
<u>LABOUR</u>				
	TO REMOVE AND REFIX REAR GLASS.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIX REAR SEAT CUSHION & ROOF L		180.00	60.00

Report Ref No. CC4/ASM18022866/Geb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIX REAR UNDERCARRIAGE.		380.00	320.00
	TO CHECK WHEEL ALIGNMENT.		150.00	60.00
	TO REPAIR REAR DAMAGE. INCLUSIVE OF THE REPAIR OF REAR RH FENDER.		880.00	600.00
	TO SPRAY PAINTING.		980.00	700.00
			2,720.00	1,740.00
GRAND TOTAL			12,380.00	9,341.04

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,450.00
--	--	--	----------

Report Ref No. CC4/ASM18022866/Geb3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.