



AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/122018/3720
Accident date : 17/12/2018
Your Ref : XD5189B

Invoice No:
Date : 18/12/2018

MOTOR CLAIM DEPARTMENT
AXA INSURANCE (S) PTE LTD
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Estimate cost of repairs to Mercedes Benz C180 SKB4859Y

1	pc	Rear RH door / <i>Bone</i>	\$	1,100.00
1	pc	Rear RH door outer handle / <i>Cut</i>	\$	110.00
1	pc	Rear RH door outer moulding <i>X - NCC</i>	\$	100.00
1	pc	Rear RH door rubber / <i>NCC</i>	\$	180.00
1	pc	Rear RH door regulator ?	\$	580.00
1	pc	Rear RH door regulator motor ?	\$	490.00
1	pc	Rear windscreen moulding <i>X</i>	\$	100.00
1	pc	Rear windscreen gum <i>X</i>	\$	60.00
1	pc	Rear RH fender? <i>X - NCC</i>	\$	1,250.00
1	pc	Rear bumper / <i>clA</i>	\$	910.00
1	pc	Rear bumper RH retainer / <i>cl</i>	\$	30.00
1	pc	Rear RH wheel sport rim / <i>Cut</i>	\$	1,380.00
1	pc	Rear RH wheel tyre <i>X</i>	\$	480.00
1	pc	Rear RH shock absorber <i>X</i>	\$	390.00
1	pc	Rear RH lower arm ?	\$	390.00
1	pc	Rear RH knuckle arm ?	\$	1,300.00
1	pc	Rear RH knuckle arm bearing / <i>NCC</i>	\$	210.00
1	pc	Rear RH top arm no 1 <i>X</i>	\$	140.00
1	pc	Rear RH top arm no 2 <i>X</i>	\$	130.00
1	pc	Rear RH side arm no 1 <i>X</i>	\$	170.00
1	pc	Rear RH side arm no 2 <i>X</i>	\$	160.00
Balance c/f			\$	9,660.00



AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/122018/3720

Date : 18/12/2018

Balance b/f \$ 9,660.00

To remove and refix rear glass	\$ 150.00	10 ?
To remove and refix rear seat cushion & roof lining	\$ 180.00	60
To remove and refix rear undercarriage	\$ 380.00	?
To check wheel alignment - Alignment report.	\$ 150.00	60
To repair rear damage (before & After)	\$ 880.00	600
To spray painting	\$ 980.00	600 700
	<u>\$ 12,380.00</u>	

1428

VIN'S MOTOR PTE LTD

6 Days.

(ump sum repair.

After repair photos.

Quo Quoy 82880282

20/12/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: