

Our Ref : TP/122018/3720
Accident date : 17/12/2018
Your Ref : XD5189B

Invoice No:
Date : 18/12/2018


MOTOR CLAIM DEPARTMENT
AXA INSURANCE (S) PTE LTD
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Estimate cost of repairs to Mercedes Benz C180 SKB4859Y

- 1 pc Rear RH door
- 1 pc Rear RH door outer handle
- 1 pc Rear RH door outer moulding
- 1 pc Rear RH door rubber
- 1 pc Rear RH door regulator
- 1 pc Rear RH door regulator motor
- 1 pc Rear windscreen moulding
- 1 pc Rear windscreen gum
- 1 pc Rear RH fender
- 1 pc Rear bumper
- 1 pc Rear bumper RH retainer
- 1 pc Rear RH wheel sport rim
- 1 pc Rear RH wheel tyre
- 1 pc Rear RH shock absorber
- 1 pc Rear RH lower arm
- 1 pc Rear RH knuckle arm
- 1 pc Rear RH knuckle arm bearing
- 1 pc Rear RH top arm no 1
- 1 pc Rear RH top arm no 2
- 1 pc Rear RH side arm no 1
- 1 pc Rear RH side arm no 2

Balance c/f

\$ -



Our Ref : TP/122018/3720

Date : 18/12/2018

To remove and refix rear glass	\$ 150.00
To remove and refix rear seat cushion & roof lining	\$ 180.00
To remove and refix rear undercarriage	\$ 380.00
To check wheel alignment	\$ 150.00
To repair rear damage	\$ 880.00
To spray painting	\$ 980.00
	<u>\$ 2,720.00</u>

VIN'S MOTOR PTE LTD

