

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1436/2018/PH
Date : 20-Dec-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle : SFU 8818 Z

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Phuia Yong Sin
Address : 85 Compassvale Bow
#12-20
Singapore 544685
Telephone : HP +6597354664
Type of Claim : Third Party Claims
Policy No. : 1700080388-01
Vehicle No : **SKA 3339 T**
Model Code : Audi Q5 SPORT 2.0 TFSI (QU)
Model / Year : Dec-17
Engine No : DAX 020045
Chassis No : WAUZZZF6J2055456
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 19-Dec-18
Place of Accident : Bt Batok East Ave 3

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKA 3339 T .

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rhs front door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00 ✓	
2	To dismantle and renew rhs front door. To repair rhs front fender. Re-organise crash management components. Reinstall all parts removed.	\$ 1,400.00 750.	
3	To respray rhs front door, rhs front fender, both wheel arch covers and door cover.	\$ 2,600.00 1450	2 x SSO = 1100. Door Cover = 200 Fender Protector = 150.
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>4,472.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKA 3339 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR - RH <i>Dented</i>	\$ 2,692.00	✓
2	BONDING AGENT <i>?</i>	\$ 43.00	?
3	CLEANING SOLUTION <i>?</i>	\$ 64.00	?
4	FRONT DOOR OUTER DOOR SEAL - RH <i>new</i>	\$ 176.00	✓
5	FRONT DOOR CATCH - RH <i>new</i>	\$ 127.00	+
6	FRONT DOOR CATCH COVER - RH <i>new</i>	\$ 15.00	+
7	FRONT WHEEL COVER - RH <i>new</i>	\$ 545.00	✓
8	FRONT DOOR COVER - RH <i>new</i>	\$ 634.00	✓
9	FRONT DOOR COVER CLIP <i>new</i>	5 \$ 77.00	✓
10	SUNDRIES <i>?</i>	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		:	\$ 4,673.00
TOTAL LABOUR CHARGES		:	\$ 4,472.00
GRAND TOTAL		:	\$ 9,145.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 02/01/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorized, 05 Days

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant