



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18022882/Nsd3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 25-01-2019

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJF 9635J	Veh. Inspected	SHD 4374D
Policy No.	5101305323	Coverage (\$)	0.00
Claim No.	MT/1024579-002	Excess (\$)	0.00
Assign From		Assign Date	20/12/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI SONATA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	KMHET41VMCA827010	Colour	BLUE
Odometer	339325	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	WEST LAKE	5 mm
L/H Front Tyre	215/60R16	WEST LAKE	5 mm
R/H Rear Tyre	215/60R16	WEST LAKE	6 mm
L/H Rear Tyre	215/60R16	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/12/2018	Inspection Date	20/12/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4374D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID	TO REPAIR SEE LABOUR	1,349.50	-
1	BOOT LID LOCK UPPER	SERVICEABLE	132.10	-
1	BOOT LID LOCK LOWER	SERVICEABLE	30.30	-
1	BOOT LID SONATA PLATE	NECESSARY	43.60	43.60
1	BOOT LID HYUNDAI PLATE	NECESSARY	24.20	24.20
1	BOOT LID 'H' EMBLEM	NECESSARY	26.10	26.10
1	BOOT LID CRDI EMBLEM	NECESSARY	22.70	22.70
1	BOOT LID TRIMBOARD	SERVICEABLE	165.40	-
10	BOOT LID TRIMBOARD CLIPS	NOT NECESSARY	10.00	-
1	REAR BUMPER	BUCKLED	578.40	578.40
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	483.30	-
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE	SERVICEABLE	137.40	-
1	REAR BUMPER UNDER COVER	DEFORMED	185.80	185.80
2	REAR BUMPER PROTECTOR (LH/RH) @ \$38.00	SERVICEABLE	76.00	-
1	REAR PANEL	DENTED	391.80	391.80
1	REAR PANEL GARNISH	SERVICEABLE	95.80	-
	LESS 20% DISCOUNT		-754.88	-258.92
			3,019.52	1,035.68
<u>SPECIAL NETT ITEMS</u>				
1	BOOT LID COMFORT LOGO & TEL NO. STICKER (SN)	NECESSARY	30.00	30.00
1	BOOT LID ADVERTISEMENT LOGO (SN)	NECESSARY	100.00	100.00
1	REAR NO. PLATE (SN)	SERVICEABLE	25.00	-
1	REAR BUMPER REVERSE SENSOR (SN)	SCRATCHED	135.70	135.70
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @ \$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
			586.70	515.70

Report Ref No. NS/INC18022882/Nsd3s2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOT LID.		800.00	500.00
	SPRAY PAINTING CHARGE.		900.00	500.00
	WIRING CHARGE.		30.00	20.00
	TUFF KOTE.		50.00	40.00
	REMOVE / REFIX REVERSE SENSOR.		80.00	20.00
			1,860.00	1,080.00
	GRAND TOTAL		5,466.22	2,631.38
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,100.00

Report Ref No. NS/INC18022882/Nsd3s2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.