

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: NGO SAU WEI SHAWN

Date: 21 Dec 2018

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|-------------------|
| Vehicle No | : SKC5858M | Accident Date | : 20/12/2018 |
| Make | : HONDA ODYSSEY | Policy No. | : D18MTPV01008162 |
| Assignment Date | : 21/12/2018 | Excess | : S\$0.00 |
| Date of Inspection | : 21/12/2018 | Est. Duration of Repair | : 6.00 |
| Inspection At | : KAH MOTOR CO SDN BHD (UBI) 15 UBI ROAD 4 SINGAPORE 408610 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and o/s body and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 13,650.82 |
| Revised Amount | :S\$ | 10,976.94 |
| Check Items (Estimated) | :S\$ | 796.38 |
| Total | :S\$ | 11,773.32 |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | | |
|--------------------|------|-----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 99,000.00 |
| COE / PARF Rebate | :S\$ | 56,512.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 42,488.00 |

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly advised vehicle excess