

9/1/2019.

PAGE 1/2



© SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

ATTN: MARCUS CHUA.

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

WD: 6 DAYS.

Customer: WH023 / SOMPO INSURANCE
Chassis No: JHMRC1890GC202948
License No: SKC5858M
Mileage: 19310
Engine No: K24W72011313

Document No: SVO18076285
Printed By: JESHURUEBEN
Order Date: 21. December 2018
Order Time: 12:08:51 PM
Service Advisor: RUEBEN THOMAS

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: 71876 POLICY/CLAIMS NO: D18MTPV01008162 OWNER: LIM CHAY LUNG CATHERINE ACC DATE: 20/12/2018 SURVEYED BY: MARCUS CHUA (LKK) DATE: 21/12/2018 AUTHORIZED ON: 22/12/2018 REF NO : CMTD1805618						
54206	EXTERNAL LABOUR SALES - INS. EXCESS	-1	800.00		-800.00	-56.00	-856.00
	SUM EXCESS:				-800.00	-56.00	-856.00
04711-T6A-900ZZ	FACE,FR.BUMPER	1	700.00	25	525.00	36.75	561.75
91505-TM8-003	CLIP,BUMPER	14	2.30	25	24.15	1.69	25.84
71193-T6A-003	SPACERR.FR.BUMPER SIDE	1	11.80	25	8.85	0.62	9.47
71112-T6A-921ZA	SPOILER ASSYR.FR.SIDE	1	94.40	25	70.80	4.96	75.76
71104-T6A-921	GARNISHR.FR.BUMPER	1	46.10	25	34.57	2.42	36.99
33100-T6A-Q11	HEADLIGHT ASSYR.WITH LED	1	2,281.90	25	1,711.42	119.80	1,831.22
60210-T6A-300ZZ	FENDER COMPR.FR.	1	548.60	25	411.45	28.80	440.25
72415-T6A-003	MOLDING ASSYR.FR.CORNER	1	87.70	25	65.77	4.60	70.37
74100-T6A-000	FENDER ASSYR.FR.INNER	1	120.70	25	90.52	6.34	96.86
67010-T6A-000ZZ	PANEL COMPR.FR.DOOR	1	895.20	25	671.40	47.00	718.40
67325-T6A-J01	TAPE,R.FR.DOOR SA	1	37.30	25	27.97	1.96	29.93
67324-T6A-305ZA	TAPE SETR.FR.DOOR SASH INNER	1	38.40	25	28.80	2.02	30.82
76208-T6A-Q03	MIRROR ASSY,R.SET	1	1,226.40	25	919.80	64.39	984.19
67510-T6A-J00ZZ	PANEL COMPR.SLIDE DOOR	1	1,000.50	25	750.37	52.53	802.90
67821-T6A-305ZA	TAPE SETR.RR.DOOR SASH INNER	1	57.10	25	42.82	3.00	45.82
42700-T6A-J81	DISK ALUMINIUM WHEEL 17X7J	1	915.00	25	686.25	48.04	734.29
D-215/55R17SP270	DUNLOP TYRE	1	265.00	20	212.00	14.84	226.84
	SUM PARTS:				6,281.94	439.76	6,721.70
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML01I	EXT-YJ	1	80.00		80.00	5.60	85.60
	INSPECT FR LIGHTING MECHANISMS & FOCUS						
	HEADLIGHTS.(N)						
BOMISC1	EXT-YJ	1	300.00		300.00	21.00	321.00
	RESET VEHICLE SMART ENTRY SYSTEM (N)						
BKDR12R	EXT-YJ	1	350.00		350.00	24.50	374.50
	REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST						
	& ALIGN FR R DR.(N)						
BKDR32R	EXT-YJ	1	450.00		450.00	31.50	481.50
	REMOVE & TRANSFER ITEMS TO NEW RR R SLIDING DR.						
	ADJUST & ALIGN RR R SLIDING DR.(N)						
BKBH01S	EXT-YJ	1	840.00		840.00	58.80	898.80
	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.						
BP06R	EXT-YBH	1	2,475.00		2,475.00	173.25	2,648.25



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

PAGE 2/2
© SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WH023 / SOMPO INSURANCE
Chassis No: JHMRC1890GC202948
License No: SKC5858M
Mileage: 19310
Engine No: K24W72011313

Document No: SVO18076285
Printed By: JESHURUEBEN
Order Date: 21. December 2018
Order Time: 12:08:51 PM
Service Advisor: RUEBEN THOMAS

SPRAY PAINTING ON REPAIRED OR
REPLACED AREAS. (6P)

		SUM LABOUR:	4,515.00	316.05	4,831.05
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1 180.00	180.00	12.60	192.60
		SUM EXT SERVICE:	180.00	12.60	192.60
		TOTAL SGD	10,176.94	712.41	10,889.35
		Total Payable (SGD)	10,889.35		

GST Amount is calculated from individual line(s)