

ASS. REC. BY:

REF: CS/lpc18022892/Asd3n2

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Gekuld poh

of lpc

Date/Time: 21/12/18 @ 10:50am

Estimated Cost:

Bill to:

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 935C

Insured:

GBB 6024H

at Workshop m/s

Yi Heng Motor

Tel:

6509 0052

of

1 kaki Bukit Ave 6 #02-19 Autobay

Policy No:

Claim No:

18/1818/vc00/021217

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/12/18

CA / REV / REP. / REV 24 HRS <sup>lup</sup>

H.O.D. Endorsement:

Date/Time:

11:18am @ 21/12/18

Person Contacted:

Wan ping

Vehicle

IN  OUT

Date/Time	Action/Instruction (✓) Estimate	
	GBE 935C - NA/CT18022357/h4	DOA: 12/12/2018
	GBB 6024H - NA/CT18022357/h4	DOA: 12/12/2018

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GBE 935C. Yr Regn: 2015 / Sept.  
 Type: M.Car / M.Cycle / Bus / Van / (Lorry) / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota Dyna. C.C. 2982  
 Colour: Silver A/C: Insured / Std / NI / NA  
 Sp. Reading: 118360 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: KDY2318920348.  
 Gen. Cond: (Good) / Fair / Poor / Burnt  
 Steering: (Inorder) / Jammed / Leaked / Burnt or  
 Brake: (Inorder) / Jammed / Leaked / Burnt or  
 Mod: (Nil) / S/Rim / STD A/Rim or  
 Tyre Size: F: 175/75R15.  
 R: 145 R13

(BS) / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_

Front		Rear	
R/Bal. <u>06</u> mm		R/Bal. <u>06</u> mm	
L/Bal. <u>06</u> mm		L/Bal. <u>06</u> mm	
D.O.A.		D.O.I. <u>21/12/18</u>	

Survey held at Yi Heng  
 Des. of Damages: Frt / Rear / (O/S) / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP ConPac.</u>

23/04/19 Continued als \$ 3,900/- @ 5 days with Adrian  
( \$ 6,092.33 Red - 61% )

RECEIVED 23 APR 2019

Date/Time, File Pass to?

1) 23/04/19  
Tyasa

Date/Time, File Return to?

2) \_\_\_\_\_

: Preli. Report  
 : Final Report

Days Of Repair: 5Resurvey No. of Trip: 3

Survey Fee:

Transportation:

Photos:

Others:

TOTAL

Add Fee:

 Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$ 3,900/- HS)

350

## Nivitha (LKK Auto)

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Friday, 21 December 2018 10:50 AM  
**To:** Admin-D (LKKAuto)  
**Cc:** MT\_Claim\_SG; Anna Tan  
**Subject:** PRE-REPAIR SURVEY OFGBE935C  
**Attachments:** 21122018104537.pdf

Our Ref : 18/18/18/VC00/021217

Dear Catherine,

Please see attached and proceed accordingly.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths  
Agents for Trade Marks  
(Incorporated with limited liability)

Company Registration No. 200721148H

ERIC NG CHING BOON  
WONG KENG LEONG RAYNEY  
AUDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALI DIO MUNIANDY  
SEGA PARAM  
ANG KIM NOI DIANE  
RAVENDRA KRISHNASAMY  
JANICE HAN JIA LIN  
TAN YINGXIAN, SELWYN  
CHEONG YUNHUI, CLARISSA  
EDISON TAM CHYI EU

**Head Office:**  
133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413  
**Branch:**  
490 Toa Payoh Lorong 6  
#03-11 HDB Hub  
Singapore 310490

**HEAD OFFICE:**  
TEL : 65342811 (Hunting)  
FAX : 65356802 (General)

E-MAIL: [annatan@visionlawllc.com](mailto:annatan@visionlawllc.com)

**BRANCH**  
TEL : 63580703  
FAX : 63580448(conveyancing)



WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to **HEAD OFFICE** for this matter

OUR REF: AKN-atv-INS-Y44-GBE935C-2018 - please reply to: [annatan@visionlawllc.com](mailto:annatan@visionlawllc.com)  
YOUR REF: GBB6024H

21 DECEMBER 2018

LONPAC INSURANCE BHD

BY FAX: 6296 3767 ONLY

100 Beach Road  
#19-00 Shaw Tower  
Singapore 189702  
Attn: Motor Claims Department

Dear Sirs

NAME OF CLAIMANT: GENERATION EQUIPMENT & ELECTRONICS PTE LTD  
VEHICLE NUMBER: GBE 935 C  
YOUR INSURED VEHICLE NUMBER: GBB 6024 H  
ACCIDENT ALONG KAKI BUKIT AVE 1 INSIDE SHUN LI INDUSTRIAL ON 12 DEC 2018 AT ABOUT 1100HOURS

We refer to your email dated 20 DECEMBER 2018 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Adrian Ling the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

**YI HENG MOTOR WORKSHOP**  
1 KAKI BUKIT AVENUE 6  
#02-19 AUTOBAY @ KAKI BUKIT  
SINGAPORE 417883  
TEL: 6509 0052 (WAN PING)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

(Head Office)

cc. GBE 935 C - By fax 6747-9402 only

**FOR SURVEYOR**

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :  
(Name & Signature) :

Date & Time of Inspection :

**CONFIDENTIALITY**

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4968W
Vehicle Details	
Vehicle No.:	GBE935C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 M
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2531560
Chassis No.:	KDY2318020348
Maximum Power Output:	-
Open Market Value:	\$28,217.00
Original Registration Date:	01 Sep 2015
First Registration Date:	01 Sep 2015
Transfer Count:	1
Actual ARF Paid:	\$1,411.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$41,562.00
COE Rebate Amount:	\$27,920.00
<b>Total Rebate Amount:</b>	<b>\$27,920.00</b>

The information contained herein is correct as at 12 Dec 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/12/2018 14:22
Date Of Accident	12/12/2018 11:00
Exact Location Of Accident	KAKI BUKIT AVE 1 INSIDE SHUN LI INDUSTRIAL
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE935C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	M/S GENERATION EQUIPMENT & ELECTRONICS PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63821818

### Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA
Exact Purpose for which vehicle was being used at time of accident	WORKING

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken

THIRD PARTY  
COMMERCIAL VEHICLE

Vehicle Category

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3061561803
Cover Note Number	-

### Driver

Name of Driver	LAM KWOK WAH (LIN GUOFA)
NRIC No	S7104835G
Date Of Birth	13/02/1971
Occupation	OUTDOOR
Date Of Driving Pass	22/05/1991
Driving Experience	27 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97575613
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address BLK 74 WHAMPOA DRIVE #13-342  
 Postcode 320074  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - MAJOR/MINOR RD  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

I WAS DRIVING STRAIGHT ALONG THE DRIVE WAY INSIDE SHUN LI INDUSTRIAL, SUDDENLY VEH B WITHOUT STOPPING AT THE STOP LINE AND DASHED OUT FROM THE MINOR ROAD, HIT ONTO MY VEH RIGHT FRONT PORTION.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number GBB6024H  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver NG YIAN HEE  
 NRIC/Passport Number S1261833F  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GI& Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time

Driver's Signature  
(if driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name  
NRIC/PIN No.:

Accident Sketch Plan

SKETCH PLAN



A: GDE 7350  
B: GDE 6024H

Down to Industrial

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to statement

DECLARATION

I/we declare the foregoing particulars are true in every respect

COMPANY INFORMATION: [illegible] PTY LTD

Company's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

[Handwritten signature]

[Handwritten signature]

Reporting Centre Personnel's Signature  
Name  
NRIC/FIN No.



PEOPLES AUTO TRADING  
 BLK 3007 UBI ROAD 1 #01-400  
 TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER	CASH	DATE	Dec 21, 2018 12:15:20 PM
LICENSE NO.	GBE 935 C		
MILEAGE	118365		
REFERENCE	CUSTOM	MODEL	TOYOTA DYNA (KDY231R)

Front Wheel	SPECS				DIAGNOSIS				ADJUSTMENT			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-1.00	0.00	1.50			4.10				4.10		
PARTIAL TOE	-0.50	0.00	0.50		1.10		3.00		2.00		2.10	
SET BACK	---	---	---			0°04"				0°04"		
CAMBER	-1°00"	0°00"	1°00"		0°14"		-1°28" 1°42"		0°14"		-1°28" 1°42"	
CASTER	2°30"	3°30"	4°30"		2°30"		2°50" 0°18"		2°30"		2°50" 0°18"	
KING-PIN	---	---	---		19°22"		12°28" 6°52"		19°22"		12°28" 6°52"	
INCL ANGLE	---	---	---		19°36"		11°00"		19°36"		11°00"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel	SPECS				DIAGNOSIS				ADJUSTMENT			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	---	---	---			0.40				0.40		
PARTIAL TOE	---	---	---		1.50		-1.10		1.50		-1.10	
SET BACK	---	---	---			-0°10"				-0°10"		
CAMBER	---	---	---		0°00"		-0°26" 0°26"		0°00"		-0°26" 0°26"	
THRUST ANGLE	-0°08"	0.00	0°08"			0°12"				0°12"		

# YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6  
#02-19 SINGAPORE 417883  
TEL: 6 5090052 FAX: 6 7479402

21-12-18

OUR REF NO. GBE 935C

TP Kontar

KDY2318020348.

GENERATION EQUIPMENT & ELETRONICS PTE LTD  
61, KAKI BUKIT  
AVE 1, #02-37  
SHUN LI IND PARK  
SINGAPORE 417943

Shirley

**ESTIMATE BILL FOR VEHICLE NO. GBE 935C**  
**MODEL : TOYOTA DYNA 3.0M**

**LIST ITEM**

1) FRONT DOOR (RH) <i>Digitated</i>	2,148.00	<i>1568</i>
2) FRONT DOOR WEATHERSTRIPE (RH) <i>cut</i>	231.55	-
3) FRONT SIGNAL LAMP (RH) <i>new</i>	214.00	+
4) FRONT DOOR OUTER HANDLE (RH) <i>cut</i>	141.00	-
5) FRONT DOOR INNER STRIPE (RH) <i>new</i>	112.00	+
6) FRONT DOOR GLASS CHANNEL (RH) <i>new</i>	147.00	+
7) FRONT DOOR GLASS CHANNEL STRIPE (RH) <i>new</i>	88.90	+
8) FRONT DOOR OUTER MOULDING (RH) <i>rebed</i>	117.20	-
9) FRONT DOOR TRIM BOARD (RH) <i>cracked</i>	687.00	<i>498</i>
10) FRONT DOOR LOCK (RH) <i>brand</i>	240.00	-
11) FRONT DOOR STRIKER (RH) <i>new</i>	32.00	+
12) FRONT DOOR ACTUATOR (RH) <i>new</i>	112.00	+
13) FRONT DOOR PILLAR (RH) <i>Repair</i>	487.00	+
14) FRONT DOOR HINGE (RH) TOP <i>3 new</i>	80.70	+
15) FRONT DOOR HINGE (RH) BOTTOM	72.10	+
16) FRONT DOOR REGULATOR (RH) <i>Damaged</i>	482.00	<i>258</i>
17) FRONT DOOR REGULATOR MOTOR <i>new</i>	381.55	+
18) FRONT ARCH PANEL (RH) <i>Repair</i>	542.00	+
19) FRONT ARCH PANEL RUBBER MOULDING (RH) <i>cut</i>	120.00	✓
20) FRONT MUDGUARD (RH) <i>cut New</i>	323.10	+

# YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6  
 #02-19 SINGAPORE 417883  
 TEL: 6 5090052 FAX: 6 7479402

21) FRONT UPPER ARM (RH) <i>Best</i>		425.00	✓
22) FRONT LOWER ARM (RH) <i>Best</i>		348.00	✓
23) FRONT KNUCKLE ARM (RH) <i>Best</i>		548.00	✓
24) FRONT BALL JOINT (RH) <i>Not need</i>		152.00	✗
25) FRONT SHOCK ABSORBER (RH) <i>new</i>		286.00	✗
26) FRONT WHEEL BEARING (OUTER) <i>new</i>	4722.75	85.00	✓
27) FRONT WHEEL BEARING (INNER) <i>new</i>	3542.06	73.00	✗
28) WING MIRROR (RH) <i>Not need</i>		143.00	✗
		8,819.10	
		2,204.78	
			6,614.33

LESS DISCOUNT - 25%

**SPECIAL NETT ITEM**

1) FRONT COMPANY STICKER (RH) <i>new</i>		38.00	✓
2) FRONT TYRE (RH) <i>Not need</i>	180	180.00	✗
3) FRONT RIM (RH) <i>cut</i>		250.00	180
			468.00

**LABOUR CHARGE**

1) TO CHECK WIRING SYSTEM		50.00	30
2) TO APPLY UNDERSEALING ON AFFECTED AREAS		120.00	✗
3) TO REMOVE AND REFIX FRONT UNDERCARRIAGE ASSY (RH)		420.00	220
4) TO REMOVE AND REFIX CUSHION, FLOOR BOARD, ROOF LINNING, TRIM, GARNISH, UPHOLSTERY AND ETC		220.00	✗
5) TO REMOVE AND REFIX FRONT DOOR FIXING AND REALIGNMENT		220.00	80
6) TO CONDUCT 4 WHEEL ALIGNMENT		120.00	80
7) TO REPLACE NEW PARTS, CUT, WELD, KNOCK AND ETC	1210	1,100.00	400

8) TO RESPRAY ON AFFECTED AREAS

the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

GRAND TOTAL

660.00 400  
 2,910.00  
9,992.33

total: 4932.06  
 h/s: 3.9k

Adrian Lim  
 h/s 21/12/18  
 OS Pays.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS/LPC18022892/Asd3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 25-04-2019	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBB 6024H	Veh. Inspected	GBE 935C
Policy No.		Coverage (\$)	0.00
Claim No.	18/18/18/VC00/021217	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	21/12/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KDY2318020348	Colour	SILVER
Odometer	118360	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/75 R15	BRIDGESTONE	6 mm
L/H Front Tyre	175/75 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	145 R13	BRIDGESTONE	6 mm
L/H Rear Tyre	145 R13	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/12/2018	Inspection Date	21/12/2018
Survey held at	YI HENG MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-19 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 935C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT DOOR (RH)	DISTORTED	2,148.00	1,568.00
1	FRONT DOOR WEATHERSTRIPE (RH)	CUT	231.55	231.55
1	FRONT SIGNAL LAMP (RH)	NOT NECESSARY	214.00	-
1	FRONT DOOR OUTER HANDLE (RH)	CUT	141.00	141.00
1	FRONT DOOR INNER STRIPE (RH)	NOT NECESSARY	112.00	-
1	FRONT DOOR GLASS CHANNEL (RH)	NOT NECESSARY	147.00	-
1	FRONT DOOR GLASS CHANNEL STRIPE (RH)	NOT NECESSARY	88.90	-
1	FRONT DOOR OUTER MOULDING (RH)	DEFORMED	117.20	117.20
1	FRONT DOOR TRIM BOARD (RH)	CRACKED	687.00	498.00
1	FRONT DOOR LOCK (RH)	DAMAGED	240.00	240.00
1	FRONT DOOR STRIKER (RH)	NOT NECESSARY	32.00	-
1	FRONT DOOR ACTUATOR (RH)	NOT NECESSARY	112.00	-
1	FRONT DOOR PILLAR (RH)	TO REPAIR SEE LABOUR	487.00	-
1	FRONT DOOR HINGE (RH) TOP	NOT NECESSARY	80.70	-
1	FRONT DOOR HINGE (RH) BOTTOM	NOT NECESSARY	72.10	-
1	FRONT DOOR REGULATOR (RH)	DAMAGED	482.00	258.00
1	FRONT DOOR REGULATOR MOTOR	NOT NECESSARY	381.55	-
1	FRONT ARCH PANEL (RH)	TO REPAIR SEE LABOUR	542.00	-
1	FRONT ARCH PANEL RUBBER MOULDING (RH)	CUT	120.00	120.00
1	FRONT MUDGUARD (RH)	NOT NECESSARY	323.10	-
1	FRONT UPPER ARM (RH)	BENT	425.00	425.00
1	FRONT LOWER ARM (RH)	BENT	348.00	348.00
1	FRONT KNUCKLE ARM (RH)	BENT	548.00	548.00
1	FRONT BALL JOINT (RH)	NOT NECESSARY	152.00	-
1	FRONT SHOCK ABSORBER (RH)	NOT NECESSARY	286.00	-
1	FRONT WHEEL BEARING (OUTER)	NECESSARY	85.00	85.00
1	FRONT WHEEL BEARING (INNER)	NOT NECESSARY	73.00	-
1	WING MIRROR (RH)	CUT	143.00	143.00
	LESS 25% DISCOUNT		-2,204.77	-1,180.69
			<b>6,614.33</b>	<b>3,542.06</b>
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT COMPANY STICKER (RH)(SN)	NECESSARY	38.00	38.00

Report Ref No. CS/LPC18022892/Asd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT TYRE (RH)(SN)	NOT NECESSARY	180.00	-
1	FRONT RIM (RH)(SN)	CUT	250.00	180.00
			468.00	218.00
	<b>LABOUR</b>			
	TO CHECK WIRING SYSTEM.		50.00	30.00
	TO APPLY UNDERSEALING ON AFFECTED AREAS.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIX FRONT UNDERCARRIAGE ASSY (RH).		420.00	220.00
	TO REMOVE AND REFIX CUSHION, FLOOR BOARD, ROOF LINNING, TRIM, GARNISH, UPHOLSTERY AND ETC.	NOT NECESSARY	220.00	-
	TO REMOVE AND REFIX FRONT DOOR FIXING AND REALIGNMENT.		220.00	80.00
	TO CONDUCT 4 WHEEL ALIGNMENT.		120.00	80.00
	TO REPLACE NEW PARTS, CUT, WELD, KNOCK AND ETC. INCLUSIVE OF THE REPAIR OF FRONT DOOR PILLAR (RH) AND FRONT ARCH PANEL (RH).		1,100.00	400.00
	TO RESPRAY ON AFFECTED AREAS.		660.00	400.00
			2,910.00	1,210.00
	<b>GRAND TOTAL</b>		<b>9,992.33</b>	<b>4,970.06</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,900.00</b>

Report Ref No. CS/LPC18022892/Asd3n2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.