

22/03/2002

/ SS. REC. BY:

REF:

CS/ICS18022902/Tlgbnz

Special Instruction:

Surveyor:
Melina

ASSIGNMENT (Office)

From (Person):

Janice Goh

of

Ics

Date/Time:

21/2/2018 10:15am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 8324A

Insured:

GBE 8550J.

at Workshop m/s

Trans Eurokars

Tel:

of

JFA Tanjung Penjun

Policy No:

MCV18A00016101

Claim No:

DMCV180009AH / JS

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08122018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

21-2-2018 10:42am

Person Contacted:

Vion

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

11/1/19@ m revised to Janice Goh via Melina.

15/01/19@ 10.07am confirmed with Catherine final fig \$3506.46, 3 days.
(Red \$3534.59, 50%)

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Janice Goh

Date: 11 Jan 2019

Preliminary Advice

Insured Vehicle No	: GBE8530J	Accident Date	: 08/12/2018
TP Vehicle No	: SLD8324A	Assignment Date	: 11/01/2019
Make	: MAZDA 3	Est. Duration of Repair	: 3
Date of Inspection	: 10/01/2019		
Inspection At	: TRANS EUROKARS		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,041.05
Revised Amount	:S\$	3,022.89
Check Items (Estimated)	:S\$	488.16
Total	:S\$	3,511.05
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Nivitha (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Friday, 21 December 2018 10:15 AM
To: assignments
Cc: catherinechua@eurokars.com.sg; samuel.ng@eurokars.com.sg;
vion.lim@eurokars.com.sg; ECICS Claims
Subject: RE: YOUR REF: GBE8530J / OUR REF: SLD8324A THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)
Attachments: RPT.PDF; SLD8324A TP ECICS (TP).pdf

10:42am @ 21/12/2018
VNI
Pusun@vion

Hi LKK

Kindly liaise with Vion for the survey arrangement.

Our ref DMCV1800099H/JG and I am the claim handler for this case.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: samuel.ng@eurokars.com.sg [mailto:samuel.ng@eurokars.com.sg]
Sent: Friday, 21 December, 2018 9:06 AM
To: ECICS Claims; vion.lim@eurokars.com.sg
Cc: catherinechua@eurokars.com.sg
Subject: YOUR REF: GBE8530J / OUR REF: SLD8324A THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

YOUR REF: GBE8530J / OUR REF: SLD8324A THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Dear Sir/Mdm,

Attached is the ESTIMATE, SAS REPORT, SKETCH PLAN for your perusal.

Kindly liaise with Vion for the survey arrangement.

Best Regards,

Samuel Ng
Insurance Claims Officer
Trans Eurokars Pte Ltd

follow us on
facebook 

follow us on
twitter 

visit our website
ecics.com.sg



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 15 February 2019 10:07 AM
To: catherinechua@eurokars.com.sg
Cc: vion.lim@eurokars.com.sg; SUR
Subject: RE: SLD8324A - FINALIZATION OF COR

Dear Catherine,

WITHOUT PREJUDICE

Confirm final fig \$3,506.46 before GST and 3 repair days.

Kindly send the relevant documents to ECICS insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)
Sent: Thursday, 14 February 2019 11:45 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: FW: SLD8324A - FINALIZATION OF COR

[CS/ICS18022902/T1qb](#)

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: catherinechua@eurokars.com.sg <catherinechua@eurokars.com.sg>
Sent: Thursday, 14 February, 2019 10:35 AM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: vion.lim@eurokars.com.sg; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: SLD8324A - FINALIZATION OF COR

Dear Taufikh

Our COR computation and B4 paint photos are attached for your agreement.

COR: \$3506.46 before GST

3 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Kindly confirm the above as soon as possible.

Thanks n Regards



Driving luxury experiences since 1985

Catherine Chua

Insurance Claims Executive

27A Tanjong Penjuru, Singapore 609042

T: (65) 6331 0680 D: (65) 6331 0682 F: (65) 6331 0690

E: catherinechua@mazda.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Eurokars Printer Scan <transeurokars@eurokars.com.sg>

Sent: 14 February 2019 7:58 AM

To: Catherine Chua <catherinechua@eurokars.com.sg>

Subject: Attached Image

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/12/2018 16:50
Date Of Accident	08/12/2018 14:45
Exact Location Of Accident	WOODLAND DRIVE 73
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD8324A
Insured/Policyholder	
Name Of Registered Owner	ANG CHUAN HENG
NRIC No	S1322363G
Email Address	ANGCH22@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91762525
Alternative Phone No	OFFICE-91762525
Vehicle Particulars	
Manufacturer	MAZDA
Model	3 4-DOOR SEDAN 1.5L SP.6EAT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01011399
Cover Note Number	

Driver

Name of Driver	ANG CHUAN HENG
NRIC No	S1322363G
Date Of Birth	01/09/1958
Occupation	INDOOR
Date Of Driving Pass	11/08/1981
Driving Experience	37 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91762525
Fax Number	
Contact Number	OFFICE-91762525
EMail Address	ANGCH22@GMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : NG LAI WOO GENDER: : FEMALE
Passenger 2	NAME: : P1 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I (SLD8324A) was stationary at a traffic light, waiting for the traffic light to turn green, along Woodlands drive 73, on the left lane when suddenly a lorry (GBE8530J) hit me from the back. No injuries involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE8530J
Vehicle Make/Model/Colour	NISSAN/CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5/SILVER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MOHAMAD SALAM BIN MD TAHIR
NRIC/Passport Number	S2193077F
Contact Number	94881022
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please read carefully the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misstatement or withholding of material facts may void insurance coverages and result in a denial of claims.
4. The issue and acceptance of this form by insurance companies is not an admission of liability for the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the QIA (Roadside Management Centre) and/or the Central Insurance Association of Singapore (CIAS) for verifying and that copies of this report will be made available to the insurers and to the police.
7. By the acceptance of this report by the insurers, you hereby consent to the archiving of this report being made available at all times.
8. Consents under the Personal Data Protection Act (PDPA)
 - (a) I understand, acknowledge, agree and consent that (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may use, disclose and/or process my personal information set out in this form and any other personal information provided to them by me or any other person who have insured vehicles involved in this accident (all insurers who have insured vehicles involved in this accident shall be referred to as the "Insurers"), the Insurers' lawyer(s) firm, the Ministry Authority of Singapore and any relevant government authority (such as the police), for the purposes of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any matters relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, notices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of any postal mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes");
 - (b) all insurers (i) who have insured vehicles involved in this accident and the Insurers' lawyer(s) firm, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyer(s) firm), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHAMMAD SULHANDI BIN
MOHD AFFANDI

Amr
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



Common Statement

ACCIDENT STATEMENT (2000 characters)

I (SLD8324A) was stationary at a traffic light, waiting for the traffic light to turn green, along Woodlands drive 73, on the left lane when suddenly a lorry (GBE8530J) hit me from the back. No injuries involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMMAD SULHANDI BIN MOH AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

9 December 2018 at 4.05 PM

Date/Time:

9 December 2018 at 4.05 PM



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



ECICS LIMITED 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987. ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Ang Chuan Heng ADDRESS : Apt Blk 239 Bukit Panjang Ring Road #12-103 Singapore 670239 TEL : 91762525		WIP : 31106 EXCESS : DATE : 21-Dec-18	
VEH NO :	SLD8324A	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	JM6BM42A8G0336435	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	29-Jun-16	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	REAR BUMPER 1	MBHN1-50-221ABB	de ✓ \$ 1,074.80 ✓
2	BRACKET CENTER, REAR BUMPER 1	MKD53-50-251	ms ✓ \$ 5.10 X
3	TOWING COVER LHS 1	MBHN1-50-EL1 BB	ms ✓ \$ 15.70 ✓
4	TOWING COVER RHS 1	MBHN1-50-EK1 BB	w/c ✓ \$ 16.20 ✓
5	REAR REINFORCEMENT 1	MB45A-50-260	? bt ✓ \$ 537.30 ✓
6	GROMMET, REAR BUMPER 4	MBHN1-50-0Z1A	re ✓ \$ 10.00 ✓
7	RIVET, REAR BUMPER 4	MBBM4-50-355	re ✓ \$ 16.80 ✓
8	GROMMET, REAR BUMPER 2	M9991-00-501	re ✓ \$ 5.60 ✓
9	FASTENER, REAR BUMPER 4	MB45A-56-146A	re ✓ \$ 11.20 ✓
10	GASKET LHS, TAILLAMP 1	MBHN1-51-163	re - need to remove ✓ \$ 20.90 ✓
11	GASKET RHS, TAILLAMP 1	MBHN1-51-153	re ✓ \$ 20.90 ✓
TOTAL PARTS			\$ 1,734.50
LESS 10%			\$ 173.45
TOTAL PARTS COST			\$ 1,561.05

Labour Description

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	660 ✓	\$ 1,980.00
2		TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL.	? 630 ✓	\$ 1,890.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	330 ✓	\$ 660.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	X m ✓	\$ 250.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150 ✓	\$ 250.00

6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.	NETT nh.	\$ 100.00
			TOTAL LABOUR	\$ - \$ 5,480.00
			TOTAL PARTS	\$ - \$ 1,561.05
			TOTAL	\$ - \$ 7,041.05
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

[Handwritten Signature]
11/1/19
Taylor 97495749
= WP
10/1/19 @ 430pm
Resurvey before paint
sur@lkkauto.com.
03 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by: Repairer
Signature:
Date:



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



ECICS LIMITED 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987.		NAME : Mr Ang Chuan Heng	WIP : 31106
ATTN. : MOTOR CLAIMS		ADDRESS : Apt Blk 239 Bukit Panjang Ring Road #12-103 Singapore 670239	EXCESS :
FAX :		TEL : 91762525	DATE: 21-Dec-18

VEH NO :	SLD8324A	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	JM6BM42A8G0336435	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	29-Jun-16	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	REAR BUMPER	\$ 1,074.80	\$ 1,074.80
2	1	BRACKET CENTER, REAR BUMPER		\$ 5.10
3	1	TOWING COVER LHS	\$ 15.70	\$ 15.70
4	1	TOWING COVER RHS	\$ 16.20	\$ 16.20
5	1	REAR REINFORCEMENT	\$ 537.30	\$ 537.30
6	4	GROMMET, REAR BUMPER	\$ 10.00	\$ 10.00
7	4	RIVET, REAR BUMPER	\$ 16.80	\$ 16.80
8	2	GROMMET, REAR BUMPER	\$ 5.60	\$ 5.60
9	4	FASTENER, REAR BUMPER	\$ 11.20	\$ 11.20
10	1	GASKET LHS, TAILLAMP	\$ 20.90	\$ 20.90
11	1	GASKET RHS, TAILLAMP	\$ 20.90	\$ 20.90
TOTAL PARTS			\$ 1,729.40	\$ 1,734.50
LESS 10%			\$ 172.94	\$ 173.45
TOTAL PARTS COST			\$ 1,556.46	\$ 1,561.05

Labour Description

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 660.00	\$ 1,980.00
2		TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL.	\$ 630.00	\$ 1,890.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	\$ 330.00	\$ 660.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00

6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.		\$ 100.00
			TOTAL LABOUR	\$ 1,950.00
			TOTAL PARTS	\$ 1,561.05
			TOTAL	\$ 3,511.05
			LESS EXCESS	\$ -
			TOTAL AFTER EXCESS	\$ 3,511.05
			GST 7%	\$ 245.45
			GRAND TOTAL	\$ 3,756.50

REMARKS:

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18022902/T1QBN2

Date: 18/02/2019

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	MCV18A00016101	
Claimant Vehicle No :	SLD8324A	Insured Vehicle No :	GBE8530J	
Date of Loss:	08/12/2018	Nature of Claim:	TP	Claim No: DMCV1800099H/JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD8324A		
Make & Model:	MAZDA 3, 1.5 4 DOOR SEDAN SP (A)	Engine No:	P520354678
Reg. Date:	29/06/2016 (Man. Year: 2016)	Chassis No:	JM6BM42A8G0336435
Colour:	Bronze	Odometer:	17278 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,661.05	1,556.46	104.59	6.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,380.00	1,950.00	3,430.00	63.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,041.05	3,506.46	3,534.59	50.20
+ GST 7.00/7.00% (S\$)	492.87	245.45	247.42	50.20
Nett Amount (S\$)	7,533.92	3,751.91	3,782.01	50.20

INSPECTION

Date of Assignment:	21/12/2018	
Date Inspected:	10/01/2019 Inspected At:	27A TANJONG PENJURU Repairer : Trans Eurokars Pte Ltd (HQ)
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Feb 2019)
Parts: 143	MAZDA 3 1.5 4 DOOR SEDAN SP (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLD8324A)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,074.80 FL	*1,074.80 FL
2	1		*BRACKET CENTER, REAR BUMPER	Not Necessary	5.10 FL	*- FL
3	1		*TOWING COVER LHS	Missing	15.70 FL	*15.70 FL
4	1		*TOWING COVER RHS	Missing	16.20 FL	*16.20 FL
5	1		*REAR REINFORCEMENT	Bent	537.30 FL	*537.30 FL
6	4		*GROMMET, REAR BUMPER	Necessary	10.00 FL	*10.00 FL
7	4		*RIVET, REAR BUMPER	Necessary	16.80 FL	*16.80 FL
8	2		*GROMMET, REAR BUMPER	Necessary	5.60 FL	*5.60 FL
9	4		*FASTENER, REAR BUMPER	Necessary	11.20 FL	*11.20 FL
10	1		*GASKET LHS, TAILLAMP	Necessary	20.90 FL	*20.90 FL
11	1		*GASKET RHS, TAILLAMP	Necessary	20.90 FL	*20.90 FL
12	1		*SUNDRIES	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,834.50	1,729.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	173.45	172.94
Total Parts (\$\$)	1,661.05	1,556.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT	New	1,980.00	660.00
2	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL	New	1,890.00	630.00
3	TO TRANSFER REVERSE SENSORS	New	660.00	330.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	0.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
Gross Labour Cost (S\$)			5,380.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >