

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

AIG

DATE 21/12/2018 10:23

VEHICLE NO : SHC 8100G

MAKE :

MODEL : HYUNDAI i40

LIS

L

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid CRDI Plate			\$ 27.90
	Rear Bumper			\$ 553.00
	Rear Bumper Reinforcement			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH)	\$	80.30	\$ 160.60
	Rear Bumper Clip 10 pcs			\$ 22.00
	Rear Bumper Bracket	\$	35.60	\$ 71.20
	Rear Bumper Sponge			\$ 103.50
	Rear Bumper Under Cover			\$ 228.00
	Exhaust Silencer,RH			\$ 967.70
	Exhaust Pipe Hanger,RH			\$ 58.55
	SUB TOTAL			\$ 2,620.85
	LESS 20%			\$ 524.17
	DISCOUNTED TOTAL			\$ 2,096.68
	Boot Lid Advertisement Logo			\$ 100.00
	Rear No.Plade			\$ 25.00
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH)	\$	100.00	\$ 200.00
				\$ 375.00
	Labour Charge			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 500.00
	Remove/Refix Exhaust Pipe			\$ 150.00
	TOTAL LABOUR			\$ 1,000.00
	ESTIMATE TOTAL			\$ 3,471.68

/NEC
 XR
 ?
 ?
 XNN
 ?
 ?
 DEF
 SCR
 ?

/NEC
 Nett
 Nett /CRK
 Nett /NBC
 Nett /NEC

300
 400
 50

NAZ LK K
 21/12/18
 LIS
 3 Day

(CHECKED ITEMS PHOTO)
 AFTER REPAIR PHOTO.

Larry Ng

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.