



Case Details

Case Reference Number :

TAX/12/18/2080

Type of Repair : Accident Repair

Vehicle Registration Number :

SHC4946J

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-5030-ID

Assigned By : Kok Wah Wong

Insurance Company Name : India International Insurance Pte Ltd

Accident Date and Time : 19/12/2018 11:40 PM

Vehicle Age(In Months) : 31

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace ▾	DEF
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace ▾	NEC
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0.00	Check ▾	
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0.00	Check ▾	
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0.00	Check ▾	
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾	NEC

Total Spare Part Cost	2,307.75	Surveyor Total	476.03
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	2,307.75	Final Sur Total	476.03

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	1	0.00	Repair ▼
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0.00	Not Give ▼
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0.00	Check ▼
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0.00	Check ▼
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0.00	Check ▼
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	0	0.00	Check ▼
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0.00	Not Give ▼
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0.00	Not Give ▼
Total Spare Part Cost									2,307.75		Surveyor Total	476.03	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost									2,307.75		Final Sur Total	476.03	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR RH REAR PORTION	845.00	200.00	
Total:		845.00	200.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		1,116.00	200.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200.00	
2	TO RESPRAY BUMPER BEAM	180.00	0	
3	TO RESPRAY REAR PANEL	180.00	0	
4	TO RESPRAY REAR FENDER RH	378.00	0	
Total:		1,116.00	200.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TOWING CHARGE	56.00	0	
2	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20.00	
3	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
4	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	
5	TO WASH AND VACUUM	60.00	0	
Total:		416.00	20.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,307.75	476.03
Total Labour Cost	845.00	200.00
Total Spray Painting	1,116.00	200.00
Other	416.00	20.00
Overall Total	4,684.75	896.03
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	896.03
Surveyor Approved Amount		896.03

	Estimator Assesment(\$)	Surveyor Assesment(\$)
No of Repair Days*	6	2
Remarks	-	P/P photo before paint.
Surveyor Name		Hwee jie
Signature		
Survey Date	21/12/2018	

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: