

INS CASE OWNER:

CC 3, 086 180

LKK:
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimon:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time:

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: MTH

Repair Cost:

PR \$53,244.37

(4 days) Reduction:

33 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 13.11.19

Confirm with: SHAW JYE

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

31

If NO or B 28, Ass. Lia:

Repair Cost:

01/67 \$53,476.35

OI TURN LEFT INTO THE MAIN ROAD.

Loss of Rental (LOR):

\$5 518.95

(5 days) * \$103.79

Loss of Use (LOU):

\$5 -

(5 x days)

Loss of Income (LOI):

\$5 -

(5 x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$52.00

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/Independent)

Legal Cost

\$5 -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

+400

Total:

\$53,997.78

Global Sum SS:

FINAL PAYMENT

Date/Time: 13.11.19

Confirm with: SHAW JYE

Email ☒ Call ☐

Payee 1:

\$53,997.78

Name 1:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

Tanfer

REF:

QSE

ASSIGNMENT

From _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res: Yes or No
Lum Sum: _____ % 3 Val: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SMD1424X Tr Regd: 2017 June
Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover /
Truck / Trailer or _____
Make: Hyundai 130 cc 1582
Colour: S/ue A/C: Insured / Std / NI / NA
Sp. Reading: 157802 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: TMAID 28146A J/28015
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/65R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Maxxis
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 20/12/18
Survey held at Home
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frd n/s
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Pip: +3,249.37 (RED: +1,621.71 33%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. \$

) Photo

) Other

) U/C

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/QBE18022921/T1ea3

Date: 24/12/2018

The Motor Claims Department
M/s QBE INSURANCE (SINGAPORE) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD 1404X

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/12/2018 at the premises of M/s Premier Automotive Services Pte Ltd - Changi) and have the following to report:-

Workshop Estimate Amount	: S\$	4,870.54	(est.)
Revised Estimate Amount	: S\$	3,249.37	(est.)
"Check" Items Amount	: S\$	-	(est.)
Total (Including Check Items)	: S\$	3,249.37	(est.)
Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
Front N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

Tan Jia 93495749
20/12/18 1pm
Ready before paint
340@lkkauto.com
4 days

19-Dec-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30A REGN NO: SHD 1404 X

1 pc	Front bumper	\$ 811.11	<i>le</i>
1 pc	Front bumper emblem	\$ 27.80	<i>x</i>
1 pc	Front bumper inner sponge	\$ 218.03	<i>x</i>
1 pc	Front bumper reinforcement	\$ 636.40	<i>x</i>
1 pc	n/s head lamp	\$ 1,531.57	<i>mt</i>
2 pcs	Front n/s & o/s side bracket @ \$32.51	\$ 65.02	<i>RH-M</i>
1 pc	Front n/s fender	\$ 514.02	<i>bt</i>
1 pc	Front n/s fender inner shield	\$ 176.72	<i>x</i>
		\$ 3,980.67	
	Less 20%	\$ 796.13	
		\$ 3,184.54	

S/NETT

1 set	Front bumper clips	\$ 48.00	<i>mt</i>
1 pc	Front n/s fender sticker	\$ 30.00	<i>mt</i>
1 set	Front n/s fender inner shield clips	\$ 28.00	<i>x</i>
	Sundry <i>mt</i>	\$ 50.00	<i>20</i>
	To check wiring and focus n/s head lamp	\$ 30.00	<i>✓</i>
	To check front n/s wheel alignment	\$ 80.00	<i>✓</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$ 750.00	<i>300</i>
	To putty and spray painting on front bumper, front n/s fender	\$ 550.00	<i>400</i>
	To apply rustproofing on the repaired and replaced panels.	\$ 120.00	<i>30</i>
		\$ 4,870.54	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before the spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mei Kwan (LKKAuto)

From: Janice Goh Siew Geok <janice.goh@qbe.com>
Sent: Tuesday, 8 October, 2019 10:00 AM
To: Mei Kwan (LKKAuto)
Cc: Asher Sng (LKKAuto); Admin A
Subject: RE: Direct Settlement - Accident Involving SBU5C (OI : QBE - TBA) AND SHD1404X (TP : LKK REF - CC3/QBE18022921/T1ea3) on 19/12/2018
Attachments: SDU5C.pdf
Categories: HMK

Hi Mei Kwan

As requested, please refer to the attachment.
Thank you.

Janice Goh
Executive, Claims
Claims | Asia
1 Raffles Quay, #29-10 South Tower, Singapore 048583
+65 6477 1243
Website [LinkedIn](#) [Twitter](#)



From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Tuesday, 8 October 2019 9:51 AM
To: Jenny Toh <jenny.toh@qbe.com>; Janice Goh Siew Geok <janice.goh@qbe.com>
Cc: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving SBU5C (OI : QBE - TBA) AND SHD1404X (TP : LKK REF - CC3/QBE18022921/T1ea3) on 19/12/2018

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: Meikwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Wednesday, 26 December, 2018 3:25 PM
To: Jenny Toh <jenny.toh@qbe.com>

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
 Owner ID Type: Company
 Owner Name: PREMIER TAXIS PTE. LTD.
 Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: SHD1404X
 Previous Vehicle No.: -
 Effective Date of Ownership: 29 Jun 2017
 Original Regn Date: 29 Jun 2017
 Registration Date: 29 Jun 2017
 Year of Manufacture: 2016
 Vehicle Type: Public Transport Taxi (Motor Car)
 Vehicle Scheme: Taxi (Company)
 Vehicle Attachment 1: Air-Con (Taxi)
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: HYUNDAI
 Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
 Primary Colour: Silver
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: TMAD281UVHJ128015
 Engine No.: D4FBGZ122114
 Engine Capacity/Power Rating: 1582 cc / -
 Maximum Power Output: 100.0 kW (134 bhp)
 Propellant: Diesel
 Max Unladen Weight: 1496 kg
 Maximum Laden Weight: 1940 kg
 Open Market Value: \$20,545.00
 PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 28 Jun 2025
 Minimum PARF Benefit: \$7,957.00
 No. of Transfers: 0
 IU Label No.: 1050700335
 COE No.: 2017062901003961Z
 COE Expiry Date: 28 Jun 2025
 COE Category: A - Car up to 1600cc & 97kW (130bhp)
 COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)
 Quota Premium (QP) / Prevailing Quota Premium: - / \$50,625.00
 PQP Paid: \$40,500.00
 QP (Regn Cat): -
 OPC Cash Rebate Eligibility: No

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5095103893

Cover : Third Party

1. Index mark and Registration Number of Vehicle

: **SHD1404X**

Chassis Number

: TMAD281UVHJ128015

2. Name of Policyholder

: PREMIER TAXIS PTE. LTD.

3. Effective Date of Insurance

: 20 Oct 2017

4. Expiry Date of Insurance

: 31 Jan 2019

5. Persons or Classes of Persons entitled to drive*

(a) The Policyholder.

(b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use*

(a) Use as a Taxi.

(b) Use for social domestic and pleasure purposes.

This Policy does not cover

(a) Use for racing, pace-making, reliability trial or speed-testing.

(b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I)

: N/A

EXCESS (SECTION II)

: S\$3,500

INSURE WITH COE

: N/A

HIRE PURCHASE COMPANY

: DBS BANK LTD

SUM INSURED

: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)

Date of Issue : 16 Oct 2017 17:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC3/QBE18022921/T1ea3q2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 09-12-2019



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SBU 5C	Veh. Inspected	SHD 1404X
Policy No.	8-V0008643-MVA-R004	Coverage (\$)	0.00
Claim No.	VC012163	Excess (\$)	0.00
Assign From		Assign Date	20/12/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I30	c.c	1582
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	TMAD281UVHJ128015	Colour	SILVER
Odometer	157802	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MAXXIS	6 mm
L/H Front Tyre	195/65 R15	MAXXIS	6 mm
R/H Rear Tyre	195/65 R15	MAXXIS	6 mm
L/H Rear Tyre	195/65 R15	MAXXIS	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/12/2018	Inspection Date	20/12/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1404X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	811.11	811.11
1	FRONT BUMPER EMBLEM	NOT NECESSARY	27.80	-
1	FRONT BUMPER INNER SPONGE	NOT NECESSARY	218.03	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	636.40	-
1	N/S HEAD LAMP	CUT	1,531.57	1,531.57
2	FRONT N/S & O/S SIDE BRACKET @\$32.51	O/S NECESSARY	65.02	32.51
1	FRONT N/S FENDER	BENT	514.02	514.02
1	FRONT N/S FENDER INNER SHIELD	NOT NECESSARY	176.72	-
	LESS 20% DISCOUNT		-796.13	-577.84
			3,184.54	2,311.37
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	FRONT N/S FENDER STICKER (SN)	NECESSARY	30.00	30.00
1	SET FRONT N/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	28.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			156.00	98.00
LABOUR				
	TO CHECK WIRING AND FOCUS N/S HEAD LAMP .		30.00	30.00
	TO CHECK FRONT N/S WHEEL ALIGNMENT.		80.00	80.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK - OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE SAME ,ETC.		750.00	300.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT N/S FENDER .		550.00	400.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	30.00
			1,530.00	840.00
GRAND TOTAL			4,870.54	3,249.37
RECOMMENDED COST OF REPAIRS				3,249.37

Report Ref No. CC3/QBE18022921/T1ea3q2



Report Ref No. CC3/QBE18022921/T1ea3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.