

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TWINCAR LEASING PTE LTD
 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

Contact : 93877599

ESTIMATE

Repair Code : CLM14962

Date in : 19/12/2018

Vehicle Num. : SKX2153Y

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104538075/1ZRY205202

TP111
 Xiao Tong

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
AIR CLEANER RESONATOR <i>changed</i>	1	271.10	271.10 ✓
FRONT BUMPER <i>changed</i>	1	581.45	581.45 ✓
FRONT BUMPER INNER SPONGE <i>new</i>	1	186.10	186.10 ✓
FRONT BUMPER LH FOGLAMP <i>changed</i>	1	378.20	325 378.20 ✓
FRONT BUMPER LH FOGLAMP COVER <i>new</i>	1	91.90	91.90 ✓
FRONT BUMPER SIDE RETAINER L/R <i>LH new</i>	2	132.10	264.20 <i>132%</i>
FRONT GRILLE <i>changed</i>	1	595.90	407 595.90 ✓
FRONT LH FENDER 'VVT-I' EMBLEM <i>new</i>	1	54.00	54.00 ✓
FRONT LH FENDER INNER SHIELD <i>new</i>	1	200.90	200.90 +
FRONT LH HEADLAMP <i>changed</i>	1	850.00	850.00 ✓
FRONT LH HEADLAMP MOULDING <i>new</i>	1	141.50	141.50 +
Subtotal before discount			3,615.25
Percentage discount 25%			903.81
Sub-total 1			2,711.44
FRONT BUMPER CLIPS - SET <i>new</i>	1	50.00	50.00 30
FRONT GRILLE CLIPS - SET <i>new</i>	1	30.00	30.00 15
FRONT LH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	50.00	50.00 +



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

TWINCAR LEASING PTE LTD

2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT

AUTOHUB

SINGAPORE 417921

Contact : 93877599

ESTIMATE

Repair Code : CLM14962

Date in : 19/12/2018

Vehicle Num. : SKX2153Y

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104538075/1ZRY205202

Subtotal before discount	130.00
Percentage discount 0%	0.00
Sub-total 2	130.00
Parts-total	2,841.44

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	990.00
Parts & Labour Total	3,831.44

730
30 50.00
400 500.00
300 400.00
x 40.00

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
L/S 27/12/18
042
total 2948.98
L/S: 2:3K.
Sly