

15/5/2010

INS. CASE OWNER:

CC 4 / AXA1802

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

(S x days)

Loss of Income (LOI):

S\$

(S x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOU ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle /AP

2) Report Format:

3) Survey fee:

COPY SENT
17/5/10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18022924/Ueb3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 21-12-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKJ 8581D	Veh. Inspected	SMG 2545R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/12/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	20/12/2018	Inspection Date	21/12/2018
Survey held at	KAH MOTOR.CO.SDN.BHD 6A MANDAI ESTATE SINGAPORE 729903		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

18-2-19

11.40am 看車

Ke

Not Authorized

22/2/19

King's Auto Spray Paint Pte Ltd

\$2798.92

WONG HOE CHEONG

160 Sin Ming Drive #05-10 Sin Ming Autocity

Singapore 575722 • Tel: 96532526 • Fax: 6266 3974

Return After Paint

Re: Estimate cost for SMG 2545 R HONDA 2.4

3 days

SUPPLY OF PARTS:

ipc front bumper	Bu \$786.30 ✓
ipc front bumper grille center	cm 205.80 ✓
ipc front bumper grille midly top	ng 210.40 ✓
ipc front bumper grille midly	sn 205.00 ✓
2pc front bumper side retainer @ 41.60 ✓	clsn 83.20 ✓
ipc front bumper lower grille	bu 95.80 ✓
ipc front bumper sport lamp	ntj cm 251.90 ✓
ipc front bumper sport lamp cover	sn 105.60 ✓
ipc front bumper midly lower side	cm 120.80 ✓
ipc front bumper brackets	n 49.50 X
ipc front bumper beam	n 280.00 ✓
8pc front bumper clips @ 5.50	n 44.00 ✓
ipc front Head lamp	sn 2237.20 X
ipc front Head lamp lower garnish	fa \$sn 49.50 ✓

ipc sport brackets \$83.20 ✓ Less 9% 20%
cm ✓

4725.00

472.50

\$4252.50

LABOUR:

ipc front number plate

\$ 40.00 X

To check wiring

\$ 40.00 15%

Repair the above mentioned parts
Knocking, cutting, welding & straighten
damaged parts.

Spray painting

350l 250l

\$ 600.00

450l 250l

\$ 600.00

\$ 5532.50

5126.56

18-2-19

King's Auto Spray Paint Pte Ltd

160 Sin Ming Drive #05-10 Sin Ming Autocity

Singapore 575722 • Tel: 96532326 • Fax: 6266 3974

WONG HOE CHEONG

Not Authorized

1/18/8?

Resurvey After Paint

Re: Estimate cost for SMG 2545 R HONDA 2.4 2days

SUPPLY OF PARTS:

1pc front bumper	Rs \$786.30 ✓
1pc front bumper grille center	205.80 ?
1pc front bumper grille mid top	210.40 ?
1pc front bumper grille mid	205.00 ?
2pc front bumper side retainer @ 41.60	clm 83.20 ✓
1pc front bumper lower grille	95.80 ?
1pc front bumper sport lamp	Rs 251.90 X
1pc front bumper sport lamp cover	Rs 105.60 ✓
1pc front bumper mid lower side	120.80 ?
1pc front bumper brackets	R 49.50 X
1pc front bumper beam	280.00 ?
8pc front bumper clips @ 5.50	Rs 44.00 ✓
1pc front Head lamp	2237.20 ?
1pc front Head lamp lower garnish	Rs \$ 49.50 X
	4725.00
	472.50
	\$ 4252.50

Less 7% 208

LABOUR:

1pc front number plate

To check wiring

Renew the above mentioned parts

Knocking, cutting, welding & straighten
damaged parts.

Spray painting

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Rs \$ 40.00 ✓

40.00 15%

\$ 600.00

\$ 600.00

\$ 5532.50



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SMG2545R
Chassis No : JHMRC1880JC206288
Model : ODYSSEY 2.4 EX-S 18YM (EURO 6)
Owner's Name : WONG HOE CHEONG
Ins Policy No. :
Date of Accident : 20/12/2018

Document No. : SQT18005442
Date : 20. Dec 2018
Customer No. : WZA006
Svc Advisor : RUEBEN THOMAS
Engine No : K24W72402506
Date | Time : 20. Dec 2018 5:10:28 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: WONG HOE CHEONG OWNER INSURER: LIBERTY INSURANCE ACC DATE: 20/12/2018 SURVEYED BY: DATE: REF NO: TP INSURER: AXA INSURANCE TP VEH: SKJ8581D						
04711-T6A-900ZZ	FACE,FR.BUMPER <i>Dis</i>	1	700.00	25	525.00	36.75	561.75
91505-TM8-003	CLIP,BUMPER <i>nc</i>	14	2.30	25	24.15	1.69	25.84
71198-T6A-003	SPACERL.FR.BUMPER SIDE <i>11</i>	1	11.80	25	8.85	0.62	9.47
71193-T6A-003	SPACERR.FR.BUMPER SIDE <i>54</i>	1	11.80	25	8.85	0.62	9.47
71140-T6A-003	BEAMR.FR.BUMPER UPPER	1	34.90	25	26.17	1.83	28.00
71151-T6A-901	BASE,MID GRILLE	1	186.50	25	139.87	9.79	149.66
75700-TA0-A00	EMBLEMFR.	1	26.70	25	20.02	1.40	21.42
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
71122-T6A-J01	MOLDINGFR.GRILLE <i>scr</i>	1	315.90	25	236.92	16.58	253.50
71152-T6A-901	UPPER MOLDING,MID GRILLE <i>scr</i>	1	184.30	25	138.22	9.68	147.90
71153-T6A-901	MID MLDG,MID GRIL <i>scr</i>	1	175.50	25	131.62	9.21	140.83
71154-T6A-901	LOWER MOLDING,R.MID GR <i>scr</i>	1	48.20	25	36.15	2.53	38.68
71105-T6A-901	GRILLEFR.BUMPER LOWER <i>scr</i>	1	67.10	25	50.32	3.52	53.84
71112-T6A-901ZA	SPOILER ASSY,R.FR. <i>scr</i>	1	79.00	25	59.25	4.15	63.40
33100-T6A-Q21	LIGHT ASSY,R.HEAD	1	835.10	25	626.32	43.84	670.16
71104-T6A-901	GARNISH,R.FR.BUMPER <i>scr</i>	1	46.10	25	34.57	2.42	36.99
33905-T6A-003	BRACKETR.FR.FOGLIGHT	1	63.20	25	47.40	3.32	50.72
33900-TY0-003	LIGHT ASSY, R. FR.FOG	1	267.10	25	200.32	14.02	214.34
76841-T6A-003	TANKWASHER	1	70.90	25	53.17	3.72	56.89
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N) <i>scr</i>	1	45.00		45.00	3.15	48.15
Sum Item					2415.32	169.06	2,584.38

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SMG2545R

Chassis No : JHMRC1880JC206288

Model : ODYSSEY 2.4 EX-S 18YM (EURO 6)

Owner's Name : WONG HOE CHEONG

Ins Policy No. :

Date of Accident : 20/12/2018

Document No. : SQT18005442 Page 2

Date : 20. Dec 2018

Customer No. : WZA006

Svc Advisor : RUEBEN THOMAS

Engine No : K24W72402506

Date | Time : 20. Dec 2018 5:10:28 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	100.00	80	100.00	7.00	107.00
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	1200.00	130	1200.00	84.00	1284.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1000.00	450	1000.00	70.00	1070.00
Sum Labor					2350.00	164.50	2,514.50

Survey By

Date & Time

Excess

Status

Signature

Total Amount 4,765.32 333.56 5,098.88

Total (Inclusive of GST) 5,098.88

L&K Auto Consultants hence notify the Repairer of the following:

- Repairs and / or spray painting
- To be done in the presence of the surveyor
- To be done on a "No Fault" basis
- The repairer must be on a "No Fault" basis
- The repairer must be on a "No Fault" basis
- The repairer must be on a "No Fault" basis
- The repairer must be on a "No Fault" basis

Acknowledged by Repairer

Signature:

Date:

Printed on 20/12/2018 5:24:40 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

Service Request Details

Claim

S8M017FN

Reference

None 

Loss Date

20 December 2018

Request Date

21 December 2018

Due Date

31 December 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

21.12.2018 C 9.46am
Rueben veh not in

Actions

Next Step

Agree to perform service

Decline WorkAccept Work

Vehicle Information

Incident Vehicle Registration #

SMG2545R

Make

TPVD HONDA

Service Address

...

Primary Contact/Insured

TEW ENG ANN

BLK 1A CANTONMENT ROAD, #07-09, 085101, Singapore

Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18022924/Keb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: XINYOU

Date : 23-05-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKJ 8581D	Veh. Inspected	SMG 2545R
Policy No.	VPA/P2069962	Coverage (\$)	0.00
Claim No.	S8M017FN	Excess (\$)	0.00
Assign From	XINYOU	Assign Date	21/12/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA ODYSSEY (A)	c.c	2356
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JHMRC1880JC206288	Colour	METALLIC MAROON
Odometer	004562	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55R17	DUNLOP	9 mm
L/H Front Tyre	215/55R17	DUNLOP	9 mm
R/H Rear Tyre	215/55R17	DUNLOP	9 mm
L/H Rear Tyre	215/55R17	DUNLOP	9 mm

4. Description of DamagesTHE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.**5. General Information**

Accident Date	20/12/2018	Inspection Date	22/12/2018
Survey held at	KAH MOTOR.CO.SDN.BHD		
Repairer	KING'S AUTO SPRAY PAINT PTE LTD		

5a. RemarksA) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.**5b. Estimate Days of Repair**ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 2545R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (CONSISTENT)	BUCKLED	786.30	786.30
1	FRONT BUMPER GRILLE CENTER (CONSISTENT)	CRACKED	205.80	205.80
1	FRONT BUMPER GRILLE MLDG TOP (CONSISTENT)	SCRATCHED	210.40	210.40
1	FRONT BUMPER GRILLE MLDG (CONSISTENT)	SCRATCHED	205.00	205.00
2	FRONT BUMPER SIDE RETAINER @ \$41.60 (CONSISTENT)	O/S DISTORTED	83.20	41.60
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	DENTED	95.80	95.80
1	FRONT BUMPER SPORT LAMP (CONSISTENT)	MTG CRACKED	251.90	251.90
1	FRONT BUMPER SPORT LAMP COVER (CONSISTENT)	SCRATCHED	105.60	105.60
1	FRONT BUMPER MLDG LOWER SIDE (CONSISTENT)	CRACKED	120.80	120.80
1	FRONT BUMPER BRACKETS (CONSISTENT)	TO REPAIR SEE LABOUR	49.50	-
1	FRONT BUMPER BEAM (CONSISTENT)	BENT	280.00	280.00
8	FRONT BUMPER CLIPS @ \$5.50 (CONSISTENT)	NECESSARY	44.00	44.00
1	FRONT HEAD LAMP (CONSISTENT)	SERVICEABLE	2,237.20	-
1	FRONT HEAD LAMP LOWER GARNISH (CONSISTENT)	SCRATCHED	49.50	49.50
1	SPORT BRACKETS (CONSISTENT)	CRACKED	83.20	83.20
	LESS 20% DISCOUNT		-961.64	-495.98
			3,846.56	1,983.92
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	SERVICEABLE	40.00	-
			40.00	-
LABOUR				
	TO CHECK WIRING.		40.00	15.00
	RENEW THE ABOVE MENTIONED PARTS KNOCKING, CUTTING, WELDING & STRAIGHTEN DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER BRACKETS.		600.00	350.00
	SPRAY PAINTING.		600.00	450.00
			1,240.00	815.00
GRAND TOTAL			5,126.56	2,798.92

Report Ref No. CC4/ASM18022924/Keb3s2



RECOMMENDED COST OF REPAIRS			2,798.92
-----------------------------	--	--	----------

Report Ref No. CC4/ASM18022924/Keb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.