

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

Registration No : SMG2545R
 Chassis No : JHMRC1880JC206288
 Model : ODYSSEY 2.4 EX-S 18YM (EURO 6)
 Owner's Name : WONG HOE CHEONG
 Ins Policy No. :
 Date of Accident : 20/12/2018

Document No. : SQT18005442 Page 1
 Date : 20. Dec 2018
 Customer No. : WZA006
 Svc Advisor : RUEBEN THOMAS
 Engine No : K24W72402506
 Date | Time : 20. Dec 2018 5:10:28 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: WONG HOE CHEONG OWNER INSURER: LIBERTY INSURANCE ACC DATE: 20/12/2018 SURVEYED BY: DATE: REF NO: TP INSURER: AXA INSURANCE TP VEH: SKJ8581D						
04711-T6A-900ZZ	FACE,FR.BUMPER <i>Dis</i>	1	700.00	25	525.00	36.75	561.75
91505-TM8-003	CLIP,BUMPER <i>ne</i>	14	2.30	25	24.15	1.69	25.84
71198-T6A-003	SPACERL.FR.BUMPER SIDE <i>11</i>	1	11.80	25	8.85	0.62	9.47
71193-T6A-003	SPACERR.FR.BUMPER SIDE <i>54</i>	1	11.80	25	8.85	0.62	9.47
71140-T6A-003	BEAMR.FR.BUMPER UPPER	1	34.90	25	26.17	1.83	28.00
71151-T6A-901	BASE,MID GRILLE	1	186.50	25	139.87	9.79	149.66
75700-TA0-A00	EMBLEMFR.	1	26.70	25	20.02	1.40	21.42
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
71122-T6A-J01	MOLDINGFR.GRILLE <i>Sen</i>	1	315.90	25	236.92	16.58	253.50
71152-T6A-901	UPPER MOLDING,MID GRILLE <i>Sen</i>	1	184.30	25	138.22	9.68	147.90
71153-T6A-901	MID MLDG,MID GRIL <i>Sen</i>	1	175.50	25	131.62	9.21	140.83
71154-T6A-901	LOWER MOLDING,R.MID GR <i>Sen</i>	1	48.20	25	36.15	2.53	38.68
71105-T6A-901	GRILLEFR.BUMPER LOWER <i>Sen</i>	1	67.10	25	50.32	3.52	53.84
71112-T6A-901ZA	SPOILER ASSY,R.FR. <i>Sen</i>	1	79.00	25	59.25	4.15	63.40
33100-T6A-Q21	LIGHT ASSY,R.HEAD	1	835.10	25	626.32	43.84	670.16
71104-T6A-901	GARNISH,R.FR.BUMPER <i>Sen</i>	1	46.10	25	34.57	2.42	36.99
33905-T6A-003	BRACKETR.FR.FOGLIGHT	1	63.20	25	47.40	3.32	50.72
33900-TY0-003	LIGHT ASSY, R. FR.FOG	1	267.10	25	200.32	14.02	214.34
76841-T6A-003	TANKWASHER	1	70.90	25	53.17	3.72	56.89
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N) <i>Sen</i>	1	45.00		45.00	3.15	48.15
Sum Item					<u>2415.32</u>	<u>169.06</u>	<u>2,584.38</u>

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SMG2545R
Chassis No : JHMRC1880JC206288
Model : ODYSSEY 2.4 EX-S 18YM (EURO 6)
Owner's Name : WONG HOE CHEONG
Ins Policy No. :
Date of Accident : 20/12/2018

Document No. : SQT18005442 Page 2
Date : 20. Dec 2018
Customer No. : WZA006
Svc Advisor : RUEBEN THOMAS
Engine No : K24W72402506
Date | Time : 20. Dec 2018 5:10:28 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	100.00	80	100.00	7.00	107.00
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	1200.00	560	1200.00	84.00	1284.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1000.00	450	1000.00	70.00	1070.00
Sum Labor					2350.00	164.50	2,514.50

Survey By

Date & Time

Excess

Status

Signature

mercus Lal

21/12/18

Nil

Not Authorized

The ph. before party.
3 dy.

Total Amount 4,765.32 333.56 5,098.88

Total (Inclusive of GST) 5,098.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display the aged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 20/12/2018 5:24:40 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)