## PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

20-Dec-18

## ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1569 D

1 pc	Rear windscreen moulding		\$ 64.10 NEC 2,292.30 DEF
1 pc	Tailgate		\$ 2 202 30 DEF
1 pc	Tailgate lower garnish		\$ 362.61
1 pc	Tailgate trim		\$ 431.12 X NN
1 pc	Tailgate weatherstrip		\$ 276.98
1 pc	Emblem I30		\$ 27.80 / № €
1 pc	Emblem CRDI		\$ 29.40
1 pc	Emblem Hyundai		\$ 29.40/NEC
1 pc	Rear bumper		\$ 811.11×5VC
1 pc	Rear bumper sponge		\$ 79.20 KSVL
1 pc	Rear bumper reinforcement		\$ 815.64 ×30(
1 pc	Rear bumper reinforcement centre		\$ 79.20 XSVL
			\$ 5,298.86
		Less 20%	\$ 1,059.77
			\$ 4,239.09
S/NETT			
1 set	Rear bumper clips		\$ 48.00 KNN
1 set	Reverse sensor		\$ 280.00 XNN
1 set	Tailgate stickers		\$ 100.00 -NEC
1 set	Tailgate lower garnish clips		\$ 38.00 /N EC
1 pc	Rear number plate		\$ 50.00 -X:SV
1 pc	Sealant		\$ 50.00 NEC.

## ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1569 D

Sundry	\$ 50.00·XNN
To dismantle and replace reverse sensor and test system	\$ 80.00 ×NN
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 × れん
To dismantle / refit the rear windscreen onto new tailgate shell	\$ 120.00 : 80
To dismantle and refit the inner components onto new tailgate shell, test wiper motor and water etc	\$ 120.00
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of same, etc.	\$ zoo.oo 180
To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish	\$ 700.00 .360
To apply rustproofing on the repaired and replaced panels	\$ 150.00 : 20
Total	\$ 6,905.09

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

NAZ LKK 21/12/18 1730 hrs Plp

2 DAYS

CHECK ITEMS PHOTOS

BEFORE PAWT PHOTOS.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- · To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- · Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

FINALIZATION SUBJECTED TO INSURANCE APROVAL.