



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

Date : 21/12/2018

TO: LONPAC Insurance Bhd
100 Beach Road
#19-00 Shaw Tower
Singapore 189702

Our Customer : Ng Zhi Qi
Vehicle No : SJQ5647T
Model : Chevrolet Optra 1.6L A/T
Manufacture Year : 2009
Date of Accident : 20/12/2018
Total Estimate Repair Days : 6
Total Pages : 1

Attn : Motor Claims Department
Fax : 6296 2706

Re: Repair Estimate For Third Party Claim against SJR7569S

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear bumper <i>no/de</i>	1	\$783.00	\$783.00	✓
2	Rear bumper side retainer RH <i>nu</i>	1	\$18.00	\$18.00	✓
3	Rear bumper side retainer LH <i>nu</i>	1	\$18.00	\$18.00	✓
4	Rear bumper reinforcement <i>5/20</i>	1	\$370.00	\$370.00	✓
5	Rear end panel <i>1</i>	1	\$290.00	\$290.00	2X
6	Rear end panel garnish <i>11</i>	1	\$95.00	\$95.00	2X
7	Boot lid <i>1</i>	1	repair	repair	X
8	Boot lid lock <i>11</i>	1	\$110.00	\$110.00	X
9	Boot lid "Chevrolet" logo <i>nu</i>	1	\$40.40	\$40.40	✓
10	Boot lid "Chevrolet" emblem <i>nu</i>	1	\$30.00	\$30.00	✓
11	Boot lid "Optra" emblem <i>nu</i>	1	\$30.00	\$30.00	✓
12	Boot lid "1.6 LT" emblem <i>nu</i>	1	\$30.30	\$30.30	✓
13	Spare tyre panel <i>1</i>	1	repair	repair	X
	Total			\$1,814.70	
	Less 10%			\$181.47	<i>1319.7</i>
	Sub-total 1			\$1,633.23	
B.	Spare Parts (S/Nett)				
1	Boot lid "VGIS" emblem <i>nu</i>	1	\$58.00	\$58.00	✓
2	Boot lid "Magnum" emblem <i>nu</i>	1	\$58.00	\$58.00	✓
3	Rear bumper clip <i>nu</i>	10	\$4.00	\$40.00	✓
4	Rear end panel garnish clip <i>11</i>	8	\$4.00	\$32.00	X
5	Reverse sensor (Set) <i>70cm / 5 whd</i>	1 set	\$250.00	\$250.00	<i>200</i>
	Sub-Total 2			\$438.00	
	Total for Parts			\$2,071.23	
C.	Labour				
1	To check wiring.			\$60.00	<i>20</i>
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$800.00	<i>480</i>
3	Spray painting all affected parts & areas.			\$1,000.00	<i>600</i>
4	To spray anti-rust undercoat.			<i>11</i>	X
	Total Labour			\$1,860.00	



Co. Reg. No.: 201416720C
 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
 Tel : 6636 9100 Fax : 6636 9113

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
	Total Repair Cost			\$3,931.23	

Yours faithfully,

 Aun Teng
 f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	<i>Marcus Hal</i>
Contact	<i>90096628</i>
Survey Date	<i>26/12/18</i>
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

not Authorize
2/58 2100
4dy.
Take photo After repair.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-
S.N - 356
10km - 1170