

ASS. REC. BY:

REF

CS/FCI/8022940/ UH301

Special Instruction:

Surveyor:

CWS

Marcus

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time:

5:24pm @ 21/12/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLX 7821H

Insured:

SHC07384

at Workshop m/s

Rico Go Auto

Tel:

of

8 kaki Bukit Ave 4 # 02-24 premier

Policy No.:

Claim No.:

D18008910MFST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/12/2018

CA / REV / REP. / REV 24 HRS

10s

21/12/2018

H.O.D. Endorsement:

Date/Time:

5:26pm @ 21/12/18

Person Contacted:

shemelle

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SLX 7821H-X

SHC07384-CC3/AXA12017176/H1hc3g2

DOA: 31/05/2012

26/12@

10:08am Revised preli advise via email.

REF: FCI

## ASSIGNMENT

From:

Date: 24/12/2018

Estimated Cost:

OD TP/WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

81X 7821H

at Workshop n/s

Rico Go Auto

of

8 kaki Bukit Ave 4 # 02-24 premier

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

1.3 / %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLX7821H

Yt Regn:

4, 18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make:

Infiniti

Q30 C.C.

1461

Colour:

Black

A/C

Insured / Std / NI / NA

Sp. Reading:

5-8799

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SJKDAAH15U 1257880

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

7 mm

R/Bal.

7 mm

L/Bal.

7 mm

L/Bal.

7 mm

D.O.A.

16/12/18

D.O.I.

24/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

31/12/18 Confirmed fine/ly \$5777.40 with Kelvin  
(Red. 26069.25; 81%)

RECEIVED 02 JAN 2019

Date/Time, File Pass to?



Prel. Report

1) 21 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format:

TP

Lump Sum / B.L. (\$

5777.40

Survey Fee:

Transportation:

S + BS, SI

Photos

Others

TOTAL

18x15

1704 290

50

50

67

604

**MOTOR SURVEY ASSIGNMENT**

Date	18-12-2018	Our Ref No. D18008910MFSH
Accident Date	16-12-2018	Claim Type. Third Party
Insured Vehicle	SHC0738U	Third Party Vehicle. SLX7821H
Survey Location	8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT	
Contact Person.	SHANELLE LIM	
Contact No.	62866060/ 91878064	Fax No. 62867060
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	RICO 60 AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Wednesday, 26 December 2018 10:08 AM  
**To:** Admin-D (LKKAuto); 'CWS Motor Claims'; assignments  
**Cc:** 'Eileen Lee'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18008910MFSH/1  
**Attachments:** PRELI ADVISED SLX 7821H.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SKX 7821H**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Friday, 21 December 2018 5:29 PM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Eileen Lee' <[EileenLee@msfirstcapital.com.sg](mailto:EileenLee@msfirstcapital.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D18008910MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 24/12/2018.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Friday, 21 December 2018 5:24 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008910MFSH

Date: 26/12/2018

Our Ref: CS/FCI18022940/Utd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLX 7821H

Please be informed that we had conducted the inspection of the abovementioned vehicle 24/12/2018 at the premises of M/s Rico 60 Auto have the following to report: -

Workshop Estimate Amount	: S\$ <u>8,880.00(LABOUR ONLY)</u>
Revised Estimate Amount	: S\$ <u>1,310.00</u>
"Check" Items Amount	: S\$ <u>0.00</u>
Market Value	: S\$ <u>          </u>
LTA Reimbursement Value	: S\$ <u>          </u>
Nett Value	: S\$ <u>          </u>

Description of Damage:

The vehicle sustained damages at the rear n/s  
portion.



**Comments/ Present Status:**

Damages Consistent.

Yours faithfully

Marcus  
Automotive Assessor



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4527K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	GLASS-FRONT DOOR WINDOW RH (DISC 10%)	SCRATCHED	1,010.00	909.00
1	FRT DOOR VIEW MIRROR (DISC 10%)	BROKEN	1,600.00	1,440.00
1	MOULDING-FRONT DOOR OUTER RH (DISC 10%)	DEFORMED	380.00	342.00
			2,990.00	2,691.00
<b>LABOUR</b>				
	TO REPAIR RH FRONT PORTION.		375.00	250.00
	TO REMOVE & REFIX SIDE WINDOW GLASS.		80.00	40.00
	TO REMOVE AND REFIX WING MIRROR.		100.00	40.00
			555.00	330.00
<b>GRAND TOTAL</b>			<b>3,545.00</b>	<b>3,021.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,021.00</b>

Report Ref No. CS/RSI12001947/R1qn

MRS

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

inchcape

Pre-Owned



6303 x 103

Wide selection of inchcape Certified Pre-owned LEXUS & TOYOTA

Christmas Sale

Free Tyre & Service Credits up to \$3,000

Interest Rate 2.28%

Extended Warranty 1yr



Post an Advertisement


Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A



2.88%p.a Lowest Interest@Gv

Cars Financing \$2000

Downpayment Monthly From \$638

GV Credit Pte Ltd StarAd


• Free VICOM evaluation

• Free grooming and 9 months maintenance

• In-house workshop ensures quality service

• Member of SVTA and hire purchase association

• 100% deposit refund for unapproved loan



YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted


20 results/page

1 vehicles

Infiniti Q30

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Infiniti Q30		Any	Any	2018	Any	Any	Any	Available
	Infiniti	Q30 Diesel 1.5T Premium	\$105,800	\$10,090 /yr	29-Mar-2018	1,461 cc	25,000 km	SUV	Available
<div><div>Fuel Type: Diesel (Euro 5 Engine and Above)</div><div>Leaving Town, Reluctant Sales Car Still Under Wearnes Servicing Care, Still Under Warranty.</div><div>Posted: 12-Dec-2018 Tags: 2018 Infiniti Q30, 2018 infiniti q30, Infiniti Q30, infiniti q30, Infiniti, Q30, q30, Used Infiniti</div></div>									

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

Home

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Article

Forum

Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Infiniti Q30, Infiniti Q30 Singapore, used Infiniti Q30 Singapore, used Infiniti Q30, used vehicles Singapore or even buy used Infiniti Q30 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	5055D
<b>Vehicle Details</b>	
Vehicle No.:	SLX7821H
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Dec 2018
Vehicle Make:	INFINITI
Vehicle Model:	Q30 1.5D DCT EU6
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	K9KG481D003937
Chassis No.:	SJKDAAH15U1057880
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$27,211.00
Original Registration Date:	11 Apr 2018
First Registration Date:	11 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$20,096.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Apr 2028
PARF Rebate Amount:	\$15,072.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	10 Apr 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,000.00
COE Rebate Amount:	\$34,447.00
<b>Total Rebate Amount:</b>	<b>\$49,519.00</b>

The information contained herein is correct as at 19 Dec 2018

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GiA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	17/12/2018 14:32
Date Of Accident	16/12/2018 18:45
Exact Location Of Accident	BRASH BASAH RD > CITY HALL(LAMP POST 37)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLX7821H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	BIS MOTORING PTE. LTD.
Co Reg No	201735055D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90000000
<b>Vehicle Particulars</b>	
Manufacturer	INFINITI
Model	Q30-1.5 D PREM DCT EU6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096898757
Cover Note Number	
<b>Driver</b>	
Name of Driver	YU WENJUN
NRIC No	S8611741Z
Date Of Birth	22/04/1986
Occupation	OUTDOOR
Date Of Driving Pass	09/01/2006
Driving Experience	12 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96379107
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 143 JALAN BUKIT MERAH #05-1136
Postcode	160143
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT MERAH EAST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	<b>ROAD:</b> 391 NEW BRIDGE ROAD POLICE CANTONMENT COMPLEX BLOCK A , <b>POSTCODE:</b> 088762 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-2369999 - <b>FAX NO:</b> 62268438
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

AS PER POLICE REPORT No.T/20181217/2008

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC738U
Vehicle Make/Model/Colour	HYUNDAI 140 1.7L
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	YEO
NRIC/Passport Number	
Contact Number	91088988
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	YU WENJUN
Approximate Age	32
Injuries Sustain	
Injured person in which vehicle?	SLX7821H
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	BLK 143 JALAN BUKIT MERAH #05-1136
Postcode	160143

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

   
 Policyholder's Signature  
 Date & Time:


  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

17 DEC 2010

**IDAC KAKI BUKIT (VAC)**  
 Reporting Centre  
 Name: Singapore 415933  
 NRIC/FIN No: 67416697  
 Fax: 67492305  
 Email: vackb@singnet.com.sg

# Accident Sketch Plan Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

17 DEC 2018  
IDAC KAKI BUKIT(VAC)  
23 KAKI BUKIT AVE 4  
Singapore 415911  
Reporting Centre Personnel's Signature  
Name: Tel: 67416697  
NRIC/FIN No: Fax: 67492305  
Email: vackb@singnet.com.sg

# Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20181217/2008

1 of 3

Report No. T/20181217/2008

Police Station Of Origin:  
Bukit Merah East N.P.C  
A 391 New Bridge Road Police Cantonment  
Complex SINGAPORE 088762  
Tel No: 1800-2369999

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/12/2018 01:33	Vide Report No.:	Station Diary No.: 12
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: YU WENJUN		Address: APT BLK 143 JALAN BUKIT MERAH #05-1136 SINGAPORE 180143	
ID Type / ID No.: NRIC NO / S8611741Z		Contact No.: Home/Office: Mobile: 96379107	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 32	Date of Birth: 22/04/1986	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: GRAB DRIVER		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 16/12/2018 18:50	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 BRAS BASAH ROAD QUEEN STREET Traffic light at cross junction of Bras Basah Rd and Queen St.				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC738U	TAXI	HYUNDAI	I40 1.7L CRDI AT ABS AIRBAG 4DR	Yellow	Slightly Damaged	1
SLX7821H	Car	INFINITI	Q30 1.5D DCT EU6	Black	Slightly Damaged	0

# Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20181217/2008

Police Station Of Origin:  
Bukit Merah East N.P.C  
A 391 New Bridge Road Police Cantonment  
Complex SINGAPORE 088762  
Tel No: 1800-2369999

2 of 3

Report No. T/20181217/2008

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	MR YEO	ID No.	NIL
Related Vehicle	SHC738U (TAXI)	Contact No.	91088988
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	YU WENJUN	ID No.	S8611741Z
Related Vehicle	SLX7821H (Car)	Contact No.	96379107
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL, EMERGENCY MEDICINE	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	16/12/2018	Date Discharge	16/12/2018
No. of Days granted Medical Leave	02	Degree of Injury	Slight

### Brief Details.

On 16/12/18, I was travelling along Bras Basah Rd in my rented vehicle SLX7821H. When I reached the cross junction Bras Basah Rd and Queen St, I stopped at the traffic light. I was on the second lane from the right. When the traffic light turned green, a taxi (SHC738U) behind my vehicle moved outwards to the left lane. My vehicle was stationary and the taxi's front right (right headlight area) collided with the back of my vehicle (area at left tail light).

I felt pain at the back of my neck and shoulder and went to SGH on 16/12/18. I was given 2 days MC from 17/12/18 to 18/12/18.

The taxi driver was Mr Yeo, HP: 91088988. My vehicle was rented from the car rental company GIS Motoring Pte Ltd.

Accident Sketch Plan Pg. 1



SINGAPORE  
POLICE FORCE



T/20181217/2008

3 of 3

Report No. T/20181217/2008

Police Station Of Origin:  
Bukit Merah East N.P.C  
A 391 New Bridge Road Police Cantonment  
Complex SINGAPORE 088762  
Tel No: 1800-2369999

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

A /  
Sgt 2 GAURI D/O DIAYALAN

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:

TP / AEIT /  
Sr Staff Sgt ONG YONG HOCK  
Contact No.: 65476436

Authentication Stamp  
NP168

Signature

Singapore Police Force

Signature Of Informant:

Date/Time:  
17/12/2018 01:33

Classification Of Case:



[illegible]





Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24  
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com  
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:  
MAKE & MODEL:  
MILEAGE:  
TYRE:  
CHASSIS NUM:

SLX 7821 H
INFINITI Q30

ATTN:

NO.	DESCRIPTION - PARTS	QTY	PRICE
1	REAR BOOTLID 11 X	1	
2	REAR BOOTLID CHROME STRIP 11 X	1	
3	REAR BOOTLID LOGO 11 X	1	
4	REAR BOOTLID EMBLEM 'INFINITI' 11 X	1	
5	REAR BOOTLID EMBLEM 'Q30' 11 X	1	
6	REAR BOOTLID LAMP LH 11 X	1	
7	REAR BOOTLID WEATHERSTRIP 11 X	1	
8	TAILLAMP LH One ✓	1	
9	TAILLAMP PANEL LH 2 X	1	
10	REAR BUMPER Dis ✓	1	
11	REAR BUMPER RELECTOR L+R 11/5 cna 1 pc	2	
12	REAR BUMPER RETAINER L+R 11/5 But 1 pc	2	
13	REAR BUMPER BRACKET L+R 11/5 But 1 pc	2	
14	REAR BUMPER REINFORCEMENT BAR 11/5	1	
15	REAR BUMPER SPONGE NF X	1	
16	REAR BUMPER LOWER Dis ✓	1	
17	REAR BUMPER SENSOR BUZZER 11 X	1	
18	REAR BUMPER REVERSE SENSOR L+R 11/5 1 pc	2	
19	REAR BUMPER REVERSE SENSOR HOLDER 11 X	1	
20	REAR BUMPER WIREHARNES 11 X	1	
21	REAR BUMPER CARRIER refiner top One ✓	1	
22	REAR FENDER LH 11 X	1	
23	REAR FENDER COWLING LH De/ton ✓	1	
24	REAR FENDER INNER TRIM LH 11 X	1	
25	REAR FENDER WHEEL ARCH LH 11 X	1	
26	END PANEL 11 X	1	
27	END PANEL TOP GARNISH 11 X	1	
28	FLOOR PANEL 11 X	1	
29	FLOOR PANEL TOP BOARD 11 X	1	
30	REAR DOOR LH 11 X	1	
NOT ACHIEVED 24/12/18			
SUBTOTAL			\$ -
LESS 10%			\$ -
PARTS TOTAL			\$ -
SPECIAL NETT		QTY	PRICE
1	REAR NUMBER PLATE 11 X	1	\$ 100.00
2	REVERSE CAM 11 X	1	\$ 1,000.00

3	REAR END PANEL SEALANT	11 X	1	\$ 120.00
4	SPARE WHEEL PANEL SEALANT	11 X	1	\$ 120.00
5	REAR BUMPER CLIPS	2u 60	10	\$ 100.00
6	REAR FENDER COWLING CLIPS	11 X	10	\$ 100.00
7	REAR FENDER INNER TRIM CLIPS	11 X	10	\$ 100.00
8	BOOTLID INNER TRIM CLIPS	11 X	10	\$ 100.00
			SPECIAL NETT TOTAL	\$ 1,740.00
LABOUR			QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN	500	1	\$ 3,000.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	600	1	\$ 2,000.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	11 X	1	\$ 120.00
4	TO RNR REAR WINDSCREEN	11 X	1	\$ 400.00
5	TO RNR REAR BOOT MECHANISM	11 X	1	\$ 120.00
6	TO RNR REAR LUGGAGE COMPARTMENT	> 80	1	\$ 120.00
7	TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS		1	\$ 400.00
8	TO RNR REVERSE SENSOR & CHECK FUNCTION.	50	1	\$ 120.00
9	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	11 X	1	\$ 250.00
10	TO CHECK WIRING LAYOUT AND BOOTLID LAMP FUNCTION	> 20	1	\$ 120.00
11	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION		1	\$ 120.00
12	TO DO WATER LEAK TEST .	11 X	1	\$ 120.00
13	TO RNR FUEL TANK TO ASSIST WORK LOAD	11 X	1	\$ 250.00
			LABOUR TOTAL	\$ 7,140.00
			GRAND TOTAL COST	\$ 8,880.00

PAGE 2 OF 2

LKK Auto Consultants hence notify the Repairer of the following:

- To remove before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third-party survey is made "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary charges involved is surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18022940/Utd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-01-2019	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 738U	Veh. Inspected	SLX 7821H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008910MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	21/12/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	INFINITI Q30 (A)	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	SJKDAAH15U1057880	Colour	BLACK	
Odometer	58799	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	CONTINENTAL	7 mm	
L/H Front Tyre	215/60 R17	CONTINENTAL	7 mm	
R/H Rear Tyre	215/60 R17	CONTINENTAL	7 mm	
L/H Rear Tyre	215/60 R17	CONTINENTAL	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	16/12/2018	Inspection Date	24/12/2018	
Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 7821H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BOOTLID	NOT NECESSARY	4,118.10	-
1	REAR BOOTLID CHROME STRIP	NOT NECESSARY	187.50	-
1	REAR BOOTLID LOGO	NOT NECESSARY	76.70	-
1	REAR BOOTLID EMBLEM 'INFINITI'	NOT NECESSARY	496.80	-
1	REAR BOOTLID EMBLEM 'Q30'	NOT NECESSARY	66.40	-
1	REAR BOOTLID LAMP LH	NOT NECESSARY	599.30	-
1	REAR BOOTLID WEATHERSTRIP	NOT NECESSARY	239.90	-
1	TAILLAMP LH	CRACKED	752.10	752.10
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	168.20	-
1	REAR BUMPER	DISTORTED	1,440.20	1,440.20
2	REAR BUMPER REFLECTOR L+R	N/S CRACKED	66.60	33.30
2	REAR BUMPER RETAINER L+R	N/S BENT	133.20	66.60
2	REAR BUMPER BRACKET L+R	N/S BENT	193.40	96.70
1	REAR BUMPER REINFORCEMENT BAR	BENT	1,021.30	825.00
1	REAR BUMPER SPONGE	NOT FITTED	273.00	-
1	REAR BUMPER LOWER	DISTORTED	907.20	650.00
1	REAR BUMPER SENSOR BUZZER	NOT NECESSARY	119.20	-
2	SET REAR BUMPER REVERSE SENSOR	SHORTED-1PC ONLY	571.00	285.50
1	REAR BUMPER REVERSE SENSOR HOLDER	NOT NECESSARY	55.20	-
1	REAR BUMPER WIREHARNES	NOT NECESSARY	450.00	-
1	REAR BUMPER RETAINER TOP	CRACKED	285.00	285.00
1	REAR FENDER LH	TO REPAIR SEE LABOUR	2,002.60	-
1	REAR FENDER COWLING LH	DEFORMED / TORN	353.10	266.50
1	REAR FENDER INNER TRIM LH	NOT NECESSARY	825.00	-
1	REAR FENDER WHEEL ARCH LH	TORN	745.20	485.10
1	END PANEL	TO REPAIR SEE LABOUR	964.70	-
1	END PANEL TOP GARNISH	NOT NECESSARY	85.00	-
1	FLOOR PANEL	NOT NECESSARY	1,744.20	-

Report Ref No. CS/FCI18022940/Utd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FLOOR PANEL TOP BOARD	NOT NECESSARY	825.80	-
1	REAR DOOR LH	NOT NECESSARY	2,053.30	-
	LESS 10% DISCOUNT		-2,181.92	-518.60
			19,637.28	4,667.40
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	100.00	-
1	REVERSE CAM (SN)	NOT NECESSARY	1,000.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
1	SPARE WHEEL PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
10	REAR BUMPER CLIPS (SN)	NECESSARY	100.00	60.00
10	REAR FENDER COWLING CLIPS (SN)	NOT NECESSARY	100.00	-
10	REAR FENDER INNER TRIM CLIPS (SN)	NOT NECESSARY	100.00	-
10	BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	100.00	-
			1,740.00	60.00
	<b><u>LABOUR</u></b>			
	TO RNR ACCIDENT DAMAGE PARTS, CUT / WELD, KNOCK & REALIGN. INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL LH, REAR FENDER LH AND END PANEL.		3,000.00	500.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.		2,000.00	400.00
	TO RUST PROOF ACCIDENT AFFECTED AREA.	NOT NECESSARY	120.00	-
	TO RNR REAR WINDSCREEN.	NOT NECESSARY	400.00	-
	TO RNR REAR BOOT MECHANISM.	NOT NECESSARY	120.00	-
	TO RNR REAR LUGGAGE COMPARTMENT. }		120.00	80.00
	TO RNR UPHOSTERY, GARNISH AND ATTACHMENT PARTS. }		400.00	-
	TO RNR REVERSE SENSOR & CHECK FUNCTION.		120.00	50.00
	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS.	NOT NECESSARY	250.00	-
	TO CHECK WIRING LAYOUT AND BOOTLID LAMP FUNCTION. }		120.00	20.00
	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION. }		120.00	-
	TO DO WATER LEAK TEST.	NOT NECESSARY	120.00	-
	TO RNR FUEL TANK TO ASSIST WORK LOAD.	NOT NECESSARY	250.00	-
			7,140.00	1,050.00

Report Ref No. CS/FCI18022940/Utd3e2



GRAND TOTAL		28,517.28	5,777.40
RECOMMENDED COST OF REPAIRS			5,777.40

Report Ref No. CS/FCI18022940/Utd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.