

TRANS-CAB AUTO SERVCIES PTE LTD

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 9925S - AXA

DOWE - KALWIN

ROEL

parts by parts

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9925S - ROEL

VF1ABL15AUC273375

RENAULT

LATITUDE

20.03.2014

AXA

		PART	LIST	
1	1	BUMPER COVER REAR L70Y ✓ <i>scratched</i>	\$	617.87
2	1	BUMPER LOWER REAR L70D X <i>an</i>	\$	428.56
3	1	BUMEPR BRACKET SIDE RH REAR L70Y ✓ <i>crq</i>	\$	75.79
4	1	BUMEPR RETAINER RH REAR L70Y ✓ <i>crq</i>	\$	25.80
5	1	BUMPER REFLECTOR RH L70Y X <i>sur</i>	\$	24.31
6	1	BUMPER BEAM REAR L70Y X <i>an</i>	\$	433.40
7	1	BUMPER BEAM BRACKET RH REAR L70Y X <i>an</i>	\$	125.95
8	1	BUMEPR BLOCK RH REAR L70Y X <i>an</i>	\$	83.71
9	1	OUTER PANEL REAR L70Y (End Panel) X <i>an</i>	\$	820.38
10	1	OUTER PANEL REAR L70Y (End Panel)TRIM X <i>an</i>	\$	225.50
11	1	SPARE WHEEL PANEL (Luggage Floor Panel) X <i>an</i>	\$	1,220.67
12	1	SPARE WHEEL PANEL INNER TRIM X <i>an</i>	\$	528.55
13	1	WHEEL SIDE PANEL BRACKET RH (Luggage Floor) X <i>an</i>	\$	67.65
14	1	FENDER PANEL REAR RH L70Y ✓ <i>dent</i>	\$	1,838.98
15	1	TAILLAMP RH L70Y ✓ <i>Broken</i>	\$	308.00
16	1	TAILLAMP PANEL RH L70Y X <i>sur</i>	\$	506.00
17	1	WHEELARCH REAR RH L70Y ✓ <i>dent</i>	\$	302.94
18	1	FENDER INNER TRIM BOARD RH X <i>sur</i>	\$	554.29
19	1	DOOR PANEL REAR RH L70Y ✓ <i>dent</i>		1,585.65

TOTAL	\$	9,774.00
10%	\$	977.40
	\$	8,796.60

Specical Nett

1	1SET	WHEELARCH CLIP(Necessary) ✓ <i>all</i>	\$	32.34
2	1SET	FENDER INNER TRIM BOARD RH CLIP(Necessary) X <i>an</i>	\$	44.00
3	1	Rear Door Sticker "6555-3333" ✓ <i>all</i>	\$	80.00
4	1SET	BUMPER RR RIVET(Necessary) ✓ <i>all</i>	\$	28.60
5	1SET	BUMPER RR CLIP(Necessary) ✓ <i>all</i>	\$	66.00
6	2	Rear windscreen sealant ✓ <i>all</i>	\$	80.00

TRANS-CAB AUTO SERVICIES PTE LTD

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 9925S - AXA

ROEL

parts by parts

7	1	Windscreen moulding ✓ <i>net</i>	\$	100.00
8	1	Rear Windscreen Inner Sponge Seal ✓ <i>net</i>	\$	100.00
9	1	CAP HUB RH REAR ✓ <i>scrubbed</i>	\$	35.60
10	1	RIM (ROUE 7J 16H 2547) RH RR X <i>an</i>	\$	385.00
11	1	TYRE RH RR X <i>an</i>	\$	330.00
12	1SET	PARKING SENSER X <i>an</i>	\$	600.00

TOTAL	\$	1,881.54
--------------	-----------	-----------------

TOTAL PARTS	\$	10,678.14
--------------------	-----------	------------------

To Check Electrical Lighting Concerned.	\$	170.00 30
---	----	-------------------------

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	1000 2,800.00
---	----	-----------------------------

Putty and spray painting of the affected portion.	\$	880 3,000.00
---	----	----------------------------

To transfer of rear fender fittings, attachment and perform water seepage test.	\$	100 170.00
---	----	--------------------------

To dismantle and refit rear seat, backrest, trimings, garnish, roof-lining, speaker shelfboard, carpeting and other to enable body work repair.	\$	200 380.00
---	----	--------------------------

To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 120
--	----	--------------------------

To reinstall rear bumper parking sensor.	\$	170.00 100
--	----	--------------------------

To check steering geometry and computer wheel alignment	\$	220.00 X
---	----	----------

To transfer of tire, rim and on wheel balancing.	\$	170.00 80
--	----	-------------------------

TRANS-CAB AUTO SERVCIES PTE LTD

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 9925S - AXA

ROEL

parts by parts

To rust-proofing of the affected areas.

\$

⁸⁰
~~170.00~~**TOTAL**

\$

7,420.00**Over All Total**

\$

18,098.14**(PARTS BY PARTS) Repair Days****10 Days***7 days.*