

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB7685Y - AIG**LI DAN**

Not Authorized
1.B.1
\$ 2179.75

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7685Y - LI DAN

LK1LA69RJBB075370*

CHEVROLET

EPICA 2.0

07.05.2013

AIG**PART****LIST**

1	1	Rear Fender LH	\$	<i>R</i>	
2	1	Rear Door LH (Panel A-RR DR LH)	\$	<i>B</i>	1,145.00 X
3	1	Front Side Rocker Panel Garnish LH	\$		1,133.00 ✓
				<i>R</i>	236.40 X
			\$		2,514.40
TOTAL			\$		628.60
25%			\$		1,885.80

Special Nett

1	Rear Door Sticker '6555-3333'	\$	<i>Net</i>	60.00 ✓
1 Set	Front Side Rocker Panel Garnish Clip	\$	<i>nn</i>	18.00 X
1	Rear Windscreen Sealant	\$	<i>nn</i>	100.00 X
1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i>	80.00 X
1	Rear Tyre Rim Hub Cap LH	\$	<i>SK</i>	62.46 X
TOTAL		\$		320.46

TOTAL PARTS \$ 2,206.26

Panel Beating, Knocking And Straightening
 The Necessary Portion, Remove And
 Renewal Of Parts, Adjust And Realign The
 Same

\$ 1,250.00 *500*

To Rust-Proofing Of The Affected Areas.

\$ 200.00 *300*

Putty And Spray Painting Of The Affected
 Portion.

\$ 900.00 *600*

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB7685Y - AIG**LI DAN**

*To Remove And Refit Interior Fittings,
Trimings, Garnish, Fittings And Other, To
Enable Repair.*

\$ 250.00 *800*

*To Transfer Of Door Fittings, Attachments
And Perform Water Seepage Test.*

\$ 150.00 *600*

*To Transfer Of Fender Fittings,
Attachments And Perform Water Seepage
Test.*

\$ *nn* 150.00 *X*

*To Remove And Refit Rear W/ Screen
Glass To Facilitate Bodywork Repair.*

\$ *nn* 150.00 *X*

To Reseal Sealant On Gap

\$ *nn* 100.00 *X*

TOTAL \$ 3,150.00

Over All Total \$ 5,356.26

Total Repair Days 05 DAYS

(Part By Part)