

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 24 Dec 2018

Preliminary Advice

Vehicle No	: SKU4777A	Accident Date	: 20/12/2018
Make	: NISSAN X-TRAIL	Policy No.	: D18MTPV01012043
Assignment Date	: 24/12/2018	Excess	: S\$0.00
Date of Inspection	: 24/12/2018	Est. Duration of Repair	: 10 days
Inspection At	: Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4 Singapore 408623		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion, o/s body , undercarriage affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,514.50
Revised Amount	:S\$	9,326.64
Check Items (Estimated)	:S\$	5,190.24
Total	:S\$	14,516.88

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	75,000.00
COE / PARF Rebate	:S\$	60,222.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,778.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :