



**TOWER** **TRANSIT**  
**ENGINEERING**

BUS REGISTRATION NUMBER	SBS3364G
BUS TYPE (SD/DD)	DD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

	Part No.	Part or Item Description	Quantity	Total Cost
	77040871	TOWER TRANSIT CUT OUT LOGO STICKERS	1	\$19.50
		GREEN WHEEL NUT POINTERS	2	\$6.00
			7% GST	\$1.37
			FINAL TOTAL COST	\$20.87

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)		TOTAL COST
TO REPLACE/REPAIR THE DAMAGED PARTS (INCLUDING SPRAY PAINTING)	800	1000 <del>\$800.00</del>
		7% GST
		FINAL TOTAL COST

# ESTIMATED ACCIDENT REPAIR COST



## SECTION 5: REPAIRS TO BUS ADVERTISEMENT VINYL/PANELS (ADVERTISEMENT COST)

TOTAL ADVERTISEMENT REPAIR COST	-
---------------------------------	---

## SECTION 6: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

## SECTION 7: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

		Date In For Repairs	28/12/2018
		Date Out From Repairs	30/12/2018
		Number of Days Under Repair	2
BUS TYPE (SD / DD)	DD	LOSS OF USE COST	
		\$800.00	

SUMMARY	
SECTION NO.	COST
1	\$20.87
2	\$856.00
3	-
4	-
5	\$800.00
ESTIMATED ACCIDENT REPAIR COST (1+2+3+4+5)	\$1,676.87

Tanpin 97495749  
 WP  
 27/12/18 4pm  
 Resurvey after repair  
 02 days  
 Sur@lkkauto.com

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: