



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 24.12.2018

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01/02
AXA Tower
Singapore 068811

Attn: Motor Claims Dept

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanjin 97445744
wp
24/12/18 @ 420pm
Resurvey after repair
840 @ 1/11/18 auto claim
Soleys

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2520L HONDA GRACE

To Supply

1) 1pc	rear bumper	\$	937.40	de
2) 1pc	rear bumper clip	\$	35.00	ne
3) 1set	rear bumper right side retainer	\$	13.90	ne
4) 1pc	rear bumper lower spoiler	\$	650.90	mb
5) 1pc	rear bumper right reflector garnish	\$	48.00	mb
6) 1pc	rear boot lid	\$	675.20	bt
7) 1pc	rear boot lid weatherstrip	\$	91.60	fw
8) 1pc	rear boot lid "GRACE" emblem	\$	45.00	ne
9) 1pc	rear boot lid "Hybrid" emblem	\$	78.00	ne
10) 1pc	rear end panel	\$	395.00	bt
11) 1pc	floor panel	\$	855.60	KS
12) 1pc	rear Luggage compartment cover	\$	254.70	X
13) 1pc	package tray trim, panel assy	\$	168.50	?
14) 1pc	right rear fender	\$	1,104.90	mb
15) 1pc	right rear fender cowl	\$	70.10	mb
16) 1set	right rear fender cowl clip	\$	25.00	ne
17) 1pc	right rear fender tail lamp with housing	\$	381.70	bt
18) 1pc	rear boot lid right lamp	\$	306.70	mb
19) 1pc	rear end panel	\$	395.70	bt
20) 1pc	rear end panel top garnish with clip	\$	86.40	?
21) 1set	rear glass moulding (4 pcs)	\$	150.00	ne

Sub total part

Less: 20% discount

\$ 6,769.30
\$ (1,353.86)
\$ 5,415.44

To supply S.Nett Parts

1)	1pc	"Prime Taxi" sticker		\$	55.00	re
2)	2pcs	"Dial -A-Cab" sticker	@\$45.00	\$	90.00	re
3)	1tube	glass sealant		\$	35.00	re
4)	1set	reverse sensor		\$	200.00	al

Sub total S.Nett Parts \$ 380.00

L/charges

1)	Towing charges with king trolley	\$	80.00	✓
2)	To tuff kote rear portion	\$	150.00	40
3)	To remove rear boot lid trim board, mechanism parts	\$	60.00	50
4)	To remove & replace reverse sensor check wiring	\$	50.00	30
5)	To remove & refit rear glass	\$	120.00	✓
6)	To remove rear bumper, cut / welding rear end panel, floor panel, right fender knock & repair right wheel house panel, replace rear bumper, boot lid, right tail lamp & boot lid lamp & etc.	\$	1,000.00	800
7)	To putty, respray painting rear boot lid inner & outer, rear bumper, right rear fender, end panel, floor panel & etc. To polish	\$	1,100.00	900

Sub total L/charges \$ 2,560.00
Estimate Total \$ 8,355.44



ISLAND RECOVERY SERVICES

Blk 3026, Ubi Road 1 #04-146 Singapore 408719

Telephone: 6747 7400

Email: islandrecovery@ymail.com

Facsimile: 6844 7233

Web: www.islandrecovery.com.sg

GST Reg.No: M90370499P

Co. Reg. 53120055L

Cash Sales/ Work Order

NO. 1201390

Date: 22/12/18

M/S: Prime Car Rental and Taxi Services PTE LTD

Vehicle No: S410 2520 Model : Honda Grace

From: 154 Yung Ho Rd Time Start: 2:10am

To: 6 Bengi Place Time End: 2:40am

Remarks: _____

☐ Change Tyres / Jump Start

☐ Accident

☐ Use Car Carrier

☐ Basement / Multi Carpark

☐ Crane Up / Winch Out

☐ Open Door

☒ Using King Dolly

☐ Dismantle Shaft / Brake

☐ Loaded

AMOUNT S\$ 8012

GST S\$ 56012

TOTAL S\$ 856012

bizSAFE₃

Important Note:

Y/L 99886

Island Recovery Services

Received By

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.