

ASS. REC. BY:

REP:

CS/FCI18023049/Dgd3

n2

Special Instruction:

Surveyor:

Bryen

CWS

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time:

8:34am @ 26/12/18

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLV 6346E

Insured:

SHA 7398G

at Workshop m/s

Kurz Work Solutions

Tel:

6844 5938

of

53 ubi Ave 1 # 02-24

Policy No:

Claim No:

D18009007MPSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/12/18

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time:

8:37am @ 26/12/18

Person Contacted:

Juwen

Vehicle:

☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLV 6346E-X
	SHA 7398G-CC3/FCI15017254/K9bd1
31/12/18 @	11.05am revised to Eileen Lee by email.

D.O.A: 30/06/15

REF:

ASSIGNMENT


COB April 2028

2019 April 1998

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLV 6346 E Yr Regn: _____
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda Civic SIR C.C. 1595
 Colour: Yellow A/C Insured / Std / NI / NA
 Sp. Reading: 371868 T/Radio: Insured / Std / NI / NA
 Eng/No: B16A41200092
 C/No: SHMEK4550WB001344
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / 5/Rim / STD A/Rim or
 Tyre Size: F: 215/45 R16
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Goodyear

Front Rear
 R/Bal: 5 mm R/Bal: 5 mm
 L/Bal: 5 mm L/Bal: 5 mm
 D.O.A: 17/12/2018 D.O.I: 26/12/2018
 Survey held at Kerz Works Pap Ubi
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 H/S Frnt
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
 First Capital SHA 7398G

* MV 60K (est)
 VIA 36023
 HL 23977

RECEIVED 12 NOV 2019

11/11/2019 Jmm 215 43001- with 4 days of work
 (Red \$5994.64, 58%)

Date/Time: File Pass to? ☐ : Preli. Report11/12/11 thmsh ☐ : Final Report

Date/Time: File Return to?

2)

Report Format:

Lump Sum / I.R. / (\$)

7P

4300

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation

) S + RS - GI

) Photos

) Others

TOTAL

170
50
50
56

326



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18009007MFSH
Our Ref: CS/FC118023049/Dqd3

Date: 31 December 2018

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLV 6346E .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 26/12/2018 at the premises of M/s KARZ WORK SOLUTIONS, and have the following to report:-

Workshop Estimate Amount	: S\$ 10,294.64 .
Revised Estimate Amount	: S\$ 5,393.84 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the n/s front portion.



Yours faithfully

Bryan Ang Tani
Motor Surveyor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	24-12-2018	Our Ref No. D18009007MFSH
Accident Date	17-12-2018	Claim Type. Third Party
Insured Vehicle	SHA7398G	Third Party Vehicle. SLV6346E
Survey Location	53 UBI AVENUE 1 #02-24 PAYA UBI INDUSTRIAL PARK	
Contact Person.	DARREN NG	
Contact No.	68445938/ 0	Fax No. 68442474
Survey Type	WITHOUT PREJUDICE: NO EST. COR (WE ADMIT LIABILITY QUANTUM TO BE AGREED)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KARZ WORK SOLUTIONS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.



PRI Header Details

Claim No	D18009007MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & KARZ WO
Workshop Name	KARZ WORK SOLUTIONS (Contact Person : DARREN NG)	Survey Location & Contact Details	53 UBI AVENUE 1 #02-24 PAYA UBI INDUSTRIAL PARK Mobile: 0 , Phone: 68445938 , Fax: 68442474 EmailId: KARZWORKS.SG@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO EST. COR (WE ADMIT LIABILITY AGREED)		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA7398G	TP Vehicle No	SLV6346E
PRI Recieved Date	24-12-2018 04:59:56 PM	Surveyor Appointed Date	26-12-2018 08:33:13 AM	Surveyor Accept Date	26-12-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	26-12-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Date	Job Remarks	Action
------	-------------	--------

FINAL SUMMARY

Surveyor Final Adjusted Amount	Surveyor Fees	Remarks	

Submit Assessment

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 31 December 2018 11:05 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D18009007MFSH/1
Attachments: CSFCI18023049Dqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SLV 6346E.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 26 December 2018 9:10 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18009007MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.


BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 26 December 2018 8:34 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18009007MFSH/1

Dear Sir/Mdm,

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6442F
Vehicle Details	
Vehicle No.:	SLV6346E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	28 Dec 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC SIR 4M
Primary Colour:	Black
Manufacturing Year:	1997
Engine No.:	B16A41200092
Chassis No.:	JHMEK4550WS001344
Maximum Power Output:	-
Open Market Value:	\$21,185.00
Original Registration Date:	23 Apr 1998
First Registration Date:	23 Apr 1998
Transfer Count:	6
Actual ARF Paid:	\$29,659.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Apr 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$38,655.00
COE Rebate Amount:	\$36,023.00
Total Rebate Amount:	\$36,023.00
Message	
Transfer of ownership or deregistration is not allowed for this vehicle.	

The information contained herein is correct as at 28 Dec 2018

OK

KARZ WORKS PTE LTD
53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934
(TEL) 6 8 4 4 5 9 3 4 (FAX) 6 8 4 4 2 4 7 4 - (E-MAIL) KARZWORKSSG@GMAIL.COM

3RD PARTY CLAIM ESTIMATION

M/s First Capital Insurance Limited
30 Robinson Road
#10-01/02 Robinson Towers
Singapore 048546

Vehicle number	SLV6346E
Make / Model	HONDA CIVIC
Chassis number	JHMEK4550WS001344
Accident date	17-12-18
Reference	KM1812-31

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER UPPER <i>distorted</i>	856.90 ✓
1	FRONT BUMPER LOWER <i>distorted</i>	798.50 ✓
1	FRONT LH SIDE RETAINER <i>SLC</i>	102.00 ✗
1	FRONT BUMPER LH PROTECTOR <i>cut</i>	223.30 ✓
1	FRONT LH HEADLAMP <i>scratched / cut</i>	569.00 ✓
1	FRONT LH HEADLAMP BRACKET <i>HL</i>	104.50 ✗
1	FRONT REINFORCEMENT <i>HL</i>	334.50 ✗
1	FRONT LH FENDER <i>Dented</i>	665.50 ✓
1	FRONT LH FENDER INNER SHIELD <i>distorted</i>	131.00 ✓
1	FRONT GRILLE <i>HL</i>	220.00 ✗
1	BONNET <i>HL</i>	880.00 ✗
1	BONNET HINGE <i>HL</i>	110.00 ✗
1	FRONT LH KNUCKLE ARM <i>distorted</i>	430.10 ✓
1	FRONT LH KNUCKLE ARM BEARING <i>Done</i>	220.40 ✓
1	FRONT LH LOWER ARM <i>distorted</i>	310.10 ✓
		5955.80
		4204.80
		3363.84
		Less 20%
		1191.16
		Subtotal
		4764.64
		Balance C/F
		4764.64
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
		Balance B/F
1 SET	SHOCK ABSORBER (AFTER MARKET) <i>distorted</i>	500/- 1500.00
1 SET	FRONT BUMPER CLIP <i>HL</i>	60.00 30/-
1 SET	FENDER INNER SHIELD CLIP <i>HL</i>	60.00 20/-
1	TYRE <i>HL</i>	600.00 ✗
1	RIM <i>rep</i>	800.00 ✗
1	BRAKE FULID <i>HL</i>	150.00 ✗
		550.00
		Subtotal
		3170.00
		Balance C/F
		7934.64
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
		Balance B/F
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 30/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2	CHECK FRONT WHEEL ALIGNMENT	150.00 60/-
3	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	200.00 150/-
4	PANEL BEATING ON AFFECTED AREAS	1000.00 600/-
5	SPRAY PAINTING ON AFFECTED AREAS	800.00 600/-
6	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
Subtotal		2360.00
Grand total		10294.64

1480.00

26/12/2018 @ 1045hrs

NA Andrew

L/Sun

4 days.

Ryan

LKK Auto

5393.84

L/S 4300/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18023049/Dqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 13-11-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7398G	Veh. Inspected	SLV 6346E	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18009007MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	26/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC SIR	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	1998	
Chassis No.	JHMEK4550WS001344	Colour	YELLOW	
Odometer	371868	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R16	GOODYEAR	5 mm	
L/H Front Tyre	215/45 R16	GOODYEAR	5 mm	
R/H Rear Tyre	215/45 R16	GOODYEAR	5 mm	
L/H Rear Tyre	215/45 R16	GOODYEAR	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/12/2018	Inspection Date	26/12/2018	
Survey held at	KARZ WORK SOLUTIONS 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 6346E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER UPPER	DISTORTED	856.90	856.90
1	FRONT BUMPER LOWER	DISTORTED	798.50	798.50
1	FRONT LH SIDE RETAINER	SERVICEABLE	102.00	-
1	FRONT BUMPER LH PROTECTOR	CUT	223.30	223.30
1	FRONT LH HEADLAMP	SCRATCHED / CUT	569.00	569.00
1	FRONT LH HEADLAMP BRACKET	NOT NECESSARY	104.50	-
1	FRONT REINFORCEMENT	NOT NECESSARY	334.50	-
1	FRONT LH FENDER	DENTED	665.50	665.50
1	FRONT LH FENDER INNER SHIELD	DEFORMED	131.00	131.00
1	FRONT GRILLE	NOT NECESSARY	220.00	-
1	BONNET	NOT NECESSARY	880.00	-
1	BONNET HINGE	NOT NECESSARY	110.00	-
1	FRONT LH KNUCKLE ARM	DISTORTED	430.10	430.10
1	FRONT LH KNUCKLE ARM BEARING	DAMAGED	220.40	220.40
1	FRONT LH LOWER ARM	DISTORTED	310.10	310.10
	LESS 20% DISCOUNT		-1,191.16	-840.96
			4,764.64	3,363.84
<u>SPECIAL NETT ITEMS</u>				
1	SET SHOCK ABSORBER (AFTER MARKET)(SN)	DISTORTED	1,500.00	500.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	60.00	30.00
1	SET FENDER INNER SHIELD CLIP (SN)	NECESSARY	60.00	20.00
1	TYRE (SN)	NOT NECESSARY	600.00	-
1	RIM (SN)	TO REPAIR SEE LABOUR	800.00	-
1	BRAKE FULID (SN)	NOT NECESSARY	150.00	-
			3,170.00	550.00
<u>LABOUR</u>				
	CHECK FRONT WIRING AND LIGHTING SYSTEM.		60.00	30.00
	CHECK FRONT WHEEL ALIGNMENT.		150.00	60.00
	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS.		200.00	150.00

Report Ref No. CS/FCI18023049/Dqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF RIM.		1,000.00	600.00
	SPRAY PAINTING ON AFFECTED AREAS.		800.00	600.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	40.00
			2,360.00	1,480.00
GRAND TOTAL			10,294.64	5,393.84
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,300.00

Report Ref No. CS/FCI18023049/Dqd3n2

MARKET VALUE: \$60,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$36,023.00=NETT VALUE: \$23,977.00

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.