

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1453/2018/PH
Date : 26-Dec-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle : SLE 4351 S

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Briens Pierre Robert
Address : 11 Arnasalam Chetty Road
: #12-04
: (S) 239949
Telephone : HP +65 90176202
Type of Claim : Third Party Claims
Policy No. : 1800114550
Vehicle No : **SME 3326 K**
Model Code : Audi A4 Sedan 2.0 TFSI (A)
Model / Year : Sep-18
Engine No : CVK 054234
Chassis No : WAUZZZF45JA104584
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Dec-18
Place of Accident : Chinatown Point

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 3326 K.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rhs front and rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 560.00	280
2	To dismantle and renew rhs front door and rhs rear door. Re-organise crash management components. Reinstall all parts removed.	\$ 1,800.00	750
3	To respray rhs front door, rhs rear door and door handle.	\$ 1,800.00	1200
4	To carry out diagnostic check.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 4,352.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 3326 K.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR - RH <i>Revised</i>	\$ 2,048.00	✓
2	FRONT DOOR OUTER DOOR SEAL - RH <i>me</i>	\$ 176.00	✓
3	BONDING AGENT <i>?</i>	\$ 43.00	?
4	CLEANING SOLUTION <i>?</i>	\$ 64.00	?
5	ATTACHMENT PARTS FOR FRONT DOOR - RH <i>me</i>	\$ 462.00	?
6	FRONT DOOR CATCH - RH <i>me</i>	\$ 92.00	✓
7	FRONT DOOR COVER - RH <i>me</i>	\$ 13.00	✓
8	FRONT DOOR TRIM PLATE FOR DOOR HANDLE-RH	\$ 22.00	?
9	FRONT DOOR LOCK CYLINDER WITH HOUSING <i>let</i>	\$ 471.00	✓
10	FRONT DOOR MOUNTING BAR - RH <i>me</i>	\$ 143.00	✓
11	REAR DOOR - RH <i>Revised</i>	\$ 1,928.00	✓
12	REAR OUTER DOOR SEAL - RH <i>me</i>	\$ 176.00	✓
13	BONDING AGENT <i>?</i>	\$ 43.00	?
14	CLEANING SOLUTION <i>Not me ?</i>	\$ 64.00	?
15	SEALING STRIP	\$ 14.00	?
16	ATTACHMENT PARTS FOR DOOR <i>me</i>	\$ 488.00	✓
17	REAR DOOR CATCH - RH <i>me</i>	\$ 105.00	?
18	DOOR CATCH COVER	\$ 12.00	?
19	DOOR WINDOW SLOT SEAL WITH TRIM STRIP <i>me</i>	\$ 265.00	✓
20	WINDOW SLOT SEAL WITH TRIM STRIP <i>me</i>	\$ 217.00	✓

SUB TOTAL SPARE PARTS CHARGES : \$ 6,846.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 3326 K.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	DATA PLATE FOR TYRE PRESSURE <i>W</i>	\$ 33.00	✓
22	SUNDRIES ?	\$ 500.00	?
TOTAL SPARE PARTS CHARGES		:	\$ 533.00
TOTAL LABOUR CHARGES		:	\$ 4,352.00
GRAND TOTAL		:	\$ 4,885.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian L
Surveyed Date : 27/12/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant