

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1444/2018/GW
Date	:	22-Dec-18

Vehicle not IN workshop. Kindly arrange for survey.

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name	:	Ms. Oh Hwee Keng
Address	:	3 Flora Drive #08-14 Singapore 507010
Telephone	:	HP +65 97303076
Type of Claim	:	Third Party Claims
Policy No.	:	2100396798-04
Vehicle No	:	SCV 1228 C
Model Code	:	Audi A3 Sedan 1.4 TFSI
Model / Year	:	Dec-14
Engine No	:	CZC 205429
Chassis No	:	WAUZZZ8V2F1031204
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	21-Dec-18
Place of Accident	:	Along Tampines Central 1 & Tampines Ave 4

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCV 1228 C

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓
2	To dismantle and renew rear bumper assy. Re-organise rear crash management components. Reinstall all parts removed.	\$ 900.00 600
3	To respray rear bumper.	\$ 800.00 600
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
SUB-TOTAL LABOUR CHARGES		: \$ 2,172.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SCV 1228 C

		<u>Damaged Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>		<u>S/Nett</u>
1	REAR BUMPER / <i>de</i>	\$	1,619.00
	REAR BUMPER SPOILER / <i>scr</i>	\$	206.00
2	REAR BUMPER FIXING PARTS / <i>mc</i>	\$	166.00
3	REAR BUMPER UPPER GUIDE SECTION-LH/RH ?	2 \$	28.00
4	REAR BUMPER LOCKING MECHANISM <i>Q?</i>	2 \$	50.00
5	REAR LIGHT RELECTOR-LH/RH <i>X NN</i>	2 \$	52.00
6	REAR SENSOR ?	2 \$	421.00
7	REAR SENSOR SEAL RING / <i>mc</i>	4 \$	14.00
8	REAR BUMPER SIDE REINFORCEMENT ?	\$	501.00
9	REAR BUMPER BRACKET-LH/RH ?	2 \$	22.00
10	SUNDRIES ?	\$	300.00
TOTAL SPARE PARTS CHARGES		:	\$ 3,379.00
TOTAL LABOUR CHARGES			\$ 2,172.00
GRAND TOTAL			<u>\$ 5,551.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Lim Qian.*
Surveyed Date :
Authorised Date : *26/12/18.*
Excess Cost :
Liability : *before paint photos.*
Remarks :
3 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant