

ASS. REC. BY:

REF:

CS/FWD18023056/Ktd3ST

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person):

Menmen
Josey loh

of

FWDDate/Time: 26/12/18 @ 10:32am

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 15814

Insured:

at Workshop m/s

Ah Lim Motor

Tel:

64831244

of

10 AMK Ind. Park 2A # 01-09

Policy No:

PNDV2017-00004190-01

Claim No:

Sum Insured:

Excess:

18A

Make of Veh:

(Client's Record)

D.O.A. 20/12/2018CA / ☒ REV / REP. / REV 24 HRS2pm
H.O.D. Endorsement:

Date/Time:

10:37am @ 26/12/18

Person Contacted:

EileenVehicle IN ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLD 15814-X</u>
	<u>need to upload photograph.</u>
<u>26/12-</u>	<u>Revert via menmen.</u>
<u>27/12/18 @</u>	<u>10.43am Clara Li informed C/A via menmen.</u>
<u>27/12/18 @</u>	<u>4pm Informed Eileen C/A to exp \$1500 by email.</u>

ASS. REC. BY:

REF:

FWD / CS / FWD / 18023056 / Ktd3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Soon:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

27/12 File sent to Carhine

2405.00 confirmed.
(Red: 4351, 66%)

RECEIVED 09 MAY 2019

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

11/3/15 Typist

Date/Time, File Return to?



: Prell. Report



: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

200
50
10

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Dec 2018 09:39 Sendback Est	26 Dec 2018 09:41 \$7,256.00	26 Dec 2018 10:32 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	ANG POH YEW, ID: S1707555A, Tel: +6594240456, Email: ANGPOHYEW@YAHOO.COM			
Vehicle Reg. No.:	SLD1581U	Date of Loss:	20/12/2018 13:00 - :59 [30 Months and 16 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD	Policy/Cover Note No.:	PNPV2017-00004190-01 (Comprehensive) Coverage: 02/05/2018 - 03/05/2019	
		Excess:		
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244			
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/01/2019]			
Driver/Custodian:	ANG POH YEW (53 / Male), NRIC: S1707555A, Tel: +6594240456			

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 27 December 2018 1:49 PM
To: ahlimmc@singnet.com.sg
Cc: SUR
Subject: VEHICLE SLD 1581U (DOA: 20/12/2018)

Dear Eileen,

As instructed by our client, please proceed to repair the insured vehicle **SLD 1581U (Excess \$1,500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	26 Dec 2018 09:37	Clim Veh Model Changed	(203601) MERCEDES-BENZ C200 2.0 (A).	[R] Eileen Chua
2	26 Dec 2018 09:37	Clim Created	Reg No: SLD1581U, Policy No: PNPV2017-00004190-01, Acct Date: 2018/12/20, Claim Type: OD, Insurer: FWD Singapore Pte. Ltd. (HQ), Workshop: Ah Lim Motor Company (AMK), Created from SAS:MALM18163888	[R] Eileen Chua
3	26 Dec 2018 09:41	Clim Submitted	7256.00.	[R] Eileen Chua
4	26 Dec 2018 10:32	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : LKK Auto Consultants Pte Ltd.	[I] Josey Loh
5	26 Dec 2018 10:32	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/01/07	[I] Josey Loh
6	26 Dec 2018 10:32	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[I] Josey Loh
7	26 Dec 2018 10:34	Assignment 1st Accessed		[A] Nivitha Govindasamy
8	26 Dec 2018 10:47	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Nivitha Govindasamy
9	26 Dec 2018 11:23	Clim Registration Modified	Excess: -> 1500.00.	[I] Josey Loh
10	26 Dec 2018 15:40	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
11	26 Dec 2018 15:51	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/01/07	[A] DENISE TAY KWEE CHENG
12	26 Dec 2018 15:52	Adj Mandate Request	Cur.Req:5076.00:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
13	27 Dec 2018 10:43	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/01/07	[I] Clara Li Zi Rong
14	27 Dec 2018 10:43	Adj Mandate Set	Approved:5076.00.	[I] Clara Li Zi Rong

Date From



Date To



Audit Type

None

Go

ACTIVITY

[26/12/2018 10:38] Nivitha Govindasamy:

Please be informed vehicle not in the workshop, repairer will arrange.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2011312	26/12/2018 09:37	Motor	Ah Lim Motor Company (AMK)	Ah Lim Motor Company (AMK)	SLD1581U		xx.xx
2012027	26/12/2018 15:40	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLD1581U		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josey Loh

Date: 26 Dec 2018

Preliminary Advice

Vehicle No	: SLD1581U	Accident Date	: 20/12/2018
Make	: MERCEDES-BENZ C200	Policy No.	: PNPV2017-00004190-01
Assignment Date	: 26/12/2018	Excess	: S\$1,500.00
Date of Inspection	: 26/12/2018	Est. Duration of Repair	: 4.00
Inspection At	: AH LIM MOTOR COMPANY (AMK) 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-09 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,256.00
Revised Amount	:S\$	2,329.00
Check Items (Estimated)	:S\$	2,747.00
Total	:S\$	5,076.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	155,000.00
COE / PARF Rebate	:S\$	69,020.00
Salvage Value	:S\$	
Margin for Repair	:S\$	85,980.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/12/2018 17:46
Date Of Accident	20/12/2018 13:00
Exact Location Of Accident	SUNGEI BULOH CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD1581U
Insured/Policyholder	
Name Of Registered Owner	ANG POH YEW
NRIC No	S1707555A
Email Address	ANGPOHYEW@YAHOO.COM
Mobile Phone No	(LOCAL) +65-94240456
Alternative Phone No	OTHERS-94240456

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C200 AUTO ABS D/AIRBAG
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company


Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00004190-01
Cover Note Number	02/05/2018 - 03/05/2019

Driver

Name of Driver	ANG POH YEW
NRIC No	S1707555A
Date Of Birth	27/05/1965
Occupation	INDOOR
Date Of Driving Pass	19/07/1986
Driving Experience	32 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94240456
Fax Number	
Contact Number	OTHERS-94240456
EMail Address	ANGPOHYEW@YAHOO.COM

Sketch Plan Pg. 1

Date of accident: 20/12/18 Time: 1:00 pm Location: Sungai Buloh car park.
 My Vehicle A: SLD15914 Vehicle B: SLN8178C Vehicle C: -
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car A was parked at Sungai Buloh carpark, beside a non parking grass patch at 1pm. The vehicle was left as is.
 I returned to the car park to retrieve my car at about 3.00pm. I only realised something was wrong when I noticed my steering wheel is 90° clockwise instead being level. I check my car and discovered the damages (front bumper, hood, grill) and wheels turned slightly right. I checked my dash cam and discovered a recording of a dark brown Toyota (SLN8178C) caused the damages by reversing into my car.

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :

Email address :

& myself :

Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



AH LIM MOTOR COMPANY



**SINGAPORE
POLICE FORCE**



T/20181221/2031

1 of 3

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

Report No: T/20181221/2031

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/12/2018 10:38	Vide Report No.:	Station Diary No.: 36
--	------------------	--------------------------

Informant's Particulars

Name of Informant: ANG POH YEW			Address: APT BLK 981D BUANGKOK CRESCENT #15-07 SINGAPORE 537981		
ID Type / ID No.: NRIC NO / S1707555A			Contact No.: Home/Office: Mobile: 94240456		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 53	Date of Birth: 27/05/1965	Type of Informant: Vehicle Owner		
Race: Chinese			Language:		Institution / School Name:
Occupation: MANAGER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 20/12/2018 13:00	Type of Location: Car Park
Location: Along Road 1 NEO TIEW CRESCENT				
Sungei Buloh Wetland Reserve Visitor Centre				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLD1581U	Car				Slightly Damaged	0
SLN8178C	Car					0

Report No. T/20181221/2031

**SINGAPORE
POLICE FORCE**



T/20181221/2031

3 of 3

Report No. T/20181221/2031

Station Of Origin:
Ang Mo Kio South N.P.C
Ang Mo Kio Avenue 3 SINGAPORE
69929
Tel No: 1800-4519999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F /
Sgt 2 TAN WEI REN

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
21/12/2018 10:38

Officer In Charge Of Case:
TP / HRT /
Sr Staff Sgt IRMAN BIN MOHAMAD S/O
Contact No. 65476145

Classification Of Case:

SN 085

Authentication Stamp
NP166



Signature:

Singapore Police Force

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 7555A

Vehicle Details

Vehicle No.: SLD1581U
Vehicle to be Exported: Yes
Intended Deregistration Date: 21 Dec 2018
Vehicle Make: MERCEDES BENZ
Vehicle Model: C200 AUTO ABS D/AIRBAG
Primary Colour: Black
Manufacturing Year: 2015
Engine No.: 27492030533812
Chassis No.: WDD2050422R140297
Maximum Power Output: 135.0 kW (181 bhp)
Open Market Value: \$40,244.00
Original Registration Date: 04 Jun 2016
First Registration Date: 04 Jun 2016
Transfer Count: 0
Actual ARF Paid: \$43,342.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 03 Jun 2026
PARF Rebate Amount: \$32,506.00

Intended COE Rebate Details

COE Expiry Date: 03 Jun 2026
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$49,000.00
COE Rebate Amount: \$36,514.00
Total Rebate Amount: \$69,020.00

The information contained herein is correct as at 21 Dec 2018

OK

REPUBLIC OF SINGAPORE DRIVING LICENCE

ANG POH YEW

27 May 1965

10 Jan 2003

000127961J

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1707555A

ANG POH YEW

洪保有

CHINESE

27-05-1965

Country of Birth: MALAYSIA

Sex: M

94240 456
 plc
 No mng.
 Car: Yes
 0/100

Email: angpohyew@yahoo.com.

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE: 19 Jul 1986

Licence No: S1707555A

NP 428A

2545587

NRIC No: S1707555A

Blood Group: AB+ Date of issue: 16-12-1994

APT BLK 981D BUANGKOK CRESCENT #15-07
 SINGAPORE 537981

NRIC No: S1707555A Date: 27-03-2006 No: 5379481

Done

Updated Documents - PNPV2017-00004190.pdf

**YOUR PRESTIGE CAR INSURANCE SUMMARY**

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.
All accidents must be reported within 24 hours or the next working day of the incident
regardless of whether it will lead to a claim.

POLICY NUMBER : PNPV2017-00004190 - 01

About this policy

Premium paid : S\$1,261.94

(Inclusive of GST)

Coverage start date : 04/06/2017

Coverage end date : 03/06/2018

Who is insured to drive: : You and any Authorised Driver

Plan Type : PRESTIGE

About you (As the policyholder)

Your name : Ang Poh Yew

Address : Blk 981D Buangkok Crescent 15-07 Singapore 537981

Email : angpohyew@yahoo.com

NRIC/FIN : S1707555A

Date of birth : 27/05/1965

Marital status : Married

Gender : Male

Current no claims discount : 20%

Mobile Number : 94240456

Years of driving experience : Three or more

Certificate of merit : Yes

About your car

Car make and model : MERCEDES BENZ C200 2.0

Car plate number : Sld1581u

Year of first registration : 2016

Issued on: : 30/06/2017

A. Shute

Please refer to contract for specific terms, conditions
and exclusions of this policy.

Please immediately inform us at +65-6820-8888

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A
#01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg
GST Reg No: M9-0009639-E

SURVEYOR COPY

INSURER: FWD Singapore Pte. Ltd. (HQ)

2,00 pm
1 km

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/FWD
Policy No:	PNPV2017-00004190-01	Date of Loss:	20/12/2018
Vehicle Reg. No.:	SLD1581U	Driveable?	
Driver Age/Info:	53 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ANG POH YEW	Contact No:	+6594240456
Driver:	ANG POH YEW		
Make/Model:	MERCEDES-BENZ C200, 2.0 (A)	Vehicle Reg. Date:	04/06/2016
Vehicle Colour:	BLACK		
Engine No:	27492030533812	Chassis No:	WDD2050422R140297
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12 & day,		
Description of Accident/Loss	REFER TO THE ATTACHED SKETCH PLAN BY DRIVER. <i>Far 62564315</i>		
Present Location:	AH LIM MOTOR COMPANY (AMK)		



*Not Notified
1-B.1
Reserve B & paint*

COST OF CLAIMS	Amount
Parts	5,206.00
Miscellaneous Items	0.00
Labour	2,050.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,256.00
+ GST 7.00% (S\$)	507.92
Nett Amount (S\$)	7,763.92

This claim is handled by: EILEEN CHUA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Dec 2018)

Parts: 143 MERCEDES-BENZ C200 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ah Lim Motor Company/SLD1581U/26/12/2018 09:41

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BONNET TOP EMBLEM	0.00	0.00	*48.00 F	✓
2	1		*FRONT GRILLE	0.00	0.00	*80.00 F	7X
3	1		*FRONT GRILLE OUTER GARNISH	0.00	0.00	*120.00 F	7X
4	2		*FRONT GRILLE OUTER GARNISH CHROME UPPER X 2	0.00	0.00	*76.00 F	✓
5	2		*FRONT GRILLE OUTER GARNISH CHROME LOWER X 2	0.00	0.00	*92.00 F	7X
6	1		*FRONT GRILLE EMBLEM	0.00	0.00	*80.00 F	7X
7	1		*HEADLAMP LED ASSY LH	0.00	0.00	*1,900.00 F	7X
8	1		*HEADLAMP TOP PANEL LH	0.00	0.00	*425.00 F	X
9	1		*FRONT BUMPER	0.00	0.00	*1,080.00 F	✓
10	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	*8.00 F	XX
11	12		*FRONT BUMPER CLIPS X 12	0.00	0.00	*48.00 F	— X
12	1		*FRONT BUMPER TOP RUBBER CENTRE	0.00	0.00	*16.00 F	XX
13	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*255.00 F	7X
14	1		*FRONT BUMPER SPONGE CENTRE	0.00	0.00	*100.00 F	7X
15	1		*FRONT BUMPER LOWER AIR GRILLE	0.00	0.00	*80.00 F	XX
16	1		*FRONT BUMPER LOWER LIP CHROME CENTRE	0.00	0.00	*180.00 F	XX
17	1		*FRONT BUMPER LOWER LIP CHROME SIDE LH	0.00	0.00	*100.00 F	XX
18	1		*FRONT BUMPER CENTRE PARKING SENSOR LH	0.00	0.00	*120.00 F	XX
19	1		*FRONT BUMPER CENTRE PARKING SENSOR HOLDER LH - CHECK PRICE	0.00	0.00	*-F	
20	1		*FRONT BUMPER LOWER SIDE GRILLE LH	0.00	0.00	*40.00 F	X
21	1		*FRONT BUMPER LOWER SIDE GRILLE PARKING SENSOR LH	0.00	0.00	*120.00 F	7X
22	1		*FRONT BUMPER LOWER SIDE GRILLE PARKING SENSOR HOLDER LH - CHECK PRICE	0.00	0.00	*-F	7X
23	1		*FRONT BUMPER SIDE PARKING SENSOR LH	0.00	0.00	*120.00 F	XX
24	1		*FRONT BUMPER SIDE PARKING SENSOR HOLDER LH - CHECK PRICE	0.00	0.00	*-F	XX
25	1		*FRONT NUMBER PLATE GARNISH	0.00	0.00	*83.00 F	✓
26	1		*FRONT NUMBER PLATE (BLACK)	0	0.00	*35.00 FS	X

F=Franchise part. S=SpcNett.

Total Parts (S\$) 5,206.00

Ah Lim Motor Company/SLD1581U/26/12/2018 09:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
----	-------------	----------	--------

Ah Lim Motor Company/SLD1581U/26/12/2018 09:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	✓ 40.00 201
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	~ 80.00 X
3	TO REMOVE & REINSTALL/REPLACE FRONT PARKING SENSOR CENTRE; SIDE LH	New	✓ 80.00 601
4	TO RESET FRONT PARKING SENSOR CENTRE;SIDE LH;HEADLAMP LED LH	New	✓ 280.00 1501
5	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT BUMPER REINFORCEMENT;HEADLAMP TOP PANEL LH. TO KNOCK & REPAIR FRONT FENDER LH; FRONT BONNET; INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	✓ 770.00 4401
6	TO SPRAY FRONT BONNET; FRONT BUMPER; FRONT FENDER LH; FRONT BUMPER REINFORCEMENT	New	✓ 800.00 4001
Gross Labour Cost (S\$)			2,050.00

Ah Lim Motor Company/SLD1581U/26/12/2018 09:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A

#01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244 Fax: 6483 6170 Email: ahlimme@singnet.com.sg

GST Reg No: M9-0009639-E

SURVEYOR COPY

INSURER: FWD Singapore Pte. Ltd. (HQ)

2.00 PM
1 Dec

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/FWD
Policy No:	PNPV2017-00004190-01	Date of Loss:	20/12/2018
Vehicle Reg. No.:	SLD1581U	Driveable?	
Driver Age/Info:	53 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ANG POH YEW	Contact No:	+6594240456
Driver:	ANG POH YEW		
Make/Model:	MERCEDES-BENZ C200, 2.0 (A)	Vehicle Reg. Date:	04/06/2016
Vehicle Colour:	BLACK		
Engine No:	27492030533812	Chassis No:	WDD2050422R140297
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12 (4 day)		
Description of Accident/Loss	REFER TO THE ATTACHED SKETCH PLAN BY DRIVER. <i>Fig 62564315</i>		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

Ry MS



Not Authorized
1-B.1
Returning B&P point

COST OF CLAIMS

	Amount
Parts	5,206.00
Miscellaneous Items	0.00
Labour	2,050.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	7,256.00
+ GST 7.00% (\$\$)	507.92
Nett Amount (\$\$)	7,763.92

This claim is handled by: EILEEN CHUA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Dec 2018)
Parts: 143 MERCEDES-BENZ C200 2.0 (A) (Catalogue: Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Ah Lim Motor Company/SLD1581U/26/12/2018 09:41
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET TOP EMBLEM	0.00	0.00	*48.00 F ✓
2	1		*FRONT GRILLE	0.00	0.00	*80.00 F ?
3	1		*FRONT GRILLE OUTER GARNISH	0.00	0.00	*120.00 F ?
4	2		*FRONT GRILLE OUTER GARNISH CHROME UPPER X 2	0.00	0.00	*76.00 F ✓
5	2		*FRONT GRILLE OUTER GARNISH CHROME LOWER X 2	0.00	0.00	*92.00 F ?
6	1		*FRONT GRILLE EMBLEM	0.00	0.00	*80.00 F ?
7	1		*HEADLAMP LED ASSY LH	0.00	0.00	*1,900.00 F ?
8	1		*HEADLAMP TOP PANEL LH	0.00	0.00	*425.00 F X
9	1		*FRONT BUMPER	0.00	0.00	*1,080.00 F ✓
10	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	*8.00 F X
11	12		*FRONT BUMPER CLIPS X 12	0.00	0.00	*48.00 F ✓
12	1		*FRONT BUMPER TOP RUBBER CENTRE	0.00	0.00	*16.00 F X
13	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*255.00 F ?
14	1		*FRONT BUMPER SPONGE CENTRE	0.00	0.00	*100.00 F ?
15	1		*FRONT BUMPER LOWER AIR GRILLE	0.00	0.00	*80.00 F X
16	1		*FRONT BUMPER LOWER LIP CHROME CENTRE	0.00	0.00	*180.00 F X
17	1		*FRONT BUMPER LOWER LIP CHROME SIDE LH	0.00	0.00	*100.00 F X
18	1		*FRONT BUMPER CENTRE PARKING SENSOR LH	0.00	0.00	*120.00 F X
19	1		*FRONT BUMPER CENTRE PARKING SENSOR HOLDER LH - CHECK PRICE	0.00	0.00	*.F
20	1		*FRONT BUMPER LOWER SIDE GRILLE LH	0.00	0.00	*40.00 F X
21	1		*FRONT BUMPER LOWER SIDE GRILLE PARKING SENSOR LH	0.00	0.00	*120.00 F ?
22	1		*FRONT BUMPER LOWER SIDE GRILLE PARKING SENSOR HOLDER LH - CHECK PRICE	0.00	0.00	*.F ?
23	1		*FRONT BUMPER SIDE PARKING SENSOR LH	0.00	0.00	*120.00 F X
24	1		*FRONT BUMPER SIDE PARKING SENSOR HOLDER LH - CHECK PRICE	0.00	0.00	*.F X
25	1		*FRONT NUMBER PLATE GARNISH	0.00	0.00	*83.00 F ✓
26	1		*FRONT NUMBER PLATE (BLACK)	0	0.00	*35.00 FS X
Total Parts (S\$)						5,206.00

F=Franchise part, S=SpcNatt

Ah Lim Motor Company/SLD1581U/26/12/2018 09:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Ah Lim Motor Company/SLD1581U/26/12/2018 09:41. Not valid without Reference section. Generated using Merimen e-Claims IEAS			

Repairer Estimates

Page 3 of 3

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00 201
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	80.00 X
3	TO REMOVE & REINSTALL/REPLACE FRONT PARKING SENSOR CENTRE; SIDE LH	New	80.00 601
4	TO RESET FRONT PARKING SENSOR CENTRE;SIDE LH;HEADLAMP LED LH	New	280.00 1501
5	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT BUMPER REINFORCEMENT;HEADLAMP TOP PANEL LH. TO KNOCK & REPAIR FRONT FENDER LH; FRONT BONNET; INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	770.00 4401
6	TO SPRAY FRONT BONNET; FRONT BUMPER; FRONT FENDER LH; FRONT BUMPER REINFORCEMENT	New	800.00 4001
Gross Labour Cost (\$5)			2,050.00

Ah Lim Motor Company/SLD1581U/26/12/2018 09:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LIK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

No	Particulars	Lab.Type	Amount	
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00	201
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	80.00	nn x
3	TO REMOVE & REINSTALL REPAIR FRONT PARKING SENSOR CENTRE; SIDE LH	New	80.00	601
4	TO RESET FRONT PARKING SENSOR CENTRE; SIDE LH; HEADLAMP LED LH	New	280.00	1501
5	TO DISMANTLE ALL DAMAGED PANELS. TO CUT & WELD FRONT BUMPER REINFORCEMENT; HEADLAMP TO PANEL LH. TO KNOCK & REPAIR FRONT FENDER LH; FRONT BOW SET; REPAIR PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME	New	770.00	4401
6	TO SPRAY FRONT BOW SET; FRONT BUMPER; FRONT FENDER LH; FRONT BUMPER REINFORCEMENT	New	800.00	4001
Gross Labour Cost (S\$)			2,050.00	

Ah Lim Motor Company

10/05/2018 09:41. Not valid without Reference section.

during Merimen e-Claims IEAS

END OF ESTIMATES >

SURPASS AUTO PARTS SUPPLIES PTE LTD

29/12/2018 10:28:45

10 KAKI BUKIT ROAD 1 #01-33 K&B INDUSTRIAL BUILDING SINGAPORE 416175

Tel: 67476016 Fax: 67449644 Email: surpass@surpass.com.sg

Co & Gst Reg No: 199904808E

AH LIM MOTOR COMPANY (A)

10 ANG MO KIO IND PARK 2A

#01-09 AMK AUTOPOINT

SINGAPORE 568047

TAX INVOICEInv No. : 19010001
Date : 02/01/2019
Page : 1 of 1

S/N	Item No.	Description	Qty	U/ Price	Amount
1		SLE			
2	A2048170616	STAR	1	48.00✓	48.00
3	A2058880173	=O= ORNAMENT MOLDING LH TOP	1	38.00✓	38.00
4	A2058880373	=O= ORNAMENT MOLDING RH TOP	1	38.00✓	38.00
5	A20588018409999	FRT BUMPER AMG	1	1,080.00✓	1,080.00
6	A2058801644	LICENSE PLATE C / AMG	1	83.00✓	83.00

Page 1

Sub Total	1,287.00
GST 7%	90.09
Total	1,377.09

Customer's Signature

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimnc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALIZATION

M/S : FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4
SINGAPORE 038986

TEL: 67275700

FAX: 67275799

ATTN: Motor Claim Department

Claim No: MC0913699
Ref No: MF1900257
Date: 02 May 2019
Policy No: PNPV2017-00004190-01
Veh Reg No: SLD1581U
Make/Model: M.BENZ C200 AUTO
ABS D/AIRBAG

Your Ref No: -

Claim Type: Own Damage/Third Party

Accident Date: 20/12/2018

Repair Cost to Vehicle No (For Finalization):SLD1581U

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 FRONT BONNET TOP EMBLEM		1 PC	48.00	
2 FRONT GRILLE OUTER GARNISH CHROME UPPER		2 PC	76.00	
3 FRONT BUMPER		1 PC	1,080.00	
4 FRONT NUMBER PLATE GARNISH		1 PC	83.00	
				1,287.00
Special Nett				
5 FRONT BUMPER CLIPS X 12		12 PC	48.00	
				48.00
LABOUR				
6 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	20.00	
7 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		1 PC	80.00	X
8 TO REMOVE & REINSTALL/REPLACE FRONT PARKING SENSOR CENTRE, SIDE LH		1 PC	60.00	
9 TO RESET FRONT PARKING SENSOR CENTRE,SIDE LH,HEADLAMP LED LH		1 PC	150.00	
10 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT BUMPER REINFORCEMENT,HEADLAMP TOP PANEL LH. TO KNOCK & REPAIR FRONT FENDER LH, FRONT BONNET, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	440.00	
11 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT BUMPER REINFORCEMENT		1 PC	400.00	
				1,150.00

8 24 05.00

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4
SINGAPORE 038986

TEL: 67275700

FAX: 67275799

ATTN: Motor Claim Department

Claim No: MC0913699
Ref No: MF1900257
Date: 02 May 2019
Policy No: PNPV2017-00004190-01
Veh Reg No: SLD1581U
Make/Model: M.BENZ C200 AUTO
ABS D/AIRBAG

Your Ref No: -

Claim Type: Own Damage/Third Party

Accident Date: 20/12/2018

Repair Cost to Vehicle No (For Finalization):SLD1581U

2405

Amount Before Excess	SS 2,485.00
Less Excess	SS 1,500.00
Amount Before GST	SS 985.00
Add GST @ 7%	68.95
Total Amount payable	SS 1,053.95

TOTAL: SINGAPORE DOLLAR ONE THOUSAND FIFTY THREE AND CENTS NINETY FIVE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 26/12/2018

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
AUTHORISED SIGNATURE
Tel: 6483 1244 Fax: 6483 6170

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Dec 2018 Sendback Est	26 Dec 2018 09:41 S\$7,256.00	26 Dec 2018 10:32 Edit Adj Rpt	S\$2,405.00 Edit Estimates	S\$2,405.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	ANG POH YEW , ID: S1707555A, Tel: +6594240456, Email: ANGPOHYEW@YAHOO.COM		
Vehicle Reg. No.:	SLD1581U	Date of Loss:	20/12/2018 13:00 - :59 [30 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201800019650	Policy/Cover Note No.:	PNPV2017-00004190-01 (Comprehensive) Coverage: 02/05/2018 - 03/05/2019
		Excess:	S\$1,500.00
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 07/01/2019]		
Driver/Custodian:	ANG POH YEW (53 / Male), NRIC: S1707555A, Tel: +6594240456 Email: ANGPOHYEW@YAHOO.COM		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- FWD_SG (27/12/2018): Alert - Adj Mandate Approved (S\$5076.00) - SLD1581U - Claim Handler: Josey Loh

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLD1581U (1201800019650)

OD

Dec 20 2018 1:00PM

[ANG POH YEW]

Ah Lim Motor Company

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View [View in Browser](#) ▼

Video

No	Finalized On	Ah Lim Motor Company (AMK)	1 per page ▼	Thumbnail	Print
1	21/12/18 14:49	Video - Accident [Linked Accident Report Documents]	1	Load MP4	
2	21/12/18 14:49	Video - Accident [Linked Accident Report Documents]	1	Load MP4	

Assessment Reports

No	Finalized On	Ah Lim Motor Company (AMK)	1 per page ▼	Thumbnail	Print
1	26/12/18 09:41	Repairer Estimates	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/12/18 15:51	Adjuster Immediate Advice	1	Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	Thumbnail	Print
1	27/12/18 13:50	General View	1	Load JPG	✓
2	27/12/18 13:50	General View	1	Load JPG	✓
3	27/12/18 13:50	General View	1	Load JPG	✓
4	27/12/18 13:50	General View	1	Load JPG	✓
5	27/12/18 13:50	General View	1	Load JPG	✓
6	27/12/18 13:50	General View	1	Load JPG	✓
7	27/12/18 13:50	General View	1	Load JPG	✓
8	27/12/18 13:50	General View	1	Load JPG	✓
9	27/12/18 13:50	General View	1	Load JPG	✓
10	27/12/18 13:50	General View	1	Load JPG	✓
11	27/12/18 13:50	General View	1	Load JPG	✓
12	27/12/18 13:50	General View	1	Load JPG	✓
13	27/12/18 13:50	General View	1	Load JPG	✓
14	27/12/18 13:50	General View	1	Load JPG	✓
15	27/12/18 13:50	Odometer Reading	1	Load JPG	✓
16	27/12/18 13:50	Chassis Number	1	Load JPG	✓

Documentation

No	Finalized On	Ah Lim Motor Company (AMK)	1 per page ▼	Thumbnail	Print
1	26/12/18 09:40	Log card (if available)	1	Load PDF	
2	26/12/18 09:40	Certificate of Insurance	1	Load PDF	
3	26/12/18 09:40	Driver's Driving License	1	Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	26/03/19 11:15	E-filed GIA report	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/12/18 15:40	ESTIMATE	1	Load PDF	

Linked Accident Report Documents

View View in Browser ▼

Video			1 per page ▼	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	21/12/18 14:49	Video - Accident	 Load MP4	
2	21/12/18 14:49	Video - Accident	 Load MP4	

Assessment Reports			1 per page ▼	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	21/12/18 15:22	Accident Statement	 Load HTM	
2	23/03/19 09:51	Addendum Sheet	 Load TIF	
3	23/03/19 09:52	Accident Statement Addm. #1	 Load HTM	

Photos/Images			3 per page ▼	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	21/12/18 15:01	Accident Photo	 Load JPG	☒
2	21/12/18 15:01	Accident Photo	 Load JPG	☒
3	21/12/18 15:01	Accident Photo	 Load JPG	☒
4	21/12/18 15:01	Accident Photo	 Load JPG	☒
5	21/12/18 15:01	Accident Photo	 Load JPG	☒
6	21/12/18 15:01	Accident Photo	 Load JPG	☒
7	21/12/18 15:01	Accident Photo	 Load JPG	☒
8	21/12/18 15:01	Accident Photo	 Load JPG	☒
9	21/12/18 15:01	Accident Photo	 Load JPG	☒
10	21/12/18 15:01	Accident Photo	 Load JPG	☒
11	21/12/18 15:01	Accident Photo	 Load JPG	☒
12	21/12/18 15:01	Accident Photo	 Load JPG	☒
13	21/12/18 15:01	Accident Photo	 Load JPG	☒
14	21/12/18 15:01	Accident Photo	 Load JPG	☒
15	21/12/18 15:01	Accident Photo	 Load JPG	☒
16	21/12/18 15:01	Accident Photo	 Load JPG	☒
17	21/12/18 15:01	Accident Photo	 Load JPG	☒
18	21/12/18 15:01	Accident Photo	 Load JPG	☒
19	21/12/18 15:01	Accident Photo	 Load JPG	☒
20	21/12/18 15:01	Accident Photo	 Load JPG	☒
21	21/12/18 15:01	Accident Photo	 Load JPG	☒
22	21/12/18 15:01	Accident Photo	 Load JPG	☒
23	21/12/18 15:01	Accident Photo	 Load JPG	☒
24	21/12/18 15:01	Accident Photo	 Load JPG	☒
25	21/12/18 15:01	Accident Photo	 Load JPG	☒
26	21/12/18 15:01	Accident Photo	 Load JPG	☒

Documentation			1 per page ▼	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	21/12/18 15:17	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD18023056/KTD3S2

Date: 03/05/2019

REFERENCE

Insured/Claimant:	ANG POH YEW	Policy No:	PNPV2017-00004190-01	Claim No:	1201800019650
Date of Loss:	20/12/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD1581U	Engine No:	27492030533812
Make & Model:	MERCEDES-BENZ C200, 2.0 (A)	Chassis No:	WDD2050422R140297
Reg. Date:	04/06/2016 (Man. Year: 2015)	Odometer:	45526 km
Colour:	Metallic Black		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	S\$155,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45R18	Rear Tyre Size:	225/45R18
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,206.00	1,335.00	3,871.00	74.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	1,070.00	980.00	47.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,256.00	2,405.00	4,851.00	66.86
+ GST 7.00/7.00% (S\$)	507.92	168.35	339.57	66.86
Nett Amount (S\$)	7,763.92	2,573.35	5,190.57	66.86

INSPECTION

Date of Assignment:	26/12/2018 Present Location:	Ah Lim Motor Company (AMK)
Date Inspected:	26/12/2018 Inspected At:	Ah Lim Motor Company (AMK)
Estimated Period of Repair:	4.0 days	10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
		Autopoint
		Singapore 568047

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 May 2019)
Parts:	143	MERCEDES-BENZ C200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD1581U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET TOP EMBLEM	Necessary	48.00 F	*48.00 F
2	1		*FRONT GRILLE	Serviceable	80.00 F	*- F
3	1		*FRONT GRILLE OUTER GANISH	Serviceable	120.00 F	*- F
4	2		*FRONT GRILLE OUTER GARNISH CHROME UPPER	Dented	76.00 F	*76.00 F
5	2		*FRONT GRILLE OUTER GARNISH CHROME LOWER X 2	Serviceable	92.00 F	*- F
6	1		*FRONT GRILLE EMBLEM	Serviceable	80.00 F	*- F
7	1		*HEADLAMP LED ASSY LH	Serviceable	1,900.00 F	*- F
8	1		*HEADLAMP TOP PANEL LH	Repair	425.00 F	*- F
9	1		*FRONT BUMPER	Buckled	1,080.00 F	*1,080.00 F
10	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	8.00 F	*- F
11	12		*FRONT BUMPER CLIPS X 12	Necessary	48.00 F	*48.00 F
12	1		*FRONT BUMPER TOP RUBBER CENTRE	Serviceable	16.00 F	*- F
13	1		*FRONT BUMPER REINFORCEMENT	Repair	255.00 F	*- F
14	1		*FRONT BUMPER SPONGE CENTRE	Repair	100.00 F	*- F
15	1		*FRONT BUMPER LOWER AIR GRILLE	Serviceable	80.00 F	*- F
16	1		*FRONT BUMPER LOWER LIP CHROME CENTRE	Serviceable	180.00 F	*- F
17	1		*FRONT BUMPER LOWER LIP CHROME SIDE LH	Serviceable	100.00 F	*- F
18	1		*FRONT BUMPER CENTRE PARKING SENSOR LH	Serviceable	120.00 F	*- F
19	1		*FRONT BUMPER CENTRE PARKING SENSOR HOLDER LH - CHECK PRICE (NPA)	Not Necessary	0.00 F	*- F
20	1		*FRONT BUMPER LOWER SIDE GRILLE LH	Serviceable	40.00 F	*- F
21	1		*FRONT BUMPER LOWER SIDE GRILLE PARKING SENSOR LH	Serviceable	120.00 F	*- F
22	1		*FRONT BUMPER LOWER SIDE GRILLE PARKING SENSOR HOLDER LH - CHECK PRICE (NPA)	Serviceable	0.00 F	*- F
23	1		*FRONT BUMPER SIDE PARKING SENSOR LH	Serviceable	120.00 F	*- F
24	1		*FRONT BUMPER SIDE PARKING SENSOR HOLDER LH - CHECK PRICE (NPA)	Not Necessary	0.00 F	*- F
25	1		*FRONT NUMBER PLATE GARNISH	Mtg Cracked	83.00 F	*83.00 F
26	1		*FRONT NUMBER PLATE (BLACK)	Serviceable	35.00 FS	*- FS
					Total Parts (\$\$)	5,206.00 1,335.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00	20.00
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	80.00	0.00
3	TO REMOVE & REINSTALL/REPLACE FRONT PARKING SENSOR CENTRE; SIDE LH	New	80.00	60.00
4	TO RESET FRONT PARKING SENSOR CENTRE;SIDE LH;HEADLAMP LED LH	New	280.00	150.00
5	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT BUMPER REINFORCEMENT;HEADLAMP TOP PANEL LH. TO KNOCK & REPAIR FRONT FENDER LH; FRONT BONNET; INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	770.00	440.00
6	TO SPRAY FRONT BONNET; FRONT BUMPER; FRONT FENDER LH; FRONT BUMPER REINFORCEMENT	New	800.00	400.00
Gross Labour Cost (S\$)			2,050.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >