

ASS. REC. BY:

REF: CS/ASM18023063/Kqd30p

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Kitty Tso

of

ASM (A x A)

Date/Time:

26/12/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 7802R

Insured:

at Workshop n/s:

K. Kim Hin

Tel:

64527018

of

160 Sin Ming Drive #02-20

Policy No:

Claim No:

S8M01621

Sum Insured:

Excess:

\$1200.00

Make of Veh:

(Client's Record)

D.O.A.

09/12/2018

CA (REV)

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:50am @ 26/12/18

Person Contacted:

Shuman

Vehicle (IN/OUT)

Date/Time	Action/Instruction (✓) Estimate
	pls get Audetex from Wlap.
	SLN 7802R-X
26/12/18 @ 5:16pm	request to Kitty Tso via Smart Claim
28/12/18 @ 2:41pm	Kitty Tso informed C/A via Smart Claim
28/12/18 @ 2:49pm	Informed Shu Man C/A & Exs \$1200 by email.
14/1/19 @ 4:24pm	confirmed with Shu Man that final fig is \$37.20, 4 days.
	(Fed 61545.00, 17%)

ASSIGNMENT

From:

Date:

Estimated Cost:

DD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Soon:

Est. Repairs:

Lump Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / R/Rim / STD A/Rim or

Tyre Size:

R: B-S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 15 MAR 2019

14/3/2019

Date/Time, File Pass to?

11/15/19

Date/Time, File Return to?

: Prell. Report

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Survey Fee:

Transportation

) S-RS, \$

) Photos

) Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

Smart Claim

7637.20

200

200



Service Request Details

Claim

S8M0162I

Reference

None 

Loss Date

December 9, 2018

Request Date

December 26, 2018

Due Date

January 2, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLN7802R

Make

SUZUKI

SERVICE ADDRESS

160 Sin Ming Drive, #... 575722

Primary Contact/Insured

PHILLIPS GRACEY REUBEN RAJAN S/O
BLK 178A RIVERVALE CRESCENT, #06-459, 541178, Singapore
83188850
REUBENRAJAN@YMAIL.COM

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Additional Instructions
EXCESS \$1200

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE



SENT

12/26/18 11:42 AM

FROM

TEO Kitty

SUBJECT

WP SURVEY

BODY

Hi Please get audatex from workshop. Thanks.



Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 14 March 2019 4:24 PM
To: 'survey@kkimhin.com.sg'
Subject: RE: SLN7802R SUZUKI SWIFT AXA OD AWAITING FOR AUTHORISATION FINALISATION

Dear Meng Huat,

WITHOUT PREJUDICE

Confirm final fig \$7,637.20 before excess \$1,200.00 & GST and 6 repair days.

Kindly upload the relevant documents via Smart Claim.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: survey@kkimhin.com.sg <survey@kkimhin.com.sg>
Sent: Wednesday, 13 March 2019 3:06 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: RE: SLN7802R SUZUKI SWIFT AXA OD AWAITING FOR AUTHORISATION FINALISATION

Hi Ms Shiau Chan,

Enclosed your attention.

P/P=\$7,637.20

Please confirm.

Thank you.

Regard

Meng Huat

K.Kim Hin Auto

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Tuesday, 12 March 2019 4:08 PM
To: service@kkimhin.com.sg; 'Simon' <simon@kkimhin.com.sg>; survey@kkimhin.com.sg
Cc: sandrakhong@gmail.com
Subject: RE: SLN7802R SUZUKI SWIFT AXA OD AWAITING FOR AUTHORISATION

Dear Simon and Meng Huat,

Kindly send us the final bill for finalise.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315



SUPPLEMENTARY UPLOADED

Type

🔔 Question

Message

Dear Kitty, please be informed that we have received supplementary of \$363.00 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair, within authorize limit. - Shiau Chan

Reply

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 28 December 2018 2:49 PM
To: 'Simon'; survey@kkimhin.com.sg
Cc: KKH
Subject: RE: SLN7802R SUZUKI SWIFT AXA OD AWAITING FOR AUTHORISATION

Dear Simon,

As spoken with Shu Man.

As instructed by our client, please proceed to repair the insured vehicle **SLN 7802R (Excess \$1,200/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Simon <simon@kkimhin.com.sg>
Sent: Friday, 28 December 2018 10:53 AM
To: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Cc: KKH <service@kkimhin.com.sg>
Subject: SLN7802R SUZUKI SWIFT AXA OD AWAITING FOR AUTHORISATION
Importance: High

Dear Siao Chan,

Kindly let us know when can authorise repair as owner wants update.

Regards
Simon
K.Kim Hin Auto Pte Ltd

◀ Service Request Details

Claim

S8M0162I

ReferenceNone **Loss Date**

December 9, 2018

Request Date

December 26, 2018

Due Date

December 26, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Finish the work

[Complete Work](#)[More ▾](#)

Vehicle Information

Incident Vehicle Registration #

SLN7802R

Make

SUZUKI

Service Address

160 Sin Ming Drive, #, ., . 575722

Primary Contact/Insured

PHILLIPS GRACEY REUBEN RAJAN S/O
BLK 178A RIVERVALE CRESCENT, #06-459, 541178, Singapore
83188850
REUBENRAJAN@YMAIL.COM

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Additional Instructions
EXCESS \$1200

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE



SENT

12/28/18 2:41 PM

FROM

TEO Kitty

SUBJECT

Re:IA OF VEHICLE SLN 7802R UPLOADED

BODY

Hi Shiau Chan Authorised.



TYPE



SENT

12/26/18 5:16 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (OD)

BODY

Dear Kitty, please be informed that the IA of veni...



TYPE



SENT

12/26/18 11:42 AM

FROM

TEO Kitty

SUBJECT

WP SURVEY

BODY

Hi Please get audatex from workshop. Thanks.



RATAN BHOSALE Pragati

From: admin1@kkimhin.com.sg
Sent: Monday, December 24, 2018 2:54 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: service@kkimhin.com.sg; 'sandrakhong'; simon@kkimhin.com.sg; survey@kkimhin.com.sg; survey2@kkimhin.com.sg
Subject: SLN 7802 R - OD claim DOA : 9/12/2018
Attachments: GIA REPORT W ADDENDUM by ah lim.pdf; KKHA0068.AudatexMS.pdf; AXA letter.pdf; COE.pdf; IC & DL.pdf; transfer fee.pdf

Categories: Pragati

Dear all,

Enclosed the GIA report, transfer fee/COE, driver IC/DL, AXA checklist and audatex.

Smart claim is invalid.

Kindly assist to create claim.

Thank you.

Best Regards,

Shuman

K. Kim Hin Auto Pte Ltd

Tel: 6452 7018 Fax: 6458 3895



Auto
Consultants
Pte Ltd

81 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408993 TEL : (065) 62563561 FAX : (065) 62564313

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 26/12/18

Survey Details:

Date of loss	9-Dec-18
Date of appointment	26-Dec-18
Date of survey	26-Dec-18
Location of survey	K KIM HIN

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SLN 7802R
Make and Model	SUZUKI SWIFT SPORT 1.6M
Date of registration	6/6/2008
Excess	\$ 1,200.00
Market Value	\$ 27,000.00
Parf Rebate	\$ 16,981.00
Nett Loss	\$ 10,019.00

Repair details:

Initial Estimate	\$ 8,820.00
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 2,996.90
Check items (estimate)	\$ 2,449.70
Labour	\$ 2,226.40
Total	\$ 7,673.00
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>6</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

31 UBI AVE 1, #01-23 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE
HAVE NOT AUTHORISE REPAIR.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	2298D

Vehicle Details

Vehicle No.:	SLN7802R
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2018
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT SPORT 1.6 M
Primary Colour:	Yellow
Manufacturing Year:	2008
Engine No.:	M16A1311910
Chassis No.:	ZC31S202765
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$15,672.00
Original Registration Date:	06 Jun 2008
First Registration Date:	06 Jun 2008
Transfer Count:	3
Actual ARF Paid:	\$15,672.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 May 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$19,096.00
COE Rebate Amount:	\$16,981.00
Total Rebate Amount:	\$16,981.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 20 Dec 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/12/2018 17:18
Date Of Accident	09/12/2018 09:15
Exact Location Of Accident	SENGKANG EAST DRIVE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLN7802R
Insured/Policyholder	
Name Of Registered Owner	REUBEN RAJAN S/O PHILLIPS GRACEY
NRIC No	S8742298D
Email Address	REUBENRAJAN@YMAIL.COM
Mobile Phone No	(LOCAL) +65-83188850
Alternative Phone No	OTHERS-83188850
Vehicle Particulars	
Manufacturer	SUZUKI
Model	SWIFT-1.6 SPORT (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA356670/1
Cover Note Number	23/05/2018 - 05/06/2019
Driver	
Name of Driver	REUBEN RAJAN S/O PHILLIPS GRACEY
NRIC No	S8742298D
Date Of Birth	01/12/1987
Occupation	INDOOR
Date Of Driving Pass	26/10/2015
Driving Experience	3 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-83188850
Fax Number	
Contact Number	OTHERS-83188850
Email Address	REUBENRAJAN@YMAIL.COM

Address	BLK 178A RIVERVALE CRESCENT #06-459
Postcode	541178
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : JOYCLYN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKX2935H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: _____
 NRIC/FIN No.: _____

Sketch Plan Pg. 2

Date of accident: 09 Dec 2018 Time: 9.15am Location: Sengkang Food Drive
 My Vehicle A: SLN 7302R Vehicle B: _____ Vehicle C: _____
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I being the other car by behind the driver purposely slow down. When see my car is coming I was still in my speed. I want the driver tell me that he want me to leave him so he can leave.

☐ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☒ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop:

Email address:

& myself

Email address:

REJALBENBAGAWA@Ymail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Officer's Signature

Name:

NRIC/FIN No.:

INVESTIGATION CODE/DATE

K.KIM HIN AUTO PTE LTD
160 Sin Ming Drive
#02-20 Sin Ming AutoCity
Singapore 575722

Claim Reference:
Assessment Number: KKHA0068
Version: K.KIMHIN/1
Date Calculated: 22/12/2018 01:29

Full Report - V1
Registration: SLN7802R
Printed: 22/12/2018 09:29

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SANDRA KHONG	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA

Claim Reference:	Estimated Repair Time:
Policy Number:	Quote Due Date:
Other Reference:	Actual Repair Days:
Third Party:	Parts Ordered Date:
Insured Amount:	Hire Car Start:
Under Warranty:	Hire Car End:
Warranty Expired:	Vehicle Collected:

Vehicle Details

Vehicle

Manufacturer:	SUZUKI
Model:	Swift
Sub Model:	SPORT
Model Sheet Number:	R03 18
Registration:	SLN7802R
Registration Month:	June
Registration Year:	2008
VIN Number:	ZC31S202765
Manufacture Year:	2008
Odometer:	Not Known
Colour:	
Engine Number:	M16A1311910
Fuel Level:	%

Model Specs

AIR CONDITIONING	FOG LAMPS
1.6 LTR 92 KW	5-SPEED
5-DOOR	PREPARE OFF VEHICLE
TWO COAT PEARL/MICA	



Not Authorised
1.B.1
Return B4 Paint
Ex 8/2008

6 days

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on
	Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	21/12/2018
Pre-Accident Damage:	

Tyres Condition:
Tread Depth LHF:
Tread Depth LHR:
Damage Areas:

Tread Depth RHF:
Tread Depth RHR:
Direction of Impact:

- Impacter of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHA0068



Version: K.KIMHIN/1

Date Calculated: 22/12/2018 01:29

Full Report - V1

Registration: SLN7802R

Printed: 22/12/2018 09:29



Addresses

Cost Summary

Total Labour	\$1,935.00
Total Paint/Material	\$291.40
Total Parts	\$6,045.60
Total of Additional Costs	\$548.00
Excess:	TBA
Grand Total Exc GST:	\$8,820.00
7 % GST:	\$617.40
Grand Total Inc GST:	\$9,437.40

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$0.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
OP 100	RENEW LEFT FRONT WING INCLUDES: R + R BUMPER, HEADLAMP, DOOR SILL COVER AND WHEELARCH TRIM, ADJUST HEADLAMP	19.0	85.50
NO NUMBER	RENEW R/F WING INCLUDES: R + R HEADLAMP AND WHEELARCH TRIM	11.0	49.50
NO NUMBER	R + R FRONT AIR GUIDE	2.0	9.00
OP 101	RENEW FRONT BUMPER (REMOVED) INCLUDES: R + R RADIATOR GRILLE	7.0	31.50
NO NUMBER	R + R FRONT BUMPER IMPACT DAMPER	2.0	9.00
SA14R0)	R + R L/F FOGLAMP	1.0	4.50
SA14R0)	R + R R/F FOGLAMP	1.0	4.50
OP 110	RENEW BONNET INCLUDES: R + R BONNET	9.0	40.50
OP 131)	RENEW L/BONNET HINGE	1.0	4.50
OP 131)	RENEW R/BONNET HINGE	3.0	13.50
NH21R0)	R + R COWL PANEL TRIM	2.0	9.00
NB03R0	R + R BONNET LOCK	5.0	22.50
NB04R0	RENEW BONNET BOWDEN CABLE	7.0	31.50
NO NUMBER	R + R BONNET SEAL	1.0	4.50
OP 148)	RENEW COMPLETE FRONT PANEL (FRONT WINGS REMOVED)	57.0	256.50
EA01R0	R + R BATTERY	3.0	13.50
NO NUMBER	DRAIN + REFILL AIR CONDITIONING	7.0	31.50
TB06R0)	R + R CONDENSER (BUMPER REMOVED)	8.0	36.00

K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHA0068

Version: K.KIMHIN/1

Date Calculated: 22/12/2018 01:29

Full Report - V1

Registration: SLN7802R

Printed: 22/12/2018 09:29

Total Excluding Pearlescent Uplift

\$291.40

Pearlescent Uplift @ 0.0%

\$0.00

Total Paint Material Cost

\$291.40

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
281	1	FRONT BUMPER	7171157K10799		0% CM 430.00* ✓
295	1	UPP BUMPER ABSORBER	7239463J00000		0% 0.7 80.00* ?
299	1	LWR BUMPER ABSORBER	7239563J00000		0% R 75.00* ?
300	1	R/F TOWING LUG COVER	7171263J00000		0% S 18.00* X
317	1	L/F BUMPER BRACKET	7173263J00000		0% R 28.00* ?
318	1	R/F BUMPER BRACKET	7173163J00000		0% R 28.00* ?
339	1	ENGINE ROOM COVER	7239363J10000		0% Red 40.00* ?
341	1	L/ENG COMPART COVER	7239763J10000		0% Red 40.00* ?
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0% M 30.00* ✓
410	1	GRILLE	7174157K105PK		0% Red 65.00* ✓
419	1	BUMPER TRIM GRILLE	7172157K005PK		0% D1 60.00* ✓
431	1	FRONT MANUFACT BADGE	7781154GC00PG		0% M 28.00* ✓
471	1	BONNET	5730062J01000		0% B 330.00* ✓
475	1	L/BONNET HINGE	5742063J00000		0% D1 25.00* ✓
476	1	R/BONNET HINGE	5741063J10000		0% D1 25.00* ✓
493	1	BONNET LOCK	8211062J00000		0% R 48.00* ✓
500	1	BONNET CABLE	8216062J00000		0% B 30.00* ?
525	1	FRONT BONNET SEAL	7236163J00000		0% G 28.00* ✓
561	1	L/HEADLAMP CPL	3532062J01000		0% M CM 270.00* ✓
562	1	R/HEADLAMP CPL	3512062J01000		0% 2 270.00* ✓
637	1	L/F FOG LAMP	3550063J04000		0% S 120.00* X
638	1	R/F FOG LAMP	3550063J04000		0% S 120.00* X
647	1	L/F FOG LAMP MLDG	7176157K0038B		0% S 30.00* X
648	1	R/F FOG LAMP MLDG	7175157K0038B		0% S 30.00* X
651	1	L/FOG LAMP COVER	7178157K102KZ	Red	0% 115 S 25.00* X
652	1	R/FOG LAMP COVER	7177157K102KZ	Red	0% 115 25.00* ?
741	1	L/F WING	5771163J10000		0% B 170.00* ✓
742	1	R/F WING	5761163J20000		0% B 170.00* ✓
789	6	L/F WING CLAMP KIT	015500612A000	M	0% M 30.00* X
790	6	R/F WING CLAMP KIT	015500612A000	M	0% M 30.00* X
843	1	L/F WHEELHOUSE COVER	7232263J10000		0% CM 60.00* ?
844	1	R/F WHEELHOUSE COVER	7232163J10000		0% CM 60.00* ?
988	1	CTR FRT PANEL STRUT	5824162J00000		0% D1 40.00* ?
989	1	L/F PANEL STRUT	5812057K00000		0% B 75.00* ?
990	1	R/F PANEL STRUT	5811063J10000		0% B 75.00* ?
1001	1	RADIATOR CROSSMEMBER	5821062J00000		0% R 75.00* ?
1007	1	FRT UPP BUMPER CARR	5827063J10000		0% B 130.00* ✓
1008	1	FRONT LOWER CARRIER	5828062J10000		0% R 115.00* ?
1017	1	CTR LOCK CARRIER	5823062J00000		0% R 70.00* ✓
1019	1	L/BONNET LANDING PNL	5826063J00000		0% D1 55.00* ?
1020	1	R/BONNET LANDING PNL	5825063J00000		0% D1 55.00* ?
4465	1	CONDENSER	9531062J10000		0% M 400.00* ✓
4481	1	COMPR/CONDENSER PIPE	9572062J00000		0% Red 88.00* ?
4483	1	COMPR/EVAP PIPE	9571062J01000		0% S 110.00* ?
4484	1	COND/EVAPORATOR PIPE	9573163J00000		0% S 140.00* X
7761	1	RADIATOR	1770062J00000		0% R 440.00* ?

K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHA0068

Version: K.KIMHIN/1

Date Calculated: 22/12/2018 01:29

Full Report - V1

Registration: SLN7802R

Printed: 22/12/2018 09:29

TB07R0)	R + R AIR CONDITIONING OUTLET PIPE	4.0	18.00
TB07R0)	R + R AIR CONDITIONING RETURN PIPE	4.0	18.00
CA01R0)	R + R RADIATOR (BUMPER REMOVED)	5.0	22.50
DB01R0	R + R AIR CLEANER	4.0	18.00
0245	PANEL WORK FRONT	<i>Nn</i> 30.0* <i>X</i>	135.00
1481	REPAIR LEFT FRONT DOOR	<i>10</i> 30.0* <i>—</i>	135.00
1482	REPAIR RIGHT FRONT DOOR	<i>Nn</i> 30.0* <i>X</i>	135.00

LABOUR COST

Total Work Units	253.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	25.3HRS	\$1,138.50
Paint Labour	17.7HRS	\$796.50
Total Labour	43.0HRS	\$1,935.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- TWO COAT PEARL/MICA		
471	BONNET NEW PART PAINTING	17.0	
741	L/F WING NEW PART PAINTING	10.0	
742	R/F WING NEW PART PAINTING	10.0	
988	CTR FRT PANEL STRUT SURFACE PAINT	4.0	
989	L/F PANEL STRUT SURFACE PAINT	4.0	
990	R/F PANEL STRUT SURFACE PAINT	4.0	
1001	RADIATOR CROSSMEMBERSURFACE PAINT	5.0	
1007	FRT UPP BUMPER CARR SURFACE PAINT	5.0	
1017	CTR LOCK CARRIER SURFACE PAINT	4.0	
1019	L/BONNET LANDING PNLSURFACE PAINT	4.0	
1020	R/BONNET LANDING PNLSURFACE PAINT	4.0	
281	FRONT BUMPER NEW PART PAINT K1R	13.0	
300	R/F TOWING LUG COVERNEW PART PAINT K1R	3.0	
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	26.0	
1482	RIGHT FRONT DOOR REPAIR PAINTING >50%	26.0	
1127	L/F UPP W-HOUSE REINSURFACE PAINT	4.0	
1128	R/F UPP W-HOUSE REINSURFACE PAINT	4.0	

LABOUR COST - PAINT

TIME(PAINT)	147.0	
Preparation Main Work Plastic	5.0	
Preparation Main Work Metal	25.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	177.0	
Total Paintwork Labour	17.7HRS	\$796.50

MATERIAL COST - PAINT

New Part Painting	\$85.65
New Part Painting - Plastic K1R	\$67.89
Material-Constant Main Work Metal	\$28.60
Surface-/Blend Paint	\$29.16
Repair Painting	\$71.10
Material-Const Main Work Plastic	\$9.00

K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHA0068

Version: K.KIMHIN/1

Date Calculated: 22/12/2018 01:29

Full Report - V1

Registration: SLN7802R

Printed: 22/12/2018 09:29

7767	1	RADIATOR SHROUD	1776063J00000	0%	CM	95.00*	2
7769	1	L/RADIATOR BRACKET	1786157K00000	0%	N	12.00*	2x
7770	1	R/RADIATOR BRACKET	1786157K00000	0%	N	12.00*	2x
7773	1	LOWER WATER HOSE	1785462J00000	0%	Sm	25.00*	2x
7776	1	UPPER WATER HOSE	1785262J00000	0%	Sm	22.00*	2x
7790	1	ELECTRIC FAN	1712062J00000	0%	Sm	298.00*	2
7793	1	COOLING FAN	1711163J00000	0%	Cpt	58.00*	2
8373	1	AIR INTAKE TUBE	1376557K00000	0%	Nol	18.00*	2
8390	1	AIR FILTER RESONATOR	1387063J00000	0%	Sm	45.00*	2x
8391	1	AIR FILTER ASSY	1370063J00000	0%	Sm	145.00*	X
1000	1	F/LWR REINFORCMT CVR	Renew	0%	Sm	30.00*	2x
1000	1	F/LWR REINF CVR CLIP	\$3 @ 6PCS	0%	Sm	18.00*	2x
1000	1	RAD TOP BUSH	\$8 @ 2 PCS	0%	Sm	16.00*	X
1000	1	RAD LWR BUSH	\$8 @ 2PCS	0%	Sm	16.00*	X
f: OEM Parts				Sub Total		\$5,496.00	
g: Original				Mark Up From Cost (10 %)		\$549.60	
h: Secondhand				Sundry Parts (Fixed)		\$0.00	
p: Parallel				Total Parts		\$6,045.60	
x: Exchange							

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FRT NUMBER PLATE SPECIALIST	0%	\$120.00
ANTIFREEZE 4 LTR SPECIALIST		\$48.00
TOP UP AIRCON GAS SPECIALIST	0%	\$100.00
BATTERY SPECIALIST		\$280.00
Total Extras		\$548.00

Final Calculation

Total Parts	\$6,045.60
Labour	
Total Panel/Mechanical	\$1,138.50
Total Paintwork	\$796.50
Total Labour	\$1,935.00
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$548.00
Total of Additional Costs	\$548.00
Total Paint/Material Costs	\$291.40
Grand Total Excludes GST	\$8,820.00
GST @ 7 %	\$617.40
Grand Total Includes GST	\$9,437.40

Assessment Notes

K.KIM HIN AUTO PTE LTD
160 Sin Ming Drive
#02-20 Sin Ming AutoCity
Singapore 575722

Claim Reference:
Assessment Number: KKHA0068
Version: K.KIMHIN/2
Date Calculated: 13/03/2019 06:42

Full Report - V1
Registration: SLN7802R
Printed: 13/03/2019 14:53

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SANDRA KHONG	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA

Claim Reference:	Estimated Repair Time:
Policy Number:	Quote Due Date:
Other Reference:	Actual Repair Days:
Third Party:	Parts Ordered Date:
Insured Amount:	Hire Car Start:
Under Warranty:	Hire Car End:
Warranty Expired:	Vehicle Collected:

Vehicle Details

Vehicle

Manufacturer:	SUZUKI
Model:	Swift
Sub Model:	SPORT
Model Sheet Number:	R03 18
Registration:	SLN7802R
Registration Month:	June
Registration Year:	2008
VIN Number:	ZC31S202765
Manufacture Year:	2008
Odometer:	Not Known
Colour:	
Engine Number:	M16A1311910
Fuel Level:	%

Model Specs

AIR CONDITIONING	FOG LAMPS
1.6 LTR 92 KW	5-SPEED
5-DOOR	PREPARE OFF VEHICLE
TWO COAT PEARL/MICA	

Vehicle Condition



Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	21/12/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

K.KIM HIN AUTO PTE LTD

Claim Reference:
 Assessment Number: KKHA0068
 Version: K.KIMHIN/2
 Date Calculated: 13/03/2019 06:42

Full Report - V1
 Registration: SLN7802R
 Printed: 13/03/2019 14:53



Addresses

Cost Summary

Total Labour	\$1,561.50
Total Paint/Material	\$291.40
Total Parts	\$5,591.30
Total of Additional Costs	\$193.00
Excess:	TBA
Grand Total Exc GST:	\$7,637.20
7 % GST:	\$534.60
Grand Total Inc GST:	\$8,171.80

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
 Price/Dent = \$0.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
OP 100	RENEW LEFT FRONT WING INCLUDES: R + R BUMPER, HEADLAMP, DOOR SILL COVER AND WHEELARCH TRIM, ADJUST HEADLAMP	19.0	85.50
NO NUMBER	RENEW R/F WING INCLUDES: R + R HEADLAMP AND WHEELARCH TRIM	11.0	49.50
NO NUMBER	R + R FRONT AIR GUIDE	2.0	9.00
OP 101	RENEW FRONT BUMPER (REMOVED) INCLUDES: R + R RADIATOR GRILLE	7.0	31.50
NO NUMBER	R + R FRONT BUMPER IMPACT DAMPER	2.0	9.00
SA14R0)	R + R L/F FOGLAMP	1.0	4.50
SA14R0)	R + R R/F FOGLAMP	1.0	4.50
OP 110	RENEW BONNET INCLUDES: R + R BONNET	9.0	40.50
OP 131)	RENEW L/BONNET HINGE	1.0	4.50
OP 131)	RENEW R/BONNET HINGE	3.0	13.50
NH21R0)	R + R COWL PANEL TRIM	2.0	9.00
NB03R0	R + R BONNET LOCK	5.0	22.50
NO NUMBER	R + R BONNET SEAL	1.0	4.50
OP 148)	RENEW COMPLETE FRONT PANEL (FRONT WINGS REMOVED)	57.0	256.50
EA01R0	R + R BATTERY	3.0	13.50
NO NUMBER	DRAIN + REFILL AIR CONDITIONING	7.0	31.50
TB02R0)	R + R COMPRESSOR	8.0	36.00
TB06R0)	R + R CONDENSER (BUMPER REMOVED)	8.0	36.00

K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHA0068

Version: K.KIMHIN/2

Date Calculated: 13/03/2019 06:42

Full Report - V1

Registration: SLN7802R

Printed: 13/03/2019 14:53

TB07R0)	R + R AIR CONDITIONING OUTLET PIPE	4.0	18.00
CA01R0)	R + R RADIATOR	5.0	22.50
	(BUMPER REMOVED)		
DB01R0	R + R AIR CLEANER	4.0	18.00
1481	REPAIR LEFT FRONT DOOR	10.0*	45.00
LABOUR COST			
	Total Work Units	170.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	17.0HRS	\$765.00
	Paint Labour	17.7HRS	\$796.50
	Total Labour	34.7HRS	\$1,561.50

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$45.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- TWO COAT PEARL/MICA		
471	BONNET NEW PART PAINTING	17.0	
741	L/F WING NEW PART PAINTING	10.0	
742	R/F WING NEW PART PAINTING	10.0	
988	CTR FRT PANEL STRUT SURFACE PAINT	4.0	
989	L/F PANEL STRUT SURFACE PAINT	4.0	
990	R/F PANEL STRUT SURFACE PAINT	4.0	
1001	RADIATOR CROSSMEMBERSURFACE PAINT	5.0	
1007	FRT UPP BUMPER CARR SURFACE PAINT	5.0	
1017	CTR LOCK CARRIER SURFACE PAINT	4.0	
1019	L/BONNET LANDING PNLSURFACE PAINT	4.0	
1020	R/BONNET LANDING PNLSURFACE PAINT	4.0	
281	FRONT BUMPER NEW PART PAINT K1R	13.0	
300	R/F TOWING LUG COVERNEW PART PAINT K1R	3.0	
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	26.0	
1482	RIGHT FRONT DOOR REPAIR PAINTING >50%	26.0	
1127	L/F UPP W-HOUSE REINSURFACE PAINT	4.0	
1128	R/F UPP W-HOUSE REINSURFACE PAINT	4.0	
LABOUR COST - PAINT			
	TIME(PAINT)	147.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	177.0	
	Total Paintwork Labour	17.7HRS	\$796.50
MATERIAL COST - PAINT			
	New Part Painting		\$85.65
	New Part Painting - Plastic K1R		\$67.89
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$29.16
	Repair Painting		\$71.10
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$291.40
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$291.40

K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHA0068

Version: K.KIMHIN/2

Date Calculated: 13/03/2019 06:42

Full Report - V1

Registration: SLN7802R

Printed: 13/03/2019 14:53

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
281	1	FRONT BUMPER	7171157K10799		0%	430.00*
295	1	UPP BUMPER ABSORBER	7239463J00000		0%	80.00*
299	1	LWR BUMPER ABSORBER	7239563J00000		0%	75.00*
317	1	L/F BUMPER BRACKET	7173263J00000		0%	28.00*
318	1	R/F BUMPER BRACKET	7173163J00000		0%	28.00*
339	1	ENGINE ROOM COVER	7239363J10000		0%	40.00*
341	1	L/ENG COMPART COVER	7239763J10000		0%	40.00*
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0%	30.00*
410	1	GRILLE	7174157K105PK		0%	65.00*
419	1	BUMPER TRIM GRILLE	7172157K005PK		0%	60.00*
431	1	FRONT MANUFACT BADGE	7781154GC00PG		0%	28.00*
471	1	BONNET	5730062J01000		0%	330.00*
475	1	L/BONNET HINGE	5742063J00000		0%	25.00*
476	1	R/BONNET HINGE	5741063J10000		0%	25.00*
493	1	BONNET LOCK	8211062J00000		0%	48.00*
525	1	FRONT BONNET SEAL	7236163J00000		0%	28.00*
561	1	L/HEADLAMP CPL	3532062J01000		0%	270.00*
562	1	R/HEADLAMP CPL	3512062J01000		0%	270.00*
651	1	L/FOG LAMP COVER	7178157K102KZ		0%	115.00*
652	1	R/FOG LAMP COVER	7177157K102KZ		0%	115.00*
741	1	L/F WING	5771163J10000		0%	170.00*
742	1	R/F WING	5761163J20000		0%	170.00*
789	6	L/F WING CLAMP KIT	015500612A000		0%	30.00*
790	6	R/F WING CLAMP KIT	015500612A000		0%	30.00*
843	1	L/F WHEELHOUSE COVER	7232263J10000		0%	60.00*
844	1	R/F WHEELHOUSE COVER	7232163J10000		0%	60.00*
988	1	CTR FRT PANEL STRUT	5824162J00000		0%	40.00*
989	1	L/F PANEL STRUT	5812057K00000		0%	75.00*
990	1	R/F PANEL STRUT	5811063J10000		0%	75.00*
1001	1	RADIATOR CROSSMEMBER	5821062J00000		0%	75.00*
1007	1	FRT UPP BUMPER CARR	5827063J10000		0%	130.00*
1008	1	FRONT LOWER CARRIER	5828062J10000		0%	115.00*
1017	1	CTR LOCK CARRIER	5823062J00000		0%	70.00*
1019	1	L/BONNET LANDING PNL	5826063J00000		0%	55.00*
1020	1	R/BONNET LANDING PNL	5825063J00000		0%	55.00*
4455	1	COMPRESSOR	9520063JA1000		0%	330.00*
4465	1	CONDENSER	9531062J10000		0%	400.00*
4481	1	COMPR/CONDENSER PIPE	9572062J00000		0%	88.00*
7761	1	RADIATOR	1770062J00000		0%	440.00*
7767	1	RADIATOR SHROUD	1776063J00000		0%	95.00*
7790	1	ELECTRIC FAN	1712062J00000		0%	298.00*
7793	1	COOLING FAN	1711163J00000		0%	58.00*
8373	1	AIR INTAKE TUBE	1376557K00000		0%	18.00*
1000	1	RAD TOP BUSH	\$8 @ 2 PCS		0%	16.00*

f: OEM Parts
g: Original
h: Secondhand
p: Parallel
x: Exchange

Sub Total
Mark Up From Cost (10 %)
Sundry Parts (Fixed)
Total Parts

\$5,083.00
\$508.30
\$0.00
\$5,591.30

K.KIM HIN AUTO PTE LTD**Claim Reference:****Assessment Number: KKHA0068****Version: K.KIMHIN/2****Date Calculated: 13/03/2019 06:42****Full Report - V1****Registration: SLN7802R****Printed: 13/03/2019 14:53**

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FRT NUMBER PLATE SPECIALIST	0%	\$45.00
ANTIFREEZE 4 LTR SPECIALIST		\$48.00
TOP UP AIRCON GAS SPECIALIST	0%	\$100.00
Total Extras		\$193.00

Final Calculation

Total Parts		\$5,591.30
Labour		
Total Panel/Mechanical	\$765.00	
Total Paintwork	\$796.50	
Total Labour		\$1,561.50
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$193.00	
Total of Additional Costs		\$193.00
Total Paint/Material Costs		\$291.40
Grand Total Excludes GST		\$7,637.20
GST @ 7 %		\$534.60
Grand Total Includes GST		\$8,171.80

Assessment Notes



友興汽車零件私人有限公司 YEW HENG AUTO PARTS PTE LTD

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708
TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858
Email: yewheng@yewhengauto.sg
Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

TAX INVOICE

M/S: K.KIM HIN AUTO PTE LTD


160 SIN MING DRIVE #02-18/19/20/21
SIN MING AUTOCITY
SINGAPORE 575722

NO: YLI1216741
PAGE: 1
DATE: 29/12/2018
A/C CODE: LYKKH001
TERMS: 60 DAYS

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1, S71711-57K00-799	BUMPER,FRONT	YDS	1	430.00	✓ 430.00
2R S71731-63J10	HOLDER,FR BUMPER SIDE (RH)	YDS	1	28.00	✓ 28.00
3 S71732-63J10	HOLDER,FR BUMPER SIDE (LH) (1N-45A)IPC	YDS	1	28.00	✓ 28.00
4 S09409-08327	CLIP	IQ-1B15	10	3.00	✓ 30.00
5 S58270-63J10	MEMBER,FR BUMPER UPPER	YDS	1	130.00	✓ 130.00
6 S58280-62J00	MEMBER,FR BUMPER LOWER	YDS	1	115.00	✓ 115.00
7 S72394-63J00	ABSORBER,FR BUMPER,UPR	YDS	1	80.00	✓ 80.00
8 S72395-63J00	ABSORBER,FR BUMPER,LWR	YDS	1	75.00	✓ 75.00
9 S71721-57K00-5PK	GRILLE,RADIATOR LOWER	YDS	1	60.00	✓ 60.00
10 S71771-57K00-2KZ	GUARD,FR BUMPER (RH)	YDS	1	115.00	✓ 115.00
11 S71781-57K00-2KZ	GUARD,FR BUMPER,LH	YDS	1	115.00	✓ 115.00
12 S71741-57K00-5PK	GRILLE,RADIATOR	YDS	1	65.00	✓ 65.00
13 S77811-54GC0-0PG	EMBLEM,MARK (S)	YDS	1	28.00	✓ 28.00
S57300-63J00	PANEL,FRONT HOOD	YDS	1	330.00	✓ 330.00
15 S72361-63J00	SEAL,HOOD FRONT	YDS	1	28.00	✓ 28.00
16 S82110-63J00	LATCH,HOOD	YDS	1	48.00	✓ 48.00
17 S57410-63J00	HINGE,FR HOOD,RH	YDS	1	25.00	✓ 25.00
18 S57420-63J00	HINGE,FR HOOD (LH)	YDS	1	25.00	✓ 25.00
19 S57611-73K10	PANEL,FRONT FENDER (RH)	YDS	1	170.00	✓ 170.00
20 S57711-73K10	PANEL,FRONT FENDER (LH)	YDS	1	170.00	✓ 170.00
21 S72321-63J10	LINING,FR FENDER (RH)	YDS	1	60.00	✓ 60.00
22 S72322-63J10	LINING,FR FENDER (LH)	YDS	1	60.00	✓ 60.00
23 S09409-07332	CLIP	YDS	20	3.00	✓ 60.00

Print / GTB / 29/12/2018 11:12:17 AM

...Cont'd





友興汽車零件私人有限公司 YEW HENG AUTO PARTS PTE LTD

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708
TEL: 6743 9658 A/C: 6392 0830 FAX: 6749 0858
Email: yewheng@yewhengauto.sg
Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

TAX INVOICE

M/S : K.KIM HIN AUTO PTE LTD

NO: YLI1216741
PAGE: 2

Part No	Description	Location	Qty	Unit Price	Amount	
				SIN	SIN	
24	S35120-63J40	UNIT,HEAD LAMP (RH)	YDS	1	270.00	✓ 270.00
25	S35320-63J40	UNIT,HEAD LAMP (LH)	YDS	1	270.00	✓ 270.00
26	S58250-63J00	MEMBER,LAMP SUPPORT,RH	YDS	1	55.00	✓ 55.00
27	S58260-63J00	MEMBER,LAMP SUPPORT,LH	YDS	1	55.00	✓ 55.00
28	S58230-63J00	MEMBER,HOOD LOCK	YDS	1	70.00	✓ 70.00
	S58110-63J10	BRACE,LAMP SUPPORT (RH)	YDS	1	75.00	✓ 75.00
30	S58120-57K00	BRACE,LAMP SUPPORT (LH)	YDS	1	75.00	✓ 75.00
31	S58241-63J00	BRACE,HOOD LOCK	YDS	1	40.00	✓ 40.00
32	S58210-63J00	MEMBER,SUPPORT LOWER	YDS	1	75.00	✓ 75.00
33	S95310-63J10	CONDENSER ASSY	YDS	1	400.00	✓ 400.00
34	S95720-63J00	HOSE,DISCHARGE	YDS	1	88.00	✓ 88.00
35	S17700-63J00	RADIATOR ASSY (MT)	YDS	1	440.00	✓ 440.00
36	S17879-75F00	MOUNT,RADIATOR SUPPORT UPPER	YDS	2	8.00	✓ 16.00
37	S72393-73K00	COVER,ENGINE FR (RH)	YDS	1	40.00	✓ 40.00
38	S72397-63J10	COVER,ENGINE UNDER (LH)	YDS	1	40.00	✓ 40.00
39	S17120-80J00	MOTOR,COOLING FAN	YDS	1	298.00	✓ 298.00
40	S17111-63J00	FAN,COOLING	YDS	1	58.00	✓ 58.00
41	S17760-63JB0	SHROUD,RADIATOR	YDS	1	95.00	✓ 95.00
42	S13765-57K00	PIPE,AIR CLNER SUCTION	YDS	1	18.00	✓ 18.00

TOTAL QUANTITY: 71 TOTAL SIN 4,753.00
ADD GST @ 7% 332.71
GRAND TOTAL **SIN 5,085.71**

DELIVERY
ATTN:MENG HUAT
SLN7802R

Print / GTB / 29/12/2018 11:12:21 AM
SALESMAN: GTB

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE





特 立 机 器 贸 易

MEGA POWER ENGINEERING & TRADING

Automobile Air Conditioning System Is Our Business

Head Office: 39 Genting Road Singapore 340485 Tel: 6842 3389 Fax: 6842 3373
Email: mega1989@singnet.com.sg Business Reg. No. 40868100W

TAX INVOICE

GST Reg# : M8-8002998-3
Invoice No. : INV 10093123
Invoice Date : 4-Jan-2019
Terms : 30 DAYS
PO No :
Vehicle No : SLN7807 R1
Chassis No :
Staff : KENTTY


Bill To: KK1001

K.KIM HIN AUTO PTE. LTD.
BLK 160 SIN MING DRIVE
#02-20 SIN MING AUTOCITY
SINGAPORE 575722
Attn : Account Dept

Ship To: A01

K.KIM HIN AUTO PTE. LTD.
BLK 160 SIN MING DRIVE
#02-18/19/20/21 SIN MING AUTOCITY
SINGAPORE 575722
Attn : ZOIE TEH / GUO ZHONG
Tel: 64527018

Remarks:



S/NC	DESCRIPTION	MOQ	BIN	WH	QTY	PRICE	SP	TOTAL (SGD)
PO Number :		DO Number :						
1	CM-01446 SUZ SWIFT ZC21 COMP 4PK/DM JP		1A0541-42	A1	1	330.00		✓ 330.00

Rate : 1 SGD : 1.000000 SGD

Note : Goods sold are not returnable.

All Brand New compressor sold are without warranty.

Late payment is subject to 2% interest per month.

SUB-TOTAL 330.00 SGD
DISC 0.00% (-) SGD
GST 7% 23.10 SGD
AMOUNT 353.10 SGD

This is a computer-generated document.

No signature is required.

Printed on: 04/01/2019 9:39:25

CUSTOMER COPY

Customer Signature & Stamp



Blk 5025, Ang Mo Kio Ind Park 2 #01-5057 S(509328) Tel: 6482 3389 Fax: 6481 1187

No. 13 Kaki Bukit Rd 4 #01-27 Bartley Bld Centre S(417807) Tel: 6305 3389 Fax: 6305 3329

No. 5 Soon Lee St #01-26 Pioneer Point S(627607) Tel: 6252 3389 Fax: 6275 3389

No. 21 Toh Guan Rd East #01-33 Toh Guan Centre S(600009) Tel: 67683399 Fax: 6310 2484



LOCAL
Page 1 of 1

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference:
Assessment Number: KKHA0068
Version: K.KIMHIN/3
Date Calculated: 14/03/2019 06:49

Full Report - V1
Registration: SLN7802R
Printed: 14/03/2019 14:50

Summary Information

Claim			
Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle		Model Specs	
Manufacturer:	SUZUKI	AIR CONDITIONING	FOG LAMPS
Model:	Swift	1.6 LTR 92 KW	5-SPEED
Sub Model:	SPORT	5-DOOR	PREPARE OFF VEHICLE
Model Sheet Number:	R03 18	TWO COAT PEARL/MICA	
Registration:	SLN7802R		
Registration Month:	June		
Registration Year:	2008		
VIN Number:	ZC31S202765		
Manufacture Year:	2008		
Odometer:	Not Known		
Colour:			
Engine Number:	M16A1311910		
Fuel Level:	%		

Vehicle Condition

Vehicle Status		
Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	21/12/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

Claim Reference:

Full Report - V1



Assessment Number: KKHA0068

Registration: SLN7802R

Version: K.KIMHIN/3

Printed: 14/03/2019 14:50

Date Calculated: 14/03/2019 06:49

**Addresses****Cost Summary**

Total Labour	\$1,561.50
Total Paint/Material	\$291.40
Total Parts	\$5,591.30
Total of Additional Costs	\$193.00
Repair Cost Exc GST:	\$7,637.20
Overall Discount (0.0%):	- \$0.00
Excess:	-\$1,200.00
After Deduction -	
Grand Total Exc GST:	\$6,437.20
7 % GST:	\$450.60
Grand Total Inc GST:	\$6,887.80

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR

Price/Dent = \$0.00/HR

Repair /**Guide Number Repair Details**

		WU	Cost Price (\$)
OP 100	RENEW LEFT FRONT WING	19.0	85.50
	INCLUDES: R + R BUMPER, HEADLAMP, DOOR		
	SILL COVER AND WHEELARCH TRIM,		
	ADJUST HEADLAMP		
NO NUMBER	RENEW R/F WING	11.0	49.50
	INCLUDES: R + R HEADLAMP AND WHEELARCH		
	TRIM		
NO NUMBER	R + R FRONT AIR GUIDE	2.0	9.00
OP 101	RENEW FRONT BUMPER	7.0	31.50
	(REMOVED)		
	INCLUDES: R + R RADIATOR GRILLE		
NO NUMBER	R + R FRONT BUMPER IMPACT DAMPER	2.0	9.00
SA14R0)	R + R L/F FOGLAMP	1.0	4.50
SA14R0)	R + R R/F FOGLAMP	1.0	4.50
OP 110	RENEW BONNET	9.0	40.50
	INCLUDES: R + R BONNET		
OP 131)	RENEW L/BONNET HINGE	1.0	4.50
OP 131)	RENEW R/BONNET HINGE	3.0	13.50
NH21R0)	R + R COWL PANEL TRIM	2.0	9.00
NB03R0	R + R BONNET LOCK	5.0	22.50
NO NUMBER	R + R BONNET SEAL	1.0	4.50
OP 148)	RENEW COMPLETE FRONT PANEL	57.0	256.50
	(FRONT WINGS REMOVED)		
EA01R0	R + R BATTERY	3.0	13.50
NO NUMBER	DRAIN + REFILL AIR CONDITIONING	7.0	31.50
TB02R0)	R + R COMPRESSOR	8.0	36.00

Claim Reference:

Full Report - V1

Assessment Number: KKHA0068

Registration: SLN7802R

Version: K.KIMHIN/3

Printed: 14/03/2019 14:50

Date Calculated: 14/03/2019 06:49

TB06R0)	R + R CONDENSER (BUMPER REMOVED)	8.0	36.00
TB07R0)	R + R AIR CONDITIONING OUTLET PIPE	4.0	18.00
CA01R0)	R + R RADIATOR (BUMPER REMOVED)	5.0	22.50
DB01R0	R + R AIR CLEANER	4.0	18.00
1481	REPAIR LEFT FRONT DOOR	10.0*	45.00

LABOUR COST

Total Work Units	170.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	17.0HRS	\$765.00
Paint Labour	17.7HRS	\$796.50
Total Labour	34.7HRS	\$1,561.50

PAINT WORK	Time Basis 10 WU = 1 HR. Price = \$45.00/HR
Guide Number Description	WU Cost Price (\$)

	- PREPARE OFF VEHICLE		
	- TWO COAT PEARL/MICA		
471	BONNET NEW PART PAINTING	17.0	
741	L/F WING NEW PART PAINTING	10.0	
742	R/F WING NEW PART PAINTING	10.0	
988	CTR FRT PANEL STRUT SURFACE PAINT	4.0	
989	L/F PANEL STRUT SURFACE PAINT	4.0	
990	R/F PANEL STRUT SURFACE PAINT	4.0	
1001	RADIATOR CROSSMEMBERSURFACE PAINT	5.0	
1007	FRT UPP BUMPER CARR SURFACE PAINT	5.0	
1017	CTR LOCK CARRIER SURFACE PAINT	4.0	
1019	L/BONNET LANDING PNLSURFACE PAINT	4.0	
1020	R/BONNET LANDING PNLSURFACE PAINT	4.0	
281	FRONT BUMPER NEW PART PAINT K1R	13.0	
300	R/F TOWING LUG COVERNEW PART PAINT K1R	3.0	
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	26.0	
1482	RIGHT FRONT DOOR REPAIR PAINTING >50%	26.0	
1127	L/F UPP W-HOUSE REINSURFACE PAINT	4.0	
1128	R/F UPP W-HOUSE REINSURFACE PAINT	4.0	

LABOUR COST - PAINT

TIME(PAINT)	147.0	
Preparation Main Work Plastic	5.0	
Preparation Main Work Metal	25.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	177.0	
Total Paintwork Labour	17.7HRS	\$796.50

MATERIAL COST - PAINT

New Part Painting	\$85.65
New Part Painting - Plastic K1R	\$67.89
Material-Constant Main Work Metal	\$28.60
Surface-/Blend Paint	\$29.16
Repair Painting	\$71.10
Material-Const Main Work Plastic	\$9.00
Total Excluding Pearlescent Uplift	\$291.40

Claim Reference:

Full Report - V1

Assessment Number: KKHA0068

Registration: SLN7802R

Version: K.KIMHIN/3

Printed: 14/03/2019 14:50

Date Calculated: 14/03/2019 06:49

Pearlescent Uplift @ 0.0%
Total Paint Material Cost

\$0.00
\$291.40

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
281	1	FRONT BUMPER	7171157K10799		0%	430.00*
295	1	UPP BUMPER ABSORBER	7239463J00000		0%	80.00*
299	1	LWR BUMPER ABSORBER	7239563J00000		0%	75.00*
317	1	L/F BUMPER BRACKET	7173263J00000		0%	28.00*
318	1	R/F BUMPER BRACKET	7173163J00000		0%	28.00*
339	1	ENGINE ROOM COVER	7239363J10000		0%	40.00*
341	1	L/ENG COMPART COVER	7239763J10000		0%	40.00*
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0%	30.00*
410	1	GRILLE	7174157K105PK		0%	65.00*
419	1	BUMPER TRIM GRILLE	7172157K005PK		0%	60.00*
431	1	FRONT MANUFACT BADGE	7781154GC00PG		0%	28.00*
471	1	BONNET	5730062J01000		0%	330.00*
475	1	L/BONNET HINGE	5742063J00000		0%	25.00*
476	1	R/BONNET HINGE	5741063J10000		0%	25.00*
493	1	BONNET LOCK	8211062J00000		0%	48.00*
525	1	FRONT BONNET SEAL	7236163J00000		0%	28.00*
561	1	L/HEADLAMP CPL	3532062J01000		0%	270.00*
562	1	R/HEADLAMP CPL	3512062J01000		0%	270.00*
651	1	L/FOG LAMP COVER	7178157K102KZ		0%	115.00*
652	1	R/FOG LAMP COVER	7177157K102KZ		0%	115.00*
741	1	L/F WING	5771163J10000		0%	170.00*
742	1	R/F WING	5761163J20000		0%	170.00*
789	6	L/F WING CLAMP KIT	015500612A000		0%	30.00*
790	6	R/F WING CLAMP KIT	015500612A000		0%	30.00*
843	1	L/F WHEELHOUSE COVER	7232263J10000		0%	60.00*
844	1	R/F WHEELHOUSE COVER	7232163J10000		0%	60.00*
988	1	CTR FRT PANEL STRUT	5824162J00000		0%	40.00*
989	1	L/F PANEL STRUT	5812057K00000		0%	75.00*
990	1	R/F PANEL STRUT	5811063J10000		0%	75.00*
1001	1	RADIATOR CROSSMEMBER	5821062J00000		0%	75.00*
1007	1	FRT UPP BUMPER CARR	5827063J10000		0%	130.00*
1008	1	FRONT LOWER CARRIER	5828062J10000		0%	115.00*
1017	1	CTR LOCK CARRIER	5823062J00000		0%	70.00*
1019	1	L/BONNET LANDING PNL	5826063J00000		0%	55.00*
1020	1	R/BONNET LANDING PNL	5825063J00000		0%	55.00*
4455	1	COMPRESSOR	9520063JA1000		0%	330.00*
4465	1	CONDENSER	9531062J10000		0%	400.00*
4481	1	COMPR/CONDENSER PIPE	9572062J00000		0%	88.00*
7761	1	RADIATOR	1770062J00000		0%	440.00*
7767	1	RADIATOR SHROUD	1776063J00000		0%	95.00*
7790	1	ELECTRIC FAN	1712062J00000		0%	298.00*
7793	1	COOLING FAN	1711163J00000		0%	58.00*
8373	1	AIR INTAKE TUBE	1376557K00000		0%	18.00*
1000	1	RAD TOP BUSH	\$8 @ 2 PCS		0%	16.00*

f: OEM Parts
g: Original
h: Secondhand

Sub Total
Mark Up From Cost (10 %)
Sundry Parts (Fixed)

\$5,083.00
\$508.30
\$0.00

Claim Reference:

Full Report - V1

Assessment Number: KKHA0068

Registration: SLN7802R

Version: K.KIMHIN/3

Printed: 14/03/2019 14:50

Date Calculated: 14/03/2019 06:49

p: Parallel
x: Exchange

Total Parts

\$5,591.30

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FRT NUMBER PLATE SPECIALIST	0%	\$45.00
ANTIFREEZE 4 LTR SPECIALIST		\$48.00
TOP UP AIRCON GAS SPECIALIST	0%	\$100.00
Total Extras		\$193.00

Final Calculation

Total Parts	\$5,591.30
--------------------	-------------------

Labour

Total Panel/Mechanical	\$765.00
Total Paintwork	\$796.50

Total Labour

\$1,561.50

Additional Costs

Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$193.00

Total of Additional Costs

\$193.00

Total Paint/Material Costs

\$291.40

Repair Costs Excludes GST

\$7,637.20

Deductions

Deduction for Excess (Fixed)	-\$1,200.00
--------------------------------	-------------

Total Deductions

-\$1,200.00

Grand Total Excludes GST (After Deduction)

\$6,437.20

GST @ 7 %

\$450.60

Grand Total Includes GST (After Deduction)

\$6,887.80

Assessment Notes