

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 2186J

DATE 22/12/2018 10:07

MAKE :

MODEL : HYUNDAI i40

*CHINA/LKK
RIGHT FRONT*

Fz

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 1,052.20
	Front Bumper Bracket (RH)			\$ 24.60
	Headlamp Support Panel Assy ?			\$ 907.40
	Headlamp (RH)			\$ 1,388.00
	Radiator Expansion Tank ?			\$ 28.30
	Front Fender (RH)			\$ 566.30
	Front Fender Shield (RH) ?			\$ 175.90
	Wiper Container ?			\$ 61.90
	Wiper Container Motor ?			\$ 75.00
	Front Wheel Rim (RH)			\$ 325.30
	Front Wheel Hub Cap (RH)			\$ 107.10
	Front Wheel Bearing ?			\$ 540.50
	Front Shock Absorber (Assy) (RH)			\$ 342.20
	Front Shock Absorber Mounting (RH) ?			\$ 108.80
	Front Drive Shaft (RH) ?			\$ 1,030.80
	Rack & Pinion Assy ?			\$ 969.60
	STG Tie End ?			\$ 62.60
	Stabilizer Bar ?			\$ 252.30
	Stabilizer Bar Bush (RH) ?			\$ 16.40
	Stabilizer Bar Link ?			\$ 61.10
	Stabilizer Bracket ?			\$ 24.00
	Front Suspension Lower Arm (RH) ?			\$ 529.30
	Knuckle Arm (RH) ✓			\$ 552.00
	ABS Sensor ?			\$ 234.00
	SUB TOTAL			\$ 9,435.60
	LESS 20%			\$ 1,887.12
	DISCOUNTED TOTAL			\$ 7,548.48
	Front Tyre (RH) ✓			\$ 216.00
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 500.00
	Wiring			\$ 50.00
	Tuff Kote			\$ 50.00
	Towing Fee			\$ 60.00
	Remove/Refix Undercarriage (FRT)			\$ 200.00
	FRT Wheel Alignment			\$ 80.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	TOTAL LABOUR			\$ 2,080.00
	ESTIMATE TOTAL			\$ 9,844.48

LKK Auto Consultants hence notify
 the insurer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • All prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

50%

Kalin LKK

24/12/18 10:07

4 Days

PIP Before Paint photo


400
~~1,000.00~~
~~500.00~~ *400*
~~50.00~~ *20*
~~50.00~~ *20*
~~60.00~~ *1*
~~200.00~~ *100*
~~80.00~~ *60*
~~150.00~~ *80?*

Nett

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition		
1. Date: <u>21/12/18</u> Time Received: <u>1510</u> 2. <input type="checkbox"/> New <input type="checkbox"/> SPARK Kakis Name of Customer : <u>Ong Han Yang</u> Contact No. : <u>96920916</u> Vehicle No. : <u>SHA 2168J</u> Make / Model / Colour : <u>1400 / Merc</u> Email : _____	3. Vehicle Type: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Taxi (CTPL/CCPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay)	4. Type of Towing: <input checked="" type="checkbox"/> Normal Tow <input type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input type="checkbox"/> Crane-up
7. Location: <u>Anchorvale Link</u>	5. Nature of Service: <input type="checkbox"/> Jumpstart <input checked="" type="checkbox"/> Recovery <input type="checkbox"/> Change Tyre / Battery	6. Parts Replaced/Remarks: _____ _____
9. Preferred Workshop: <input type="checkbox"/> Braddell <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Pandan <input type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Ubi <input type="checkbox"/> Senoko <input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Cycle & Carriage (PD) <input type="checkbox"/> Others: _____	8. Vehicle Tow - In Workshop: <input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed <input type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty <input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty <input type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power <input checked="" type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled <input type="checkbox"/> Return Taxi	11. Radio / CD Player <input type="checkbox"/> OK <input type="checkbox"/> Faulty <input checked="" type="checkbox"/> Not tested
10. Odometer Reading : _____ Fuel Level : <input type="checkbox"/> F <input type="checkbox"/> 1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> E	12. Tow Truck / Recovery Van : <input type="checkbox"/> VRS <input checked="" type="checkbox"/> QA <input type="checkbox"/> GAO <input type="checkbox"/> TZ <input type="checkbox"/> YISHUN <input type="checkbox"/> OTHERS Name of Driver : <u>Parr</u> Vehicle No. : <u>YH291M</u> Time Dispatch : <u>1515</u> Time of Arrival : <u>1535</u> Time Completed : <u>1600</u>	 # : Cracked X : Dented / : Scratched O : Missing _____ Signature of Customer
13. Cash Invoice No. : _____		
Customer Acknowledgement a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc. b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses. c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.		
_____ Date	_____ Time	_____ Signature of Customer
14. WORKSHOP _____ Name of Attending Staff/Guard		
_____ Date & Time of Arrival		
_____ Signature of Attending Staff/Guard		