

## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO : SHC 8514X

DATE 24/12/2018 9:48

MAKE :

MODEL : HYUNDAI i40

Chine  
gm

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille			\$ 1,110.10
	Radiator Grille H Emblem			\$ 39.50
	Front Bumper Cover			\$ 1,052.20
	Front Bumper Sponge			\$ 99.20
	Front Bumper Reinforcement			\$ 402.10
	Front Bumper Bracket Top (LH/RH)?		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH)?		\$ 24.60	\$ 49.20
	<b>SUB TOTAL</b>			<b>\$ 2,797.10</b>
	<b>LESS 20%</b>			<b>\$ 559.42</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 2,237.68</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>350.00</del> 200
	Spray Painting Charge			\$ <del>250.00</del> 200
	<b>TOTAL LABOUR</b>			<b>\$ 600.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,837.68</b>
<p>Kahn (Alc)</p> <p>24/12/18 1020L</p> <p>2 Rm</p> <p>P/P</p> <p>Attn Repair U</p> <div> <p>KK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				