

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

20/12/2018

TPAXA
Ashes.

Accident date: 18/12/2018

Estimated repair cost for vehicle no: SGR3668B MITSUBISHI LANCER 1.6 M '07

S/n	Qty	Items / Nett	U/price	Amount
1	1	Rear Boot Lid <i>Repair</i>		\$587.00 X
2	2	Rear Boot Lid Hinge <i>new</i>	\$69.00	\$138.00 X
3	1	Rear Boot Lid Emblem Logo <i>2</i>		\$45.00 ✓
4	1	Rear Boot Lid Lancer Logo <i>new</i>		\$46.00 ✓
5	1	Rear Boot Lid GLX Logo		\$42.00 ✓
6	1	Rear Boot Lid C&C Logo		\$55.00 ✓
7	1	Rear Boot Lid Inner Lock <i>new</i>		\$125.00 +
8	1	Rear Boot Lid Inner Rubber <i>new</i>		\$158.00 X.
9	1	Rear R/H Tail Lamp <i>Crushed.</i>		\$436.00 <i>334.</i>
10	4	Rear R/H Tail Lamp Clip <i>new</i>	\$8.00	\$32.00 <i>10</i>
11	1	Rear R/H Tail Lamp Panel <i>Dented.</i>		\$121.00 ✓
12	1	Rear Bumper <i>Distorted</i>		\$624.00 ✓
13	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 <i>30</i>
14	2	Rear Bumper Side Retainer <i>new</i>		\$52.00 ✓
15	1	Rear R/H Bumper Mud Shield <i>given</i>		\$63.00 +
16	4	Rear R/H Bumper Mud Shield Clip	\$6.50	\$26.00 +
17	1	Rear Bumper Centre Beam <i>new</i>		\$219.00 X
18	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$350.00 <i>200(su)</i>
19	1	Rear End Panel <i>Distorted</i>		\$398.00 ✓
20	1	Rear End Panel Top Garnish <i>new</i>		\$141.00 X.
21	1	Rear R/H Fender <i>Distorted</i>		\$696.00 ✓
22	1	Rear R/H Fender Inner Trim Board <i>new</i>		\$212.00 +
23	10	Rear R/H Fender Inner Trim Board Clip <i>new</i>	\$6.50	\$65.00 +
24	1	Rear Windscreen Top Moulding <i>new</i>		\$108.00 ✓
25	1	Rear Windscreen Lower Moulding		\$166.00 ✓
26	20	Rear Windscreen Side Moulding Clip <i>new</i>	\$3.50	\$70.00 <i>30</i>
27	1	Rear Exhaust <i>new</i>		\$674.00 X
28	1	Rear Centre Exhaust <i>new</i>		\$628.00 +

2757
2481.30

S.N: 200

Subtotal :- \$6,342.00

Labour charges

To remove & refit cushion	\$280.00 60.
To remove & refit reverse sensor	\$100.00 50.
To remove & refit boot lid top spoiler	2620 \$280.00 x.
To remove & refit rear & centre exhaust	\$380.00 x.
To remove & refit rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
To check wiring	\$100.00 30.
Towing fee	?? \$100.00 50
Tuff kote	\$150.00 50.
Panel beating	\$1,400.00 1200
Spray painting	\$1,400.00 1000
Subtotal :-	<u>\$4,360.00</u>
Total:-	<u>\$10,702.00</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 5301.30
L/S AK
(Nett)

Adrian Lj
L/S 08 Days.

AK