

INS. CASE OWNER:

CC

4, Asm 180

23073, 1/1/18

LKK:

IDAC:

89746

Surveyor:

TAUWUN

DOI:

ASSIGNMENT

12/03/19

Date / Time:

26/12/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKZ 789

Name of Insured:

Goli Lohun

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

21/12/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

58m017jk

Policy No.:

Make / Model:

Place of Accident:

Steven Rd

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

pmv



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

26/12/18
26/12/18

585676-x; SKZ 789, x

02/01/19
11:24am- GROWN TO OI. COMPLETED ACCIDENT
DETAILS 4 KATH-ENDED TP. INFORMED TP
CEAHU, AGREED TO SETTLE IN AUSTRE
NCB 100%.

01/02/19

- SMALL LIABILITY CLIMATE
- GROW TO OI.
- UNOBTAIN IA IN EC.

29/12/19

File -> MIC to JOK.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 02/01/19 - 20P

After call ltr to OI: 01/02/19 - VIC

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

27/12/19

Confirm with:

(Continue)

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS

8442.21

(OI REPAIR-ENDED TP)

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

500.00 (\$ 100 x 5 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only ☐ LOU only ☐

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

Legal Cost

SS

-

Total:

SS

8944.21

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

8944.21

Name 1:

Performance Motors Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Surveyor

Taupkin

REF:

ASM(CAXA)

230 731 110

ASSIGNMENT

From:

Date:

13/13/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

S1956 TE

at Workshop m/s

performance
303 Alexandra Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Kevin
Before 3pm

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

S1956 TE

Yr Regn:

2006 / July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 320i

c.c.

1995

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

085 983

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBALVA 7200 KX 20735

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205 / 55 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

13/3/19

Survey held at

PM L

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

VIP \$ 789.92 Red \$ 648.03 / 438

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	4902L
Vehicle Details	
Vehicle No.:	S1956TE
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Dec 2018
Vehicle Make:	B.M.W.
Vehicle Model:	320I
Primary Colour:	Green
Manufacturing Year:	2006
Engine No.:	A395H670N46B20BA
Chassis No.:	WBAVA72000KX20733
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$42,843.00
Original Registration Date:	28 Jul 2006
First Registration Date:	28 Jul 2006
Transfer Count:	4
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 26 Dec 2018

OK

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

26 DEC 2018

ESTIMATE

Estimate No. : b1 49527
Date Estimated : 26/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Anlleliz Cordero Diaz

City Vista Residences
Singapore
Singapore 228314

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
S1956TE	KX20733	28/07/2006	320iA/4	0

DESCRIPTION

To replace rear bumper, boot, end panel & all attachments
cause by accident.

Painting on rear bumper, boot, end panel & trunk floor

To remove and install boot compartment carpet and garnish
to facilitate repairs.

To check electrical wiring systems at the rear section
for proper function.

To carry out body cavity preservation.
(Per panel) Boot

To carry out body cavity preservation.
(For cut panel)End panel

Sundries.

Total Labour 1: 9,064.00

DESCRIPTION

TAIL END PANEL
BOOTLID
REAR BUMPER SET MOUNTING PARTS
RR BUMPER CARRIER
RR BUMPER LH GUIDE
RR BUMPER RH GUIDE
RR BUMPER CTR GUIDE
RR BUMPER TAILLAMP LH GUIDE
RR BUMPER TAILLAMP RH GUIDE
PDC HOLDER INSIDE LH
PDC HOLDER INSIDE RH
PDC HOLDER OUTSIDE LH
PDC HOLDER OUTSIDE RH

QTY	PRIC	VALUE
1	809.40	809.40
1	1,185.55	1,185.55
1	33.15	33.15
1	434.80	434.80
1	58.50	58.50
1	58.50	58.50
1	32.40	32.40
1	31.10	31.10
1	31.10	31.10
1	8.65	8.65
1	8.55	8.55
1	7.40	7.40
1	7.70	7.70

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 49527
Date Estimated : 26/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
S1956TE	KX20733	28/07/2006	320iA/4	0

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER CTR BOTTOM GUIDE	1	61.20	61.20
RR BUMPER (PDC)	1	1,136.80	1,136.80
RR BUMPER TOW HOOK COVER	1	38.95	38.95
EMBLEM ADHERED REAR 320i	1	64.10	64.10
GROMMET	2	0.75	1.50
PLAQUE 74MM	1	71.25	71.25
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
PDC sensor	1	368.80	368.80
BLIND RIVET AVIBVLB	16	0.55	8.80
SCREW (SF PLUS M5X15)	2	0.55	1.10
(DG/SL) BODY ADHESIVE K5B (195ML)	1	326.80	326.80
PUNCH RIVET N5	8	0.55	4.40
(DG) CLEANER R1 (100ML)	1	26.15	26.15
PUNCH RIVET N4	6	0.55	3.30
(S/L) SEAM SEAL 300ML	1	33.80	33.80

Total Parts : 4,873.95

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 13/3/19 01230 Express SS _____

Surveyor's Name Taufik Sign _____

Surveyor's Tel 97495449 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ FIML Yes / No _____

Surveyor's E-mail Taufik@lkkauto.com

No. of Working Days Recommend 5 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary claim(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

13977.95

Labour 1	:	9,064.00
Parts	:	4,873.95
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	975.66
Grand Total	:	14,913.61

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **

14020.78

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 49527
Date Estimated : 26/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Anlleliz Cordero Diaz
06/03/19 12:00:00 AM
City Vista Residences
Singapore
Singapore 228314

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
S1956TE	KX20733	28/07/2006	320iA/4	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	1.00	2.00	3.00	1.94
# UNDERFLOOR COATING ACTIV.CHARCOAL *	63.40	1.00	3.00	61.50

Total Labour :	0.00
Total Parts :	63.44
Total Labour & Parts :	63.44

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 49527
Date Estimated : 26/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Anlleliz Cordero Diaz
06/03/19 12:00:00 AM
City Vista Residences
Singapore
Singapore 228314

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
S1956TE	KX20733	28/07/2006	320iA/4	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
*① To replace rear bumper and attachments, boot lid include making good the tail end panel and knocking out dents caused by the accident	2550.00	10.00	2,295.00	
*② To spray paint rear bumper, boot lid and tail end panel	2399.00	10.00	2,159.10	
* To remove and install boot compartment carpet and garnish to facilitate repairs	230.00	10.00	207.00	✓
To check electrical wiring systems and lightings at the rear section for proper function	150.00	10.00	135.00	✓
To carry out body cavity preservation (Per panel)	100.00	10.00	90.00	✓
Sundries.	80.00	0.00	80.00	✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,185.55	1.00	3.00	1,149.98 ✓
# EXPANDING NUT *	1.00	2.00	3.00	1.94 ✓
RR BUMPER CARRIER	458.55	1.00	3.00	444.79 ✓
RR BUMPER CTR BOTTOM GUIDE	59.00	1.00	3.00	57.23 ✓
RR BUMPER (PDC)	1,181.65	1.00	3.00	1,146.20 ✓
EMBLEM ADHERED REAR 320i	64.10	1.00	3.00	62.18 ✓
# UNDERFLOOR COATING ACTIV.CHARCOAL *	63.40	1.00	3.00	61.50 ✓

SUPPLEMENTARY ITEMS

Total Labour :	4,966.10
Total Parts :	2,923.82
Total Labour & Parts :	7,889.92
Deduction for Excess :	0.00
Total Repair Costs less Excess:	7,889.92
GST @7%:	552.29
Grand Total :	8,442.21

Nivitha (LKK Auto)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 12 March 2019 5:20 PM
To: assignments
Cc: Kevin Leong Wai Kit
Subject: Re: REQUEST FOR DIRECT SETTLEMENT - S1956TE & SKZ218Y ON 21/12/2018 ***
LKK REF: CC4/ASM18023073/ha3

Dear Sirs

Please arrange survey tomorrow between 8am - 2pm.

Owner will send car in by 8am and collect by 2pm.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP
Sent: Wednesday, 9 January 2019 9:30:17 AM
To: Kevin Leong Wai Kit
Subject: Fw: REQUEST FOR DIRECT SETTLEMENT - S1956TE & SKZ218Y ON 21/12/2018 *** LKK REF:
CC4/ASM18023073/ha3

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Tuesday, 8 January 2019 3:32 PM
To: PBSP
Cc: CS A Team; 甯琨 ©; Vic (LKKAuto); assignments
Subject: RE: REQUEST FOR DIRECT SETTLEMENT - S1956TE & SKZ218Y ON 21/12/2018 *** LKK REF:
CC4/ASM18023073/ha3

Without Prejudice

Dear Sirs/Mdm,

Further to our below email.

Kindly arrange for survey.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."




Service Request Details

Claim

S8M017JK

Reference

None 

Loss Date

21 December 2018

Request Date

26 December 2018

Due Date

2 January 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

26/12/2018 @ 10:47am
Caroline with not in

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

S1956TE

Make

TPVD BMW

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Menu

Service Address

...

Primary Contact/Insured

GOH LAI LIN

1 BUKIT BATOK ST 25, #04-03, 658882, Singapore
97873888

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Catherine Chong (LKK Auto)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Wednesday, 26 December, 2018 9:33 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: REQUEST FOR DIRECT SETTLEMENT - S1956TE & SKZ218Y ON 21/12/2018
Attachments: SKM_558e18122609280.pdf; IMG_8069.JPG; IMG_8071.JPG; IMG_8073.JPG; IMG_8075.JPG; IMG_8077.JPG

Categories: Pragati

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

PK.

Hsiao Tong (LKKAUTO)

From: Taufikh (LKKAUTO)
Sent: Friday, 12 July 2019 12:03 PM
To: 'PBSP'
Cc: Celine Fong (LKKAUTO); Hsiao Tong (LKKAUTO)
Subject: RE: FINAL REPORT/ S1956TE

Hi Caroline,

COR \$7889.92 , 5 days. Subject to insurance approval.

Regards
Taufikh
Lkk Auto

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Thursday, 11 July 2019 5:32 PM
To: taufikh@lkkauto.com; Celine Fong (LKKAUTO); SUR; Joy Irene (LKKAUTO); vicalpeh@lkkauto.com
Subject: Fw: FINAL REPORT/ S1956TE

Gentle reminder

From: PBSP
Sent: Thursday, 4 July 2019 6:33 PM
To: taufikh@lkkauto.com; Joy Irene (LKKAUTO)
Subject: FINAL REPORT/ S1956TE

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 4,966.10

Total Parts : 2,923.82

Total Labour & Parts : 7,889.92

Repair days: 5

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

10 Sin Ming Drive Singapore 575701
www.lta.gov.sg

08 Aug 2018

Our ref 0808180203N057020316

ANLLELIZ CORDERO DIAZ
27 NAPIER ROAD
AMERICAN EMBASSY
SINGAPORE 258508

Dear Sir/Madam

NOTIFICATION ON SUCCESSFUL REPLACEMENT OF VEHICLE REGISTRATION NO. S2431CD WITH VEHICLE REGISTRATION NO. S1956TE

You may be pleased to know that your application of 08 Aug 2018 for replacement of registration number is approved.

2. The details of the vehicle after the transaction are as follows:

Vehicle Registration No. : S1956TE (Previously S2431CD)
Vehicle Make : B.M.W.
Vehicle Model : 320I
Chassis No. : WBAVA72000KX20733
Engine No./ Motor No. : A395H670N46B20BA / -

3. Please change the number plates on your existing vehicle (ie. Chassis No. : WBAVA72000KX20733, Engine No./ Motor No. : A395H670N46B20BA / -) to display the new/ replacement registration number, S1956TE by 11 Aug 2018. It is an offence to keep or use a vehicle without displaying the correct vehicle registration number assigned. The penalty for first offence is a fine not more than \$1,000 or imprisonment of not more than 3 months. For second or subsequent offence, the fine is not more than \$2,000 or imprisonment of not more than 6 months.

4. Please contact our customer service officers on tel: 1800-CALL LTA (1800-2255 582) if you have any questions. You can either quote the Business Transaction Reference No. 20180808101654551453 or the vehicle registration number when making your enquiry.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Foreign Identification Number

Owner ID:

4902L

Vehicle Details

Vehicle No.:

S1956TE

Vehicle to be Exported:

No

Intended Deregistration Date:

22 Dec 2018

Vehicle Make:

B.M.W.

Vehicle Model:

320i

Primary Colour:

Green

Manufacturing Year:

2006

Engine No.:

A395H670N46B20BA

Chassis No.:

WBAVA72000KX20733

Maximum Power Output:

110.0 kW (147 bhp)

Open Market Value:

\$42,843.00

Original Registration Date:

28 Jul 2006

First Registration Date:

28 Jul 2006

Transfer Count:

4

Actual ARF Paid:

\$0.00

Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Rebate Amount:

\$0.00

Total Rebate Amount:**\$0.00**

The information contained herein is correct as at 22 Dec 2018

[OK](#)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 1/4/2019

Survey Details:

Date of loss	21-Dec-18
Date of appointment	26-Dec-18
Date of survey	13-Mar-19
Location of survey	PERFORMANCE MOTORS LIMITED

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	S 1956TE
Make and Model	BMW 320i - 1995cc
Date of registration	28-Jul-06
Parf Rebate	
Market Value (est)	\$ -
Parf Rebate (est)	\$ -
Nett Loss (est)	\$ -

Repair details:

Initial Estimate	13,937.95
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 4,815.45
Check items (estimate)	\$ -
Labour	\$ 4,511.00
Total	\$ 9,326.45
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>5 day</u>
---------------------------	--------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

We have not authorized repairs. We had spoken to Insured Ms Goh where she confirmed accident details and rear-ended TP. Informed TP claim, agreed to settle and aware NCD issues. A letter was sent out to Insured. COR havent finalized yet. NO TP LOD in yet.

Mandate:

Liability(TP)		100%	
Proposed repair cost (w/gst)	\$	9,979.30	TBC
Loss of use (TBC)	\$	-	no. of days
Loss of rental w/gst (TBC)	\$	1,348.20	(\$180 x 7 day)
Loss of income	\$	-	no. of days
LTA search fees	\$	7.45	TBC
Others			
Proposed Total	\$	11,334.95	TBC
***TBC = To Be Confirmed			



Service Request Details

Claim

S8M017JK

Reference

CC4/ASM18023073/T1ha3 

Loss Date

21 December 2018

Report Date

21 Dec 2018 3:48:00 PM

Request Date

26 December 2018

Due Date

26 December 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work

More ▾

Vehicle Information

Make

TPVD BMW

Model

320 2.0i

Service Address

...

Primary Contact/Insured

GOH LAI LIN
1 BUKIT BATOK ST 25, #04-03, 658882, Singapore
97873888

Claim Handler

ANG Richard

richard.angbs@axa.com.sg
Additional Instructions

- Messages3
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

New Message

TYPE



SENT

18/4/19 3:39 PM

FROM

ANG Richard

SUBJECT

Re:<MANDATE IA> S8M017JK

BODY

Hi, pls proceed as per mandate. As for LOR, pls of...



LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Menu

SENT 16/4/19 11:49 AM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT <MANDATE IA> S8M017JK

BODY Dear Richard, We refer to the subject matter. Plea...



TYPE ?

SENT 1/4/19 11:51 AM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT <IA> S8M017JK

BODY Dear Richard, We refer to the subject matter. Plea...



TYPE ?

SENT 27/12/18 11:33 AM

FROM ANG Richard

SUBJECT Pls engage OI on TP's claim & proceed to DS. TY.

BODY .



TYPE ?

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Menu

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

VNI

BODY

Please be informed that vehicle currently not in t...



THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKZ 218Y (Insd veh)	Model:	B.M.W. 320I
	S 1956TE (TP veh)		
Date of Accident:	21/12/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	15,002.23
Final Repair Cost	:	\$	8,442.21
Loss of Use	:	\$	500.00
Rental (if any)	:	\$	
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	8,944.21

Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ 100 _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown			
1)	PERFORMANCE MOTORS LTD	:	\$ 8,944.21

NUR SHAQILAH BTE ABDOL
WAHAB

02/08/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18023073/T1pa3s2

8 SHENTON WAY #24-01
 AXA TOWERSINGAPORE 068811
 ATTN: RICHARD ANG

Date : 02-08-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKZ 218Y	Veh. Inspected	S 1956TE
Policy No.	VPA/P2047917	Coverage (\$)	0.00
Claim No.	S8M017JK	Excess (\$)	0.00
Assign From	RICHARD ANG	Assign Date	26/12/2018

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 320I	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	WBAVA72000KX20733	Colour	GREY
Odometer	085783	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/55R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/55R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/55R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/12/2018	Inspection Date	13/03/2019
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. S 1956TE

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAIL END PANEL (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	809.40	-
1	BOOTLID (SN) (CONSISTENT)	BENT	1,185.55	1,149.98
1	SET REAR BUMPER MOUNTING PARTS (SN) (CONSISTENT)	NOT NECESSARY	33.15	-
1	RR BUMPER CARRIER (SN) (CONSISTENT)	BENT	444.79	444.79
1	RR BUMPER LH GUIDE (SN) (CONSISTENT)	NOT NECESSARY	58.50	-
1	RR BUMPER RH GUIDE (SN) (CONSISTENT)	NOT NECESSARY	58.50	-
1	RR BUMPER CTR GUIDE (SN) (CONSISTENT)	NOT NECESSARY	32.40	-
1	RR BUMPER TAILLAMP LH GUIDE (SN) (CONSISTENT)	NOT NECESSARY	31.10	-
1	RR BUMPER TAILLAMP RH GUIDE (SN) (CONSISTENT)	NOT NECESSARY	31.10	-
1	PDC HOLDER INSIDE LH (SN) (CONSISTENT)	NOT NECESSARY	8.65	-
1	PDC HOLDER INSIDE RH (SN) (CONSISTENT)	NOT NECESSARY	8.55	-
1	PDC HOLDER OUTSIDE LH (SN) (CONSISTENT)	NOT NECESSARY	7.40	-
1	PDC HOLDER OUTSIDE RH (SN) (CONSISTENT)	NOT NECESSARY	7.70	-
1	RR BUMPER CTR BOTTOM GUIDE (SN) (CONSISTENT)	BENT	61.20	57.23
1	RR BUMPER (PDC) (SN) (CONSISTENT)	DEFORMED	1,146.20	1,146.20
1	RR BUMPER TOW HOOK COVER (SN) (CONSISTENT)	NOT NECESSARY	38.95	-
1	EMBLEM ADHERED REAR 320I (SN) (CONSISTENT)	NECESSARY	64.10	62.18
2	GROMMET (SN) (CONSISTENT)	NOT NECESSARY	1.50	-
1	PLAQUE 74MM (SN) (CONSISTENT)	NOT NECESSARY	71.25	-
4	DECOUPLING RING PDC TORQUE CONVERTE (SN) (CONSISTENT)	NOT NECESSARY	20.20	-
1	PDC SENSOR (SN) (CONSISTENT)	NOT NECESSARY	368.80	-
16	BLIND RIVET AVIBVLB (SN) (CONSISTENT)	NOT NECESSARY	8.80	-
2	SCREW (SF PLUS M5X15) (SN) (CONSISTENT)	NOT NECESSARY	1.10	-
1	(DG/SL) BODY ADHESIVE K5B (195ML) (SN) (CONSISTENT)	NOT NECESSARY	326.80	-
8	PUNCH RIVET N5 (SN) (CONSISTENT)	NOT NECESSARY	4.40	-
1	(DG) CLEANER R1 (100ML) (SN) (CONSISTENT)	NOT NECESSARY	26.15	-
6	PUNCH RIVET N4 (SN) (CONSISTENT)	NOT NECESSARY	3.30	-
1	(S/L) SEAM SEAL 300ML (SN) (CONSISTENT)	NOT NECESSARY	33.80	-

Report Ref No. CC4/ASM18023073/T1pa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	150.00	80.00
2	EXPANDING NUT (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	1.94	1.94
1	UNDERFLOOR COATING ACTIV.CHARCOAL (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	61.50	61.50
			5,106.78	3,003.82
	LABOUR			
	TO REPLACE REAR BUMPER, BOOT, END PANEL & ALL ATTACHMENTS CAUSE BY ACCIDENT, INCLUSIVE OF THE REPAIR OF TAIL END PANEL.		5,100.00	2,295.00
	PAINTING ON REAR BUMPER, BOOT, END PANEL & TRUNK FLOOR.		2,717.00	2,159.10
	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.		271.00	207.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	135.00
	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL) BOOT.		118.00	90.00
	TO CARRY OUT BODY CAVITY PERSERVATION. (FOR CUT PANEL) END PANEL.	NOT NECESSARY	531.00	-
			8,914.00	4,886.10
GRAND TOTAL			14,020.78	7,889.92
RECOMMENDED COST OF REPAIRS				7,889.92

Report Ref No. CC4/ASM18023073/T1pa3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.