



# UCB Engineering Pte Ltd

GST Registration Number: 19-9501338-G

Business Reg. No. 199501338G

Our ref: 181202.RGT(PA7700Y)

24<sup>th</sup> December 2018

Ready Go Trading  
25 Elias Road  
#07-12 Ris Grandeur  
Singapore 519931

QUOTATION  
without Prejudice

Dear Sir,

## COST OF REPAIR FOR PA 7700 Y

QTY	DESCRIPTIONS	PRICE S\$
1 pc	LHS panel <i>* check part price less 25%</i>	13,500.00 <i>bt -</i>
4 pcs	Labour charges for dismantle & assemble side window Glass	1,200.00 <i>900</i>
	Labour charges for remove & replace the above damaged parts Dismantle & assemble the passenger seat & checking alignment <i>380</i>	4,200.00 <i>2280</i>
	To putty & spray painting onto complete RHS body panel	1,400.00 <i>900</i>
<b>Total</b>		<b>20,300.00</b>

(SGD: Twenty Thousand Three Hundred Only)

Price quoted above is subjected to 7% GST

Yours faithfully,  
Tan Tiong Chia

*Tan Tiong Chia 97495749  
WP  
77/12/18e*

*8 days - 9 days*

*umpsum  
Resur after repair*

*sure@lkkauto.com*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: