

15/5/2010

INS. CASE OWNER:

CC 4 KEM 18073076, KEM 18073076

LKK:

IDAC:

Surveyor:

Finneth

DOI:

ASSIGNMENT

7/1/9

Date / Time:

26/1/11

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

XD 22975

Name of Insured:

M1 BOON HAT

Insured Tel No.:

HP:

D.O.A:

27/1/18

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LHE MADUKAL SUMAN

Driver Tel No.:

(VL: YES / NO)

Claim No.:

SGM 017 N6 / 89680

Policy No.:

11570438

Make / Model:

MITSUBISHI

Place of Accident:

MIN OF TAMP N6 KH. K
KOUTHWAH KUE 7

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:BH
AnteINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time	STAGE	DATE / PIC
1/1/19	Non-Reporting ltr (1st):	
1/1/19	Non-Reporting ltr (2nd):	
1/1/19	Non-Reporting ltr (Final):	
1/1/19	Notification ltr (if non-pickup):	
1/1/19	Call OI:	
1/1/19	After call ltr to OI:	
1/1/19	Documentation Check List:	Handler Typist
1/1/19	Notification ltr (if non-pickup)	☒
1/1/19	After call ltr to OI:	☒
1/1/19	Authorisation To Act:	☒
1/1/19	Release Voucher:	☒
1/1/19	Final Repair Bill:	☒
1/1/19	Car Rental Invoice:	☒
1/1/19	Towing Invoice:	☒
1/1/19	LTA / GIA:	☒
1/1/19	Medical Bill:	☒
1/1/19	PIR:	☒
1/1/19	Mandate/Reject Instruction:	☒
1/1/19	LOD:	☒
1/1/19	Payment Breakdown Form:	☒
1/1/19	Post-Repair Photos:	☒
1/1/19	Others:	☒

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

Email ☐ Call ☐

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

SS 7012.08

(4 days)

Reduction:

80.76 %

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

Repair Cost:

SS 7503.92

(10 days)

x

\$120

Loss of Rental (LOR):

SS 1200.00

(10 days)

x

\$120

Loss of Use (LOU):

SS -

(\$ x days)

Loss of Income (LOI):

SS -

(\$ x days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GLA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/Independent)

Legal Cost

SS -

Total:

SS 8704.92

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS 8704.92

Name 1:

BH Auto Services Pte Ltd

Payee 2: (Strike if N.A.)

SS -

Name 2:

Payee 3: (Strike if N.A.)

SS -

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$350.

COPY SENT
21/01/2020

✓ GIA

22/09/2002

AES, R BY:

REF: CS/ASM18023076/ Sb

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Jas Tan

of

ASM

Date/Time: 26/22018 10:48am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 2583C

Insured:

XD 2297S

at Workshop m/s

Brt Auto

Tel:

of

Blk 1 Sin Ming Ind Est #01-115

Policy No:

Claim No:

S8M017N(1)

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22/22018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

26/22018 11:25am

Person Contacted:

Yun Shi

Vehicle IN/OUT

Date/Time

Action/Instruction (✓)

Estimate

'Virtual'

SLX 2583C - X

XD 2297S - X

REF: ASM(AXA)

ASSIGNMENT

From: _____ Date: 03012019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX 2583C

at Workshop n/s: BH Auto

of: Blk 1 Sin Ming Ind Est #01-115

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 'Virtual'

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$80k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 13.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLX 2583C Yr Regn: 08/15

Type: ☒ M / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or: Wagon

Make: Peugeot 308 C.C. 1199

Colour: M. Brown A/C: Insured / Std / NI / NA

Sp. Reading: 052651 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VI-3LRHNYWIFSD060168

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: GY 225/45R17

R: M10

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	Rear
R/Bal. 2 mm	R/Bal. 6 mm
L/Bal. 2 mm	L/Bal. 6 mm
D.O.A. 22/12/18	D.O.I. 3/1/19

Survey held at: _____

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
4/1	Don't Inspected
	File para to Corbin

PIR \$7012.08 (Redv. \$11,180.76/bi/7)

* 4 repair days + 2 sat + 2 sun + 2 PRS = 10 days.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation

2)

Add Fee: ☐ : Site Insp (\$)

) \$ + RS \$

☐ : Interview (\$)

) Photos

☐ : Tech. Invs (\$)

) Others

☐ : Weekend (\$)

) -

Report Format :

Lump Sum / I.B.I.: (\$)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18023076/Keb3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 26-12-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 2297S	Veh. Inspected	SLX 2583C	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M017NG	Excess (\$)	0.00	
Assign From	SMART CLAIM (JAS TAN)	Assign Date	26/12/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/12/2018	Inspection Date	03/01/2019	
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference:
Assessment number: BA1037
Version: 1712
Date calculated: 01/02/2019 06:39 PM

Full Report
Registration: SLX2583C
Printed: 01/02/2019 6:43 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Janice Koh	Currency:	SGD
Claim Reference:		Date of Incident:	2018-12-22
Estimated Repair Time:	12	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	PEUGEOT
Model:	308 II SW L
Sub Model:	ALLURE
Model Sheet Number:	11 4C 04
Registration:	SLX2583C
VIN number:	
Odometer:	

Model Specs

BLIND SPOT SENSOR	REAR PARKING SYSTEM	REARVIEW CAMERA	PARK-ASSIST
-------------------	---------------------	-----------------	-------------

BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference: SLX2583C
 Assessment number: BA1037
 Version: 1810

Date calculated: 17/05/2019 11:35 AM

Full Report
 Registration: SLX2583C
 Printed: 17/05/2019 11:35 AM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection: 25/01/19

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
92.E9KA)	R + R RIGHT REAR SIDE WINDOW GLASS	6.0		27.00
74.EJ2A	R + R REAR BUMPER	11.0		49.50
	INCLUDES: R + R TAILLAMPS			
74.EMGA)	RENEW REAR BUMPER	6.0		27.00
NO NUMBER	R + R REAR PARKING SYSTEM SENSOR/S	7.0		31.50
NO NUMBER	R + R REAR CENTRE BUMPER BRACKET	2.0		9.00
74.EP9A)	R + R TAILGATE	12.0		54.00
74.E16A)	RENEW TAILGATE (REMOVED)	2.0		9.00
92.E1US	R + R REAR SCREEN	20.0		90.00
63.E6AA)	REPLACE BOTH REAR LIGHTS (REMOVED)	2.0		9.00
70.EDXA	R + R LEFT BOOT TRIM	4.0		18.00
70.EDXA	R + R RIGHT BOOT TRIM	4.0		18.00
70.E1PA	R + R REAR PANEL TRIM	2.0		9.00
2711	REAR PANEL CPL REPAIR	25.0*		112.50
3482	R/R WING REPAIR	25 45.0*		202.50
				112.50

BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference: SLX2583C

Assessment number: BA1037

Version: 1810

Date calculated: 17/05/2019 11:35 AM

Full Report

Registration: SLX2583C

Printed: 17/05/2019 11:35 AM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	14.80	148.0	666.00
Total of Labour			666.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description	WU Price SGD
	BOOTLID/TAILGATE NEW PART PAINTING	18.0
	REAR BUMPER NEW PART PAINT K1R	11.0
	L/R INN PARKING SENS NEW PART PAINT K1R	3.0
	R/R INN PARKING SENS NEW PART PAINT K1R	3.0
	REAR PANEL CPL REPAIR PAINTING <50%	9.0
	R/R WING REPAIR PAINTING <50%	14.0

Paint Material Per Part

Code	Description	Price SGD
2931	BOOTLID/TAILGATE NEW PART PAINTING	47.96
2581	REAR BUMPER NEW PART PAINT K1R	44.32
2655	L/R INN PARKING SENS NEW PART PAINT K1R	0.35
2656	R/R INN PARKING SENS NEW PART PAINT K1R	0.35
2711	REAR PANEL CPL REPAIR PAINTING <50%	7.25
3482	R/R WING REPAIR PAINTING <50%	18.25

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		58.0	
Preparation Main Work Metal	1.70	17.0	76.50
Preparation Comp. Work Plastic	0.30	3.0	13.50
Total	10 WU/h	78.0	351.00

Material Cost - Paint	Price SGD
New Part Painting	47.96
New Part Painting - Plastic K1R	45.02
Repair Painting	25.50
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	145.58

BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference: SLX2583C

Assessment number: BA1037

Version: 1810

Date calculated: 17/05/2019 11:35 AM

Full Report

Registration: SLX2583C

Printed: 17/05/2019 11:35 AM

Spare Parts

				prices as at 2001-01-01
Code	Description	Part Number	Supplier	Price SGD
2581	REAR BUMPER	16 116 091 80		540.00
2627	RR BUMPER BRKT SET	16 116 165 80		60.00
2628	RR CTR BUMPER BRKT	98 009 819 80		55.00
2655	L/R INN PARKING SENS	16 083 217 80		135.00
2656	R/R INN PARKING SENS	16 083 217 80		135.00
2673	RR SENSOR BRKT SET	16 116 163 80		115.00
2679	RR CAMERA BRACKET	98 048 581 80		20.00
2931	BOOTLID/TAILGATE	16 116 371 80		1,980.00
2975	TAILGATE CONTROL	96 760 283 80		95.00
2977	BOOT/TAILGATE LOCK	98 047 620 80		130.00
3013	BADGE "308"	98 058 297 VD		65.00
3020	REAR BADGE	98 057 002 VD		65.00
3160	REAR SCREEN BOND KIT	16 188 585 80		0.00
3281	L/R LAMP	96 780 939 80		340.00
3282	R/R LAMP	96 780 938 80		340.00
3283	L/R INNER LAMP	96 780 980 80		290.00
3284	R/R INNER LAMP	96 780 948 80		290.00
3285	L/R REFLECTOR	98 043 152 80		45.00
3862	R/S WINDOW BOND KIT	16 188 585 80		0.00
4907	LOWER TAILGATE TRIM	98 018 952 ZD		Ref 240.00 ✓
4986	REAR SILL TRIM	98 133 886 ZD		Ref 190.00 ✓
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			5,130.00
u: Used parts	Addition(+15.00%)			769.50
	Total			5,899.50

Extras

Code	Description	Price SGD
1000	sealant Rear windscreen	50.00* 40.50
	Total Extras	50.00

BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference: SLX2583C

Assessment number: BA1037

Version: 1810

Date calculated: 17/05/2019 11:35 AM

Full Report

Registration: SLX2583C

Printed: 17/05/2019 11:35 AM

Final Calculation

	SGD	SGD
Parts	5,130.00	
Addition(+15.00%)	769.50	
Total Parts		5,899.50
Labour Time Base 10 WU/h		
Total 148.0 WU X 45.00 SGD/h	666.00	
Total of Labour		666.00
Total Of Extras		50.00
Paint Work Time Base 10 WU/h		
Labour Cost 78.0 WU X 45.00 SGD/h	351.00	
Material Cost	145.58	
Total Paint Including Material		496.58
Repair Cost Excludes GST		7,112.08
GST (+7.0%)		497.85
Repair Cost Included GST		7,609.93

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Kw

BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference: SLX2583C

Assessment number: BA1037

Version: 1810

Date calculated: 17/05/2019 11:35 AM

Full Report

Registration: SLX2583C

Printed: 17/05/2019 11:35 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Janice Koh	Currency:	SGD
Claim Reference:	SLX2583C	Date of Incident:	22/12/18
Estimated Repair Time:	12	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	PEUGEOT
Model:	308 II SW L
Sub Model:	ALLURE
Model Sheet Number:	11 4C 04
Registration:	SLX2583C
VIN number:	
Odometer:	

Model Specs

BLIND SPOT SENSOR	REAR PARKING SYSTEM	REARVIEW CAMERA	PARK-ASSIST
-------------------	---------------------	-----------------	-------------

BH Auto Services Pte Ltd

1 Sin Ming Industrial Est Sector C

575636

Claim Reference:

Assessment number: BA1037

Version: 1712

Date calculated: 01/02/2019 06:39 PM

Full Report

Registration: SLX2583C

Printed: 01/02/2019 6:43 PM

Vehicle Condition

Vehicle Status


Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐

Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
72.F5RA	RENEW REAR FLOOR PANEL INCLUDES: RENEW REAR PANEL		98.0	441.00
72.F5SA	STRIP + RETRIM REAR FLOOR PANEL INCLUDES: R + R REAR BUMPER, TAIL LAMPS AND ALL NECESSARY TRIMS		21.0	94.50
NO NUMBER	RENEW R/R WING INCLUDES: R + R REAR DOOR SEAL, REAR STRIKER PIN AND NECESSARY TRIMS		56.0	252.00
92.E9KA)	R + R RIGHT REAR SIDE WINDOW GLASS		6.0	27.00
NO NUMBER	RENEW L/TAILLAMP PANEL		20.0	90.00
NO NUMBER	RENEW R/TAILLAMP PANEL		20.0	90.00
74.EMGA)	RENEW REAR BUMPER		6.0	27.00
NO NUMBER	R + R REAR PARKING SYSTEM SENSOR/S		7.0	31.50
74.EP9A)	R + R TAILGATE		12.0	54.00
74.E16A)	RENEW TAILGATE (REMOVED)		2.0	9.00
92.E1US	R + R REAR SCREEN		20.0	90.00

BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference:

Assessment number: BA1037

Version: 1712

Date calculated: 01/02/2019 06:39 PM

Full Report

Registration: SLX2583C

Printed: 01/02/2019 6:43 PM

Code	Description	WU	Price SGD
74.EPGA)	R + R TAILGATE HINGE/S	2.0	9.00
63.E6AA)	REPLACE BOTH REAR LIGHTS (REMOVED)	2.0	9.00
75.E8VA)	R + R L/BOOT TRIM (REMOVED)	1.0	4.50
75.E8VA)	R + R R/BOOT TRIM (REMOVED)	1.0	4.50
70.E2LA	R + R HEADLINING	11.0	49.50
Labour Cost		Hrs	WU
Panel / Mechanical Labour		28.50	285.0
Total of Labour			1,282.50

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description	WU Price SGD
	REAR PANEL CPL NEW PART PAINTING	15.0
	BOOTLID/TAILGATE NEW PART PAINTING	18.0
	R/R WING NEW PART PAINTING	26.0
	L/R LAMP PANEL SURFACE PAINT	4.0
	R/R LAMP PANEL SURFACE PAINT	4.0
	REAR BUMPER NEW PART PAINT K1R	11.0
	L/R INN PARKING SENS NEW PART PAINT K1R	3.0
	R/R INN PARKING SENS NEW PART PAINT K1R	3.0
	L/R OUT PARKING SENS NEW PART PAINT K1R	3.0
	R/R OUT PARKING SENS NEW PART PAINT K1R	3.0
	REAR FLOOR PANEL SURFACE PAINT PLAST.	10.0

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL CPL NEW PART PAINTING	12.67
2931	BOOTLID/TAILGATE NEW PART PAINTING	47.96
3482	R/R WING NEW PART PAINTING	31.90
3579	L/R LAMP PANEL SURFACE PAINT	0.70
3580	R/R LAMP PANEL SURFACE PAINT	0.70
2581	REAR BUMPER NEW PART PAINT K1R	44.32
2655	L/R INN PARKING SENS NEW PART PAINT K1R	0.35
2656	R/R INN PARKING SENS NEW PART PAINT K1R	0.35
2657	L/R OUT PARKING SENS NEW PART PAINT K1R	0.35
2658	R/R OUT PARKING SENS NEW PART PAINT K1R	0.35
3901	REAR FLOOR PANEL SURFACE PAINT PLAST.	39.93

BH Auto Services Pte Ltd

1 Sin Ming Industrial Est Sector C

575636

Claim Reference:

Assessment number: BA1037

Version: 1712

Date calculated: 01/02/2019 06:39 PM

Full Report

Registration: SLX2583C

Printed: 01/02/2019 6:43 PM

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		100.0	
Preparation Main Work Metal	1.70	17.0	76.50
Preparation Comp. Work Plastic	0.30	3.0	13.50
Total	10 WU/h	12.00	540.00

Material Cost - Paint

	Price SGD
New Part Painting	92.53
New Part Painting - Plastic K1R	45.72
Surface-/Blend Paint	1.40
Surface Painting Plastic	39.93
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	206.68

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2001-01-01	Price SGD
2581	REAR BUMPER	16 116 091 80	CRA	540 ✓	900.00
2593	REAR BUMPER SKIRT	98 009 970 XT	FM	X	130.00
2627	RR BUMPER BRKT SET	16 116 165 80	NEC	✓ 20	50.00
2628	RR CTR BUMPER BRKT	98 009 819 80	NEC	55 ✓	65.00
2636	RR BUMPER BRKT SET	16 116 167 80	NN	✓	55.00
2640	REAR BUMPER C-MEMBER	96 773 784 80	SVC	✓	390.00
2655	L/R INN PARKING SENS	16 083 217 80	FM	✓	85.00
2656	R/R INN PARKING SENS	16 083 217 80	FM	✓	85.00
2657	L/R OUT PARKING SENS	16 083 217 80	FM	✓	85.00
2658	R/R OUT PARKING SENS	16 083 217 80	FM	✓	85.00
2673	RR SENSOR BRKT SET	16 116 163 80	NEC	✓	115.00
2677	RR CAMERA	98 125 039 80	NN	✓	260.00
2679	RR CAMERA BRACKET	98 048 581 80	NEC	✓	20.00
2681	RR CAMERA TRIM	98 027 637 XT	NN	✓	0.00
2702	REAR NUMBER PLATE	KNPL6	FM	✓	35.00
2711	REAR PANEL CPL	16 109 141 80	FM	✓	680.00
2931	BOOTLID/TAILGATE	16 116 371 80	CRA	✓	1,400.00
2944	BOOT/TAILGATE SEAL	98 062 494 80	AN SVC	✓	195.00
2953	L/TAILGATE HINGE	96 787 958 80	B	✓	90.00
2954	R/TAILGATE HINGE	96 778 301 80	A	✓	90.00
2973	T-GATE LOCK STRIKER	8724 J1	K	✓	55.00

BH Auto Services Pte Ltd

1 Sin Ming Industrial Est Sector C

575636

Claim Reference:

Assessment number: BA1037

Version: 1712

Date calculated: 01/02/2019 06:39 PM

Full Report

Registration: SLX2583C

Printed: 01/02/2019 6:43 PM

Code	Description	Part Number	Supplier	Price SGD
2975	TAILGATE CONTROL	96 760 283 80	DGM	50.00
2977	BOOT/TAILGATE LOCK	98 047 620 80	DGM	80.00
2997	L/TAILGATE STAY	98 003 773 80	sn	55.00
2998	R/TAILGATE STAY	98 003 773 80	sn	55.00
3013	BADGE "308"	98 058 297 VD	sn	58.00
3020	REAR BADGE	98 057 002 VD	sn	28.00
3160	REAR SCREEN BOND KIT	16 188 585 80	sn	0.00
3221	REAR WIPER MOTOR	98 195 231 80	sn	185.00
3225	REAR WIPER ARM	16 094 283 80	sn	75.00
3281	L/R LAMP	96 780 939 80	CM	220.00
3282	R/R LAMP	96 780 938 80	CM	220.00
3283	L/R INNER LAMP	96 780 980 80	Bu	170.00
3284	R/R INNER LAMP	96 780 948 80	Bu	170.00
3285	L/R REFLECTOR	98 043 152 80	sn	30.00
3286	R/R REFLECTOR	98 043 134 80	sn	30.00
3361	L/NUMBER PLATE LAMP	6340 G3	nn	18.00
3362	R/NUMBER PLATE LAMP	6340 G3	nn	18.00
3482	R/R WING	16 115 032 80	R	2,400.00
3579	L/R LAMP PANEL	98 105 306 80	R	250.00
3580	R/R LAMP PANEL	98 105 305 80	R	250.00
3862	R/S WINDOW BOND KIT	16 188 585 80	sn	0.00
3901	REAR FLOOR PANEL	98 036 970 80	R	1,150.00
4202	R/R WHEELHOUSE CVR	96 785 667 80	R	210.00
4907	LOWER TAILGATE TRIM	98 018 952 ZD	Bu	440.00
4908	UPPER TAILGATE TRIM	98 019 088 ZD	nn	270.00
4978	LUGG COMPART CARPET	16 112 705 ZD	R	550.00
4981	L/BOOT TRIM COVER	98 089 204 ZD	sn	650.00
4982	R/BOOT TRIM COVER	98 089 202 ZD	sn	650.00
4986	REAR SILL TRIM	98 133 886 ZD	sn	250.00
4997	JACK HOUSING	98 058 205 80	R	380.00
1000	5 X 10 PCS	Trim board clip	nn	5.00
1001	Flap cover LH	Trim board	sn	48.00
1002	Rear bumper	Sensor wiring	sn	240.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings

Subtotal

Addition(+15.00%)

Sundry Parts(+2.0%)

Total

Deductions

0.00

14,055.00

2,108.25

6.74

16,169.99

-6.33

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference:
 Assessment number: BA1037
 Version: 1712
 Date calculated: 01/02/2019 06:39 PM

Full Report
 Registration: SLX2583C
 Printed: 01/02/2019 6:43 PM

Final Calculation

	SGD	SGD
Parts	14,055.00	
Addition(+15.00%)	2,108.25	
Sundry Parts(+2.0%)	6.74	17600.59
Total Parts		16,169.99
Labour Time Base 10 WU/h		
Total 285.0 WU X 45.00 SGD/h	1,282.50	666
Total of Labour		1,282.50
Paint Work Time Base 10 WU/h		
Labour Cost 120.0 WU X 45.00 SGD/h	540.00	351
Material Cost	206.68	145.58
Total Paint Including Material		746.68
Repair Cost Excludes GST		18,199.17
GST (+7.0%)		1,273.94
Repair Cost Included GST		19,473.11
Deductions (Excludes GST)		
Betterment Deduction From Parts	-6.33	
Total Of Deductions (Excludes GST)		-6.33
Grand Total Excludes GST		18,192.84
GST (+7.0%)		1,273.50
Grand Total Included GST		19,466.34

Not Authorised
1.B.1
Return by paint
4 days

19 679.77

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Singapore NRIC

Owner ID:

5813Z

Vehicle Details

Vehicle No.:

SLX2583C

Vehicle to be Exported:

No

Intended Deregistration Date:

24 Dec 2018

Vehicle Make:

PEUGEOT

Vehicle Model:

308 SW ALLURE PURETECH 1.2 A/T 2WD S/R

Primary Colour:

Brown

Manufacturing Year:

2015

Engine No.:

10XT180058260

Chassis No.:

VF3LRHNYWFS060168

Maximum Power Output:

96.0 kW (128 bhp)

Open Market Value:

\$20,493.00

Original Registration Date:

28 Aug 2015

First Registration Date:

28 Aug 2015

Transfer Count:

1

Actual ARF Paid:

\$10,691.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

27 Aug 2025

PARF Rebate Amount:

\$8,018.00

Intended COE Rebate Details

COE Expiry Date:

27 Aug 2025

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$57,498.00

COE Rebate Amount:

\$38,378.00

Total Rebate Amount:**\$46,396.00**

The information contained herein is correct as at 24 Dec 2018

OK

500+ dealers
competed to
buy my car!



Sell ur Car for More Cash
Highest Price or Get \$100 Free
Get Paid Now, Handover Later

SELL YOUR CAR



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 10 Years Coe Renewal Toyota Estima 2.4A



2.88% p.a. Lowest Interest @ GV
Cars Financing \$5800
Downpayment Monthly From
\$988
GV Credit Pte Ltd StarAd

PRIME MOTOR & LEASING
(SHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)
With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.

Browse by Category

Sort by Date Posted

20 results/page

4 vehicles

Peugeot 308

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Peugeot 308	Any	Any	2015	Any	Any	Any	Available
	Peugeot 308 SW 1.2A PureTech Allure	\$56,800	\$8,500 /yr	15-May-2015	1,199 cc	42,000 km	Stationwagon	Available
Car House Group Year End Promotion! All Pre-Owned Cars Purchased Within 24th-26th December Will Be Delivered By 31st December! Enjoy Promotional 2.18% Interest Rates! Free Sta Evaluation Report And Ma...								
Posted: 23-Dec-2018 Tags: 2015 Peugeot 308, 2015 peugeot 308, Peugeot 308, peugeot 308, Peugeot, 308, Used Peugeot								
	Peugeot 308 1.2A PureTech	\$56,000	\$8,660 /yr	27-Feb-2015	1,199 cc	33,000 km	Hatchback	Available
1 Owner, Lowest Priced In The Market At Just 8K Depre/Year! \$12,000 Driveaway! Agent Unit With Full Service History, High Spec Active Model. This Unit Comes With 2 Years Warranty By Agent. Low Mileage...								
Bavarian Marques Pte Ltd								
Posted: 19-Dec-2018 Tags: 2015 Peugeot 308, 2015 peugeot 308, Peugeot 308, peugeot 308, Peugeot, 308, Used Peugeot								
	Peugeot 308 1.2A PureTech	\$65,900	\$10,010 /yr	24-Apr-2015	1,199 cc	57,089 km	Hatchback	Available
Irresistible Offer! Selling \$1k Above Scrap! High Paper Value Drive With Assurance! All Our Quality Consignment Cars Are Selling At The Most Reasonable With A Peace Of Mind! STA/VICOM Inspection Welco...								
CarQuotz Singapore								
Posted: 04-Dec-2018 Tags: 2015 Peugeot 308, 2015 peugeot 308, Peugeot 308, peugeot 308, Peugeot, 308, Used Peugeot								
	Peugeot 308 SW 1.2A PureTech Allure	\$80,000	\$11,240 /yr	31-Jul-2015	1,199 cc	45,000 km	Stationwagon	Available
Beautiful Condition. 1 Owner. Special Interest Rate For In House Finance. Call For Viewing.								
Posted: 25-Oct-2018 Tags: 2015 Peugeot 308, 2015 peugeot 308, Peugeot 308, peugeot 308, Peugeot, 308, Used Peugeot								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Peugeot 308, Peugeot 308 Singapore, used Peugeot 308 Singapore, used Peugeot 308, used vehicles Singapore or even buy used Peugeot 308 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2018 sgCarMart. All rights reserved.

Compare



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9781 / 6745 9039



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 6792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

BH AUTO SERVICES PTE LTD

BLK 1, #01-115

SIN MING INDUSTRIAL SECTOR C

[MUST WRITE PO]

SINGAPORE 575636

TEL : 65598944 FAX : 62692404

ATTN : K.T.CHEONG 9101 3232 ERIC/ JANICE

VF3LRHNYWFS060168

TAX INVOICE : AR201902-09796

DATE : 26/02/2019

CUSTOMER ID : BHA001

VEH REG. NO. : SLX2583C

TERMS : 60 days

PO NO. : 2672

PAGE NO. : Page 1 of 2

CURR : S\$

STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 1611637180	2931 TAIL GATE	CC CC10-A-07FRT	1	1980.00	1,980.00
2. 98018952ZD	4907 TAIL GATE INNER TRIM	CC CC10-G-07B	1	240.00	240.00
3. 98057002VD	3020 REAR TAIL GATE BADGE	CC CC10-J-08BK	1	65.00	65.00
4. 98058297VD	3013 308 BADGE	CC CC10-F-10AF	1	65.00	65.00
5. 9804762080	2977 REAR TAIL GATE LOCK	CC CC10-J-08BF	1	130.00	130.00
6. 6490 RZ	2975 REAR BOOT SWITCH	CC CC10-J-08BB	1	95.00	95.00
7. 9678098080	3283 TAIL GATE LAMP LH	CC CC10-F-10B	1	290.00	290.00

CONTINUE NEXT PAGE

[P] 26/02/2019 12:18:13PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 26/02/2019 11:54:45AM



日美汽車私人有限公司

JAE AUTO PTE LTD

BLK 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:


48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Arrange By	Driver
------------	--------



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea)
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

BH AUTO SERVICES PTE LTD
BLK 1, #01-115
SIN MING IND EST SECTOR C
[MUST WRITE PO]
SINGAPORE 575636
TEL : 65598944 FAX : 62692404
ATTN : K.T.CHEONG 9101 3232 ERIC/ JANICE
VF3LRHNYWFS060168

TAX INVOICE : AR201902-09796
DATE : 26/02/2019
CUSTOMER ID : BHA001
VEH REG. NO. : SLX2583C
TERMS : 60 days
PO NO. : 2672
PAGE NO. : Page 2 of 2
CURR : S\$

STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
8. 9678094880	3284 TAIL GATE LAMP RH	CC CC10-F-08C	1	290.00	290.00
9. 9678093980	3281 TAIL LAMP LH	CC CC10-I-04C	1	340.00	340.00
10. 9678093880	3282 TAIL LAMP RH	CC CC10-F-09B	1	340.00	340.00
11. 1611609180	2581 REAR BUMPER	CC CC10-B-09A	1	540.00	540.00
12. 9800981980	2628 REAR BUMPER CENTRE BRACKET	CC CC10-G-09C	1	55.00	55.00
13. 1608321780	2655/2656 PARKING SENSOR	CC CC10-D-10AB	2	135.00	270.00
14. 98133886ZD	4986 REAR END PANEL TRIM	CC CC10-G-07C	1	190.00	190.00

SUB-TOTAL : 4,890.00
ADD GST 7.00 % 342.30

E. & O E TOTAL AMOUNT S\$: 5,232.30

[P] 26/02/2019 12:18:13PM

[E] 26/02/2019 11:54:45AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: CHONG

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9529



TOYOTA

LEXUS

DAIHATSU

Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9754

Dept Direct: 6417 9755

Dept Direct: 6417 9756

Dept Direct: 6417 9757

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

BH AUTO SERVICES PTE LTD
BLK 1, #01-115
SIN MING IND EST SECTOR C
[MUST WRITE PO]
SINGAPORE 575636
TEL : 65598944 FAX : 62692404
ATTN : K.T.CHEONG 9101 3232 ERIC/ JANICE
VF3LRHNYWFS060168

TAX INVOICE : AR201903-00769
DATE : 02/03/2019
CUSTOMER ID : BHA001
VEH REG. NO. : SLX2583C
TERMS : 60 days
PO NO. : 2682
PAGE NO. : Page 1 of 1
CURR : S\$

STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 1611616780	REAR BUMPER SIDE RETAINER SET 2627	CC CC10-I-070B	1	60.00	60.00

SUB-TOTAL : 60.00
ADD GST 7.00 % 4.20

E. & O.E

TOTAL AMOUNT S\$: 64.20

[P] 02/03/2019 10:25:43AM

[E] 02/03/2019 10:19:56AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: CHONG

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

BH AUTO SERVICES PTE LTD
BLK 1, #01-115
SIN MING IND EST SECTOR C
[MUST WRITE PO]
SINGAPORE 575636
TEL : 65598944 FAX : 62692404
ATTN : K.T.CHEONG 9101 3232 ERIC/ JANICE
VF3LRHNYWFS060168

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9754

Dept Direct: 6417 9755

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade) Sliper (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201902-09797
DATE : 26/02/2019
CUSTOMER ID : BHA001
VEH REG. NO. : SLX2583C
TERMS : 60 days
PO NO. : 2672
PAGE NO. : Page 1 of 1
CURR. : S\$

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
9804315280	RR BUMPER REFLECTOR LH	U1 2D2-L	1	45.00	45.00

SUB-TOTAL : 45.00
ADD GST 7.00 % 3.15

E. & O.E TOTAL AMOUNT S\$: 48.15

[P] 26/02/2019 12:40:02PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 26/02/2019 11:54:49AM

JAE Auto Pte. Ltd.

Sales Executive : CHONG

This is computer generated document.

No signature is required.



* AR201902-09797 *

ORIGINAL

Goods Received in Good Order



Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

BH AUTO SERVICES PTE LTD

BLK 1, #01-115

SIN MING IND EST SECTOR C

[MUST WRITE PO]

SINGAPORE 575636

TEL : 65598944 FAX : 62692404

ATTN : K.T.CHEONG 9101 3232 ERIC/ JANICE

F3LRHNYWFS060168

TAX INVOICE : AR201903-10295

DATE : 21/03/2019

CUSTOMER ID : BHA001

VEH REG. NO. : SLX2583C

TERMS : 60 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 98185353XT	CAMERA TRIM 2679	U1	1	20.00	20.00
		SUPPLIER			
2. 9678093880	X TAIL LAMP RH X	U1	1	340.00	340.00
		SUPPLIER			

Return

SUB-TOTAL : 360.0
ADD GST 7.00 % 25.2

E. & O.E

TOTAL AMOUNT S\$ 385.2

[P] 21/03/2019 9:27:12AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 21/03/2019 9:25:41AM

JAE Auto Pte. Ltd.

Sales Executive : CHONG



* AR201903-10295 *

This is computer generated document.

No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



Service Request Details

Claim

S8M017NG

Reference

None

Loss Date

22 December 2018

Request Date

26 December 2018

Due Date

2 January 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

'Virtual'
Yun Shi veh in
26.12.2018 @ 11:25am
don't survey first, will call and arrange survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLX2583C

Make

TPVD PEUGEOT

Service Address

...

Primary Contact/Insured

NG BOCK CHAI

BLK 637 HOUGANG AVENUE 8, #08-119, 530637, Singapore

Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

VIRTUAL ACC NON REPORTING PRI only

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE



SENT

26/12/18 10:49 AM

FROM

TAN Jas

SUBJECT

NR

BODY

hi, please do not send NR letter. we will send the...



Catherine Chong (LKK Auto)

From: BHAS - Chan Yun Shi <yunshi.chan@bhauto.com.sg>
Sent: Monday, 24 December, 2018 10:16 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey; NGUETTE Kadi
Cc: BHAS - Jacelyn Loh; BHAS - Moo Wen Zheng; BHAS - Bernard Kee
Subject: PER REPAIR INSPECTION AND CHECKING LIABILITY (OUR VEHICLE SLX2583C / YOUR VEHICLE XD2297S)
Attachments: GIA REPORT.PDF; PRI.PDF
Categories: Pragati

To: the officer in charge

Dear sir/ mdm,

I would like to arrange surveyor and check liability on of the above mentioned accident vehicle.

Ps- vehicle currently in our workshop.

Appreciate awaiting for your favourable reply asap. Please kindly assist.

Greatly appreciate it. Thank you and have a nice day



Thank You & Best Regards,

Yun Shi

BH AUTO SERVICES PTE LTD

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singaopre:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: yunshi.chan@bhauto.com.sg

Website: <http://www.bhauto.com.sg>



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 20/12/2019

Survey Details:

Date of loss	22-Dec-18
Date of appointment	26-Dec-18
Date of survey	3-Jan-19
Location of survey	BH AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLX 2583C
Make and Model	PEUGEOT 308
Date of registration	28/8/2015
Excess	
Market Value	\$80,000
Parf Rebate	\$44,390
Nett Loss	\$35,610

Repair details:

Initial Estimate	\$ 18,192.84
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 5,939.50
Check items (estimate)	\$ -
Labour	\$ 1,162.58
Total	\$ 7,102.08
Lump Sum(if applicable)	-

Number of days for repair	4
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

04 RECOMMENDED REPAIR DAYS + 2 SAT + 2 SUN + 2PRS = 10DAYS

Mandate:

Liability(TP)		100%
Proposed repair cost (W/GST)	\$	7,502.92
Loss of use	\$	-
Loss of rental	\$	1,200.00
Loss of income	\$	-
LTA search fees	\$	2.00
Others	\$	-
Proposed Total	\$	8,704.92



<MANDATE IA> - S8M017NG {ACCIDENT INVOLVING XD 2297S & SLX 2583C ON 22/12/2018}

Type

🔔 Question

Message

LIABILITY: 100% BOLA S27 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$8,704.92 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL 20/12/2019

Reply

BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636

Tel: 6559 8944 Fax: 6269 2404

CO. REG. NO. 200917512K

GST REG NO. 200917512K

PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING

Your Reference: XD2297S

Our Reference: SLX2583C

Date: 13/12/2019

M/s AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

BY POST ONLY

Attention: Claims Department

CLAIMANT: VIVIANNE SHEN LUJING.

PROPERTY DAMAGED CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 22/12/2018 ALONG TAMPINES ROAD INVOLVING VEHICLE NO SLX2583C & XD2297S.

We act for VIVIANNE SHEN LUJING who was the owner of motor vehicle no. SLX2583C.

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on 22/12/2018 involving our client's vehicle registration number SLX2583C and vehicle registration number XD2297S, driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/you insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1	Cost of Repair (Included 7% GST)	\$ 7,502.92
2	Loss of Use (\$ 120.00 x 60days)	\$ 7,200.00
3	LTA Search Fee	\$ 2.00
	Total :	\$ 14704.92

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA/ Police report lodged by driver of;
- (b) Final Repair Bill
- (c) Rental Invoice / Loss Of Use
- (d) LTA Search Fee Invoice
- (e) Letter Of Authorization

Kindly revert to our client's claim within the next 7 days.

Yours faithfully,

Wen Zheng

(O): 6559 8944 (F): 6269 2404

Email: wenzheng.moo@bhauto.com.sg



Re:<MANDATE IA> - S8M017NG {ACCIDENT INVOLVING XD 2297S & SLX 2583C ON 22/12/2018}

Type

🔍 Question

Message

Please proceed. thanks.

Reply

BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE
SECTOR C #01-115 SINGAPORE 575636

Tel: 6559 8944

Fax: 6269 2404

CO. REG. NO. 201006106C

GST REG NO. 201006106C

TAX INVOICE

Final Repair Bill

Our Ref: SLX2583C

Date: 19/10/2019

M/s AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

BY POST ONLY

Vehicle No : SLX2583C
Make/ Model : PEUGEOT 308 SW ALLURE PURETECH 1.2
Year of Manufacture : 2015
Chassis No. : VF3LRHNYWFS060168
Colour : BROWN
D.O.A : 22/12/2018

QTY	ITEM/PARTICULARS	AMOUNT (S\$)
-----	------------------	--------------

1. Repair Cost for Motor Vehicle No. SLX2583C
Type of repair: Part By Part :S\$ 7,012.08

GST @ 7% : S\$ 490.84

GRAND TOTAL:S\$ 7,502.92

Total : Singapore Dollars Seven Thousand Five Hundred Two and Ninety - Two Cents Only.


Company's Stamp & Signature

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18023076/Kga3s2

8 SHENTON WAY #24-01

AXA TOWERSINGAPORE 068811

Date : 23-01-2020



ATTN: JAS TAN

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 2297S	Veh. Inspected	SLX 2583C
Policy No.	P1595438	Coverage (\$)	0.00
Claim No.	S8M017NG	Excess (\$)	0.00
Assign From	JAS TAN	Assign Date	26/12/2018

2. Vehicle Particulars & Condition

Make & Model	PEUGEOT 308 (A)	c.c	1199
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VF3LRHNYWFS060168	Colour	METALLIC BROWN
Odometer	052651	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	GOODYEAR	2 mm
L/H Front Tyre	225/45 R17	GOODYEAR	2 mm
R/H Rear Tyre	225/45 R17	MICHELIN	6 mm
L/H Rear Tyre	225/45 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/12/2018	Inspection Date	03/01/2019
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 2583C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (WCP) (CONSISTENT)	CRACKED	900.00	540.00
1	REAR BUMPER SKIRT (WCP) (CONSISTENT)	SERVICEABLE	130.00	-
1	RR BUMPER BRKT SET (WCP) (CONSISTENT)	NECESSARY	60.00	60.00
1	RR CTR BUMPER BRKT (WCP) (CONSISTENT)	NECESSARY	65.00	55.00
1	RR BUMPER BRKT SET (WCP) (CONSISTENT)	NOT NECESSARY	55.00	-
1	REAR BUMPER C-MEMBER (WCP) (CONSISTENT)	SERVICEABLE	390.00	-
2	L/R INN PARKING SENS (WCP) (CONSISTENT) }	NECESSARY	85.00	270.00
2	R/R INN PARKING SENS (WCP) (CONSISTENT) }		85.00	-
2	L/R OUT PARKING SENS (WCP) (CONSISTENT) }		85.00	-
2	R/R OUT PARKING SENS (WCP) (CONSISTENT) }		85.00	-
1	RR SENSOR BRKT SET (WCP) (CONSISTENT)	NECESSARY	115.00	115.00
1	RR CAMERA (WCP) (CONSISTENT)	NOT NECESSARY	260.00	-
1	RR CAMERA BRACKET (WCP) (CONSISTENT)	NECESSARY	20.00	20.00
1	RR CAMERA TRIM (WCP) (CONSISTENT) (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER PLATE (WCP) (CONSISTENT)	SERVICEABLE	35.00	-
1	REAR PANEL CPL (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	680.00	-
1	BOOTLID / TAILGATE (WCP) (CONSISTENT)	CRACKED	1,980.00	1,980.00
1	BOOT / TAILGATE SEAL (WCP) (CONSISTENT)	SERVICEABLE	195.00	-
1	L/TAILGATE HINGE (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	90.00	-
1	R/TAILGATE HINGE (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	90.00	-
1	T-GATE LOCK STRIKER (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	55.00	-
1	TAILGATE CONTROL (WCP) (CONSISTENT)	DAMAGED	95.00	95.00
1	BOOT/TAILGATE LOCK (WCP) (CONSISTENT)	DAMAGED	130.00	130.00
1	L/TAILGATE STAY (WCP) (CONSISTENT)	SERVICEABLE	55.00	-
1	R/TAILGATE STAY (WCP) (CONSISTENT)	SERVICEABLE	55.00	-
1	BADGE "308" (WCP) (CONSISTENT)	NECESSARY	65.00	65.00
1	REAR BADGE (WCP) (CONSISTENT)	NECESSARY	65.00	65.00
1	REAR SCREEN BOND KIT (WCP) (CONSISTENT) (NPA)	NOT NECESSARY	-	-

Report Ref No. CC4/ASM18023076/Kga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WIPER MOTOR (WCP) (CONSISTENT)	SERVICEABLE	185.00	-
1	REAR WIPER ARM (WCP) (CONSISTENT)	SERVICEABLE	75.00	-
1	L/R LAMP (WCP) (CONSISTENT)	CRACKED	340.00	340.00
1	R/R LAMP (WCP) (CONSISTENT)	CRACKED	340.00	340.00
1	L/R INNER LAMP (WCP) (CONSISTENT)	BROKEN	290.00	290.00
1	R/R INNER LAMP (WCP) (CONSISTENT)	BROKEN	290.00	290.00
1	L/R REFLECTOR (WCP) (CONSISTENT)	CRACKED	45.00	45.00
1	R/R REFLECTOR (WCP) (CONSISTENT)	SERVICEABLE	30.00	-
1	L/NUMBER PLATE LAMP (WCP) (CONSISTENT)	NOT NECESSARY	18.00	-
1	R/NUMBER PLATE LAMP (WCP) (CONSISTENT)	NOT NECESSARY	18.00	-
1	R/R WING (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	2,400.00	-
1	L/R LAMP PANEL (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	250.00	-
1	R/R LAMP PANEL (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	250.00	-
1	R/S WINDOW BOND KIT (WCP) (CONSISTENT) (NPA)	SERVICEABLE	-	-
1	REAR FLOOR PANEL (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	1,150.00	-
1	R/R WHEELHOUSE CVR (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	210.00	-
1	LOWER TAILGATE TRIM (WCP) (CONSISTENT)	BROKEN	440.00	240.00
1	UPPER TAILGATE TRIM (WCP) (CONSISTENT)	NOT NECESSARY	270.00	-
1	LUGG COMPART CARPET (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	550.00	-
1	L/BOOT TRIM COVER (WCP) (CONSISTENT)	SERVICEABLE	650.00	-
1	R/BOOT TRIM COVER (WCP) (CONSISTENT)	SERVICEABLE	650.00	-
1	REAR SILL TRIM (WCP) (CONSISTENT)	NECESSARY	250.00	190.00
1	JACK HOUSING (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	380.00	-
10	TRIM BOARD CLIP	NOT NECESSARY	5.00	-
1	TRIM BOARD FLAP COVER LH (WCP) (CONSISTENT)	SERVICEABLE	48.00	-
1	REAR BUMPER SENSOR WIRING (WCP) (CONSISTENT)	SERVICEABLE	240.00	-
	COST PLUS 15%		2,294.85	769.50
			17,593.85	5,899.50

Report Ref No. CC4/ASM18023076/Kga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SUNDRY PARTS (SN) (CONSISTENT)	NOT NECESSARY	6.74	-
1	SEALANT REAR WINDSCREEN (SN) (CONSISTENT)	NECESSARY	50.00	40.00
			56.74	40.00
	LABOUR			
	TOTAL LABOUR. INCLUSIVE OF THE REPAIR OF REAR PANEL CPL, L/TAIlgATE HINGE, R/TAIlgATE HINGE, T-GATE LOCK STRIKER, R/R WING, L/R LAMP PANEL, R/R LAMP PANEL, REAR FLOOR PANEL, R/R WHEELHOUSE CVR, LUGG COMPART CARPET AND JACK HOUSING.		1,282.50	666.00
	PAINT WORK: LABOUR COST.		540.00	351.00
	PAINT WORK: MATERIAL COST.		206.68	145.58
			2,029.18	1,162.58
	GRAND TOTAL		19,679.77	7,102.08
RECOMMENDED COST OF REPAIRS				7,012.08

Report Ref No. CC4/ASM18023076/Kga3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.