

Kw

BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference: SLX2583C

Assessment number: BA1037

Version: 1810

Date calculated: 17/05/2019 11:35 AM

Full Report

Registration: SLX2583C

Printed: 17/05/2019 11:35 AM

Summary Information

Claim

Location: Singapore (SG)
Printed by: Janice Koh
Claim Reference: SLX2583C
Estimated Repair Time: 12
Actual Repair Days:

Work Provider: AXA Insurance Pte Ltd
Currency: SGD
Date of Incident: 22/12/18
Hire Car Start:
Hire Car End:

Vehicle Details

Vehicle

Manufacturer: PEUGEOT
Model: 308 II SW L
Sub Model: ALLURE
Model Sheet Number: 11 4C 04
Registration: SLX2583C
VIN number:
Odometer:

Model Specs

BLIND SPOT SENSOR	REAR PARKING SYSTEM	REARVIEW CAMERA	PARK-ASSIST
-------------------	---------------------	-----------------	-------------

BH Auto Services Pte Ltd

1 Sin Ming Industrial Est Sector C

575636

Claim Reference: SLX2583C

Assessment number: BA1037

Version: 1810

Date calculated: 17/05/2019 11:35 AM

Full Report

Registration: SLX2583C

Printed: 17/05/2019 11:35 AM

Vehicle Condition

Vehicle Status


Pre-Accident Damage:

Date of Inspection: 25/01/19

Damage Areas

All ☐

Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
92.E9KA)	R + R RIGHT REAR SIDE WINDOW GLASS		6.0	27.00
74.EJ2A	R + R REAR BUMPER		11.0	49.50
	INCLUDES: R + R TAILLAMPS			
74.EMGA)	RENEW REAR BUMPER		6.0	27.00
NO NUMBER	R + R REAR PARKING SYSTEM SENSOR/S		7.0	31.50
NO NUMBER	R + R REAR CENTRE BUMPER BRACKET		2.0	9.00
74.EP9A)	R + R TAILGATE		12.0	54.00
74.E16A)	RENEW TAILGATE (REMOVED)		2.0	9.00
92.E1US	R + R REAR SCREEN		20.0	90.00
63.E6AA)	REPLACE BOTH REAR LIGHTS (REMOVED)		2.0	9.00
70.EDXA	R + R LEFT BOOT TRIM		4.0	18.00
70.EDXA	R + R RIGHT BOOT TRIM		4.0	18.00
70.E1PA	R + R REAR PANEL TRIM		2.0	9.00
2711	REAR PANEL CPL REPAIR		25.0*	112.50
3482	R/R WING REPAIR		45.0*	202.50

BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference: SLX2583C
 Assessment number: BA1037
 Version: 1810
 Date calculated: 17/05/2019 11:35 AM

Full Report
 Registration: SLX2583C
 Printed: 17/05/2019 11:35 AM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	14.80	148.0	666.00
Total of Labour			666.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description	WU Price SGD
	BOOTLID/TAILGATE NEW PART PAINTING	18.0
	REAR BUMPER NEW PART PAINT K1R	11.0
	L/R INN PARKING SENS NEW PART PAINT K1R	3.0
	R/R INN PARKING SENS NEW PART PAINT K1R	3.0
	REAR PANEL CPL REPAIR PAINTING <50%	9.0
	R/R WING REPAIR PAINTING <50%	14.0

Paint Material Per Part

Code	Description	Price SGD
2931	BOOTLID/TAILGATE NEW PART PAINTING	47.96
2581	REAR BUMPER NEW PART PAINT K1R	44.32
2655	L/R INN PARKING SENS NEW PART PAINT K1R	0.35
2656	R/R INN PARKING SENS NEW PART PAINT K1R	0.35
2711	REAR PANEL CPL REPAIR PAINTING <50%	7.25
3482	R/R WING REPAIR PAINTING <50%	18.25

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		58.0	
Preparation Main Work Metal	1.70	17.0	76.50
Preparation Comp. Work Plastic	0.30	3.0	13.50
Total	10 WU/h	78.0	351.00

Material Cost - Paint	Price SGD
New Part Painting	47.96
New Part Painting - Plastic K1R	45.02
Repair Painting	25.50
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	145.58

BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference: SLX2583C
 Assessment number: BA1037
 Version: 1810
 Date calculated: 17/05/2019 11:35 AM

Full Report
 Registration: SLX2583C
 Printed: 17/05/2019 11:35 AM

Spare Parts

				prices as at 2001-01-01
Code	Description	Part Number	Supplier	Price SGD
				540.00
2581	REAR BUMPER	16 116 091 80		60.00
2627	RR BUMPER BRKT SET	16 116 165 80		55.00
2628	RR CTR BUMPER BRKT	98 009 819 80		135.00
2655	L/R INN PARKING SENS	16 083 217 80		135.00
2656	R/R INN PARKING SENS	16 083 217 80		115.00
2673	RR SENSOR BRKT SET	16 116 163 80		20.00
2679	RR CAMERA BRACKET	98 048 581 80		1,980.00
2931	BOOTLID/TAILGATE	16 116 371 80		95.00
2975	TAILGATE CONTROL	96 760 283 80		130.00
2977	BOOT/TAILGATE LOCK	98 047 620 80		65.00
3013	BADGE "308"	98 058 297 VD		65.00
3020	REAR BADGE	98 057 002 VD		0.00
3160	REAR SCREEN BOND KIT	16 188 585 80		340.00
3281	L/R LAMP	96 780 939 80		340.00
3282	R/R LAMP	96 780 938 80		290.00
3283	L/R INNER LAMP	96 780 980 80		290.00
3284	R/R INNER LAMP	96 780 948 80		45.00
3285	L/R REFLECTOR	98 043 152 80		0.00
3862	R/S WINDOW BOND KIT	16 188 585 80		240.00
4907	LOWER TAILGATE TRIM	98 018 952 ZD		190.00
4986	REAR SILL TRIM	98 133 886 ZD		0.00
f: OEM Parts				0.00
n: Non-OEM Parts				5,130.00
u: Used parts				769.50
Savings				
Subtotal				
Addition (+15.00%)				
Total				5,899.50

Extras

Code	Description	Price SGD
1000	sealant Rear windscreen	50.00*
	Total Extras	50.00

BH Auto Services Pte Ltd

1 Sin Ming Industrial Est Sector C

575636

Claim Reference: SLX2583C

Assessment number: BA1037

Version: 1810

Date calculated: 17/05/2019 11:35 AM

Full Report
Registration: SLX2583C
Printed: 17/05/2019 11:35 AM

Final Calculation

	SGD	SGD
Parts	5,130.00	
Addition(+15.00%)	769.50	
Total Parts		5,899.50
Labour Time Base 10 WU/h	666.00	
Total 148.0 WU X 45.00 SGD/h		666.00
Total of Labour		50.00
Total Of Extras		
Paint Work Time Base 10 WU/h	351.00	
Labour Cost 78.0 WU X 45.00 SGD/h	145.58	
Material Cost		496.58
Total Paint Including Material		7,112.08
Repair Cost Excludes GST		497.85
GST (+7.0%)		7,609.93
Repair Cost Included GST		

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6417 9795

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

BH AUTO SERVICES PTE LTD
BLK 1, #01-115
SIN MING IND EST SECTOR C
[MUST WRITE PO]
SINGAPORE 575636
TEL : 65598944 FAX : 62692404
ATTN : K.T.CHEONG 9101 3232 ERIC/ JANICE
VF3LRHNYWFS060168

TAX INVOICE : AR201902-09796
DATE : 26/02/2019
CUSTOMER ID : BHA001
VEH REG. NO. : SLX2583C
TERMS : 60 days
PO NO. : 2672
PAGE NO. : Page 1 of 2
CURR : S\$

STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 1611637180	2931 TAIL GATE	CC CC10-A-07FRT	1	1980.00	1,980.00
2. 98018952ZD	4907 TAIL GATE INNER TRIM	CC CC10-G-07B	1	240.00	240.00
3. 98057002VD	3020 REAR TAIL GATE BADGE	CC CC10-J-08BK	1	65.00	65.00
4. 98058297VD	3013 308 BADGE	CC CC10-F-10AF	1	65.00	65.00
5. 9804762080	2977 REAR TAIL GATE LOCK	CC CC10-J-08BF	1	130.00	130.00
6. 6490 RZ	2975 REAR BOOT SWITCH	CC CC10-J-08BB	1	95.00	95.00
7. 9678098080	3283 TAIL GATE LAMP LH	CC CC10-F-10B	1	290.00	290.00

CONTINUE NEXT PAGE

[P] 26/02/2019 12:18:13PM

[E] 26/02/2019 11:54:45AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794



Dept Direct: 6417 9795



Dept Direct: 6417 9796

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

BH AUTO SERVICES PTE LTD
BLK 1, #01-115
SIN MING IND EST SECTOR C
[MUST WRITE PO]
SINGAPORE 575636
TEL : 65598944 FAX : 62692404
ATTN : K.T.CHEONG 9101 3232 ERIC/ JANICE
VF3LRHNYWFS060168

TAX INVOICE : AR201902-09796
DATE : 26/02/2019
CUSTOMER ID : BHA001
VEH REG. NO. : SLX2583C
TERMS : 60 days
PO NO. : 2672
PAGE NO. : Page 2 of 2
CURR : S\$

STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
8. 9678094880	3284 TAIL GATE LAMP RH	CC CC10-F-08C	1	290.00	290.00
9. 9678093980	3281 TAIL LAMP LH	CC CC10-I-04C	1	340.00	340.00
10. 9678093880	3282 TAIL LAMP RH	CC CC10-F-09B	1	340.00	340.00
11. 1611609180	2581 REAR BUMPER	CC CC10-B-09A	1	540.00	540.00
12. 9800981980	2628 REAR BUMPER CENTRE BRACKET	CC CC10-G-09C	1	55.00	55.00
13. 1608321780	2655/2656 PARKING SENSOR	CC CC10-D-10AB	2	135.00	270.00
14. 98133886ZD	4986 REAR END PANEL TRIM	CC CC10-G-07C	1	190.00	190.00

SUB-TOTAL : 4,890.00
ADD GST 7.00 % 342.30

TOTAL AMOUNT S\$: 5,232.30

E. & O E

[E] 26/02/2019 11:54:45AM

[P] 26/02/2019 12:18:13PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: CHONG

This is computer generated document.

No signature is required.



* A R 2 0 1 9 0 2 - 0 9 7 9 6 *

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792

TOYOTA

LEXUS

DAIHATSU



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

BH AUTO SERVICES PTE LTD

BLK 1, #01-115

SIN MING IND EST SECTOR C

[MUST WRITE PO]

SINGAPORE 575636

TEL : 65598944 FAX : 62692404

ATTN : K.T.CHEONG 9101 3232 ERIC/ JANICE

VF3LRHNYWFS060168

TAX INVOICE : AR201903-00769
DATE : 02/03/2019
CUSTOMER ID : BHA001
VEH REG. NO. : SLX2583C
TERMS : 60 days
PO NO. : 2682
PAGE NO. : Page 1 of 1
CURR : S\$

STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 1611616780	REAR BUMPER SIDE RETAINER SET	CC	1	60.00	60.00
	2627	CC10-I-070B			

SUB-TOTAL : 60.00
ADD GST 7.00 % 4.20

E. & O.E

TOTAL AMOUNT S\$: 64.20

[P] 02/03/2019 10:25:43AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 02/03/2019 10:19:56AM

JAE Auto Pte. Ltd.

Sales Executive: CHONG

This is computer generated document.

No signature is required.



* AR 201903-00769 *

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

BH AUTO SERVICES PTE LTD

BLK 1, #01-115

SIN MING IND EST SECTOR C

[MUST WRITE PO]

SINGAPORE 575636

TEL: 65598944 FAX: 62692404

ATTN: K.T.CHEONG 9101 3232 ERIC/ JANICE

VF3LRHNYWFS060168

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201902-09797

DATE : 26/02/2019

CUSTOMER ID : BHA001

VEH REG. NO. : SLX2583C

TERMS : 60 days

PO NO. : 2672

PAGE NO. : Page 1 of 1

CURR. : S\$

SO STOCKID

DESCRIPTION

StkLoc

QTY

U/PRICE

AMOUNT

9804315280

RR BUMPER REFLECTOR LH

U1
2D2-L

1

45.00

45.00

SUB-TOTAL : 45.00

ADD GST 7.00 % 3.15

E. & O.E

TOTAL AMOUNT S\$: 48.15

[P] 26/02/2019 12:40:02PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 26/02/2019 11:54:49AM

JAE Auto Pte. Ltd.

Sales Executive : CHONG



* A R 2 0 1 9 0 2 - 0 9 7 9 7 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order



Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

BH AUTO SERVICES PTE LTD

BLK 1, #01-115

SIN MING IND EST SECTOR C

[MUST WRITE PO]

SINGAPORE 575636

TEL : 65598944 FAX : 62692404

ATTN : K.T.CHEONG 9101 3232 ERIC/ JANICE

F3LRHNYWFS060168



Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201903-10295

DATE : 21/03/2019

CUSTOMER ID : BHA001

VEH REG. NO. : SLX2583C

TERMS : 60 day

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 98185353XT	CAMERA TRIM 2679	U1	1	20.00	20.00
2. 9678093880	X TAIL LAMP RH X	U1	1	340.00	340.00

SUB-TOTAL : 360.00

ADD GST 7.00 % 25.20

E. & O.E

TOTAL AMOUNT S\$: 385.20

[P] 21/03/2019 9:27:12AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 21/03/2019 9:25:41AM

JAE Auto Pte. Ltd.

Sales Executive : CHONG

This is computer generated document.

No signature is required.



* AR201903-10295 *

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL