

REPAIR ESTIMATE

VEHICLE NO : SHD 3503E

24/12/2018 9:51

MAKE :

MODEL : TOYOTA PRIUS

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>X4</i>			\$ 889.70
REAR TRUNK LID LOGO(PRIUS) ✓			\$ 52.90
REAR TRUNK LID LOGO(HYBRID) ✓			\$ 52.90
REAR TRUNK LID LOGO(TOYOTA STAR) ✓			\$ 47.00
REAR BUMPER ✓			\$ 458.60
REAR BUMPER RE-INFORCEMENT ?			\$ 318.80
REAR BUMPER UNDER COVER ✓			\$ 552.60
REAR BUMPER TOWING COVER ?			\$ 82.70
REAR BUMPER CLIPS ✓			\$ 22.00
SEAL, REAR BUMPER SIDE, LH ✓			\$ 148.40
TAIL LAMP ASSY (LOWER) (LH) ✓			\$ 548.40
SUB TOTAL			\$ 3,174.00
LESS 25%			\$ 793.50
DISCOUNTED TOTAL			\$ 2,380.50
REAR NO. PLATE WITH TRIM COVER ✓			\$ 100.00 ⁵⁰
REAR TRUNK LID APPS STICKER ✓			\$ 40.00
REAR TRUNK LID COMFORT & TEL NO. STICKER ✓			\$ 60.00
REAR BUMPER REVERSE SENSOR ✓			\$ 135.70
REAR BUMPER RUBBER MAT ✓			\$ 50.00
			\$ 385.70
LABOUR CHARGE			
Panel Beating			\$ 400.00 ³⁰⁰
Spray Painting Charge			\$ 500.00 ⁴⁰⁰
Wiring Charge			\$ 30.00 ²⁰
Remove/Refix Reverse Sensor			\$ 80.00 ⁷⁰
TOTAL LABOUR			\$ 1,010.00
ESTIMATE TOTAL			\$ 3,776.20

Kalin (UKK)

24/12/18 1030h

3 Rep.

P/P

Before Part photo

the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.