

# 趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

*Not Noted*  
*1/1 Imp & ?*  
*Resurvey After Paint*  
*4 days*

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: \_\_\_\_\_ Third Party

Date: **21.12.2018**

**Accident Date : 18.12.2018**

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
<b>Estimate Cost Of Repair To "Kia K2500" Reg. No. GBE9708H Claiming Against Your Insured Reg. No. GBH1800K</b>			
1pc	Tailgate		<i>B1</i> 1,600.00 ✓
1pc	Tailgate Hinge Pin		<i>R</i> 65.00 x
1pc	Tailgate Sticker "Kia Motors"		<i>m</i> 75.00 ✓
1pc	Tailgate Badge "C&C"		<i>m</i> 50.00 ✓
2pcs	Tailgate Lower Stoppers	35.00	<i>W</i> 70.00 ✓
1pc	Rear Number Plate Holder		<i>B1</i> 125.00 ✓
1pc	Rear Number Lamp		<i>SN</i> 38.00 x
2pcs	Rear End Panel Stickers "Round Black"	6.00	<i>m</i> 12.00 ✓
2pcs	Taillamps Assy	185.00	370.00 ✓
2pcs	Taillamp Panels	93.00	<i>B1</i> 186.00 ✓
			2,591.00
	Less 10%		259.10
			2,331.90
1pc	Tailgate Sticker "70KM"		<i>m</i> 18.00 SN ✓
1pc	Tailgate Sticker "13Pax"		<i>m</i> 18.00 SN ✓
1pc	Rear Number Plate		<i>B1</i> 45.00 SN ✓
1pc	Rear Reverse Sensor		<i>W</i> 280.00 SN 200.00 ✓
1pc	Rear Step Bracket		<i>R</i> 350.00 SN x
	To Conduct Electrical Check, Replace Reverse Sensors, Module, Rewiring Etc		120.00 <i>500</i>
	Labour Charge - Panel Beating, Repairing Of Rear End Panel and Parts Replacement		700.00 <i>500</i>
	To Respray Affected Areas		700.00 <i>450</i>
<b>Total :</b>			<b>4,562.90</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: