COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHC 8508P

MAKE

: HYUNDAI i40

Aig Asia

DATE 24/12/2018

KK-Kalvin

1430

Qty	Parts Description/ Labour	Type	Unit Price	+	mount
	Rear Bumper XMM			\$	553.00
	Rear Bumper Clip 10 pcs × **			\$	22.00
	SUB TOTAL			\$	575.00
	LESS 20%			\$	115.00
	DISCOUNTED TOTAL			\$	460.00
	Rear Bumper Advertisement Logo ***			\$	50.00
				6	50.00
			*.	\$	50.00
	Labour Charge				200
	Panel Beating			\$	380.00
	Spray Painting Charge			\$	250.00
	Wiring Charge	-		\$	59.00
				\$	60.00
	Towing Fees Remove/Refix Reverse Sensor			s	80.00
	Remove/Renx Reverse Sensor			\$	
	TOTAL LABOUR			\$	820.00
	ESTIMATE TOTAL			\$	1,330.00
	Koluk (lllk) 1 26/2/18 1105 La 2 Rys.	(1) PM	to Consultants hence no pairer of the following:		
	2 hys. Us Alle Requir plo	To rest To disp Parts Third No ille	they before after spray points by damaged part(s) during re- prices are subject to confirmal party survey is an a "Without fe egal modification(s) is allowed tementary item(s) must be res bject to final approval from Ins wedged by Repairer	lion Prejudice"	nd
		1			
			- v		

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.