

## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO : SHD 3519K

DATE 24/12/2018 11:01

MAKE :

MODEL : HYUNDAI i40

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 553.00	
	Rear Bumper Reinforcement ✓			\$ 428.40	
	Rear Bumper Reinforcement Bracket (LH/RH) ✓		\$ 80.30	\$ 160.60	
	Rear Bumper Clip 10 pcs ✓			\$ 22.00	
	Rear Bumper Bracket ?		\$ 35.60	\$ 71.20	
	Rear Bumper Sponge ✓			\$ 103.50	
	Rear Bumper Under Cover ✓			\$ 228.00	
	<i>Rear Bootlid ✓</i>				
	<i>Rear End Panel ✓</i>				
	<i>Rear End Panel top garnish ✓</i>				
	SUB TOTAL			\$ 1,566.70	
	LESS 20%			\$ 313.34	
	DISCOUNTED TOTAL			\$ 1,253.36	
	Rear Bumper Reverse Sensor ✓			\$ 135.70	Nett
				\$ 135.70	
	<b>Labour Charge</b>				
	Panel Beating			<del>\$ 400</del>	
	Spray Painting Charge			<del>\$ 600</del>	
	Wiring Charge			<del>\$ 800</del> 600	
	Remove/Refix Reverse Sensor			\$ 30.00 x	
				\$ 80.00 30	
	TOTAL LABOUR			\$ 810.00	
	ESTIMATE TOTAL			\$ 2,199.06	
<p><i>Ka/lu (UCC)</i></p> <p><i>24/12/18 1335h.</i></p> <p><i>4 Pys.</i></p> <p><i>P/P</i></p> <p><i>Before Part photo</i></p>					
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					