



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SME 2469 M

Parts	(a) Cost / List Price Items	\$	5,117.50
	Plus/Less 20%	\$	1,023.50
	Total of Cost / List	\$	4,094.00
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	50.00
Total Parts Cost		\$	4,144.00
Labour		\$	2,900.00
Total		\$	7,044.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be reviewed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 31/12/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 4-6 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 31/12/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SME 2469 M**
Make & Model : **HONDA FREED**
Chassis No : **GB71072757**

Submit By : **Carmen Lim**
Year Manufacture : **2018**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH rear sliding door <i>R</i>	1	\$1,153.00		✓
2	LH rear sliding door top hinge <i>R</i>	1	\$135.00		X
3	LH rear sliding door bottom hinge <i>R</i>	1	\$165.00		X
4	LH rear sliding door glass outer moulding <i>Ln</i>	1	\$95.60		X
5	LH rear sliding door power window motor	1	\$380.00		?
6	LHR door power window regulator	1	\$145.00		?
7	LH rear sliding door auto roller motor <i>Ln</i>	1	\$968.00		X
8	LH rear fender <i>R</i>	1	\$852.00		?
9	LH rear fender undershield <i>Ln</i>	1	\$65.00		X
10	LH rear fender undershield clip <i>nn</i>	10	\$35.00		X
11	LH rear fender glass moulding	1	\$135.00		?
12	LH rear fender glass sealant	1	\$50.00	S.N	?
13	Rear bumper <i>R</i>	1	\$925.00		X
14	Rear bumper clip <i>nn</i>	10	\$39.00		X
15	Rear bumper side retainer LH <i>Ln</i>	1	\$24.90		X
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SME 2469 M** Submit By : **Carmen Lim**
Make & Model : **HONDA FREED** Year of Manufacture : **2018**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (LHR SLIDING DOOR,LHR FENDER,RR BUMPER,LH SIDE SKIRT)	\$1,000.00	500-800
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (LHR SLIDING DOOR,LHR FENDER,RR BUMPER,LH SIDE SKIRT)	\$1,000.00	500
3	To check wiring	\$50.00	20
4	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$180.00	60
5	To tuff coat	\$150.00	?
6	To remove & refit LH rear fender glass to assist work load	\$120.00	?
7	To remove & refit inner seat & upholstery to assist work load.	\$250.00	80
8	To remove & refit petrol tank to assist work load.	\$150.00	?

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.