



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)
UNKNOWN

Singapore

Claimant Insurer: HL Assurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	18/12/2018
Vehicle Reg. No.:	SKU3139Z	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	ONG JUNXIONG (WANG JUNXIONG)		
Make/Model:	MAZDA 3, 1.5 4 DOOR SEDAN SP (A)	Vehicle Reg. Date:	16/07/2015
Vehicle Colour:	GREY	Chassis No:	JM6BM42A8G0313058
Engine No:	P520295499		
Odometer:	0 KM		
Paint Type:		Nett Item Discount:	10.00 %
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	-		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	2,364.80
Miscellaneous Items	10.00
Labour	1,280.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	3,654.80
+ GST 7.00% (\$\$)	255.84
Nett Amount (\$\$)	3,910.64

This claim is handled by: JACELYN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Dec 2018)

Parts: 143 MAZDA 3 1.5 4 DOOR SEDAN SP (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Mova Automotive Pte Ltd/SKU3139Z/24/12/2018 16:34

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*HEADLAMP LH <i>sch</i>	20.00	0.00	*795.00 FL
2	1		*HEADLAMP LOWER BRACKET LH <i>?</i>	20.00	0.00	*25.00 FL
3	1		*FRONT BUMPER <i>DE</i>	20.00	0.00	*945.00 FL
4	1		*FRONT BUMPER SIDE RETAINER LH <i>m</i>	20.00	0.00	*25.00 FL
5	10		*FRONT BUMPER CLIPS <i>m</i>	20.00	0.00	*50.00 FL
6	1		*FRONT FOGLAMP GARNISH LH <i>sch</i>	20.00	0.00	*55.00 FL
7	1		*FRONT FENDER LH <i>m</i>	20.00	0.00	*368.00 FL
8	1		*FRONT FENDER COWLING LH <i>DE</i>	20.00	0.00	*98.00 FL
9	10		*FRONT FENDER COWLING CLIPS <i>m</i>	20.00	0.00	*50.00 FL
10	1		*FRONT WHEEL BEARING LH <i>sch</i>	20.00	0.00	*545.00 FL
11	1		*FRONT WHEEL LH - REPAIR	20.00	0.00	-

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)

2,956.00

- List Item Discount on L Items (\$\$)

591.20

Total Parts (\$\$)

2,364.80

Mova Automotive Pte Ltd/SKU3139Z/24/12/2018 16:34. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

10.00

Sub Total (\$\$)

10.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 TO INSPECT FRONT LIGHTING MECHANISM

New

30 50.00

2 TO REPAIR FRONT WHEEL LH

New

60 100.00

3 TO REPLACE UNDERCARRIAGE DAMAGED ITEMS

New

X 100.00

4 TO REMOVE & REPLACE DAMAGED ITEMS. REALIGN CONNECTION

New

350 400.00

5 TO SPRAY PAINT ON REPAIRED AREAS

New

400 500.00

6 TO CHECK WHEEL ALIGNMENT

New

60 80.00

7 TO CONDUCT TYRE BALANCING

New

20 50.00

Gross Labour Cost (\$\$)

1,280.00

Mova Automotive Pte Ltd/SKU3139Z/24/12/2018 16:34. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Rose
 Hg 90010068
 4 days
 4/5
 19/04/19 @ 1800
 Resy after report

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: