

REF: CS3 / AXA 17015633 / Bv6-7

Special Instruction:

ASSIGNMENT (Office)

From (Person): Tan Chee Kiong of Seah Ong Date/Time: 26/2/2018
Estimated Cost: _____ Bill to: _____

46: \$28700.00

Third Parties:

Claimant:

Surveyor: PAR Automotive

Workshop: N-51 Automotive

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SK 9398C Insured: SJH 4922C

at Workshop m/s N-51 Automotive
of 2 Kaki Bukit Ave 2 #D1-17

Policy No: _____ Claim No: 18.25471

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 08-08-2017


(Client's Record)

H.O.D. Enrolment/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 21/10 Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 12 days)

Date/Time: 9/1/19 Submit Final Fig LS 11,750, 10 days (Red \$ 16950 / 59 %; Original days)

Date/Time	Action/Instruction
	SAK 9318C - CS3 / PPA17015633 / Gbr2
	STH 4922C - X
	DNF: 03082017
	
	8/1/2019

Para(1) : Parts found not replaced	(To highlight <i>R or UB, LR, Etc</i>)
------------------------------------	---

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 0 9 JAN 2019

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date: _____

Basic & Add

Transport

Photos

Others

Total

1) Date/Time 9/1- typist File Pass to

2) Date/Time

File Return to

3) Date/Time _____ File Pass to _____

4) Date/Time

File Return to

5) Date/Time _____ File Pass to _____

6) Date/Time

File Return to

Catherine Chong (LKK Auto)

From: Chee Kiong <cheekiong@seahong.com.sg>
Sent: Wednesday, 26 December, 2018 2:20 PM
To: 'Catherine Chong (LKK Auto)'
Cc: june tan; 'Xin Yi'; samson@seahong.com.sg; amanda@seahong.com.sg; sharon@seahong.com.sg
Subject: RE : SURVEY REPORT - VEHICLE - SGK 9398C : MC 15094/ 2018 : CS3/AXA17015633/GBE2 : 18.25471
Attachments: LKK PRI.pdf; LOD.pdf; GIA SGK9398C.pdf; INSD GIA SJH 4922C.pdf

Dear Catherine

We enclose herewith your PRS report.

The Plaintiff declined to give RI now as they said your surveyor has carried out post-repair inspection already.

The Plaintiff's LOD wit Plaintiff's survey report and the parties' GIA statements are enclosed.

Please let us have your survey report urgently.

Thanks !

Yours
Tan Chee Kiong
Seah Ong & Partners LLP

ASS. REC. BY: _____

REF: _____

CS³/AXA17015633/Gber

Special Instruction: _____

5/1/17

ASSIGNMENT (Office)

From (Person):

menmen Khur Saw Theng of AXA Date/Time: 11/08/2017 5:47pm

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: _____

GBK 9398C

Insured: _____

SJH 4522C

at Workshop m/s _____

N-51 Automotive

Tel: _____

6847 0051

of _____

2 Kaki Bukit Ave 2 #01-17

Policy No: _____

GA118897

Claim No: _____

C0447579

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. _____

08082017

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement: _____

Date/Time: 11/08/2017 10:22am

Person Contacted: _____

Hui Xin

Vehicle: IN LOUT

Date/Time	Action/Instruction (X) Estimate
	GBK 9398C - X
	SJH 4522C - X
	Dismantle Part: 16-08-2017
	After repair: 22082017
26/08/17 12:47pm	Email to Khur Saw Theng thru menmen

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors **Commissioner for Oaths** **Notary Public**
UEN NO : 201523418E
(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16
MANHATTAN HOUSE
SINGAPORE 169876
TEL : (65) 6532 2455
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)


EMAIL: lhling@tcmg.com.sg

Our Ref : LLH/ing/1259/0618/N51

Your Ref : SJH 4922 C

26 JUN 2018

MD AZAHAR BIN ISMAIL
427 Woodlands Street 41
#05-212
Singapore 730427



61168373

3019431034 - - -

By Certificate of Posting
(For your attention without enclosures)

M/S AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way#27-01
AXA Tower
Singapore 068811

BY PDX NO. 8176

PDX Intercompany Exchange Pte Ltd



010806426616
FROM **TOMMY CHOO, MARK GO LLC**
PDX Box No. **8141**

Attn: Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING SGK 9398 C AND SJH 4922 C ON 8 AUGUST 2017 ALONG PIE TOWARDS TUAS AFTER ADAM ROAD EXIT 20A

We are instructed by **Tan Choo Heng**, to claim damages against you or your insured, the driver of motor vehicle no. **SJH 4922 C**, in connection with a road traffic accident on 8 of August 2017, at about 17:55 hours along PIE towards Tuas after Adam Road Exit 20A, involving our client's motor vehicle no. **SGK 9389 C** and motor vehicle no. **SJH 4922 C** driven by your insured at the material time.

We are instructed that the accident was caused by your insured's negligence and/or management of his motor vehicle. As a result of the accident, our client's motor vehicle was damaged and our client had been put to loss and expenses, particulars of which are as follows:

1 Costs of Repair	\$ 30,709.00 (incl GST)
2 Rental (\$120 x 5 days)(\$140 x 7 days)	\$ 1,580.00
3 LTA Search Fee	\$ 5.35
4 Survey Report Fee	\$ 1,573.00
5 Disbursement (at this stage)	\$ 93.00
6 Legal Cost (at this stage)	\$ 1,200.00
	<u>\$ 35,160.35</u>

DIRECTOR : LING LEONG HUI

CONSULTANTS : TOMMY CHOO TUCK SOON
POOTS LAURENCE JAMES

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors Commissioner For Oaths Notary Public

UEN NO : 201523418E

(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16

MANHATTAN HOUSE

SINGAPORE 169876

TEL : (65) 6532 2455

FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

Email: lhling@tcmg.com.sg

A copy each of the following supporting documents is enclosed:

1. Copy of accident report and LTA search;
2. Copy of Certificate of Insurance;
3. Copy of survey report and invoice and repair bill;
4. Colour photographs pertaining to our client's motor vehicle for your perusal.

Our client had on 11 of August 2017 notified your insurer, M/s AXA Insurance (S) Pte Ltd about the accident and the pre-repair inspection was conducted.

Please note that if you are insured and you wish to claim from your insurance policy, you should immediately pass this letter to your insurer

Please note that you should send us an acknowledgment of receipt of this letter within fourteen (14) days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you or your insured.

Please note that if you have a counterclaim against our client arising out of the accident, you are also required to send us a letter giving full particulars of the counterclaim together with the relevant documents within 8 weeks of your receipt of this letter.

Yours faithfully,



Encs.

cc. client

Enquire Vehicle & Owner Information (Vehicle No. SJH4922C As At 08 Aug 2017 / 17:55:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: LLH.SGK9398C.N51

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S1582491C

Owner Name: MD AZAHAR BIN ISMAIL

Registered Address Type: HDB / HUDC

Registered Block/House
No.: 427

Registered Street Name: WOODLANDS STREET 41

Registered Unit No.: # 05 - 212

Registered Building Name: -

Registered Postal Code: 730427

Current Vehicle Details

Vehicle No.: SJH4922C

Make Description/Model: PERODUA / VIVA SXI MT

Insurance Company Name: AXA INSURANCE PTE LTD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/08/2017 13:20
Date Of Accident	08/08/2017 17:55
Exact Location Of Accident	PIE TOWARDS TUAS AFTER ADAM RD EXIT 20A
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGK9398C
Insured/Policyholder	
Name Of Registered Owner	TAN CHOO HENG
NRIC No	S8072025D
Email Address	ANDYTAN09@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92289398
Alternative Phone No	OFFICE-92289398
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HARRIER-2.0 PREMIUM CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA214299/1
Cover Note Number	
Driver	
Name of Driver	TAN CHOO HENG
NRIC No	S8072025D
Date Of Birth	26/10/1980
Occupation	OUTDOOR
Date Of Driving Pass	05/05/2009
Driving Experience	8 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92289398
Fax Number	
Contact Number	OFFICE-92289398
Email Address	ANDYTAN09@GMAIL.COM

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

AS PER STATEMENT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJH4922C
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver NORZAIKUL BIN NORJALI
 NRIC/Passport Number S8816044D
 Contact Number 91906484
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJG8712X
 Vehicle Make/Model/Colour

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By its lodgement of this report to the Insurers, you hereby consent in the archiving of this report at the centre and to copies of the report being made available if needed.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurers who have insured vehicle(s) involved in this accident (all Insurers who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my Insurer's or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the sums as well as on the external cover of envelopes/freight packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes");
 - (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time
10/08/2017
11:35am

Driver's Signature (if a bar to not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Details Of Properties

Name of Driver

MOHD SALLEHUDDIN ONG BIN ABDULLAH

NRIC/Passport Number

S2587304A

Contact Number

96945548

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Describe Circumstances of the Accident

On 08th August 2017 at 5:50pm, I was travelling along D1E towards TWA5 after Aulom Road Exit (20A). The vehicle C in front of me slow down & stopped. I follow to slow down & stopped behind him. Suddenly vehicle B hit into my back of my vehicle causes my vehicle to move forward and hit into the front vehicle C.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature : Date & Time
10/08/2017
11.35am.

Driver's Signature (if driver is not the policyholder) : Date & Time



Witnessed by Reporting Centre
Personnel

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 10 Aug 2017 / 18:15:02

Receipt Date/Time : 10 Aug 2017 / 18:15:02

Tax Invoice/Receipt

Receipt No. : ITNET-00000-170810-001404

Previous Receipt No. :

**S/N Item Description/
Business Transaction
Reference No.**

Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
--------------------------------	-------------------------	-------------------------------

Result of Insurance Enquiry - SJH4922C
As at 08 Aug 2017/17:55:00
Insurance Co: AXA INSURANCE PTE LTD

1 Insurance Enquiry - SJH4922C
Enquiry Fee
20170810181424223455

5.00	0.35	5.35
------	------	------

Sub-Total	5.00	0.35	5.35
------------------	------	------	------

Total Before Rounding	5.00	0.35	5.35
------------------------------	------	------	------

Rounding Difference			0.00
----------------------------	--	--	------

Total Amount Payable			5.35
-----------------------------	--	--	------

Paid By

xxxxxxxxxx<x2392	Credit Card: Visa/MasterCard	5.35
------------------	---------------------------------	------

Total			5.35
--------------	--	--	------

Cash Change			0.00
--------------------	--	--	------

Tendered Amount			5.35
------------------------	--	--	------

Excess Refundable Amount			0.00
---------------------------------	--	--	------

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



redefining / insurance

AXA Insurance Pte Ltd
 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

Certificate of Insurance

account number
14537

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 - Road Transport Act, 1987 (Malaysia)
 -Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	TAN CHOO HENG	Certificate number	GA214239 / 1
Cover	Comprehensive	Chassis number	ZSL600040581
Plan name	Flexi	Engine number	3ZFB532272
NCD applicable	50%		
Vehicle registration number	SGK9398C		
Period of Insurance	from 17/06/2017 to 16/06/2018 (both dates inclusive)		
Finance loan company	SINGAPLRA FINANCE LTD		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 300.00
	Windscreen Excess	SGD 100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if you have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

TAN CHOO HENG

BLK 668A JURONG WEST ST 64 #06-120

SINGAPORE 641668

Contact : 92289398

TAX INVOICE

Date : 20/06/2018

Date in : 10/08/2017

Vehicle Num. : SGK9398C

Make/Model : TOYOTA HARRIER PREMIUM 2.0 CVT-2015

Chassis/Eng# : ZSU600040581/3ZRB532272

Accident Date : 08/08/2017

Claim No : CLM14166

Reference : AUG-31/2017

Policy No. : GA214299/1 (16/06/2018)

LUMPSUM REPAIR BILL

AS PER SURVEYOR REPORT

REF : 0316-18-N51 DATED 11/06/2018

BY PAR AUTOMOTIVE CONSULTANCY

Amount S\$

28,700.00



E. & O.E. Sub S\$: 28,700.00

Add GST (7 %) S\$: 2,009.00

Total Amount S\$: 30,709.00

for N-51 AUTOMOTIVE PTE LTD



*bizSAFE*₃



WIN WIN RENT-A-CAR PTE LTD

Invoice

SGK9398C
TAN CHOO HENG
BLK 668A JURONG WEST ST 64
#06-120
S(641668)

Invoice No : WPLIN0001397
Invoice Date : 31/8/2017
Due Date : 31/8/2017
VHA No : 1790
Referral ID : N001

Description :	Amount
Rental for 7 Day/s @ \$140 per Day	\$980

Vehicle No : SKT 8174 T

Vehicle Description : Vezel 1.5 A

Rental Period : 15/08/2017 to 22/08/2017

Total Amount Payable : \$980

WIN WIN RENT-A-CAR PTE LTD

8 Kaki Bukit Ave 4 #06-04 Premier@Kaki Bukit Singapore 415875

Tel: 6315 8479 H/P: 9833 0807

VHA No: 1790

UEN: 201505115E

VEHICLE RENTAL AGREEMENT

10PLIN1397

SGK9398C(N51)

HIRER'S PARTICULARName: (as in I/C) WIN CHOO HENGNRIC/PASSPORT No: S 8022025DAddress (Res): BLK 668A JURONG MSTR ST 64H04-120 S(64/668)

Name & Address of Employer _____

Occupation: _____ Driving Exp: _____

Driving Licence No: S8022025D D/L Type: Local / InternationalIssue Date: 05/05/2009 Date of Birth: 6/10/1970Tel: (O) _____ (R) _____ HP/PG 92289398**ADDITIONAL DRIVER'S PARTICULARS**

Name: (as in I/C) _____


NRIC/PASSPORT No: _____

Address (Res): _____

Driving License No: _____ D/L Type: Local / International

Issue Date: _____ Date of Birth: _____

Occupation: _____ Driving Exp: _____

VEHICLE CHECK LIST**ACCESSORIES CHECK**

- ☐ Ashtray ☐ Cig Lighter ☐ S/Tyre
☐ STD Tools ☐ Jack ☐ Hub Caps
☐ Radio/Cass ☐ CD ☐ Cartridges

Vehicle No: SKT8174T Replace Veh No: _____Mileage Out: 41917 Mileage Out: _____Make & Model: H. VEZEL Auto / Manual

Group: _____

Out : Date 15/8/17 Time: _____

HIRE / PERIOD EXPIRY Time: _____

NON-WAIVER EXCESS=\$ 2000/-**CHARGES**Daily 7 @ \$ 140 per day \$ 980 -

Weekly @ \$ _____ per week

Monthly @ \$ _____ per month

Hours @ \$ _____ per hour

Others @ \$ _____

CDW @ \$ _____ per day/month

PAI @ \$ _____ per day/month

Delivery/Collection Service

SUB-TOTAL \$ _____

TOTAL CHARGES \$ _____

PETROL LEVELOut E 1/4 1/2 3/4 F

In E 1/4 1/2 3/4 F

EXTENSION

Misc. _____

TOTAL CHARGES \$ _____

Hirer's Signature _____

Additional Driver's Signature _____

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/credit card for payment. I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given WIN WIN RENT-A-CAR PTE LTD in connection with this agreement is true.

***IMPORTANT**

- ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY WIN WIN RENT-A-CAR PTE LTD.

RETURN OF VEHICLE. THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN " SINGAPORE OF HIRER / DRIVER " FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO WIN WIN RENT-A-CAR PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
<u>15/08/17</u>	<u>15:40M</u>				

TWINCAR RENTAL

Business Registration Number : 53092815M

Blk 2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 68420051 Fax : 67410510 email: sales@n51.com.sg

Invoice To :

TAN CHOO HENG
BLK 668A JURONG WEST ST 64
#06-120
SINGAPORE 641668

INVOICE

Invoice No. 13-1822

Date 15/8/2017

		Hirer's Car No.	VHA No.	Terms
		SGK9398C	71596	CASH
No. of Day	Description	Per Day	Amount (S\$)	
5	Car Rental from the period of 10/08/2017 to 15/08/2017. Vehicle no. SKW3546X Singapore Dollars Six Hundred Only	120.00	600.00	
		Total	\$600.00	

TWINCAR RENTAL



Authorised Signature



TWINCAR RENTAL

Kaki Bukit Autohub @ 2 Kaki Bukit Ave. 2 #01-18
Singapore 417921 Tel: 6744 0510 / 6842 0051

SKR 9398E (N571)

VHA No: 71396

ROC NO. 53092815M

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULAR


Name: (as in I/C) TAN CHOO HENG
NRIC/PASSPORT No: S 8072025D
Address (Res): BLK 668A JURONG WEST ST 64
#06-120 S (64/668)
Name & Address of Employer: _____
Occupation: _____ Driving Exp: _____
Driving Licence No: S 8072025D D/L Type: Local / International
Issue Date: 05/05/2009 Date of Birth: 26/10/1980
Tel: (O) _____ (R) _____ HP/PG: 92289398

ADDITIONAL DRIVER'S PARTICULARS

Name: (as in I/C) _____
NRIC/PASSPORT No: _____
Address (Res): _____
Driving Licence No: _____ D/L Type: Local / International
Issue Date: _____ Date of Birth: _____
Occupation: _____ Driving Exp: _____

VEHICLE CHECKLIST

INDICATE:
D - DENTS
S - SCRATCHES
A - ACCIDENTS



ACCESSORIES CHECK

☐ Ashtray ☐ Cig Lighter ☐ S/Tyre
☐ STD Tools ☐ Jack ☐ Hub Caps
☐ Radio / Cass ☐ CD ☐ Cartidges

Vehicle No: SKW 3546X Replace Veh No: SKR 9398E

Mileage Out: _____ Mileage Out: _____

Make & Model: Toyota Axio Auto / Manual
Group: _____

OUT: Date 10/8/2017 Time: 6.35pm

HIRE/PERIOD EXPIRY

NON-WAIVER EXCESS: \$ 4000

CHARGES

	@ \$	per day	per week	per month	per hour
Daily	120	5	600	00	
Weekly					
Monthly					
Hours					
Others					
CDW		per day/month			
PAI		per day/month			

Delivery Service

SUB-TOTAL \$

PETROL LEVEL

Out	E	1/4	1/2	3/4	F
In	E	1/4	1/2	3/4	F

EXTENSION

Collection Service

Misc.

TOTAL CHARGE \$ 600 00

Rented out by:

Hirer's Signature

Addition Driver's Signature _____

I have read and agree to the terms & condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given TWINCAR RENTAL in connection with this Agreement is true.

* IMPORTANT

- ONLY PERSONS ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN, AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY TWINCAR RENTAL.

RETURN OF VEHICLE - THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO TWINCAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
15/08/2017	12:30 HRS				

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0316-18-N51

11 June 2018

Tan Choo Heng
c/o N-51 Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-18
Kaki Bukit Auto Hub
Singapore 417921

INVOICE No. 0316-18-N51


Vehicle No. SGK9398C

<u>S/NO.</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$1,573.00
Total amount payable		<u>\$1,573.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0316-18-N51

11 June 2018

ACCIDENT VEHICLE SURVEY REPORT

Tan Choo Heng
c/o N-51 Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-18
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

Vehicle Reg No.:	SGK9398C	Odometer:	32537km
Make & Model:	Toyota Harrier 2.0 A	Colour:	White
Chassis number:	ZSU600040581	Date of accident:	08/08/2017
Year of Regn.:	17/06/2015	Date inspected:	15/08/2017
Repairer at:	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	22/08/2017

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	6mm/Bridgestone	6mm/Bridgestone	235/55R18
Rear:	6mm/Bridgestone	6mm/Bridgestone	235/55R18

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear and front portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
AIRCON CONDENSER	1	bent	1,447.80	1,447.80 SLV XNN
AIRCON CONDENSER AIR GUIDE L/R	2	warped	79.60	79.60
AIRCON CONDENSER FAN BLADE	1	reuse	79.40	0.00
AIRCON CONDENSER FAN MOTOR	1	reuse	366.30	0.00
AIRCON CONDENSER SENSOR	1	reuse	238.40	0.00
FAN COWLING ASSY	1	reuse	689.10	0.00
FRONT BONNET	1	repair	1,308.10	0.00
FRONT BONNET CHROME MOULDING	1	reuse	239.70	0.00
FRONT BONNET MECHANISM LOCK	1	bent	239.10	239.10 NNX
FRONT BONNET RUBBER GUIDE STOPPER L/R	2	reuse	20.00	0.00
FRONT BRACE PANEL	1	bent	220.00	220.00 XNN
FRONT BUMPER	1	squashed	1,450.40	1,450.40 CRAV
FRONT BUMPER FOGLAMP COVER L/R	2	warped	230.60	230.60 NNX
FRONT BUMPER FOGLAMP L/R	1 - 2	fractured	608.00	304.00 608.00 BRV
FRONT BUMPER INNER AIR GUIDE L/R	1	warped	39.80	39.80 NNX
FRONT BUMPER LOWER AIR GUIDE	1	warped	128.80	128.80 XNA
FRONT BUMPER LOWER COVER	1	fractured	135.70	135.70 XAN
FRONT BUMPER LOWER GRILLE	1	fractured	405.10	405.10 CRAV
FRONT BUMPER LOWER SPOILER	1	deformed	404.15	404.15 XNN
FRONT BUMPER REINFORCEMENT	1	bent	443.10	443.10 BTV
FRONT BUMPER SIDE RETAINER L/R	2	necessary	240.00	240.00 NECV
FRONT BUMPER TOP BEAM	1	bent	238.50	238.50 XNN
FRONT BUMPER TOW HOOK COVER	1	warped	68.25	68.25 XNN
FRONT GRILLE	1	fractured	785.10	785.10
FRONT GRILLE 'LOGO' EMBLEM	1	necessary	210.35	210.35
FRONT GRILLE BRACKET L/R	2	bent	290.60	290.60 XSC
FRONT GRILLE UPPER RUBBER SEAL	1	deformed	12.50	12.50 XNN
FRONT HEADLAMP L/R	1 - 2	fractured	6,442.00	3221.00 6,442.00 CRAV
FRONT HEADLAMP LOWER BRACKET L/R	2	bent	249.00	249.00 XNN
FRONT HEADLAMP LOWER PANEL L/R	2	repair	570.60	0.00
FRONT HEADLAMP LOWER PANEL SPONGE L/R	2	deformed	210.60	210.60 XAN
FRONT HORN (HIGH & LOW)	2	distortion	516.80	516.80 NNX
FRONT SUPPORT PANEL	1	bent	798.80	798.80 XR
FRONT SUPPORT PANEL INNER TOP GARNISH	1	warped	317.20	317.20
RADIATOR (AUTO)	1	bent	2,068.30	2,068.30 XNN
RADIATOR FAN BLADE	1	reuse	179.50	0.00
RADIATOR FAN MOTOR	1	reuse	538.70	0.00
RADIATOR UPPER BRACKET GARNISH	1	reuse	215.40	0.00
REAR BUMPER	1	squashed	1,395.30	1,395.30 DDV
REAR BUMPER INNER SPONGE	1	deformed	110.85	110.85 BRV
REAR BUMPER LH END SEAL COVER	1	warped	125.30	125.30
REAR BUMPER LOWER SPOILER	1	fractured	534.10	534.10

REAR BUMPER REFLECTOR L/R	1 - 2	fractured	196.00	98.00 196.00 BR ✓
REAR BUMPER SIDE RETAINER L/R	2	necessary	138.00	138.00 NEC ✓
REAR END PANEL	1	buckled	721.30	721.30 DD ✓
REAR END PANEL ANTENNA SENSOR	1	shorted	285.40	285.40 NN X
REAR END PANEL BUZZLE SENSOR	1	reuse	195.50	0.00
REAR END PANEL INNER TOP GARNISH	1	fractured	347.00	347.00 CRA ✓
REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	2	deformed	918.20	918.20 NN X
REAR LH FENDER AIR VENT	1	warped	138.40	138.40 NN X
REAR LH FENDER AIR VENT COVER	1	reuse	23.00	0.00
REAR NUMBER PLATE LAMP L/R	2	fractured	230.00	230.00 X NN
REAR SPARE TYRE INNER TOP SPONGE	1	reuse	335.40	0.00
REAR SPARE TYRE INNER TOP UPHOLSTERY BOARD COVER	1	reuse	483.10	0.00
REAR SPARE TYRE INNER TRAY GARNISH	1	reuse	315.40	0.00
REAR SPARE TYRE LH INNER SIDE STORAGE BOX	1	deformed	395.30	395.30 X NN
RR SPARE TYRE LH INNER SIDE STORAGE BOX TOP COVER	1	reuse	145.00	0.00
REAR TAILGATE	1	buckled	1,521.50	1,521.50 DD ✓
REAR TAILGATE 'HARRIER' EMBLEM	1	necessary	68.00	68.00 NEC ✓
REAR TAILGATE DAMPER L/R	2	bent	2,082.60	2,082.60 NN X
REAR TAILGATE HINGES L/R	2	bent	200.40	200.40 NN X
REAR TAILGATE INNER CLOSE BUTTON GARNISH	1	warped	234.30	234.30 NN X
REAR TAILGATE INNER DAMPER MOUNTING	1	reuse	131.90	0.00
REAR TAILGATE INNER PULL GARNISH	1	carped	305.10	305.10 NN X
REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH	1	fractured	269.00	269.00
REAR TAILGATE MECHANISM LOCK	1	bent	509.00	509.00
REAR TAILGATE MECHANISM LOCK COVER	1	warped	74.00	74.00 X NN
REAR TAILGATE MECHANISM LOCK MOTOR	1	shorted	581.90	581.90 X NN
REAR TAILGATE MECHANISM LOCK STRIKER	1	bent	38.00	38.00 X NN
REAR TAILGATE NETWORK CONTROL UNIT	1	shorted	585.30	585.30 X NN
REAR TAILGATE OPENER BUTTON SENSOR	1	shorted	195.00	195.00 X NN
REAR TAILGATE OUTER GARNISH	1	fractured	1,132.50	1,132.50 X NN
REAR TAILGATE OUTER GARNISH 'LOGO' EMBLEM	1	necessary	211.50	211.50 NEC ✓
REAR TAILGATE OUTER GARNISH MOULDING	1	reuse	95.30	0.00
REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R	2	necessary	102.20	102.20 X NN
REAR TAILGATE REFLECTOR L/R	2 - 1	fractured - LH, RH - NN	832.00	416 832.00 X
REAR TAILGATE RUBBER GUIDE STOPPER L/R	2	deformed	90.00	90.00 NN X
REAR TAILGATE SIDE SENSOR L/R	2	shorted	488.60	488.60 NN X
REAR TAILGATE WEATHER STRIP	1	deformed	357.00	357.00
REAR TAILGATE WINDSCREEN MOULDING	1	necessary	136.40	136.40 NEC ✓
REAR TAILGATE WIPER MOTOR	1	shorted	630.40	630.40 NN X
REAR TAILLAMP L/R	2	fractured LH, RH - NN	853.80	426.90 853.80 X
REAR TAILLAMP LOWER BRACKET L/R	2	bent	192.20	192.20 NN X
Subtotal before discount			S\$ 41,675.80	S\$ 35,506.00
Percentage discount 25% and 25%			S\$ 10,418.95	S\$ 8,876.50
Sub-total 1			S\$ 31,256.85	S\$ 26,629.50

AIRCON CONDENSER AIR GUIDE CLIPS - SET	2	necessary	60.00	30 60.00 NECV
FRONT BONNET CHROME MOULDING CLIPS - SET	1	necessary	30.00	30.00 X NN
FRONT BONNET INSULATOR MAT CLIPS - SET	1	reuse	50.00	0.00
FRONT BUMPER CLIPS - SET	1	necessary	80.00	30 80.00 NECV
FRONT BUMPER INNER AIR GUIDE CLIPS L/R - SET	2	necessary	60.00	20 60.00
FRONT GRILLE CLIPS - SET	1	necessary	30.00	20 30.00
FRONT NUMBER PLATE	1	bent	25.00	25.00 BT ✓
FRONT NUMBER PLATE HOLDER	1	bent	50.00	40.00 50.00 BT ✓
FRONT SUPPORT PANEL INNER TOP GARNISH CLIPS - SET	1	necessary	50.00	30 50.00
RADIATOR COOLANT - BOT	1	necessary	80.00	80.00 NN X
REAR BUMPER CLIPS - SET	1	necessary	50.00	30 50.00 NECV
REAR BUMPER END SEAL COVER CLIPS L/R - SET	2	necessary	60.00	30 60.00
REAR BUMPER REVERSE SENSOR	1	shorted	350.00	200.00 350.00 CUT ✓
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	necessary	30.00	20 30.00 NECV
REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R - SET	2	necessary	100.00	100.00 NN X
REAR NUMBER PLATE	1	reuse	25.00	0.00
REAR NUMBER PLATE HOLDER	1	reuse	50.00	0.00
REAR SPARE TYRE INNER TOP RUBBER MAT COVER	1	necessary	500.00	500.00 X NN
REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS - SET	1	necessary	100.00	40 100.00 NECV
REAR TAILGATE OUTER GARNISH CLIPS - SET	1	necessary	30.00	20 30.00
REAR TAILGATE REVERSE CAMERA	1	reuse	800.00	0.00
REAR TAILGATE WINDSCREEN SEALANT	1	necessary	100.00	40.00 100.00 NECV
REAR TAILLAMP CLIPS L/R - SET	2	necessary	60.00	20 60.00
Subtotal before discount			S\$ 2,770.00	S\$ 1,845.00
Sub-total 2			S\$ 2,770.00	S\$ 1,845.00
Parts-total			S\$ 34,026.85	S\$ 28,474.50

LABOUR

To remove, change air con parts, vacuums, refill air con gas.	180.00	150.00	X
To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	200.00	140.00	50
To remove, reinstall tailgate windscreen	300.00	80.00 150.00	120
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	200.00	60.00	X
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1,700.00	1,200.00	900
To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.	1,500.00	1,000.00	700
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2,800.00	2,420.00	1300
To apply anti-rust chemical on repaired and replaced panel.	150.00	150.00	90
Labour Total	S\$ 7,030.00	S\$ 5,270.00	
Parts & Labour Total	S\$ 41,056.85	S\$ 33,744.50	

10 days

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

**Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 28,700.00
and the recommended number of working days for the repairs is within 12 day(s).**



B J Loi (I Eng., MIMI, AIRTE)
Automotive Appraiser



Your Ref: 18.25471

Date: 10th Jan 2019

Our Ref : CS3/AXA17015633/Bvbe2-1

M/s AXA Insurance Pte Ltd
C/O: Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877
(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SGK 9398C
INSURED VEHICLE: SJH 4922C
ACCIDENT DATE: 08/08/2017

We thank you for your instruction on 26/12/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SGK 9398C from M/s Par Automotive Consultancy.
- b) Singapore Accident Statement of Vehicle SGK 9398C.
- c) Final Repair Bill of SGK 9398C from N-51 Automotive Pte Ltd
- d) Colour damaged vehicle photographs of SGK 9398C.

Pre-Repair Inspection Date : 15/08/2017 at M/s N-51 Automotive Pte Ltd, 2 Kaki Bukit Ave 2
#01-17 Kaki Bukit Autohub, Singapore 417921.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SGK 9398C
Make & Model	: Toyota Harrier Premium 2.0 CVT
Year of Registration	: 2015
Chassis Number	: ZSU600040581
Engine Capacity	: 1986 cc
2. We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGK 9398C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	AIRCON CONDENSER	NOT NECESSARY	1,447.80	-
2	AIRCON CONDENSER AIR GUIDE L/R	WARPED	79.60	79.60
1	AIRCON CONDENSER FAN BLADE	REUSE	79.40	-
1	AIRCON CONDENSER FAN MOTOR	REUSE	366.30	-
1	AIRCON CONDENSER SENSOR	REUSE	238.40	-
1	FAN COWLING ASSY	REUSE	689.10	-
1	FRONT BONNET	TO REPAIR SEE LABOUR	1,308.10	-
1	FRONT BONNET CHROME MOULDING	REUSE	239.70	-
1	FRONT BONNET MECHANISM LOCK	NOT NECESSARY	239.10	-
2	FRONT BONNET RUBBER GUIDE STOPPER L/R	REUSE	20.00	-
1	FRONT BRACE PANEL	NOT NECESSARY	220.00	-
1	FRONT BUMPER	CRACKED	1,450.40	1,450.40
2	FRONT BUMPER FOGLAMP COVER L/R	NOT NECESSARY	230.60	-
2	FRONT BUMPER FOGLAMP L/R	N/S BROKEN	608.00	304.00
1	FRONT BUMPER INNER AIR GUIDE L/R	NOT NECESSARY	39.80	-
1	FRONT BUMPER LOWER AIR GUIDE	NOT NECESSARY	128.80	-
1	FRONT BUMPER LOWER COVER	NOT NECESSARY	135.70	-
1	FRONT BUMPER LOWER GRILLE	CRACKED	405.10	405.10
1	FRONT BUMPER LOWER SPOILER	NOT NECESSARY	404.15	-
1	FRONT BUMPER REINFORCEMENT	BENT	443.10	443.10
2	FRONT BUMPER SIDE RETAINER L/R	NECESSARY	240.00	240.00
1	FRONT BUMPER TOP BEAM	NOT NECESSARY	238.50	-
1	FRONT BUMPER TOW HOOK COVER	NOT NECESSARY	68.25	-
1	FRONT GRILLE	FRACTURED	785.10	785.10
1	FRONT GRILLE 'LOGO' EMBLEM	NECESSARY	210.35	210.35
2	FRONT GRILLE BRACKET L/R	SERVICEABLE	290.60	-
1	FRONT GRILLE UPPER RUBBER SEAL	NOT NECESSARY	12.50	-
2	FRONT HEADLAMP L/R	N/S CRACKED	6,442.00	3,221.00
2	FRONT HEADLAMP LOWER BRACKET L/R	NOT NECESSARY	249.00	-
2	FRONT HEADLAMP LOWER PANEL L/R	TO REPAIR SEE LABOUR	570.60	-
2	FRONT HEADLAMP LOWER PANEL SPONGE L/R	NOT NECESSARY	210.60	-
2	FRONT HORN (HIGH & LOW)	NOT NECESSARY	516.80	-

Report Ref No. CS3/AXA17015633/Bvbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	798.80	-
1	FRONT SUPPORT PANEL INNER TOP GARNISH	WARPED	317.20	317.20
1	RADIATOR (AUTO)	NOT NECESSARY	2,068.30	-
1	RADIATOR FAN BLADE	REUSE	179.50	-
1	RADIATOR FAN MOTOR	REUSE	538.70	-
1	RADIATOR UPPER BRACKET GARNISH	REUSE	215.40	-
1	REAR BUMPER	DENTED	1,395.30	1,395.30
1	REAR BUMPER INNER SPONGE	BROKEN	110.85	110.85
1	REAR BUMPER LH END SEAL COVER	WARPED	125.30	125.30
1	REAR BUMPER LOWER SPOILER	FRACTURED	534.10	534.10
2	REAR BUMPER REFLECTOR L/R	BROKEN-1PC ONLY	196.00	98.00
2	REAR BUMPER SIDE RETAINER L/R	NECESSARY	138.00	138.00
1	REAR END PANEL	DENTED	721.30	721.30
1	REAR END PANEL ANTENNA SENSOR	NOT NECESSARY	285.40	-
1	REAR END PANEL BUZZLE SENSOR	REUSE	195.50	-
1	REAR END PANEL INNER TOP GARNISH	CRACKED	347.00	347.00
2	REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	NOT NECESSARY	918.20	-
1	REAR LH FENDER AIR VENT	NOT NECESSARY	138.40	-
1	REAR LH FENDER AIR VENT COVER	REUSE	23.00	-
2	REAR NUMBER PLATE LAMP L/R	NOT NECESSARY	230.00	-
1	REAR SPARE TYRE INNER TOP SPONGE	REUSE	335.40	-
1	REAR SPARE TYRE INNER TOP UPHOLSTERY BOARD COVER	REUSE	483.10	-
1	REAR SPARE TYRE INNER TRAY GARNISH	REUSE	315.40	-
1	REAR SPARE TYRE LH INNER SIDE STORAGE BOX	NOT NECESSARY	395.30	-
1	RR SPARE TYRE LH INNER SIDE STORAGE BOX TOP COVER	REUSE	145.00	-
1	REAR TAILGATE	DENTED	1,521.50	1,521.50
1	REAR TAILGATE 'HARRIER' EMBLEM	NECESSARY	68.00	68.00
2	REAR TAILGATE DAMPER L/R	NOT NECESSARY	2,082.60	-
2	REAR TAILGATE HINGES L/R	NOT NECESSARY	200.40	-
1	REAR TAILGATE INNER CLOSE BUTTON GARNISH	NOT NECESSARY	234.30	-
1	REAR TAILGATE INNER DAMPER MOUNTING	REUSE	131.90	-
1	REAR TAILGATE INNER PULL GARNISH	NOT NECESSARY	305.10	-
1	REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH	FRACTURED	269.00	269.00
1	REAR TAILGATE MECHANISM LOCK	BENT	509.00	509.00

Report Ref No. CS3/AXA17015633/Bvbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILGATE MECHANISM LOCK COVER	NOT NECESSARY	74.00	-
1	REAR TAILGATE MECHANISM LOCK MOTOR	NOT NECESSARY	581.90	-
1	REAR TAILGATE MECHANISM LOCK STRIKER	NOT NECESSARY	38.00	-
1	REAR TAILGATE NETWORK CONTROL UNIT	NOT NECESSARY	585.30	-
1	REAR TAILGATE OPENER BUTTON SENSOR	NOT NECESSARY	195.00	-
1	REAR TAILGATE OUTER GARNISH	NOT NECESSARY	1,132.50	-
1	REAR TAILGATE OUTER GARNISH 'LOGO' EMBLEM	NOT NECESSARY	211.50	-
1	REAR TAILGATE OUTER GARNISH MOUDLING	REUSE	95.30	-
2	REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R	NOT NECESSARY	102.20	-
2	REAR TAILGATE REFLECTOR L/R	N/S FRACTURED / O/S NOT NECESSARY	832.00	416.00
2	REAR TAILGATE RUBBER GUIDE STOPPER L/R	NOT NECESSARY	90.00	-
2	REAR TAILGATE SIDE SENSOR L/R	NOT NECESSARY	488.60	-
1	REAR TAILGATE WEATHER STRIP	DEFORMED	357.00	357.00
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	136.40	136.40
1	REAR TAILGATE WIPER MOTOR	NOT NECESSARY	630.40	-
2	REAR TAILLAMP L/R	N/S FRACTURED / O/S NOT NECESSARY	853.80	426.90
2	REAR TAILLAMP LOWER BRACKET L/R	NOT NECESSARY	192.20	-
	LESS 25% DISCOUNT		-10,418.95	-3,657.38
			31,256.85	10,972.12
SPECIAL NETT ITEMS				
2	SET AIRCON CONDENSER AIR GUIDE CLIPS (SN)	NECESSARY	60.00	30.00
1	SET FRONT BONNET CHROME MOULDING CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET FRONT BONNET INSULATOR MAT CLIPS (SN)	REUSE	50.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
2	SET FRONT BUMPER INNER AIR GUIDE CLIPS L/R (SN)	NECESSARY	60.00	20.00
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	30.00	20.00
1	FRONT NUMBER PLATE (SN) }	BENT	25.00	40.00
1	FRONT NUMBER PLATE HOLDER (SN) }		50.00	-
1	SET FRONT SUPPORT PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	50.00	30.00
1	BOT RADIATOR COOLANT (SN)	NOT NECESSARY	80.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
2	SET REAR BUMPER END SEAL COVER CLIPS L/R (SN)	NECESSARY	60.00	30.00

Report Ref No. CS3/AXA17015633/Bvbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER REVERSE SENSOR (SN)	CUT	350.00	200.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	30.00	20.00
2	SET REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R (SN)	NOT NECESSARY	100.00	-
1	REAR NUMBER PLATE (SN)	REUSE	25.00	-
1	REAR NUMBER PLATE HOLDER (SN)	REUSE	50.00	-
1	REAR SPARE TYRE INNER TOP RUBBER MAT COVER (SN)	NOT NECESSARY	500.00	-
1	SET REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS (SN)	NECESSARY	100.00	40.00
1	SET REAR TAILGATE OUTER GARNISH CLIPS (SN)	NECESSARY	30.00	20.00
1	REAR TAILGATE REVERSE CAMERA (SN)	REUSE	800.00	-
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	100.00	40.00
2	SET REAR TAILLAMP CLIPS L/R (SN)	NECESSARY	60.00	20.00
			2,770.00	570.00
	LABOUR			
	TO REMOVE, CHANGE AIR CON PARTS, VACUUMS, REFILL AIR CON GAS.	NOT NECESSARY	180.00	-
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR.		200.00	50.00
	TO REMOVE, REINSTALL TAILGATE WINDSCREEN.		300.00	120.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	NOT NECESSARY	200.00	-
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.		1,700.00	900.00
	TO RE-SPRAY PAINTING ON THE FRONT BONNET, FRONT SUPPORT PANEL, FRONT FENDER (L/R) AND FRONT BUMPER.		1,500.00	700.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BONNET, FRONT HEADLAMP LOWER PANEL L/R AND FRONT SUPPORT PANEL.		2,800.00	1,300.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		150.00	90.00
			7,030.00	3,160.00
	GRAND TOTAL		41,056.85	14,702.12

Report Ref No. CS3/AXA17015633/Bvbe2-1



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			11,700.00
---	--	--	-----------

Report Ref No. CS3/AXA17015633/Bvbe2-1

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.